



Aviation Investigation Notification

Location:	Mineral Point, WI	Accident Number:	CEN21LA452
Date & Time:	July 20, 2021, 13:30 Local	Registration:	N44XB
Aircraft:	ROBINSON HELICOPTER R44	Injuries:	1 None
Flight Conducted Under:	Part 137: Agricultural		

The NTSB is conducting a [Class 4 investigation](#) into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:	ROBINSON HELICOPTER	Registration:	N44XB
Model/Series:	R44	Aircraft Category:	Helicopter
Amateur Built:			
Operator:	MF HELICOPTERS LLC	Operating Certificate(s) Held:	Agricultural aircraft (137)
Operator Designator Code:			

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	KMRJ	Observation Time:	16:30 Local
Distance from Accident Site:		Temperature/Dew Point:	29°C /18°C
Lowest Cloud Condition:	Clear	Wind Speed/Gusts, Direction:	8 knots, 340°
Lowest Ceiling:		Visibility:	10 miles
Altimeter Setting:	30.09 inches Hg	Type of Flight Plan Filed:	NONE
Departure Point:	Mineral Point, WI	Destination:	Mineral Point, WI

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	42.874434,-90.208609 (est)

Administrative Information

Investigator In Charge (IIC):	Hatch, Craig
Additional Participating Persons:	Mike Brockel; FAA FSDO; Milwaukee, WI
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.