













Aviation Investigation Preliminary Report

Location: Millen, GA **Accident Number:** ERA21LA386

Date & Time: September 29, 2021, 10:30 Local N430NR Registration:

Aircraft: Hiller UH-12E Injuries: 1 Minor

Flight Conducted Under: Part 137: Agricultural

Aircraft and Owner/Operator Information

Aircraft Make: Hiller Registration: N430NR

Model/Series: **UH-12E Aircraft Category:** Helicopter

Amateur Built:

On file **Operating Certificate(s)** Agricultural aircraft (137) Operator:

Held:

Operator Designator Code:

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	TBR,187 ft msl	Observation Time:	13:55 Local
Distance from Accident Site:	16 Nautical Miles	Temperature/Dew Point:	29°C /16°C
Lowest Cloud Condition:	Clear	Wind Speed/Gusts, Direction:	6 knots / , 300°
Lowest Ceiling:	None	Visibility:	10 miles
Altimeter Setting:	30.02 inches Hg	Type of Flight Plan Filed:	None
Departure Point:	Metter, GA	Destination:	Metter, GA

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	32.615,-82.002222

Administrative Information

Investigator In Charge (IIC): Spencer, Lynn

Additional Participating Persons: Rodney Hood; FAA/FSDO; Atlanta, GA

Investigation Class: Class 3

Note: The NTSB did not travel to the scene of this accident.

Page 2 of 2 ERA21LA386