



Aviation Investigation Notification

| | | | |
|--------------------------------|---|-------------------------|------------|
| Location: | Miamisburg, OH | Accident Number: | CEN22LA041 |
| Date & Time: | November 19, 2021, 11:30 Local | Registration: | N221HG |
| Aircraft: | Robinson Helicopter R22 Beta | Injuries: | 1 None |
| Flight Conducted Under: | Part 91: General aviation - Instructional | | |

The NTSB is conducting a [Class 4 investigation](#) into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

| | | | |
|----------------------------------|---|---------------------------------------|------------|
| Aircraft Make: | Robinson Helicopter | Registration: | N221HG |
| Model/Series: | R22 Beta | Aircraft Category: | Helicopter |
| Amateur Built: | | | |
| Operator: | Higher Ground Helicopters of Cincinnati LLC | Operating Certificate(s) Held: | None |
| Operator Designator Code: | | | |

Meteorological Information and Flight Plan

| | | | |
|---|----------------------|-------------------------------------|----------------------|
| Conditions at Accident Site: | VMC | Condition of Light: | Day |
| Observation Facility, Elevation: | MGY,957 ft msl | Observation Time: | 11:53 Local |
| Distance from Accident Site: | 0 Nautical Miles | Temperature/Dew Point: | 4°C /-6°C |
| Lowest Cloud Condition: | Clear | Wind Speed/Gusts, Direction: | 8 knots / , 10° |
| Lowest Ceiling: | None | Visibility: | 10 miles |
| Altimeter Setting: | 30.53 inches Hg | Type of Flight Plan Filed: | VFR |
| Departure Point: | Miamisburg, OH (MGY) | Destination: | Miamisburg, OH (MGY) |

Wreckage and Impact Information

| | | | |
|----------------------------|--------|-----------------------------|----------------------------|
| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
| Passenger Injuries: | | Aircraft Fire: | None |
| Ground Injuries: | | Aircraft Explosion: | None |
| Total Injuries: | 1 None | Latitude, Longitude: | 39.588972,-84.224861 (est) |

Administrative Information

| | |
|--|--|
| Investigator In Charge (IIC): | Fox, Andrew |
| Additional Participating Persons: | Paige E. Kakas; Federal Aviation Administration - Cincinnati FSDO ; Cincinnati, OH |
| Investigation Class: | Class 4 |
| Note: | The NTSB did not travel to the scene of this accident. |