













Aviation Investigation Notification

Location: Miamisburg, OH Accident Number: CEN22LA041

Date & Time:November 19, 2021, 11:30 LocalRegistration:N221HG

Aircraft: Robinson Helicopter R22 Beta Injuries: 1 None

Flight Conducted Under: Part 91: General aviation - Instructional

The NTSB is conducting a <u>Class 4 investigation</u> into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:	Robinson Helicopter	Registration:	N221HG
Model/Series:	R22 Beta	Aircraft Category:	Helicopter

Amateur Built:

Operator: Higher Ground Helicopters of Operating Certificate(s) None

Cincinnati LLC Held:

Operator Designator Code:

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	MGY,957 ft msl	Observation Time:	11:53 Local
Distance from Accident Site:	0 Nautical Miles	Temperature/Dew Point:	4°C /-6°C
Lowest Cloud Condition:	Clear	Wind Speed/Gusts, Direction:	8 knots / , 10°
Lowest Ceiling:	None	Visibility:	10 miles
Altimeter Setting:	30.53 inches Hg	Type of Flight Plan Filed:	VFR
Departure Point:	Miamisburg, OH (MGY)	Destination:	Miamisburg, OH (MGY)

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	39.588972,-84.224861 (est)

Administrative Information

Investigator In Charge (IIC):	Fox, Andrew
Additional Participating Persons:	Paige E. Kakas; Federal Aviation Administration - Cincinnati FSDO ; Cincinnati, OH
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.

Page 2 of 2 CEN22LA041