



Aviation Investigation Notification

Location:	Scio, OR	Accident Number:	WPR22LA045
Date & Time:	November 22, 2021, 15:10 Local	Registration:	N102LD
Aircraft:	ELVIN JACK R JR ROTORWAY EXEC 162F	Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Flight test		

The NTSB is conducting a [Class 4 investigation](#) into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:	ELVIN JACK R JR	Registration:	N102LD
Model/Series:	ROTORWAY EXEC 162F	Aircraft Category:	Helicopter
Amateur Built:	Yes		
Operator:	Jack R Elvin JR	Operating Certificate(s) Held:	None
Operator Designator Code:			

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	KCVO,250 ft msl	Observation Time:	14:56 Local
Distance from Accident Site:	21 Nautical Miles	Temperature/Dew Point:	9°C /6°C
Lowest Cloud Condition:		Wind Speed/Gusts, Direction:	3 knots / , 330°
Lowest Ceiling:	Overcast / 8000 ft AGL	Visibility:	10 miles
Altimeter Setting:	30.08 inches Hg	Type of Flight Plan Filed:	NONE
Departure Point:	Scio, OR	Destination:	Scio, OR

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	44.638285,-122.82748 (est)

Administrative Information

Investigator In Charge (IIC): Salazar, Fabian

Additional Participating Persons: Jason Lawver; Federal Aviation Administration; Portland, OR

Investigation Class: [Class 4](#)

Note: The NTSB did not travel to the scene of this accident.