



Aviation Investigation Notification

Location:	Bridgeport, TX	Accident Number:	CEN22LA078
Date & Time:	December 14, 2021, 13:50 Local	Registration:	N862YB
Aircraft:	BELL HELICOPTER TEXTRON CANADA 407	Injuries:	1 Minor, 1 None
Flight Conducted Under:	Part 91: General aviation - Personal		

The NTSB is conducting a [Class 4 investigation](#) into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:	BELL HELICOPTER TEXTRON CANADA	Registration:	N862YB
Model/Series:	407	Aircraft Category:	Helicopter
Amateur Built:			
Operator:	OREGON AIRBUS LLC	Operating Certificate(s) Held:	None
Operator Designator Code:			

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	KXBP, 851 ft msl	Observation Time:	13:55 Local
Distance from Accident Site:	0 Nautical Miles	Temperature/Dew Point:	24°C / 15°C
Lowest Cloud Condition:	Scattered / 3200 ft AGL	Wind Speed/Gusts, Direction:	9 knots / 16 knots, 210°
Lowest Ceiling:	None	Visibility:	10 miles
Altimeter Setting:	30.1 inches Hg	Type of Flight Plan Filed:	NONE
Departure Point:	Fort Worth, TX (AFW)	Destination:	Bridgeport, TX

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 Minor, 1 None	Latitude, Longitude:	33.1739,-97.8284 (est)

Administrative Information

Investigator In Charge (IIC):	Link, Samantha
Additional Participating Persons:	Michael Baker; Federal Aviation Administration; Fort Worth, TX
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.