

UNCLAS //N16500//

SUBJ: POST MARINE INCIDENT SURVEY

A. COMCOGARD SECTOR HOUSTON GALVESTON TX 311514Z OCT 11.

1. CONDUCTED POST MARINE INCIDENT SURVEY IN VICINITY OF HOUSTON SHIP CHANNEL LIGHTS 71-83 AND BAYPORT SHIP CHANNEL.

2. THE FOLLOWING AIDS WERE FOUND DISCREPANT:

A. MORGANS POINT APPROACH OUTER RANGE REAR LIGHT, LLNR 24000, FOUND WITH DAY OPTIC OPERATING AT REDUCED INTENSITY.

3. THE FOLLOWING AIDS WERE FOUND WATCHING PROPERLY:

A. HOUSTON SHIP CHANNEL LIGHT 71 LLNR 24365 B. HOUSTON SHIP CHANNEL LIGHT 72 LLNR 25370 C. HOUSTON SHIP CHANNEL LIGHT 73 LLNR 24375 D. HOUSTON SHIP CHANNEL LIGHT 74 LLNR 24380 E. HOUSTON SHIP CHANNEL LIGHT 75 LLNR 24385 F. HOUSTON SHIP CHANNEL LIGHT 76 LLNR 24390 G. HOUSTON SHIP CHANNEL LIGHT 78 LLNR 24520 H. HOUSTON SHIP CHANNEL LIGHT 82 LLNR 24530 I. HOUSTON SHIP CHANNEL LIGHT 83 LLNR 24535 J. BAYPORT SHIP CHANNEL JUNCTION LIGHT B LLNR 24455 K. BAYPORT SHIP CHANNEL LIGHT 2 LLNR 24460 L. BAYPORT SHIP CHANNEL LIGHT 3 LLNR 24475 M. BAYPORT SHIP CHANNEL LIGHT 4 LLNR 24480 N. BAYPORT SHIP CHANNEL LIGHT 5 LLNR 24485 O. BAYPORT SHIP CHANNEL LIGHT 6 LLNR 24490 P. BAYPORT SHIP CHANNEL LIGHT 7 LLNR 24495 Q. MORGANS POINT APPROACH OUTER RANGE FRONT LIGHT LLNR 24395 R. UPPER GALVESTON BAY INNER RANGE REAR LIGHT LLNR 24220 S. UPPER GALVESTON BAY INNER RANGE FRONT LIGHT LLNR 24215 T. BAYPORT SHIP CHANNEL OUTER RANGE REAR LIGHT LLNR 24440 U. BAYPORT SHIP CHANNEL OUTER RANGE FRONT LIGHT LLNR 24430 V. BAYPORT SHIP CHANNEL INNER RANGE FRONT LIGHT LLNR 24465 W. BAYPORT SHIP CHANNEL INNER RANGE REAR LIGHT LLNR 24470