## MAJOR MAINTENANCE AND REPAIR WORK IN THE ENGINE.

## **WEEK.6. 2000**

- 1. CHANGED BOTTOM BLOWING VALVE FROM DRUM ON BOILER # 24.
- 2. CONTINUE REPAIRS ON BOILER # 23, BLU-RAM, WELDING OF NEW DRAINS.
- 3. NEW PUMP AND NEW PIPES ON TRANSFER SYSTEM FOR BILGE WATER TO SEPARATOR. (FWD)
- 4. MADE NEW SPINDLE FOR AUMA VALVE ON FEED PUMP # 21.
- 5. ADJUSTED AND TESTED AUMA VALVE ON FEED PUMP # 21 LOCALLY.
- 6. WORK WITH SHEETMETAL ON BOILER # 23, AIR LEAKS. ALSO AROUND THE HATCHES FOR UPPER AND LOWER EQONOMICERS.
- 7. CHANGING OF BEARINGS ON THE AFT. PORT TENDER DAVIT.
- 8. CHANGING MOTOR ON FIRE PUMP # 22.
- 9. CHANGING BILGE LINE IN FORWARD ENGINE ROOM.
- 10. PREPARING NEW BILGE LINE IN AFT. ENGINE ROOM.