

62

MAJOR MAINTENANCE AND REPAIR WORK
IN THE ENGINE.

WEEK. 08-2001

1. BYPASSED 1 LEAK TUBE ON GREEN ECONOMIZER. MB-23
2. CHANGED MAIN STEAM VALVE, INTEC CUT AND WELDING ON STEAM PIPE TO TG.# 10
3. OVERHAULED CONDENSAT PUMP FOR EVAP.# 22
4. PREFABRICATED PIPES FOR WATER ON DECK LINE IN AFT AUX.ENG.ROOM.
5. CHANGED MAIN STEAM VALVES, INTEC CUT AND WELDING STEAM PIPES FOR TG.# 20-22
6. FULL OVERHAULING OF SEAWATER COOLING PUMP FOR TG.# 22
7. MAJOR CLEANING ON TANK TOP IN ENGINE ROOMS.
8. MOUNTING NEW TANK FOR SAW DUST, MAIN CONDENSER P/S.
9. CHANGED CYL.HEAD # 3 MAK.#16
10. PREFABRICATED PIPES FOR HOT WATER IN FWD. BOILER ROOM.
11. STARTED DISMANTLING OF P.2 PUMP FOR OSMOSIS.
12. MOVING UP STERN TUBE GLAND S/B - P/S.