

**New York City Fire Department Units Responding to the *Andrew J. Barberi* Allision  
May 8, 2010**

Source: FDNY Incident Report 3-0040-0

Unit <sup>1</sup>	Time on scene/ cleared <sup>2</sup>	Actions taken	Unit Location	Distance to St. George Terminal <sup>3</sup>
Battalion Commander 22	0930/1222	Incident Commander until relieved by Division 8 Commander; then supervised operations on the lower deck of the <i>Andrew J. Barberi</i> .	1189 Castleton Ave Staten Island, NY	3.4 mi
Engine Company 155	0930/1052	Assisted with assessment, treatment, and stabilization of passengers. Boarded six passengers. Assisted EMS personnel by carrying injured passengers off of the <i>Andrew J. Barberi</i> . Conducted search of upper level of vessel (with Ladder Company 78). Set up and cordoned off triage area.	14 Brighton Ave Staten Island, NY	1.3 mi
Engine Company 153	0931/1101	Operated on second deck. Provided aid to three female and one male. Boarded 1 female and provided oxygen to 1 male. Assisted with triage of 13 yellow tag patients.	74 Broad Street Staten Island, NY	1.5 mi
Ladder Company 077	0931/1102	Instructed the civilians to take seats and remain calm. Noted the nature and number of injuries and began administering first aid and conducted a primary search of the first and second deck. Carried patients off the <i>Andrew J. Barberi</i> on backboards. Conducted a second search of the upper levels of the <i>Andrew J. Barberi</i> and of the water around the boat, both searches were negative.	74 Broad Street Staten Island, NY	1.5 mi
Battalion Commander 21	0932/1115	Supervised operations on the upper deck of the <i>Andrew J. Barberi</i> .	256 Hylan Boulevard Staten Island, NY	2.5 mi
District Commander 8	0933/1206	Incident Commander (Relieved BC22 as IC)	1850 Clove Road Staten Island, NY	3.0 mi
Rescue Squad 05	0933/1038	Evaluated damage and injuries in wheel house and below decks. Assisted in packaging patients on the second level. Performed secondary searches on the first level and all below deck areas of the <i>Andrew J. Barberi</i> with negative results.	1850 Clove Road Staten Island, NY	3.0 mi

<sup>1</sup> The normal manning of a unit consists of the members of the company on call during a given tour, consisting of a Lieutenant or a Captain plus a number of firefighters depending on the type of unit: 3-4 firefighters on an engine company, 5 on a ladder company, (also known as a truck company), 5 for a rescue company, 5 for a squad company, 4 for a marine company, and 6 for the hazardous materials company.

<sup>2</sup> The accident occurred at 0919 EDT and the NYPD notified the NYFD at 0923 EDT.

<sup>3</sup> Distance determined using unit address and St. George Terminal address of 30Richmond Terrace. Tool used: Bing Maps Driving Directions.

Tactical Support Unit 02	0934/1041	Assisted Rescue Squad 5.	1850 Clove Road Staten Island, NY	3.0 mi
Engine Company 152	0934/1108	Operated on the middle level of the <i>Andrew J. Barberi</i> . Conducted patient assessment of a victim with a leg injury and removed patient w/leg injury on a long board. Then assisted the disembarkation and triage of other patients.	256 Hylan Boulevard Staten Island, NY	2.5 mi
Ladder Company 079	0935/1046	Assigned as SOC Support Ladder (SOC Support Ladder Companies purpose is to assist in detecting the presence of hazardous materials, including chemical warfare agents and radioactive materials). Reported on ferry with first responder medical equipment and multiple backboards. Helped carry multiple patients off the ferry. Conducted secondary search on 2nd level of vessel. Results were negative.	1189 Castleton Avenue Staten Island, NY	3.4 mi
Engine Company 161	0940/1221	Designated as Water Rescue. Boarded a patient on the second deck and removed to EMS triage area. Assisted EMS loading patients in to ambulances.	278 McClean Avenue Staten Island, NY	3.9 mi
Marine Unit 6	0940/1037	Conducted primary and secondary search of water near the <i>Andrew J. Barberi</i> . Results negative.	Brooklyn Navy Yard Bldg 292 Brooklyn, NY	6.3 mi (by water)
Rescue Squad 01	0943/1035	Conducted searches on the upper levels of the ship. Assisted other fire companies with searches on the upper decks of the <i>Andrew J. Barberi</i> . All searches negative.	788 Union Street Brooklyn, NY	13.6 mi
Safety Battalion 01	0950/1116	Incident safety officer	Brooklyn Navy Yard Bldg 292 Brooklyn, NY	15.1 mi
Engine Company 160	0950/1109	Placed a victim on a backboard and removed victim to the triage area.	1850 Clove Road Staten Island, NY	3.0 mi
Ladder Company 081	0951/1210	Conducted search on top deck, pilot houses and exterior top deck the <i>Andrew J. Barberi</i> . Assisted with patient transport from triage area to MTA buses.	278 McClean Avenue Staten Island, NY	3.9 mi
Engine Company 156	0952/1204	Assisted with the removal of injured from the <i>Andrew J. Barberi</i> .	412 Broadway Staten Island, NY	3.0 mi
Engine Company 157	0953/1049	Treated and assisted in the disembarkation of passengers from the <i>Andrew J. Barberi</i> .	1573 Castleton Avenue Staten Island, NY	4.1 mi
Marine Unit 9	0953/1401	Conducted a visual assessment of the ferry's hull from the water side. Conducted a search for victims on the water side. All searches negative.	350 Front Street, Pier 14 Staten Island, NY	1.0 mi (by water)
Ladder Company 080	0954/1151	Assigned as FAST Truck (Fire Assistance Search Team; designed to assist NYFD personnel in trouble during response). After incident commander declared	1573 Castleton Avenue Staten Island, NY	4.1 mi

		incident under control, assisted triaging and removing patients to an MTA bus for transportation to RUMC.		
Ladder Company 083	0955/1057	Assisted with the injured in the triage area.	875 Jewett Avenue Staten Island, NY	4.3 mi
Rescue Battalion 01	0956/1029	Performed survey of below deck area. Found no evidence of flooding. Conferred with NYPD and ship's officers (on bridge). Verified patient count with incident commander.	Roosevelt Island, NY	21.8
Engine Company 166	0956/1221	Treated one ferry employee and then was assigned to the number two (yellow) triage area to assist EMS carrying injured to busses.	1400 Richmond Avenue Staten Island, NY	6.8 mi
Battalion Commander 40	0957/1224	Supervised triage sector.	5011 7 Avenue Brooklyn, NY	8.8 mi
Engine Company 158	0957/1109	Stood fast at the on scene command post.	65 Harbor Road Staten Island, NY	5.4 mi
Engine Company 159	0958/1106	Coordinated triage area.	1592 Richmond Road Staten Island, NY	4.3 mi
Satellite Truck 5	0959/1049	Did not operate. (A Satellite unit is a truck that dispenses water with foam).	1592 Richmond Rd Staten Island, NY	4.3 mi
Battalion Commander 23	1002/1152	Operated as resource unit officer.	256 Nelson Ave Staten Island, NY	9.2 mi
Field Com 01	1015/1158	Established Field Headquarters, monitored all radio communications, transmitted progress reports as directed, provided necessary incident history and reports as needed.	25 Rockaway Ave. Brooklyn, NY	17.9 mi