

DAILY RECORD OF FACILITY OPERATION				PAGE NO Page 1 of 1
				DATE Feb 14, 2014
LOCATION	IDENTIFICATION	TYPE FACILITY	OPERATING POSITION	CHECKED BY [REDACTED]
Birmingham, AL	BHM	ATCT	OSIC	AIR TRAFFIC MANAGER Donald Schrader
UTC TIME	REMARKS			
0600	M.GILMORE ON. WCLC.RWY 24/18 IN USE. CFPL; RWY 6 SFL INDCS FAILURE WHEN ACTVTD.LOCAL2 POSITION LIGHT GUN RED LIGHT PORTION OTS. IFR TO CAB. -- HI			
1100	IFR OPERATION MOVED TO TRACON. -- HI			
1155	R. CLAY ON. -- RC			
1410	WCLC. -- RC			
1640	L.DEMORY ON. -- LD			
2234	WCLC. -- LD			
0015	B.SHARP ON. -- LD			
E 0054	E/G ON. -- BS			
E 0325	E/G OFF. -- RD			
Q 0420	SOUTH RADAR LOST RADAR AND RADIOS WITH N723EJ AFTER ISSUING HIM A TURN TO JOIN THE LOCLIZER FOR RUNWAY 24,14 MILES NORTH EAST OF BIRMINGHAM. -- RD			
0545	IFR OPERATION MOVED TO CAB. -- RD			
0559	COB. -- RD			
0559	COB. -- RD			
I CERTIFY that entries above are correct, that all scheduled operations have been accomplished except as noted, and that all abnormal occurrences and conditions have been recorded.			SIGNATURE(S) OF WATCH SUPERVISOR(S) [REDACTED]	

FAA Form 7230-4

BHM-ATCT-0112
N732EJ