

U.S. Department of Transportation
Federal Aviation Administration

Daily Record of Facility Operation

Date 7/26/02

Location Tallahassee, FL	Identification TLH	Type Facility Combined TRACON/Tower	Operating Position All	Checked By <i>BE/FR</i> Air Traffic Manager ART EICKENBERG <i>Ac</i>
-----------------------------	-----------------------	---	---------------------------	---

Time (UTC)	REMARKS
E 1000	R. HORNE ON. RY27 RVR TD OTS. AIRCRAFT BURNING 1/2 MILE WEST OF RY09/27. ACN. CFPL: SECON DELTA, H2O LEAK BTN WINDOWS 5&6/6&7/ 8&9, RY36 GS OTS, ATCT CEILING H2O LEAK, ASR8 WX OUTLINE OTS, RY18/36 PAPI OTS, MODE S OTS, RY18/36 CLSD, RY36 LOC OTS.
1005	AIRCRAFT SUSPECTED TO BE FDX1478 (N497FE). VISUALLY APPEARS TO BE A B727. ACN.
1010	DAYLIGHT NOW AVAILABLE, AIRCRAFT CONFIRMED TO BE FDX1478, FDX LOGO OBSERVED ON AIRCRAFT VISUALLY FROM TOWER. GROUND STOP ISSUED FOR TLH. ACN.
1110	TLH AIRPORT NOTAM CLSD.
Q 1130	TAPES WERE REVIEWED AT WOC REQUEST, NO INFO AVAILABLE, QAR RESOLVED.
1210	WCLC.
E 1255	RY27 RVR TD RTS.
E 1255	RY27 ILS OTS.
1325	RY27 SWEEP COMPLETE FOR AUTHORIZED ARIVALS.
1338	FDX9115 (LR45) LANDED RY27.
1430	TLH AIRPORT OPEN.
E 1530	ILS RY27 LOC RTS.
1628	EMERG GNRTRS ON.
E 1637	ILS RY27 GS RTS.
1700	R. FISHER ON. WCLC.
1743	EMERG GNRTRS OFF.
0130	M. HALL ON.
0300	COB.

I CERTIFY that entries above are correct; that all scheduled operations have been accomplished, except as noted, and that all abnormal occurrences and conditions have been recorded.

Watch Supervisor(s) Signature	Watch Supervisor(s) Signature	Watch Supervisor(s) Signature
<i>[Signature]</i>		