

Name	ModeC	Name2	Mode3	Latitude	Longitude	F7
1:42:33 AM	2900	3100T	6677	39:14:39.00N	85:48:25.99W	CVG
1:42:38 AM	2900	3100T	6677	39:14:41.99N	85:48:12.01W	CVG
1:42:43 AM	3000	3200T	6677	39:14:50.00N	85:47:58.00W	CVG
1:42:47 AM	3000	3200T	6677	39:14:52.99N	85:47:43.99W	CVG
1:42:52 AM	3000	3200T	6677	39:14:55.00N	85:47:31.00W	CVG
1:42:57 AM	3100	3300T	6677	39:14:57.99N	85:47:17.98W	CVG
1:43:01 AM	3100	3300T	6677	39:15:01.00N	85:47:04.99W	CVG
1:43:06 AM	3200	3400T	6677	39:15:03.99N	85:46:52.00W	CVG
1:43:10 AM	3200	3400T	6677	39:15:07.00N	85:46:40.00W	CVG
1:43:15 AM	3200	3400T	6677	39:15:08.99N	85:46:27.01W	CVG
1:43:20 AM	3300	3500T	6677	39:15:12.00N	85:46:11.98W	CVG
1:43:24 AM	3300	3500T	6677	39:15:09.99N	85:46:00.01W	CVG
1:43:29 AM	3400	3600T	6677	39:15:12.00N	85:45:46.00W	CVG
1:43:34 AM	3400	3600T	6677	39:15:19.00N	85:45:29.99W	CVG
1:43:38 AM	3500	3700T	6677	39:15:20.99N	85:45:16.01W	CVG
1:43:43 AM	3500	3700T	6677	39:15:19.00N	85:45:04.01W	CVG
1:43:47 AM	3500	3700T	6677	39:15:17.00N	85:44:50.99W	CVG
1:43:52 AM	3500	3700T	6677	39:15:24.00N	85:44:35.00W	CVG
1:43:57 AM	3600	3800T	6677	39:15:20.99N	85:44:21.98W	CVG
1:44:01 AM	3600	3800T	6677	39:15:19.00N	85:44:08.99W	CVG
1:44:06 AM	3700	3900T	6677	39:15:25.99N	85:43:53.99W	CVG
1:44:11 AM	3700	3900T	6677	39:15:33.00N	85:43:39.00W	CVG
1:44:15 AM	3800	4000T	6677	39:15:30.00N	85:43:27.00W	CVG
1:44:20 AM	3800	4000T	6677	39:15:33.00N	85:43:14.00W	CVG
1:44:24 AM	3900	4100T	6677	39:15:35.00N	85:43:00.99W	CVG
1:44:29 AM	3900	4100T	6677	39:15:36.99N	85:42:47.01W	CVG
1:44:34 AM	4000	4200T	6677	39:15:35.00N	85:42:37.01W	CVG
1:44:38 AM	4000	4200T	6677	39:15:41.99N	85:42:23.00W	CVG
1:44:43 AM	4100	4300T	6677	39:15:48.99N	85:42:08.99W	CVG
1:44:47 AM	4100	4300T	6677	39:15:51.00N	85:41:56.99W	CVG
1:44:52 AM	4100	4300T	6677	39:15:47.99N	85:41:44.99W	CVG
1:45:01 AM	4200	4400T	6677	39:15:52.99N	85:41:19.01W	CVG
1:44:57 AM	4200	4400T	6677	39:15:55.00N	85:41:29.99W	CVG
1:45:06 AM	4200	4400T	6677	39:15:55.00N	85:41:05.99W	CVG
1:45:11 AM	4300	4500T	6677	39:16:01.00N	85:40:50.99W	CVG
1:45:15 AM	4300	4500T	6677	39:16:03.00N	85:40:36.98W	CVG
1:45:20 AM	4300	4500T	6677	39:15:56.00N	85:40:26.98W	CVG
1:45:24 AM	4400	4600T	6677	39:16:02.00N	85:40:11.99W	CVG
1:45:29 AM	4400	4600T	6677	39:15:59.99N	85:39:59.99W	CVG
1:45:34 AM	4400	4600T	6677	39:16:06.00N	85:39:46.01W	CVG
1:45:38 AM	4500	4700T	6677	39:16:03.00N	85:39:32.99W	CVG
1:45:43 AM	4500	4700T	6677	39:16:04.99N	85:39:20.00W	CVG
1:45:48 AM	4500	4700T	6677	39:16:07.00N	85:39:05.99W	CVG
1:45:52 AM	4600	4800T	6677	39:16:08.00N	85:38:52.01W	CVG
1:45:57 AM	4600	4800T	6677	39:16:09.99N	85:38:38.99W	CVG
1:46:01 AM	4600	4800T	6677	39:16:12.00N	85:38:26.00W	CVG

1:46:06 AM	4700 4900T	6677 39:16:13.00N	85:38:13.01W	CVG
1:46:11 AM	4700 4900T	6677 39:16:14.99N	85:37:59.99W	CVG
1:46:15 AM	4800 5000T	6677 39:16:15.99N	85:37:46.01W	CVG
1:46:20 AM	4800 5000T	6677 39:16:18.00N	85:37:32.99W	CVG
1:46:25 AM	4800 5000T	6677 39:16:23.00N	85:37:17.99W	CVG
1:46:29 AM	4900 5100T	6677 39:16:20.99N	85:37:07.99W	CVG
1:46:34 AM	4900 5100T	6677 39:16:21.99N	85:36:55.00W	CVG
1:46:38 AM	4900 5100T	6677 39:16:24.00N	85:36:43.00W	CVG
1:46:43 AM	5000 5200T	6677 39:16:30.00N	85:36:28.99W	CVG
1:46:48 AM	5000 5200T	6677 39:16:31.99N	85:36:16.99W	CVG
1:46:52 AM	5000 5200T	6677 39:16:32.99N	85:36:04.00W	CVG
1:46:57 AM	5000 5200T	6677 39:16:37.99N	85:35:51.01W	CVG
1:47:02 AM	5100 5300T	6677 39:16:40.00N	85:35:37.99W	CVG
1:47:06 AM	5100 5300T	6677 39:16:41.00N	85:35:25.99W	CVG
1:47:11 AM	5100 5300T	6677 39:16:42.99N	85:35:15.99W	CVG
1:47:15 AM	5200 5400T	6677 39:16:52.99N	85:35:00.00W	CVG
1:47:20 AM	5200 5400T	6677 39:16:53.99N	85:34:48.00W	CVG
1:47:25 AM	5200 5400T	6677 39:16:54.99N	85:34:36.00W	CVG
1:47:29 AM	5200 5400T	6677 39:17:01.00N	85:34:21.99W	CVG
1:47:34 AM	5200 5400T	6677 39:17:02.00N	85:34:09.99W	CVG
1:47:39 AM	5300 5500T	6677 39:17:03.00N	85:33:57.99W	CVG
1:47:43 AM	5300 5500T	6677 39:17:03.99N	85:33:45.98W	CVG
1:47:48 AM	5400 5600T	6677 39:17:09.99N	85:33:32.99W	CVG
1:47:57 AM	5400 5600T	6677 39:17:08.00N	85:33:08.00W	CVG
1:47:52 AM	5400 5600T	6677 39:17:14.00N	85:33:18.00W	CVG
1:48:02 AM	5500 5700T	6677 39:17:15.99N	85:32:51.00W	CVG
1:48:06 AM	5600 5800T	6677 39:17:20.99N	85:32:36.99W	CVG
1:48:11 AM	5600 5800T	6677 39:17:18.00N	85:32:24.99W	CVG
1:48:15 AM	5700 5900T	6677 39:17:21.99N	85:32:09.99W	CVG
1:48:20 AM	5700 5900T	6677 39:17:23.00N	85:31:57.00W	CVG
1:48:25 AM	5700 5900T	6677 39:17:24.00N	85:31:45.00W	CVG
1:48:29 AM	5800 6000T	6677 39:17:27.99N	85:31:32.01W	CVG
1:48:34 AM	5800 6000T	6677 39:17:32.99N	85:31:18.00W	CVG
1:48:39 AM	5900 6100T	6677 39:17:32.99N	85:31:05.01W	CVG
1:48:43 AM	5900 6100T	6677 39:17:34.00N	85:30:53.00W	CVG
1:48:48 AM	5900 6100T	6677 39:17:35.00N	85:30:41.00W	CVG
1:48:52 AM	6000 6200T	6677 39:17:38.99N	85:30:26.99W	CVG
1:48:57 AM	6000 6200T	6677 39:17:40.00N	85:30:14.99W	CVG
1:49:02 AM	6000 6200T	6677 39:17:41.00N	85:30:02.99W	CVG
1:49:06 AM	6100 6300T	6677 39:17:47.99N	85:29:45.99W	CVG
1:49:11 AM	6100 6300T	6677 39:17:52.99N	85:29:33.00W	CVG
1:49:16 AM	6200 6400T	6677 39:17:49.99N	85:29:23.00W	CVG
1:49:20 AM	6200 6400T	6677 39:17:53.99N	85:29:08.99W	CVG
1:49:25 AM	6200 6400T	6677 39:17:53.99N	85:28:56.99W	CVG
1:49:29 AM	6300 6500T	6677 39:18:02.00N	85:28:41.00W	CVG
1:49:34 AM	6300 6500T	6677 39:18:02.00N	85:28:27.98W	CVG
1:49:39 AM	6400 6600T	6677 39:18:02.00N	85:28:14.99W	CVG

1:49:43 AM	6400 6600T	6677 39:18:04.99N	85:28:00.00W	CVG
1:49:48 AM	6400 6600T	6677 39:18:02.00N	85:27:50.00W	CVG
1:49:53 AM	6500 6700T	6677 39:18:05.99N	85:27:35.00W	CVG
1:49:57 AM	6500 6700T	6677 39:18:09.00N	85:27:21.00W	CVG
1:50:02 AM	6500 6700T	6677 39:18:13.00N	85:27:06.99W	CVG
1:50:06 AM	6600 6800T	6677 39:18:11.99N	85:26:54.00W	CVG
1:50:11 AM	6600 6800T	6677 39:18:15.99N	85:26:39.00W	CVG
1:50:16 AM	6600 6800T	6677 39:18:15.99N	85:26:27.00W	CVG
1:50:20 AM	6700 6900T	6677 39:18:15.99N	85:26:15.00W	CVG
1:50:25 AM	6700 6900T	6677 39:18:19.00N	85:26:02.00W	CVG
1:50:29 AM	6800 7000T	6677 39:18:22.99N	85:25:48.00W	CVG
1:50:34 AM	6800 7000T	6677 39:18:22.99N	85:25:36.98W	CVG
1:50:39 AM	6900 7100T	6677 39:18:30.00N	85:25:21.99W	CVG
1:50:43 AM	6900 7100T	6677 39:18:30.00N	85:25:11.00W	CVG
1:50:48 AM	6900 7100T	6677 39:18:29.00N	85:24:58.01W	CVG
1:50:53 AM	6900 7100T	6677 39:18:29.00N	85:24:44.99W	CVG
1:50:57 AM	7000 7200T	6677 39:18:31.99N	85:24:29.99W	CVG
1:51:02 AM	7000 7200T	6677 39:18:33.99N	85:24:15.00W	CVG
1:51:06 AM	7100 7300T	6677 39:18:33.99N	85:24:02.01W	CVG
1:51:11 AM	7100 7300T	6677 39:18:36.00N	85:23:46.98W	CVG
1:51:16 AM	7100 7300T	6677 39:18:35.00N	85:23:33.00W	CVG
1:51:20 AM	7200 7400T	6677 39:18:33.99N	85:23:21.00W	CVG
1:51:30 AM	7200 7400T	6677 39:18:31.99N	85:22:54.00W	CVG
1:51:25 AM	7200 7400T	6677 39:18:32.99N	85:23:08.01W	CVG
1:51:34 AM	7300 7500T	6677 39:18:35.00N	85:22:39.00W	CVG
1:51:39 AM	7300 7500T	6677 39:18:33.99N	85:22:25.98W	CVG
1:51:43 AM	7300 7500T	6677 39:18:35.00N	85:22:10.00W	CVG
1:51:48 AM	7300 7500T	6677 39:18:35.00N	85:21:58.00W	CVG
1:51:53 AM	7400 7600T	6677 39:18:32.99N	85:21:45.01W	CVG
1:51:57 AM	7400 7600T	6677 39:18:36.00N	85:21:29.98W	CVG
1:52:02 AM	7400 7600T	6677 39:18:35.00N	85:21:19.00W	CVG
1:52:07 AM	7400 7600T	6677 39:18:36.99N	85:21:04.99W	CVG
1:52:11 AM	7200 7400T	6677 39:18:36.00N	85:20:52.00W	CVG
1:52:16 AM	7000 7200T	6677 39:18:35.00N	85:20:39.01W	CVG
1:52:25 AM	6800 7000T	6677 39:18:27.99N	85:20:10.99W	CVG
1:52:30 AM	6600 6800T	6677 39:18:25.99N	85:19:56.98W	CVG
1:52:34 AM	6500 6700T	6677 39:18:24.00N	85:19:41.99W	CVG
1:52:39 AM	6400 6600T	6677 39:18:25.00N	85:19:26.99W	CVG
1:52:44 AM	6300 6500T	6677 39:18:26.99N	85:19:11.99W	CVG
1:52:20 AM	6900 7100T	6677 39:18:32.99N	85:20:23.98W	CVG
1:52:48 AM	6200 6400T	6677 39:18:25.00N	85:18:59.99W	CVG
1:52:53 AM	6100 6300T	6677 39:18:26.99N	85:18:45.00W	CVG
1:52:57 AM	6000 6200T	6677 39:18:27.99N	85:18:32.00W	CVG
1:53:02 AM	6000 6200T	6677 39:18:30.00N	85:18:17.01W	CVG
1:53:07 AM	5900 6100T	6677 39:18:33.99N	85:18:01.98W	CVG
1:53:11 AM	5800 6000T	6677 39:18:33.99N	85:17:51.99W	CVG
1:53:16 AM	5700 5900T	6677 39:18:37.99N	85:17:36.00W	CVG

1:53:21 AM	5600 5800T	6677 39:18:36.99N	85:17:24.99W	CVG
1:53:25 AM	5500 5700T	6677 39:18:37.99N	85:17:12.00W	CVG
1:53:30 AM	5400 5600T	6677 39:18:40.00N	85:16:57.99W	CVG
1:53:34 AM	5300 5500T	6677 39:18:43.99N	85:16:42.99W	CVG
1:53:39 AM	5200 5400T	6677 39:18:46.00N	85:16:30.99W	CVG
1:53:44 AM	5000 5200T	6677 39:18:51.00N	85:16:18.00W	CVG
1:53:48 AM	5000 5200T	6677 39:18:56.00N	85:16:06.00W	CVG
1:53:53 AM	4900 5100T	6677 39:19:00.99N	85:15:53.99W	CVG
1:53:57 AM	4800 5000T	6677 39:19:08.00N	85:15:44.98W	CVG
1:54:02 AM	4800 5000T	6677 39:19:15.00N	85:15:36.99W	CVG
1:54:07 AM	4700 4900T	6677 39:19:20.00N	85:15:34.99W	CVG
1:54:11 AM	4700 4900T	6677 39:19:30.00N	85:15:26.01W	CVG
1:54:16 AM	4600 4800T	6677 39:19:37.99N	85:15:19.00W	CVG
1:54:21 AM	4600 4800T	6677 39:19:42.99N	85:15:14.00W	CVG
1:54:25 AM	4500 4700T	6677 39:19:51.00N	85:15:07.99W	CVG
1:54:30 AM	4400 4600T	6677 39:19:59.00N	85:15:02.99W	CVG
1:54:34 AM	4200 4400T	6677 39:20:09.00N	85:15:00.98W	CVG
1:54:39 AM	4100 4300T	6677 39:20:13.00N	85:15:02.99W	CVG
1:54:44 AM	4000 4200T	6677 39:20:24.00N	85:15:02.00W	CVG
1:54:48 AM	4000 4200T	6677 39:20:31.00N	85:15:02.99W	CVG
1:54:53 AM	3900 4100T	6677 39:20:41.00N	85:15:02.00W	CVG
1:54:58 AM	3800 4000T	6677 39:20:48.99N	85:15:02.00W	CVG
1:55:02 AM	3800 4000T	6677 39:20:53.99N	85:15:04.99W	CVG
1:55:07 AM	3700 3900T	6677 39:21:01.99N	85:15:05.98W	CVG
1:55:11 AM	3600 3800T	6677 39:21:11.99N	85:15:04.99W	CVG
1:55:16 AM	3500 3700T	6677 39:21:22.99N	85:15:02.99W	CVG
1:55:21 AM	3400 3600T	6677 39:21:27.99N	85:15:05.98W	CVG
1:55:25 AM	3300 3500T	6677 39:21:38.99N	85:15:04.99W	CVG
1:55:30 AM	3200 3400T	6677 39:21:47.00N	85:15:05.98W	CVG
1:55:35 AM	3100 3300T	6677 39:21:54.00N	85:15:10.98W	CVG
1:55:39 AM	3100 3300T	6677 39:22:04.00N	85:15:09.99W	CVG
1:55:44 AM	3000 3200T	6677 39:22:11.99N	85:15:09.99W	CVG
1:55:48 AM	2900 3100T	6677 39:22:20.00N	85:15:10.98W	CVG
1:57:02 AM	1500 1700T	6677 39:22:01.99N	85:13:22.99W	CVG
1:57:07 AM	1400 1600T	6677 39:22:05.99N	85:13:22.99W	CVG
1:56:44 AM	1900 2100T	6677 39:22:25.00N	85:13:17.00W	CVG
1:56:58 AM	1600 1800T	6677 39:22:09.00N	85:13:14.99W	CVG
1:56:49 AM	1800 2000T	6677 39:22:21.99N	85:13:10.98W	CVG
1:56:53 AM	1700 1900T	6677 39:22:16.99N	85:13:09.99W	CVG
1:55:53 AM	2800 3000T	6677 39:22:30.00N	85:15:07.99W	CVG
1:55:58 AM	2700 2900T	6677 39:22:36.00N	85:15:04.01W	CVG
1:56:02 AM	2600 2800T	6677 39:22:44.99N	85:14:52.99W	CVG
1:56:07 AM	2500 2700T	6677 39:22:47.00N	85:14:42.00W	CVG
1:56:12 AM	2400 2600T	6677 39:22:49.00N	85:14:25.99W	CVG
1:56:16 AM	2300 2500T	6677 39:22:47.00N	85:14:15.01W	CVG
1:56:21 AM	2300 2500T	6677 39:22:47.00N	85:14:01.00W	CVG
1:56:25 AM	2200 2400T	6677 39:22:43.99N	85:13:49.98W	CVG

1:56:30 AM	2100 2300T	6677 39:22:39.99N	85:13:41.99W	CVG
1:56:35 AM	2100 2300T	6677 39:22:33.99N	85:13:32.98W	CVG
1:56:39 AM	2000 2200T	6677 39:22:30.00N	85:13:24.99W	CVG
