



## **NATIONAL TRANSPORTATION SAFETY BOARD**

Office of Aviation Safety  
Western Pacific Region

# **ACCIDENT SITE IMAGES**

**WPR12LA265**

Accident Date: June 15, 2012

This document contains 6 embedded images  
(Courtesy FAA)

## A. ACCIDENT

Location: Rexburg, Idaho  
Date: June 15, 2012  
Aircraft: Roetman Eagle, N106BD, Serial # BR001  
NTSB IIC: Tealeye Cornejo

## B. SUMMARY

On June 15, 2012, about 1940 mountain daylight time, an experimental amateur-built Roetman Eagle, N106BD, was substantially damaged when it impacted terrain while conducting aerobatic maneuvers at the Rexburg-Madison County Airport (RXE), Rexburg, Idaho. The pilot/owner sustained serious injuries, and there were no ground injuries. The airplane was being operated under the provision of 14 Code of Federal Regulations Part 91. Visual meteorological conditions prevailed for the local area flight, and no flight plan had been filed.

## C. SITE IMAGES



Figure 1 - Ground Scars



Figure 2 - Front View



**Figure 3 - Engine and Propeller**



Figure 4 - Right View



Figure 5 - Left Rear View



Figure 6 - Left Front View