

AIRCRAFT MAINTENANCE LOG

WORK ORDER: 6215

106125

No: 1		DISCREPANCY		CORRECTIVE ACTION	
Name (Print): <i>Luis Sauer</i>				Removed and replaced Avionics Fan	
Location: <i>PEC</i>		Date: <i>9-12-10</i>		and operationally checked w/normal	
<i>AVIONICS NOSE FAN C.BROOKER Popped</i>				<i>results I/A/w/ 21-20-00</i>	
		P/N ON: <i>01179</i>		S/N ON: <i>101136881</i>	
		Date: <i>9-12-2010</i>		Cert. #: <i>CESTV2J1078L</i>	
P/N OFF: <i>01179</i>		S/N OFF: <i>T66941</i>		Signature: <i>[Signature]</i>	
				Employee #: <i>600</i>	
No: 2		DISCREPANCY		CORRECTIVE ACTION	
Name (Print): <i>T Olmsted</i>					
Location: <i>KPJE</i>		Date: <i>09-12-10</i>			
<i>Mx Check Start Required Due To</i>					
<i>L/H Elevator Replacement</i>					
		P/N ON:		S/N ON:	
		Date:		Cert. #	
P/N OFF:		S/N OFF:		Signature:	
				Employee #:	
No:		DISCREPANCY		CORRECTIVE ACTION	
Name (Print):					
Location:		Date:			
		P/N ON:		S/N ON:	
		Date:		Cert. #	
P/N OFF:		S/N OFF:		Signature:	
				Employee #:	
Date: <i>9/13/10</i>	A/C Serial No:	A/C M/M:	A/C Registry:		