RECORDING TOTAL DATE DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS TODAYS TACH TIME IN ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF TIME FLIGHT SERVICE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.) 19____ 20 1062.1 T.T. 3166.7 TACH AIACRAFT WAS OPENUP SEAT WAS Removed Insp ALL CABIE and policys Check wing ATT PONT Chock BAAKE Check Light. Check ALL CONTOCK. FOR A.O. Check Engin See Engine Log INSTALL FIRE SLEEVE ON FULL LINE AT See LesT. CARBURETON TO GAS COLATORS and ELT BATTERY REPLACE CLEAN GAS COLATOR and SCREEN , N CARR. INSP THIS AIRCRAFT IN ACC WITH ANNUAL EXP. ONTE. Sep 1 INSPETT IN ACC LITA and was found A A work and was Appoared FOR RETURN TO SERVICE. FAAS 912070

They

RECORDING TOTAL DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS DATE OF TACH TODAYS TIME IN ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF 5.) FLIGHT TIME SERVICE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.) 18 20 ACK 1062.1 TOTAL. TIME 2008:2 SMOH. 566.4 Change Oir and Filter Service with 697 OF ARROSAELL 15W 50 FILTER WAS COT and WAS FOUND TO BE CLEAN INSTALL NEW Chylog-1 Finter puby was Removed and Composition WAS CLARK KER ALL CYL WAS 71/80 and Higher TO 80/80 TESTRIN and All Ind WAS NONTH- INSPIRIS ENGINE IN AGE, with ANNUAL and WAS FOUNd TO BEAIR WORTH, and WAS Appoqued FOR RETURN TO SERVICE June 1