



70 to 80 knots aircraft started to hydroplane

Aircraft exit runway

Left landing gear collapsed on impact with north taxiway edge

Aircraft rotated 180° to the left

Image © 2016 DigitalGlobe
© 2016 Google

©2010 Google