







1. CFI N499DR positions aircraft on non-movement area parallel to TWY D before starting engine.
2. CFI notices aircraft moving and applies brake.
3. CFI relayed there was a problem with brake and N499DR collides with N1955L.

