→ AGL

Ø001

Page 1 of 2

AISR

FF KRFWYAYX 090325 KFODYFYX ALNOT N174BH FLIGHT RULES: VFR NUMBER: 1 AIRCRAFT TYPE: PA31 EQUIPMENT: N/A AIRSPEED: N/A DEPARTURE POINT: SGS PROPOSED DEPARTURE TIME: 2012 06 09 01:57:00Z ACTUAL DEPARTURE TIME: 2012 06 09 01:57:00Z ALTITUDE: N/A ETA: 2012 06 09 01:58:00Z ROUTE OF FLIGHT: DLH DESTINATION: SGS ETE: 00:01 ACTUAL ARRIVAL TIME: N/A ALTN AERODROME: N/A 2ND ALTN AERODROME: N/A REMARKS: N/A FUEL ON BOARD: N/A PEOPLE ON BOARD: 1 PILOT INFORMATION: COLOR OF AIRCRAFT: W/R/B BEACON CODE: N/A ADIZ POINT: N/A ADIZ TIME : N/A FS21 NOTES: N/A ADDITIONAL ADDRESSES: N/A AIRCRAFT DEPARTED AT 1815Z ON A MAINTENANCE FLIGHT FOR THE RIGHT ENGINE. IT IS BELIEVED THAT THE AIRCRAFT WAS TO FLY TO AN AREA NORTH OF KDLH AND RETURN BACK TO KSGS WITH A MAXIMUM ENROUTE TIME OF

ABOUT 4 HOURS. LAST KNOWN CONTACT WITH THE AIRCRAFT WAS AT ABOUT 1800Z AT AN FBO IN KSGS. THE OWNER OF THE FBO TOWED THE AIRCRAFT TO THE PUMPS AND WENT ABOUT HIS BUSINESS, WHEN HE RETURNED HIS ATTENTION BACK TO THE AIRCRAFT 15 MINUTES LATER, "IT WAS ALREADY GONE" ACCORDING TO THE FBO OWNER. AT THE TIME KSGS WAS EXPERIENCING LIGHT RAIN SHOWERS AND THE FBO AND PILOT WERE DECIDING WHERE HE SHOULD BREAK IN THE RIGHT ENGINE TO WHICH ACCORDING TO THE FBO OWNER

THE PILOT STATED "I'M GOING TO GO WHEREVER IT'S NOT RAINING".

AISR

.

.

ASW ROC

 \rightarrow AGL

k<u>/</u> 002

Page 2 of 2

.

•

PILOTS WIFE STATED HE WAS HEADED NORTH OF KDLH.

•

•

.