

## MBS Leak Alarm - Analysis by MBS Support

If the Shift Lead determines that an MBS Alarm requires analysis by MBS Support:

- Notify MBS Support.

If after 10 minutes, an analysis of the alarm is not complete:

- Shut down the pipeline and standby for analysis.

If MBS Support advise the alarm is valid:

- Execute the [MBS Valid Alarm <Link>](#) procedure

If MBS Support advise the alarm is false:

- Execute the [MBS Temporary Alarm <Link>](#) procedure