



RECORD OF CONVERSATION

Timothy N. Sorensen
Aviation Accident Investigator
Central Region

Date: January 3, 2017
Person Contacted: Doug Hammon, OSU Airport Manager
NTSB Accident Number: CEN17FA072 – Cleveland, Ohio

Narrative:

Mr. Hammon stated the following:

- The accident airplane was based at OSU;
- The airplane was maintained elsewhere as OSU does not have turbine maintenance capability;
- The accident pilot did not employ a flight crew – he flew the airplane himself (single-pilot);
- The accident pilot had previously owned a Cessna Mustang;
- He did not know the accident pilot personally; however, his understanding was that the accident pilot was very detailed . . . knew what was going on.
- The accident pilot hangered an airplane at OSU for about the previous 5 years.

Mr. Hammon will provide fueling records for the accident airplane. When airport management became aware of the accident, a fuel sample was taken and submitted for testing. The testing did not reveal any anomalies with respect to the airport fuel supply.

----- End of entries -----