



Exhibit 42-Photo Showing Damaged Fuel Tank of BNSF 9159