

DAILY RECORD OF FACILITY OPERATION

PAGE NO.

1

DATE

7/24/04

LOCATION

DENVER, COLORADO

IDENTIFICATION

D01

TYPE FACILITY

TRACON

OPERATING POSITION

OS/CIC

CHECKED BY

RT

CHIEF

Ka

TIME
(GMT)

REMARKS

0600 W. SIMMONS ON. WCLC. CFPL:LAND NORTH, 2 RWYS, ILS APPROACHES, SECON LVL YELLOW, IDS4 MONITOR OVR FUT 2 W/DOS PROMPT. NUMEROUS OTHER IDS4 MONITORS NOT RCVG DEN TDWR OR DEN WX. AF NOTIFIED.

0605 LAND SOUTH. 2 RWYS.

E 0610 IDS4 MONITORS RTS.

0746 LAND NORTH, 2 RWYS.

1130 E. CHAVIANO ON.

1135 W. SMITH ON, WCLC.

E 1415 RY34R GS OTS, 2 RYS ILS.

1700 D. SHOUP ON.

E 1745 RY34R GS RTS.

1806 N69CL, BE58, IFR, FNL-OMA, BELIEVED TO HAVE CRASHED NW OF FNL, FNL FIRE RESCUE ADVISED.

Q 1844 LARIMER COUNTY SHERIFF REPORTS N69CL CRASHED INTO NEIBORHOOD, KNOWN FATALITIES, ROC (OCONNER), ATM, AWP505 NOTIFIED. ARTS CLOCK VERIFICATION COMPLETED RESULTS NORMAL. ACCIDENT PACKAGE D01-TRACON-020 COMPLETED AND FORWARDED TO QA, FAXED TO ROC.

Q

E 2000 GJT FDIO OTS.

2030 R. TWEDT ON, WCLC.

2144 LND NORTH/EAST

0000 CARRYVOVER FROM TTMU LOG; LND NORTH/WEST, AAR 3 RYS ILS, P/L 1 RTE NMIT,ZDV.

0010 LND NORTH/EAST

0130 LND SOUTH/EAST.

0159 ALL RTES NORMAL.

0243 LND SOUTH.

0400 E. CHAVIANO ON, WCLC.

0559 COB.

I CERTIFY that all entries above are correct; that all scheduled operations have been accomplished, except as noted, and that all abnormal occurrences and conditions have been recorded.

SIGNATURE(S) OF WATCH SUPERVISORS

