/EAR	Entries m	ust be endorsed with Name, R	ts, Repairs and Alterations ating and Certificate Number of
ATE	Technicia	n or Repair Facility. (See back	pages for other specific entries.)
SAVE UNIT	-		
D. STANCE			
AND THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED			
	TIEIR MARIE		
al.	BRNANL Vgines		
22, 222		0 SMOH	
IO-550-	-EXP, serial #TC-5826 overhaul	in accordance with Teledyne	Continental overhaul
manual	#X30568A latest revision, excep	t as modified for experimenta	l use, this engine for
experim	nental use only. All airworth ness	directives complied to date, s	ee AD compliance
with plu	following accessories included: s	ingle side Plasma III CDI elec	etronic ignition kit
6 each I	ugs & wires (new), 6310 magneto URHB32E spark plugs (new), PN	(new), right 1/2 Coo-HBS-II	Mire namess (new),
1E1775	oil cooler (ovh), 649053A5 fuel	system (ovh) Engine function	nally tested and
approve	ed for safe operation. Other pertir	ent data on file at:	miny tested and
2007 A		NCE ENGINES, INC.	
Work	COrder #5826	Date:	10/3/2006
7700	Signed _	75777	

a.

YEAR 2009 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)		
Feb 20	39		0.0	I have installed this engine in the		
				Lancair Legacy in accordance with		
				The engine isostallation section of the		
				Lancair Legacy assembly manual.		
				I have installed the Hartzell		
				Propeller HC-J3YF-1RF/F7391D-3		
				Serial No K48148 K48149 K48150		
				Ass Serial No JN94B		
				2-11-09		
				I have inspected this engine in		
				accordance with FAB Part 43.		
				Appendix D and have touch it to be		
				in a condition for soft operation		
				2-11-01		