



Federal Aviation Administration

Memorandum

Date: JAN 15 2014

To: Director, Accident Investigation and Prevention, AVP-1
ATTN: Robert Hendrickson, AVP-100

From: John S. Duncan, Director, Flight Standards Service, AFS-1 [REDACTED]

Prepared by: Jeffrey Cupp, AFS-140 with input from Donald V. Dodge, ASO-

Subject: NTSB Accident/Incident Investigation Support Request 14-069 dated
12/16/2013

The following is our response to NTSB Accident/Incident Investigation Support Request 14-069 regarding the aircraft accident involving N58784 on October 29, 2011.

ACC/INC 14-069: The subject aircraft (N58784) was registered in the experimental exhibition category. Please provide copies of any program letters/amendments the pilot submitted to the appropriate FAA FSDO. Additionally, please provide any available copies of correspondence between the owner of the aircraft and the FAA/FSDO regarding major changes to the aircraft, or any other general correspondence pertinent to the subject aircraft.

FAA Response: The Miami and Orlando Flight Standards District Office have no record of receiving a program letter for Skyboy N58784. See attached.

Attachments