

RECORD OF <input type="checkbox"/> VISIT <input type="checkbox"/> CONFERENCE OR <input type="checkbox"/> TELEPHONE CALL		TIME	DATE 4/4/2019
NAME (S) OF PERSON (S) CONTACTED OR IN CONFERENCE AND LOCATION		ROUTING	
		SYMBOL	INITIALS
Inspector Statement for N8397W			
Joshua Lidberg NTSB			
SUBJECT N8397W Accident			
DIGEST			
<p>ON MARCH 29, 2019, N8397W, PA-28-180 DEPARTED HAMLITON, AL (KHAB) AROUND 5:15 PM LOCAL TIME. AIRCRAFT WAS ENROUTE TO MONROE COUNTY AIRPORT (M40), WITH TWO PERSONS ON BOARD. BEFORE DEPARTING KHAB, THE WEATHER WAS DISCUSSED BEFORE DEPARTURE. THEY ALSO TALKED ABOUT SAFETY PROCEDURES. APPROXIALMATELY 15 MILES FROM M40, THEY WERE LISTENING TO ATIS. THE PASSENGER STATED THEY WERE ON GLIDE SLOPE AND WHEN THEY GOT CLOSER TO THE RUNWAY, THE AIRCRAFT MADE AN ABRUPT TURN TO THE LEFT. MR. MAYO (PIC) APPLIED POWER AND ATTEMPTED A GO AROUND. THE AIRCRAFT WAS UNABLE TO MAKE ALTITUDE TO CLEAR A FENCE EAST OF THE TAXI WAY. THE AIRCRAFT HIT THE FENCE AND ENDED UP IN A RAVINE. FURTHER INSPECTION OF THE AIRCRAFT SHOWED THE FLAPS WERE IN THE FULL DOWN POSITION. ALL FLIGHT CONTROLS HAD CONTINUITY. THE PASSENGER SUFFERED MINOR INJURIES. THE PILOT SUFFERED A CONCUSSION AND WAS TRANSPORTED TO A HOSPITAL.</p>			
ROBERT F MAHAFFEY		Digitally signed by ROBERT F MAHAFFEY Date: 2019.04.04 10:38:12 -05'00'	
Robert F. Mahaffey Aviation Safety Inspector			
CONCLUSION, ACTION TAKEN, OR REQUIRED			
DATE 4/4/2019	TITLE Aviation Safety Inspector	SIGNATURE ROBERT F MAHAFFEY Digitally signed by ROBERT F MAHAFFEY Date: 2019.04.04 10:39:02 -05'00'	