

INSPECTION REPORT

Inspector's Name Clarke, Craig C.			Inspector's Signature				Inspector's ID No. [REDACTED]	Report No. 133	Date yy mm dd 2016 12 20				
Railroad/Company Name & Address BNSF RAILWAY COMPANY Newcastle WY					R/C R	Division POWDER	RR/Co. Representative (Receipt Acknowledged) Name Dennis Stirmel Title Track Inspector Email Signature						
From: City NEWCASTLE		Codes 0610	Destination City & County				Codes	From Latitude					
State WY		56	City ROZET				0734	From Longitude					
County WESTON		C045	County CAMPBELL				C005	To Latitude					
Mile Post: From 0520.75 To 0571.00			Inspection Point MAIN TRACK				To Longitude						
Activity Code:	TOM	MTW	MTH	RWP									
Units:	17	1	49	2									
Sub Units:	0	0	0	4									
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	0535.25	MT #1	T	213	0139	D	60	4	E. BACK TRK. SW	N	N	1	TOM
Description INSUFFICIENT COMPRESSION IN SPRING TO HOLD WING RAIL AGAINST POINT RAIL. (snow causing the wing rail not to close against the point creating a gap)													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code			Date(mm/dd/yyyy):		Comments on back?		
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	0556.55	MT #1	T	213	0139	D	60	4		N	N	1	TOM
Description INSUFFICIENT COMPRESSION IN SPRING TO HOLD WING RAIL AGAINST POINT RAIL. (snow between the wing rail and point creating a gap)													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code			Date(mm/dd/yyyy):		Comments on back?		

INSPECTION REPORT

(Continuation)

Inspector's ID No. <div style="background-color: black; width: 40px; height: 15px; margin: 5px;"></div>	Report No. 133	Report Date 12/20/2016
--	-------------------	---------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	0556.55	MT #1	T	213	0133	A14	60	4	E. SET OUT TRK.	N	N	1	TOM

Description
LOOSE, WORN OR MISSING GUARD RAIL CLAMPS, WEDGE, SEPARATOR BLOCK, END BLOCK, OR OTHER COMPONENTS.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	0560.30	MT #1	T	213	0133	A9	60	4	E. 1/2 XO	N	N	1	TOM

Description
LOOSE OR MISSING ADJUSTABLE RAIL BRACES.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5	0560.34	MT #1	T	213	0133	A8	60	4	W. 1/2 XO	N	N	1	TOM

Description
LOOSE OR MISSING RIGID RAIL BRACES. (plow bolt on rigid rail brace on the moveable point frog is broken)

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
6										N	N	0	

Description - [** Comment to Railroad/Company **]
This inspection report was sent to BNSF Roadmaster Chuck Oleson, Division Engineer John Bainter, and Track Inspector Dennis Stirmel as an attachment to an email on 12-20-2016. A read receipt was requested to act as their signature of acceptance of having received the report.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------