

INSPECTION REPORT

Inspector's Name Walker, Francis J.	Inspector's Signature	Inspector's ID No. 92855	Report No. 136	Date		
				yy 2014	mm 10	dd 28

Railroad/Company Name & Address AMTRAK (NATIONAL RAILROAD PASSENGER CORPORAT PHILADELPHIA TRACK OFFICE PENN COACH YARD PHILADELPHIA PA	R/C R	Division MIDATL	RR/Co. Representative (Receipt Acknowledged) Name TOM TIPPING		
	RR/Co. Code ATK	Subdivision NORTHEAST CORR	Title TRACK SUPERVISOR	Email	Signature _____

From: City PHILADELPHIA	Codes 6540	Destination City & County	Codes	From Latitude									
State PA	42	City		From Longitude									
County PHILADELPHIA	C101	County		To Latitude									
Mile Post: From 0087.10	To 0080.90	Inspection Point VARIOUS SPOTS & SHORE INT.		To Longitude									
Activity Code:	MTW	RWP	TOM	DER									
Units:	3	1	8	1									
Sub Units:	0	6	0	0									

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	0087.10	1	M	213	0103	D	70	4		N	N	1	MTW

Description
FOULED BALLAST CAUSING 1 INCH OF PROFILE AT WELD JUST WEST OF I-JOINT AT EAST END OF MANTUA INTERLOCKING

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:	
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code <input type="text"/>	Date(mm/dd/yyyy): <input type="text"/>	Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	0086.90	2	M	213	0103	D	80	4		N	N	1	MTW

Description
FOULED BALLAST CAUSING 1 INCH OF PROFILE AT CATPOLE 86+4660

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:	
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code <input type="text"/>	Date(mm/dd/yyyy): <input type="text"/>	Comments on back?

Source Code D	File Number NECFB14	ID's of Accompanying Inspector(s)
------------------	------------------------	-----------------------------------

INSPECTION REPORT

(Continuation)

Inspector's ID No. 92855	Report No. 136	Report Date 10/28/2014
-----------------------------	-------------------	---------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	0086.80	3	M	213	0103	D	80	4		N	N	1	MTW

Description
FOULED BALLAST CAUSING 1 INCH OF PROFILE 100 FEET EAST OF CATPOLE 86+4514

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	0086.70	3	M	213	0103	D	80	4		N	N	1	MTW

Description
FOULED BALLAST CAUSING 1 INCH OF PROFILE 100 FEET WEST OF CATPOLE 86+3428

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5	0086.60	3	M	213	0103	D	80	4		N	N	2	MTW

Description
FOULED BALLAST CAUSING 1 INCH OF PROFILE AT 2 LOCATIONS ABOUT 100 FEET EAST OF CATPOLE 86+3124

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
6	0085.60	4	M	213	0103	D	80	4		N	N	1	MTW

Description
FOULED BALLAST CAUSING 1 INCH OF PROFILE JUST EAST OF CATPOLE 85+3141

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Source Code D	File Number NECFB14	ID's of Accompanying Inspector(s)
------------------	------------------------	-----------------------------------

INSPECTION REPORT

(Continuation)

Inspector's ID No. 92855	Report No. 136	Report Date 10/28/2014
-----------------------------	-------------------	---------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
7	0085.60	4	M	213	0103	D	80	4		N	N	1	MTW

Description
FOULED BALLAST CAUSING 1-1/2 INCH OF PROFILE AT I-JOINTS AT WEST END OF LEHIGH INTERLOCKING

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
8	0085.40	1	M	213	0103	D	70	4		N	N	2	MTW

Description
FOULED BALLAST CAUSING 1 INCH OF PROFILE AT WEST END OF LEHIGH INTERLOCKING (CATPOLE 86-3246) AND 100 FEET WEST OF LEHIGH INTERLOCKING (2 LOCATIONS)

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
9	0084.80	3	M	213	0103	D	80	4		N	N	1	MTW

Description
FOULED BALLAST CAUSING 1 INCH DIFFERENCE IN CROSSLEVEL IN CURVE EAST OF READING RR UG BRIDGE

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
10	0082.30	3	M	213	0103	D	80	4		N	N	1	MTW

Description
FOULED BALLAST CAUSING 1 INCH OF PROFILE 1 RAIL LENGTH WEST OF EASTBOUND SIGNAL AT SHORE INTERLOCKING

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Source Code D	File Number NECFB14	ID's of Accompanying Inspector(s)
------------------	------------------------	-----------------------------------

INSPECTION REPORT

(Continuation)

Inspector's ID No. 92855	Report No. 136	Report Date 10/28/2014
-----------------------------	-------------------	---------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
11	0082.30	1	M	213	0103	D	70	4		N	N	1	MTW

Description
FOULED BALLAST CAUSING 1 INCH OF PROFILE 1 RAIL LENGTH EAST OF DED THAT IS LOCATED WEST OF EASTBOUND SIGNAL AT SHORE INTERLOCKING

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
12	0082.20	3	M	213	0103	D	80	4		N	N	1	MTW

Description
FOULED BALLAST CAUSING 1 INCH OF PROFILE AT PS OF WEST END 32 XOVER IN SHORE INT.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
13	0082.00	3	M	213	0103	D	80	4		N	N	1	MTW

Description
FOULED BALLAST CAUSING 1 INCH OF PROFILE 100 FEET WEST OF MP 81

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
14	0082.00	1	M	213	0103	D	70	4		N	N	1	MTW

Description
FOULED BALLAST CAUSING 1 INCH OF PROFILE 100 FEET EAST OF MP 81

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Source Code D	File Number NECFB14	ID's of Accompanying Inspector(s)
------------------	------------------------	-----------------------------------