

## **RECORD OF CONVERSATION**

Timothy N. Sorensen Aviation Accident Investigator Central Region

Date: February 24, 2020 Person Contacted: Dave Pogorzelski, Flight Instructor NTSB Accident Number: CEN20LA095 – Chesterfield, Missouri

Narrative:

Mr. Pogorzelski provided the following information:

As the flight instructor, on short final I checked gear handle down with a green light that was illuminated. I visually looked out the copilot side window and saw the right landing gear was down in its normal location. The airplane landed about 500 feet short of the 1,000-foot markers on runway 26R. As the airplane was rolling out, the landing gear collapsed near the E3 taxiway.

----- End of entries ------