

**GEORGIA BUREAU OF INVESTIGATION
REGION 7
INVESTIGATIVE CASE SUMMARY**

07-0163-01-13

On Tuesday, August 6, 2013, at approximately 2:00 PM, SPECIAL AGENT S. W. FOSTER and SPECIAL AGENT S. R. LUE examined a Cedar tree at the northwest corner of the Milliken factory at 2598 Washington Road. The request to examine the tree was made by NTSB INVESTIGATOR MARK GEORGE and coordinated through Milliken legal council LISA RICHARDSON and Milliken engineering services manager MICHAEL REARDON.

INVESTIGATOR GEORGE advised AGENT FOSTER that he had received information that the aircraft involved in the accident under investigation may have contacted the top of the tree prior to the crash on February 20, 2013.

The tree is located at 33°31'45.51" N by 82°30'17.29"W; it is approximately 31'4" North and 43'4" West of the Milliken building.

AGENT FOSTER made ground level photographs of the tree and the northwest corner of the building. Measurements of the tree and building revealed that the top edge of the northwest corner of the factory is approximately 20' from the ground and the top of the tree (displaying some damage) is approximately 33'4" from the ground. The base of the tree is slightly below the grade of the building and the area of the tree above the building's roofline is approximately 13'.

The photographs of the tree will be made part of this case file. Also, a Leica C10 scanner was incorporated to memorialize the tree and n/w corner of the building. The scan data will be attached to this investigative summary.

ATTACHMENTS:

1. CRIME SCENE PHOTOS
2. OTHER ; LEICA C10 SCAN DATA

SPECIAL AGENT STEVEN W FOSTER: 8/6/2013

PROPERTY OF GBI