



## RECORD OF CONVERSATION

**Robert Gretz**  
**Senior Air Safety Investigator**  
**Eastern Region Aviation**

---

**Date: February 5, 2019**  
**Person Contacted: Steve Wallace, McLean, VA**  
**NTSB Accident Number: ERA18FA006**

---

### **Narrative:**

Mr. Wallace was interviewed via telephone. He was asked about his GoPro camera recording suddenly stopping during the accident flight. Mr. Wallace stated that he had not used the camera too many times prior to the accident flight, perhaps three or four. During the accident flight, he noticed it stopped recording and he started a new recording a few seconds later. He cannot recall if that had happened during the previous times he used the camera, but had heard from other pilots that it's a common occurrence.