



BNSF 5958

Buffer BNSF 808314

{Behind Pile}  
B-END  
GATX 33119

B-END

GATX 33123

A-END

TAEX 1475

B-END

ADLX 500176

A-END

SHPX 206675

B-END

SHPX 206670

B-END

TAEX 1528

B-END

TAEX 1602

A-END

SHPX 206668

B-END

GATX 33125

B-END

GATX 33139

A-END

TAEX 1630

{Behind Pile}  
A-END  
TAEX 1638

B-END  
TAEX 1472

{Behind Pile}  
B-END

SHPX 208541

{Behind Pile}  
B-END

SHPX 206638

A-END

SHPX 208536



BNSF 5958

Buffer BNSF 808314

B-END

GATX 33123 TAEX 1475

A-END

B-END

ADLX 500176

A-END

SHPX 206675

B-END

SHPX 206670

B-END

TAEX 1528

B-END

TAEX 1602

A-END

SHPX 206668

B-END

GATX 33125

B-END

GATX 33139

A-END

TAEX 1630

A-END

SHPX 208536



{Behind Pile}  
B-END  
GATX 33119

B-END  
TAEX 1472

{Behind Pile}  
A-END  
TAEX 1638

{Behind Pile} B-END SHPX 208541  
{Behind Pile} B-END SHPX 206638