## NATIONAL TRANSPORTATION SAFETY BOARD OFFICE OF RAILROAD, PIPELINE AND HAZARDOUS MATERIALS WASHINGTON, D.C. 20594

## PACIFIC GAS & ELECTRIC COMPANY NATURAL GAS TRANSMISSION PIPELINE RUPTURE SAN BRUNO, CA SEPTEMBER 9, 2010

## PUBLIC HEARING EXHIBIT LIST

1A	Order of Hearing
1B	Notice of Designation of Chairman of Board of Inquiry
1C	Designation of Hearing Officer
1D	Designation of Parties to Hearing
1E	Notice of Hearing
1F	Public Hearing Exhibit List
1G	Public Hearing Witness List
2A	Operations Group Chairman Factual Report
2B	Operations - PG&E Event Timeline
2C	Operations - 49CFR 619(a)(3) and PG&E Documentation (NTSB 011-011)
2D	Operations – Schematic Showing Relative Locations of Nearby Services and L132 in the Trench
2E	Operations – Former PG&E Employee Photograph Near Rupture Area
2F	Operations – PG&E Retiree Interview
2G	Operations – Milpitas Terminal One-Line
2H	Operations – SCADA Screenshot of Peninsula System & Milpitas to Martin &
	Milpitas Terminal
2I	Operations – SCADA Alarms (NTSB 0014-008)
2J	Operations – SCADA Alarm Policy
2K	Operations – SCADA Pressure Readings on 9-9-10 (16:12 through 18:42)
2L	Operations – Photo of Monitor Valve Pneumatic Controller
2M	Operations – PG&E Pressure Transducer Location's Along Lines 101, 109 and 132
2N	Operations – PG&E SCADA Trends from 9-9-10
20	Operations – Excerpts from the PG&E ECDA Plan RMP-09
2P	Operations – PG&E Survey Sheets of Line 132
2Q	Operations – Senior Consulting Engineer MEMO to File
2R	Operations – 49 CFR 192.903
2S	Operations – PG&E PIR and HCA Drawings
2T	Operations – Standard Cathodic Maintenance Report
2U	Operations – Interview Transcript of Supervising Engineer for the ILI and DA Programs

- 2VOperations – Interview Transcript of SCADA and Controls Group Supervising Engineer 2WOperations – Line 132 Cross Ties Schematic 2XOperations – NTSB (008-003) Healy Station and Cross Ties Valve 2Y Operations – SF Control Room Logs 09-09-10 2ZOperations – (NTSB 046-001) L132 Risk Factors 2AA Operations – Where Did 1961 5/16-Inch Pipe on Glenview Extension Come From? (NTSB 038-004) 2AB Operations – How was Welded Pipe Entered as Seamless into the Records (NTSB 035-018) 2AC Operations – Is it Possible that the 5/16-Inch Pipe Purchased in 1948 and Sent to Oakland was Used in 1956 Relocation Job (NTSB 038-003) Operations – Highest Recorded Pressures on Line 132 (NTSB 004-005 &036-003) 2AD Operations – Provide a List of Transmission Lines with Corresponding MAOPs in 2AE San Bruno 2AF Operations – Who Manufactured the Pipe at the Accident Site and the Manufacturing Process Operations – 5-Year Overpressure Requirement RMI-06 Rev 1 2AG Operations – All PG&E Overpressures of any Lines and Documentation (NTSB 2AH 027-002)2AI Operations – All Lines that PG&E Overpressures in Order to Maintain MAOP (NTSB 036-005) 2AJ Operations – Milpitas Operations & Maintenance (NTSB 033-006) Operations – Milpitas UPS Upgrade Project Documentation (NTSB 036-008) 2AK 2AL Operations -2AM Operations – Milpitas Clearance August thru September, 2010 (NTSB 011-008) 2AN Operations – Cross Tie Procedures (Seasonal Settings) (NTSB 033-009) 2AO Operations – All Cross Tie Valves on L101, 109 and 132 (NTSB 033-008) 2AP Operations – GM 151181 and 1961 L132 Relocation Project Documentation (NTSB 008-004 & -004S1) Operations – 1956 Drawings Relocation L132 (NTSB 001-002-S1 and NTSB 010-2AQ005) Operations – NTSB 035-018 PG&E Description How Welded Pipe Was Entered as 2AR Seamless Pipe in GIS System 2AS Operations – Audit Change Log to GIS System Operations – Listing of Seamless Pipe Greater than 24-Inch Diameter (NTSB 033-2AT 001) 2AU Operations – Integrity Management Program (RMP 06-10-11 &13) 2AV Operations – Risk Management Plan (RMP 01-02-03-05-05 & 08) Operations – Line 132 Baseline Integrity Management Assessment 2AW 2AXOperations – 2AY Operations – CPUC 2005 and 2010 IMI Audit Items (NTSB 008-001)

Operations – Excerpts of Job Files for Line 132 Work (NTSB 010-005 and NTSB

Operations – Excerpts from NTSB 018-002 1948 Construction of Line 132

Operations – 1956 Journal Voucher and Pipeline Survey Sheet

2AZ

2BA

2BB

010-005s)

```
2BC
           Operations – Glenview Subdivision Maps Identifying Fire Damaged Properties
2BD
           Operations – Interview of Aguiar, PG&E 1-3-11
2BE
           Operations – Interview of Armato, PG&E 1-6-11
           Operations – Interview of Bosch, City of San Bruno 1-3-11
2BF
2BG
           Operations – Interview of Breiz, PG&E 1-3-11
           Operations – Interview of Brown, PG&E 1-5-11
2BH
2BI
           Operations - Interview of Burke-Perralta, PG&E 1-6-11
2BJ
           Operations – Interview of Ceniceros, PG&E 1-5-11
2BK
           Operations – Interview of Daubin, PG&E 1-7-11
2BL
           Operations – Interview of Fong, PG&E 1-6-11
2BM
           Operations – Interview of Garriesere, 1-5-11
2BN
           Operations – Interview of Genera, PG&E 1-5-11
2BO
           Operations – Interview of Groppetti, PG&E Contractor 1-5-11
           Operations – Interview of Hannigan, City of San Bruno 1-3-11
2BP
2BQ
           Operations – Interview of Harty, D'Arcy & Harty Construction 1-3-11
2BR
           Operations – Interview of Haynes, PG&E 1-7-11
2BS
           Operations – Interview of Hong, PG&E 1-5-11
2BT
           Operations – Interview of Karkazis, PG&E 1-3-11
2BU
           Operations – Interview of Manegold, PG&E 1-7-11
2BV
           Operations – Interview of Mitchell, PG&E 1-7-11
2BW
           Operations – Interview of Ornelas, D'Arcy & Harty Construction 1-6-11
2BX
           Operations – Interview of Pena, PG&E 1-5-11
2BY
           Operations – Interview of Poulo, PG&E 1-5-11
2BZ
           Operations – Interview of Reinhardt, City of San Bruno 1-3-11
2CA
           Operations – Interview of Robertson, PG&E 1-6-11
2CB
           Operations – Interview of Roccholz, PG&E 1-6-11
2CC
           Operations – Interview of Shori, CPUC 1-5-11
2CD
           Operations – Interview of Sickinger, PG&E 1-5-11
2CE
           Operations – Interview of Stepanian, CPUC 1-6-11
2CF
           Operations – Interview of Valenti, PG&E 1-4-11
2CG
           Operations – Interview of Wagner, PG&E 1-4-11
2CH
           Operations – Interview of Wenzel, PG&E 1-5-11
2CI
           Operations – Interview of West, PG&E 1-4-11
2CJ
           Operations – Interview of Wong, City of San Bruno 1-3-11
2CK
           Operations – PHMSA Advisory Bulletin ADB 11-01
           Operations – Excerpts From PG&E Camera Inspection of Line 132, Segment 180
2CL
2CM
           Operations – PG&E Pipeline 2020 Program
2CN
           Operations - PHMSA Pipeline Mileage Data
2CO
           Operations - PG&E Operator Report - Incident and Mileage Data
2CP
           Operations – PHMSA Serious Pipeline Incident Stats 2000-2009 all
2CQ
           Operations – Transmission Onshore Significant Incidents 1990 – 2009 Charts
2CR
           Operations – Transmission Serious Incidents by Cause 2000 – 2009 Pie Charts
2CS
           Operations – California Gas Transmission Incident Data (PHMSA)
2CT
           Operations – Age of Transmission and Hazardous Liquid Pipelines
           (pipelinesafetytrust)
```

Operations - Age of Transmission Pipelines PG&E vs. Southern CA Gas

2CU

- Operations Pipeline Rupture Site Looking North, 10 Sept 2010 IMG\_0097 NTSB (Downs)
   Operations Ruptured Pipeline Segment North End, 11 Sept 2010 IMG\_0128 NTSB (Downs)
- 2CX Operations Segment of Ruptured Pipeline Resting in Glenview Avenue, 10 Sept 2010 IMG\_0098 NTSB (Downs)
- 2CY Operations Fire Damage Looking East Toward Crestmoor Canyon, 10 Sept 2010 IMG 101 NTSB (Downs
- 2CZ Operations Property Damage Near Rupture Location, 11 Sept 2010 IMG\_0133 NTSB (Downs)
- 2DA Operations Photograph of Glenview Avenue Looking North, 10 Sept 2010 ((197) San Bruno Fire Dept.)
- 2DB Operations Photograph of Glenview Avenue Looking South, 10 Sept 2010 ((198) San Bruno Fire Dept.)
- 2DC Operations Photo of Pipeline Fire Sept 9, 2010 (DSC06572 San Bruno Police)
- 2DD Operations San Bruno, CA Google Earth Image Sept 11, 2010
- 2DE Operations San Bruno Aerial Photo on September 1, 2010
- 2DF Operations Interview of John Corona, PG&E September 16, 2010
- 2DG Operations CPUC General Order 112E
- 2DH Operations PG&E Response to CPUC 2010 IM Inspection
- 2DI Operations PG&E Response to CPUC 10-21-10 Letter
- 2DJ Operations CPUC 10-21-10 Letter to PG&E
- 2DK Operations PG&E Response of 12-16-10 to CPUC May 2010 IM Audit.pdf
- 2DL Operations CPUC 9-24-10 Letter to PG&E Regarding GO 112E Audit of Peninsula Division
- 2DM Operations CPUC 10-17-08 Letter to PG&E Regarding GO 112E Audit
- 2DN Operations CPUC Post Accident Responses to San Bruno Pipeline Explosion
- 2DO Operations Summary of CPUC 2005 IM Audit of PG&E
- 2DP Operations CPUC 2005 PG&E IM Audit Meeting Summary
- 2DQ Operations PHMSA Report on "Building Safe Communities: Pipeline Risk and Its Application to Local Development"
- 2DR Operations Congressional Hearing Pipeline Safety Public Awareness Testimony
- 2DS Operations Journal Entries from 1948 L132 Construction
- 2DT Operations CPUC and PG&E Correspondence since December 16, 2010
- 2DU Operations PG&E Comments to PHMSA-RSPA
- 2DV Operations 1956 Relocation Source of Pipe Material
- 2DW Operations Geological Hazard Evaluations
- 2DX Operations Timeline of Events for September 9, 2010
- 2DY Operations PG&E Memo dated June 24, 1996, re: Remote/Automatic Valves
- 2DZ Operations White Paper on Equivalent Safety for Alternative Valve Spacing, INGAA, November 15, 2005
- 2EA Operations PG&E Milpitas and SCADA Data
- 2EB Operations NTSB 014-008 CITECH Data September 9, 2010 to September 10, 2010 Rev 1
- 2EC Operations PG&E Presentation How Line 132 got Listed as Seamless

2ED	Operations – San Bruno Gas Transmission Line Rupture Investigation CPUC Data Request 069
3A 3B	Metallurgical Group Chairman Factual Report Metallurgical - Addendum 1
4A 4B 4C 4D 4E 4F 4G 4H	Survival Factors Group Chairman Factual Report Survival Factors – Transcript of Fire Department Radio Communications Survival Factors – San Bruno Fire Department Incident Reports Survival Factors – List of Responding Fire Departments Survival Factors – Injury List Survival Factors – Federal Public Awareness Regulation Survival Factors – PG&E's Summary Table for Public Awareness Messages Survival Factors – PG&E's Public Awareness Program Plan
4I 4J 4K 4L	Survival Factors - Map of Affected Neighborhood Survival Factors - Example of Bill Stuffer for the Affected Public (Distribution) Survival Factors - Example of a Brochure for the Affected Public (Transmission) Survival Factors - Cover Letters for the 2009 and 2010 Mailings for Emergency Officials
4M 4N 4O 4P 4Q 4R 4S 4T 4U 4V 4W 4X 4Y	Survival Factors – Emergency Officials Mailing List Survival Factors – Public Liaison Workshop Invitation Letter Survival Factors – Organizations Invited to the Public Liaison Workshop Survival Factors – List of Organizations that Attended the Public Liaison Workshop Survival Factors – Public Liaison Workshop Survival Factors – Announcement Flyer for a Responding to Gas and Electric Emergencies Seminar Survival Factors – List of Responding to Gas and Electric Emergencies Seminar Survival Factors – List of Attendees for Responding to Gas and Electric Emergencies Seminar Survival Factors – Example of a Brochure for Public Officials Survival Factors – Public Awareness Program Review Conducted in 2009 Survival Factors – Excerpts from API Recommended Practice 1162 Survival Factors – PG&E Public Awareness Program Review Conducted in 2010 Survival Factors – PG&E Web Site Screen Shot of Gas Transmission Line Information
5A 5B 5C	Fire Scene Factual Report Fire – Belmont – San Carlos Fire Department Origin and Cause Report Fire – Belmont – San Carlos Fire Department Origin and Cause Narrative
6A	Human Performance Factual Report
7A	Meteorology Group Chairman Factual Report
8A	Presentation by Mr. Geoff Foreman, Growth and Strategy Leader, General Electric Oil and Gas

8B	Presentation by Mr. Robert Smith, Research and Development Manager, PHMSA
8C	Presentation by Mr. Charles Dippo, AGA, VP of Engineering Services and System
	Integrity, South Jersey Gas
8D	Presentation by Ms. Christina Sames, AGA, VP of Operations and Engineering
8E	Table Excerpted from NACE Report