



**HIGHWAY FACTORS GROUP CHAIRMAN'S  
FACTUAL REPORT**

**Highway Attachment – CSX “Trouble Tickets” for All City of  
Biloxi Railroad Crossings, March 2012 – March 2017**

**Biloxi, Mississippi**

**HWY17MH010**

(218 pages)

**Attachment Contents:**

Oak Street..... 3  
Crawford Street..... 7  
Dorries Street ..... 14  
Holley Street ..... N/A\*  
Keller Avenue ..... 18  
Lee Street ..... 20  
Nixon Street ..... 26  
Main Street..... 28  
Lameuse Street..... 47  
Delauney Street..... N/A\*  
Magnolia Street..... 55  
Reynoir Street ..... 57  
Caillavet Street..... 62  
Bohn Street..... 82  
Hopkins Boulevard ..... 92  
Seal Avenue ..... 96  
Iroquois Street..... 98  
Benachi Avenue ..... 100  
Querens Avenue..... 106  
Porter Avenue ..... 108  
Gill Avenue..... 122  
White Avenue ..... 125  
Iberville Drive..... 136  
Rodenberg Avenue..... 148  
McDonnell Avenue..... 156  
Veterans Avenue..... 165  
Iris Street..... 187  
Beauvoir Road ..... 193  
Eisenhower Drive..... 210

\* - There were no incidents recorded by CSX at the Holley Street or Delauney Street Grade Crossings between March 2012 and March 2017.

**Oak Street**

**DOT Crossing #: 340177E**

**RR Milepost #: 725.52**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 5

Status All AssetType All RootAssetType All Department Signals AssetNum 340177E

---

**Log#** [7573744](#) **Status** Closed **Entered** 03-25-2016 23:19:48 **by** Rockhill, Jerry **Type** Train-vehicle collision (Signals)

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 725.5 **Block** 2762

**Section** 3090-7M16 **Asset** OAK ST **AssetNum** 340177E **Maintainer**

**Description** 03/25/2016 23:19:48 **by** Jerry Rockhill **Dept** Signals **IT+** Unknown

**Updated** 03/25/2016 23:21:37 **by** Jerry Rockhill **Dept** Signals **IT+** Train-vehicle collision (Signals)

Last Update 03-25-2016 22:58 By DRT Type General Business Impact 3 Priority 3 Incident Type: TRK Dispatch incident  
Number: 09675 Incident Date: 25-MAR-16 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000, 0723.1305 Right Mile  
Post: 000, 0727.0000 Asset: 2762 001, Asset Name: MAIN PTC Flag: N Incident Description: NORTHBOUND Q61225  
STRUCK A VEHICLE ON THE TRACK AT OAK STREET MILEPOST 000725.5. ....AF 36728 Asset: OAK ST Status  
Changed To: Out Of Service PCC Notification Sent 03/25/2016 23:21:37

**Updated** 03/25/2016 23:24:21 **by** Alyson Trouba **Dept** PSCC **IT+**

**Contacted On** 03-25-2016 23:24:00 **Agency** Biloxi Police Department **Contact Name** . **Phone** 228-392-0641  
PSCC Incident Report - Edit #7573729

**Updated** 03/26/2016 00:09:33 **by** Jerry Rockhill **Dept** Signals **IT+** Train-vehicle collision (Signals)

0005 exhausted call list .... escalated to signal mgr g. james... aa disp reports no fatalities ... car has damaged gate mech  
.... activation failure msg on crossing...

**Updated** 03/26/2016 01:13:01 **by** Jerry Rockhill **Dept** Signals **IT+** Train-vehicle collision (Signals)

0110 SIG MGR ENROUTE TO CROSSING...

**Updated** 03/26/2016 03:43:10 **by** Jerry Rockhill **Dept** Signals **IT+** Train-vehicle collision (Signals)

0335 SIG MGR REPORTS EAST GATE MECH DESTROYED... WARNING TIME FOR ACCIDENT 47 SEC.... PMD3  
ONSITE...WILL BE REPLACED DURING DAYLIGHT HOURS...PARTS, BACKHOE AND MULTIPLE MTRS WILL BE  
REQUIRED... ACT FAILURE PROTECTION ON CROSSING...

**Closed** 03/26/2016 17:46:35 **by** Matthew Kite **Dept** Signals **IT+** Train-vehicle collision (Signals)

Incident Resolved: 03/26/2016 17:46:00 Equipment Type: Gate Mechanism Action Taken: Replaced component(s)  
Mntr reports repairs made to gate mech. Performed op checks, no exceptions noted to equip, turned back over to disp,  
annulled with #37033 at 17:03. Crossing BIS with disp.  
Operational Checks Performed Asset: OAK ST Status Changed To: In Service PCC Notification Sent 03/26/2016 17:46:35

---

**Log#** [7555529](#) **Status** Closed **Entered** 03-11-2016 20:11:07 **by** Gaspar, Sean **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 725.5 **Block** 2762

**Section** 3090-7M16 **Asset** OAK ST **AssetNum** 340177E **Maintainer** Mannion, R - ETA: 21:51

**Description** 03/11/2016 20:11:07 **by** Sean Gaspar **Dept** Signals **IT+** Unknown

**Updated** 03/11/2016 20:14:16 **by** Sean Gaspar **Dept** Signals **IT+** .False or partial activation reported

xing is activated w/ no train. dot provided. disp protecting w/ f/p. Notification Sent to -Signal Control Center - Atlanta at  
03/11/2016 20:14:16 Asset: OAK ST Status Changed To: Out Of Service PCC Notification Sent 03/11/2016 20:14:16

**Updated** 03/11/2016 20:21:20 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported

Status changed to Dispatched for Roger Mannion ETA of: 21:51

**Updated** 03/11/2016 20:28:00 **by** Jackie McGuirt **Dept** PSCC **IT+**

**Contacted On** **Agency** local police **Contact Name** jennifer **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 03/11/2016 21:55:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 03/11/2016 23:50:59 **by** Roger Mannion **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 03/11/2016 23:50:00 Equipment Type: Gate Mechanism Action Taken: Replaced component(s) gate was stuck on cant. and would not go all the way up. gate appeared to be hit recently, top U-bracket on gate mech was broken and gate mech was turned just enough to catch on cant. turned gate mech, replaced broken bracket. Operational Checks Performed Asset: OAK ST Status Changed To: In Service PCC Notification Sent 03/11/2016 23:50:59

**Closed** 03/11/2016 23:54:05 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 03/11/2016 23:50:00 Equipment Type: Gate Mechanism Action Taken: Replaced component(s) / Operational Checks Performed

**Updated** 03/11/2016 23:56:10 **by** Kiwana Tompkins **Dept** PSCC **IT+**  
**Contacted On** 03-11-2016 23:55:00 **Agency** local police **Contact Name** 3501 **Phone** 228-392-0641

---

**Log#** [7524844](#) **Status** Closed **Entered** 02-18-2016 11:51:50 **by** McVey, Bruce **Type** Vehicle on Track

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 725.5 **Block** 2762

**Section** 3090-7M16 **Asset** OAK ST **AssetNum** 340177E **Maintainer** Stanfill, M O - ETA: 12:08

**Description** 02/18/2016 11:51:50 **by** Bruce McVey **Dept** Signals **IT+** Unknown

**Updated** 02/18/2016 11:52:22 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track

**COPIED FROM DIRT Notification**

Incident Type: TRK Dispatch incident Number: 70226 Incident Date: 18-FEB-16 Pri.Train ID: SubDivision Code:  
NM Left Mile Post: 000, 0723.2000 Right Mile Post: 000, 0726.0000 Asset: 2762 001, Asset Name: MAIN PTC  
Flag: N **Incident Description: VEHICLE ON TRACK AT 000725.5**  
Asset: OAK ST Status Changed To: Out Of Service PCC Notification Sent 02/18/2016 11:52:22

**Updated** 02/18/2016 11:52:56 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track

The AA is protecting the Crossing with a **Type 1 Activation Failure Message# 17583.**

**Updated** 02/18/2016 11:53:48 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Michael Stanfill ETA of: 12:08

**Updated** 02/18/2016 12:10:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Updated** 02/18/2016 13:54:12 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track

**Update** - The ESS texted a message requesting an update on the Signal Maintainers cell phone.

**Closed** 02/18/2016 16:03:59 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 02/18/2016 14:05:00 Equipment Type: N/A Action Taken: NTF - UTD

**The Signal Maintainer reported that there was no signal damage. Operational Checks were performed.  
The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: OAK ST Status Changed To: In Service PCC Notification Sent 02/18/2016 16:03:59

**Updated** 02/18/2016 16:07:03 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** 02-18-2016 16:05:00 **Agency** Biloxi Police Department **Contact Name** 3500 **Phone** 228-392-0641

**Log#** [7317458](#)    **Status** Closed    **Entered** 09-12-2015 05:58:01    **by** Hillard, James    **Type** .False or partial activation reported  
**Supv** Merritt, D    **Reg** SO    **Div** AT    **Sub** NM    **IRI** 0    **Milepost** 000 725.5    **Block** 2762  
**Section** 3090-7M16    **Asset** OAK ST    **AssetNum** 340177E    **Maintainer** Brown, K L - ETA: 08:11  
**Description** 09/12/2015 05:58:01    **by** James Hillard    **Dept** Signals    **IT+** Unknown  
**Updated** 09/12/2015 06:00:12    **by** James Hillard    **Dept** Signals    **IT+** .False or partial activation reported  
OSP reports one gate down one up. Not trains present Disp protecting with f/p message# 24655 Notification Sent to -Signal Control Center - Atlanta at 09/12/2015 06:00:12 Asset: OAK ST Status Changed To: Out Of Service PCC Notification Sent 09/12/2015 06:00:12  
**Updated** 09/12/2015 06:41:21    **by** Jerry Rockhill    **Dept** Signals    **IT+** .False or partial activation reported  
Status changed to Dispatched for Kenneth Brown ETA of: 08:11  
**Updated** 09/12/2015 06:53:09    **by** Byron Tinsley    **Dept** PSCC    **IT+**  
**Contacted On** 09-12-2015 06:27:00 **Agency** Biloxi Police Department **Contact Name** April    **Phone** 228-392-0641  
@ RR St.  
**Updated** 09/12/2015 08:15:00    **by** TCIS AUTOMATION    **Dept** Signals    **IT+** .False or partial activation reported  
ETA time reached Status changed to Active  
**Closed** 09/12/2015 08:53:32    **by** Bruce McVey    **Dept** Signals    **IT+** .False or partial activation reported  
Incident Resolved: 09/12/2015 08:50:00 Equipment Type: Gate Mechanism Action Taken: Repaired/Replaced Contacts  
**Employee:** K. Brown  
- Cleared/cleaned ants out of contact of gate mech. due to all the rain ... applied bug kill  
Did OP Checks, Back/released to AA disp.  
Operational Checks Performed Asset: OAK ST Status Changed To: In Service PCC Notification Sent 09/12/2015 08:53:32  
**Updated** 09/12/2015 08:56:15    **by** Emily Morton    **Dept** PSCC    **IT+**  
**Contacted On** 09-12-2015 08:55:00 **Agency** Biloxi Police Department **Contact Name** Brenda **Phone** 228-392-0641

---

**Log#** [5758271](#)    **Status** Closed    **Entered** 08-28-2012 08:35:49    **by** Gibson, Bob    **Type** -Informational  
**Supv** Merritt, D    **Reg** SO    **Div** AT    **Sub** NM    **IRI**    **Milepost** 000 725.5    **Block** 2762  
**Section** 3090-Ocean Springs    **Asset** OAK ST    **AssetNum** 340177E    **Maintainer**  
**Closed** 08/31/2012 18:30:36    **by** Terrence Smale II    **Dept** Signals    **IT+** -Informational  
Incident Resolved: 08/28/2012 18:29:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended Suspected Reason: Other weather crossing tested in service Operational Checks Performed

Page Execution Time: 029.90 seconds

**Crawford Street**

**DOT Crossing #: 340178L**

**RR Milepost #: 725.69**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 13

Status All AssetType All RootAssetType All Department Signals AssetNum 340178L

---

**Log#** [7973706](#) **Status** Closed **Entered** 01-23-2017 10:23:05 **by** Price, David **Type** .Other Failure  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 725.7 **Block** 2762  
**Section** 3090-7M16 **Asset** CRAWFORD ST - BILOXI MS **AssetNum** 340178L **Maintainer** James Jr, G H - ETA: 10:42  
**Description** 01/23/2017 10:23:05 **by** David Price **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340178L). Fault detected - sigOStCsAlarm\_000-725.69-340178L-005 \*\*AC POWER OFF FOR 20 MINUTES - TCIS:4 at Crawford St - Biloxi MS 01/23/2017 09:07:25 (MP:000-725.69, DOT:340178L) [ Count: 1 on Mon Jan 23 09:06:37 2017 ]  
**Updated** 01/23/2017 10:42:38 **by** David Price **Dept** Signals **IT+** Unknown  
Status changed to Escalated, George James Jr ETA of: N/A  
**Updated** 01/23/2017 10:43:07 **by** David Price **Dept** Signals **IT+** .Other Failure  
Ticket escalated to the supervisor to find a MTR.  
**Updated** 01/23/2017 12:32:55 **by** Michael Stanfill **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 01/23/2017 12:32:00 Equipment Type: Power/Batteries Action Taken: Reset/Replaced Breaker/Fuse reset power off relay. Operational Checks Performed  
**Closed** 01/23/2017 12:34:53 **by** Jesuito Mercado **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 01/23/2017 12:32:00 Equipment Type: Power/Batteries Action Taken: Reset/Replaced Breaker/Fuse . Operational Checks Performed

---

**Log#** [7822938](#) **Status** Closed **Entered** 09-30-2016 03:02:39 **by** Buksar, Jake **Type** .Other Failure  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 725.7 **Block** 2762  
**Section** 3090-7M16 **Asset** CRAWFORD ST - BILOXI MS **AssetNum** 340178L **Maintainer**  
**Description** 09/30/2016 03:02:40 **by** Jacob Buksar **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340178L). Fault detected - sigOStCsAlarm\_000-725.69-340178L-062 \*\*93% LOW OB: 10.6 V - 93% LOW OB BATT ALARM - TCIS:3 at Crawford St - Biloxi MS 09/30/2016 02:57:54 (MP:000-725.69, DOT:340178L) [ Count: 1 on Fri Sep 30 06:57:45 2016 ]  
**Updated** 09/30/2016 03:03:05 **by** Jacob Buksar **Dept** Signals **IT+** .Other Failure  
Orange 3 Dispatch during business day (Monday-Friday 0700-1500), but handle to resolution during same business day (even if overtime is required). Use deferment procedure after business hours. Maintainer must obtain protection if the crossing is not working as designed upon arrival.  
**Closed** 09/30/2016 11:47:55 **by** Bruce McVey **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 09/30/2016 11:47:00 Equipment Type: N/A Action Taken: NTF - UTD

**Employee:** M. Stanfill

- Could not duplicate the trouble, working as intended.

Did OP Checks

Operational Checks Performed

---

**Log#** [7400245](#) **Status** Closed **Entered** 11-12-2015 14:04:35 **by** Jackson Jr, Marv **Type** .Other Failure  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 725.7 **Block** 2762



**Section** 3090-7M16 **Asset** CRAWFORD ST - BILOXI MS **AssetNum** 340178L **Maintainer** Stanfill, M O - ETA: 16:26

**Description** 11/12/2015 14:04:35 **by** Marv Jackson Jr **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340178L). Fault detected - sigOStCsAlarm\_000-725.69-340178L-006 GATES NOT INDICATING "UP" AFTER TRAIN CLEARED - TCIS:3 at Crawford St - Biloxi MS 11/12/2015 13:51:08 (MP:000-725.69, DOT:340178L) [ Count: 2 on Thu Nov 12 18:51:05 2015 ]

**Updated** 11/12/2015 14:05:01 **by** Marv Jackson Jr **Dept** Signals **IT+** .Other Failure  
SMARTS Notification Sent to -Signal Control Center - Atlanta at 11/12/2015 14:05:01

**Updated** 11/12/2015 14:26:36 **by** Louis Rosenblatt **Dept** Signals **IT+** .Other Failure  
Status changed to Dispatched for Michael Stanfill ETA of: 16:26

**Closed** 11/12/2015 14:52:04 **by** Louis Rosenblatt **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 11/12/2015 14:51:00 Equipment Type: N/A Action Taken: NTF - UTD

**The Signal Maintainer reported that the Crossing was working when he got there. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed

---

**Log#** [7048115](#) **Status** Closed **Entered** 03-11-2015 07:16:43 **by** Jackson Jr, Marv **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 1 **Milepost** 000 725.7 **Block** 2762

**Section** 3090-7M16 **Asset** CRAWFORD ST - BILOXI MS **AssetNum** 340178L **Maintainer** Stanfill, M O - ETA: 08:49

**Description** 03/11/2015 07:16:43 **by** Marv Jackson Jr **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340178L). Fault detected - sigOStCsAlarm\_000-725.69-340178L-062 \*\*93% LOW OB: 10.5 V - 93% LOW OB BATT ALARM - TCIS:3 at Crawford St - Biloxi MS 03/11/2015 06:43:59 (MP:000-725.69, DOT:340178L) [ Count: 2 on Wed Mar 11 10:44:06 2015 ]

**Updated** 03/11/2015 07:17:24 **by** Marv Jackson Jr **Dept** Signals **IT+** .Other Failure  
SMART ALARM 93% LOW OB: 10.5 V - 93% LOW OB BATT ALARM - TCIS:3 at Crawford St - Biloxi MS 03/11/2015 06:43:59 (MP:000-725.69, DOT:340178L) [ Count: 2 on Wed Mar 11 10:44:06 2015 ] Notification Sent to -Signal Control Center - Atlanta at 03/11/2015 07:17:24

**Updated** 03/11/2015 07:17:26 **by** Marv Jackson Jr **Dept** Signals **IT+** .Other Failure  
An email notification for Multi Failure Count (MFC) asset CRAWFORD ST - BILOXI MS (5) has been sent to the following:  
George James Jr  
Danny McKenzie  
David Olson

**Updated** 03/11/2015 07:19:08 **by** Jason Gothard **Dept** Signals **IT+** .Other Failure  
Status changed to Dispatched for Michael Stanfill ETA of: 08:49

**Updated** 03/11/2015 08:50:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .Other Failure  
ETA time reached Status changed to Active

**Closed** 03/11/2015 13:32:17 **by** Jason Gothard **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 03/11/2015 13:32:00 Equipment Type: Power/Batteries Action Taken: Reset/Replaced  
Breaker/Fuse replaced the ckt breaker at the pwr feed. made op checks Operational Checks Performed

---

**Log#** [7047700](#) **Status** Closed **Entered** 03-10-2015 21:00:39 **by** Oglesby, Brad **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.5 **Milepost** 000 725.7 **Block** 2762

**Section** 3090-7M16 **Asset** CRAWFORD ST - BILOXI MS **AssetNum** 340178L **Maintainer**

**Description** 03/10/2015 21:00:39 **by** Brad Oglesby **Dept** Signals **IT+** Unknown

Smarts alert notification for njax-aserver-04.dmz.csxr(340178L). Fault detected - sigOStCsAlarm\_000-725.69-340178L-005 \*\*AC POWER OFF FOR 20 MINUTES - TCIS:4 at Crawford St - Biloxi MS 03/10/2015 20:56:45 (MP:000-725.69, DOT:340178L) [ Count: 14 on Wed Mar 11 00:56:52 2015 ]

**Updated** 03/10/2015 21:03:19 **by** Brad Oglesby **Dept** Signals **IT+** .Other Failure  
THERE ISN'T A POWER-OFF INDICATION SHOWING AT THE CONTROL POINT OR IN THE BLOCK.

**Updated** 03/10/2015 21:03:21 **by** Brad Oglesby **Dept** Signals **IT+** .Other Failure  
An email notification for Multi Failure Count (MFC) asset CRAWFORD ST - BILOXI MS (4) has been sent to the following:  
George James Jr  
Danny McKenzie

**Updated** 03/10/2015 22:18:46 **by** Brad Oglesby **Dept** Signals **IT+** .Other Failure  
Smarts alert notification for njax-aserver-04.dmz.csxr(340178L). Fault detected - sigOStCsAlarm\_000-725.69-340178L-005 CLEARED:AC POWER BACK ON - TCIS:5 at Crawford St - Biloxi MS 03/10/2015 21:04:02 (MP:000-725.69, DOT:340178L)

**Closed** 03/10/2015 22:19:06 **by** Brad Oglesby **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 03/10/2015 22:18:00 Equipment Type: N/A Action Taken: NTF - UTD . Operational Checks Performed

---

**Log#** [7046254](#) **Status** Closed **Entered** 03-10-2015 06:41:21 **by** Martin, Mike **Type** .Other Failure  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.25 **Milepost** 000 725.7 **Block** 2762  
**Section** 3090-7M16 **Asset** CRAWFORD ST - BILOXI MS **AssetNum** 340178L **Maintainer**  
**Description** 03/10/2015 06:41:21 **by** Mike Martin **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340178L). Fault detected - sigOStCsAlarm\_000-725.69-340178L-005 \*\*AC POWER OFF FOR 20 MINUTES - TCIS:4 at Crawford St - Biloxi MS 03/10/2015 05:46:33 (MP:000-725.69, DOT:340178L) [ Count: 6 on Tue Mar 10 09:46:40 2015 ]

**Updated** 03/10/2015 06:42:00 **by** Mike Martin **Dept** Signals **IT+** .Other Failure  
Yellow 4 Dispatch during business day (Monday-Friday 0700 – 1500). Resolve by end of next business day, should not involve overtime. Use deferment procedure after business hours. Maintainer must obtain protection if the crossing is not working as designed upon arrival

**Updated** 03/10/2015 06:42:01 **by** Mike Martin **Dept** Signals **IT+** .Other Failure  
An email notification for Multi Failure Count (MFC) asset CRAWFORD ST - BILOXI MS (3) has been sent to the following:  
George James Jr  
Danny McKenzie

**Closed** 03/10/2015 14:18:02 **by** Jason Gothard **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 03/10/2015 14:18:00 Equipment Type: Power/Batteries Action Taken: Commercial Power Restored 2015/03/10 11:29:34 AC POWER BACK ON - TCIS:5#5#0#5#5## Operational Checks Performed

---

**Log#** [7041249](#) **Status** Closed **Entered** 03-06-2015 11:58:16 **by** Jackson Jr, Marv **Type** .Other Failure  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 725.7 **Block** 2762  
**Section** 3090-7M16 **Asset** CRAWFORD ST - BILOXI MS **AssetNum** 340178L **Maintainer** Stanfill, M O - ETA: 14:19  
**Description** 03/06/2015 11:58:17 **by** Marv Jackson Jr **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340178L). Fault detected - sigOStCsAlarm\_000-725.69-340178L-005 \*\*AC POWER OFF FOR 20 MINUTES - TCIS:4 at Crawford St - Biloxi MS 03/06/2015 10:39:30 (MP:000-725.69, DOT:340178L) [ Count: 14 on Fri Mar 6 15:38:19 2015 ]

**Updated** 03/06/2015 11:58:52 **by** Marv Jackson Jr **Dept** Signals **IT+** .Other Failure  
SMART ALARM Notification Sent to -Signal Control Center - Atlanta at 03/06/2015 11:58:52

**Closed** 03/06/2015 15:43:18 by Louis Rosenblatt Dept Signals IT+ .Other Failure  
Incident Resolved: 03/06/2015 15:42:00 Equipment Type: Power/Batteries Action Taken: Commercial Power Restored

**The Signal Maintainer reported that the Commercial Power has been restored. Operational Checks were performed. LVR**

Operational Checks Performed

---

**Log#** [7024333](#) **Status** Closed **Entered** 02-24-2015 16:48:17 **by** Oglesby, Brad **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 725.7 **Block** 2762

**Section** 3090-7M16 **Asset** CRAWFORD ST - BILOXI MS **AssetNum** 340178L **Maintainer**

**Description** 02/24/2015 16:48:17 by Brad Oglesby Dept Signals IT+ Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340178L). Fault detected - sigOStCsAlarm\_000-725.69-340178L-005 \*\*AC POWER OFF FOR 20 MINUTES - TCIS:4 at Crawford St - Biloxi MS 02/24/2015 16:45:14 (MP:000-725.69, DOT:340178L) [ Count: 2 on Tue Feb 24 21:44:10 2015 ]

**Updated** 02/24/2015 16:49:21 by Brad Oglesby Dept Signals IT+ .Other Failure  
THERE ISN'T A POWER-OFF INDICATION SHOWING AT THE CONTROL POINT OR IN THE BLOCK.

**Updated** 02/24/2015 21:31:55 by Brad Oglesby Dept Signals IT+ .Other Failure  
Smarts alert notification for njax-aserver-04.dmz.csxr(340178L). Fault detected - sigOStCsAlarm\_000-725.69-340178L-005 CLEARED:AC POWER BACK ON - TCIS:5 at Crawford St - Biloxi MS 02/24/2015 17:00:18 (MP:000-725.69, DOT:340178L)

**Closed** 02/24/2015 21:32:15 by Brad Oglesby Dept Signals IT+ .Other Failure  
Incident Resolved: 02/24/2015 21:32:00 Equipment Type: N/A Action Taken: NTF - UTD . Operational Checks Performed

---

**Log#** [6765324](#) **Status** Closed **Entered** 08-24-2014 11:20:06 **by** Gaspar, Sean **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 725.7 **Block** 2762

**Section** 3090-7M16 **Asset** CRAWFORD ST - BILOXI MS **AssetNum** 340178L **Maintainer** Lumpkin, K J - ETA: 13:08

**Description** 08/24/2014 11:20:06 by Sean Gaspar Dept Signals IT+ Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340178L). Fault detected - sigOStCsAlarm\_000-725.69-340178L-002 ESCALATED:ACT FAIL - \*\*WARNING TIME TK1: 5 - SHORT WARNING - TCIS:1 at Crawford St - Biloxi MS 08/24/2014 11:19:04 (MP:000-725.69, DOT:340178L) [ 1 at ]

**Updated** 08/24/2014 11:24:05 by Sean Gaspar Dept Signals IT+ .Other Failure  
Red 1 Notify dispatcher to protect the crossing with an Activation Failure or False Activation. Notify maintainer. Type of dispatcher protection must be communicated to the maintainer. Must be investigated immediately. disp protecting w/ act/failure message as per smarts. td pate has eci at this location at time of alarm. Notification Sent to -Signal Control Center - Atlanta at 08/24/2014 11:24:05 Asset: CRAWFORD ST - BILOXI MS Status Changed To: Out Of Service PCC Notification Sent 08/24/2014 11:24:05

**Updated** 08/24/2014 11:28:30 by Alexis Romine Dept PSCC IT+  
**Contacted On** 08-24-2014 11:28:00 **Agency** Biloxi Police Department **Contact Name** Tiffany **Phone** 228-392-0641 @ Railroad Street

**Updated** 08/24/2014 12:08:15 by Bruce McVey Dept Signals IT+ .Other Failure  
Status changed to Dispatched for Kevin Lumpkin ETA of: 13:08

**Updated** 08/24/2014 13:10:00 by TCIS AUTOMATION Dept Signals IT+ .Other Failure  
ETA time reached Status changed to Active

**Updated** 08/24/2014 13:55:48 **by** Sean Gaspar **Dept** Signals **IT+** .Other Failure  
Smarts alert notification for njax-aserver-04.dmz.csxr(340178L). Fault detected - sigOStCsAlarm\_000-725.69-340178L-002 CLEARED:WARNING TIME NORMAL TK1 - TCIS:5 at Crawford St - Biloxi MS 08/24/2014 13:51:57 (MP:000-725.69, DOT:340178L)

**Closed** 08/24/2014 13:56:40 **by** Bruce McVey **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 08/24/2014 13:56:00 Equipment Type: N/A Action Taken: NTF - UTD

**Employee:** K. Lumpkin

- Crossing working as intended, tk insp hyrailed thru at time of incident

Did OP Checks, Back/released to AA disp. Watched NB (Q572) train thru crossing, no exceptions.

Operational Checks Performed Asset: CRAWFORD ST - BILOXI MS Status Changed To: In Service PCC  
Notification Sent 08/24/2014 13:56:40

**Updated** 08/24/2014 13:59:53 **by** Avie Saunders **Dept** PSCC **IT+**  
**Contacted On** 08-24-2014 13:59:00 **Agency** Biloxi Police Department **Contact Name** Tiffany **Phone** 228-392-0641

---

**Log#** [6493623](#) **Status** Closed **Entered** 02-15-2014 11:36:42 **by** Lewis, Wendell **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 725.7 **Block** 2762

**Section** 3090-Ocean Springs **Asset** CRAWFORD ST - BILOXI MS **AssetNum** 340178L **Maintainer**

**Description** 02/15/2014 11:36:42 **by** Wendell Lewis **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340178L). Fault detected - sigOStCsAlarm\_000-725.69-340178L-006 GATES STAYED DOWN BEHIND TRAIN - TCIS:3 at Crawford St - Biloxi MS 02/15/2014 11:16:03 (MP:000-725.69, DOT:340178L) [ 1 at ]

**Updated** 02/15/2014 11:39:38 **by** Wendell Lewis **Dept** Signals **IT+** .Other Failure  
PLEASE HAVE MNTR. CHECK PRIORITY 3 ALARM WHEN BACK ON DUTY.

**Closed** 02/17/2014 13:23:12 **by** Bruce McVey **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 02/17/2014 13:23:00 Equipment Type: N/A Action Taken: NTF - UTD

**Employee:** M. Stanfill

- Could not duplicate the trouble, working as intended.

Did OP Checks

Operational Checks Performed

---

**Log#** [6410623](#) **Status** Closed **Entered** 12-19-2013 13:02:21 **by** Lewis, Wendell **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 725.7 **Block** 2762

**Section** 3090-Ocean Springs **Asset** CRAWFORD ST - BILOXI MS **AssetNum** 340178L **Maintainer** Stanfill, M O - ETA: 13:17

**Description** 12/19/2013 13:02:21 **by** Wendell Lewis **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340178L). Fault detected - sigOStCsAlarm\_000-725.69-340178L-006 GATES STAYED DOWN BEHIND TRAIN - TCIS:3 at Crawford St - Biloxi MS 12/19/2013 12:08:22 (MP:000-725.69, DOT:340178L) [ 1 at ]

**Updated** 12/19/2013 13:04:51 **by** Wendell Lewis **Dept** Signals **IT+** .Other Failure  
. Notification Sent to -Signal Control Center - Atlanta at 12/19/2013 13:04:51

**Updated** 12/19/2013 13:17:18 **by** Matthew Kite **Dept** Signals **IT+** .Other Failure  
Status changed to Dispatched for Michael Stanfill ETA of: N/A

**Updated** 12/19/2013 13:20:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .Other Failure  
ETA time reached Status changed to Active

**Closed** 12/19/2013 13:22:22 **by** Matthew Kite **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 12/19/2013 13:20:00 Equipment Type: N/A Action Taken: NTF - UTD  
Mntr on-site doing test, setting up island ckt. Mntr set unit to User Test Mode. FRM WAMS: 2013/12/19 13:08:49  
GATES UP, "CROSSING CLEAR" - TCIS:5# Closing incident.  
Operational Checks Performed

---

**Log#** [5933072](#) **Status** Closed **Entered** 01-08-2013 12:48:38 **by** Lewis, Wendell **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 725.7 **Block** 2762

**Section** 3090-Ocean Springs **Asset** CRAWFORD ST - BILOXI MS **AssetNum** 340178L **Maintainer** Stanfill, M O - ETA: 12:57

**Description** 01/08/2013 12:48:38 **by** Wendell Lewis **Dept** Signals **IT+** Unknown  
Smarts alert notification for nind2008app.dmz(340178L). Fault detected - sigOStCsAlarm\_000-725.69-340178L-  
006 GATES STAYED DOWN BEHIND TRAIN - TCIS:3 at Crawford St - Biloxi MS 01/08/2013 12:31:38 (MP:000-  
725.69, DOT:340178L) [ 1 at ]

**Updated** 01/08/2013 12:51:10 **by** Wendell Lewis **Dept** Signals **IT+** .Other Failure  
. Notification Sent to -Signal Control Center - Atlanta at 01/08/2013 12:51:10

**Updated** 01/08/2013 12:55:04 **by** TCIS AUTOMATION **Dept** Signals **IT+** .Other Failure  
Status changed to Dispatched for ETA of: 12:57

**Closed** 01/08/2013 12:56:03 **by** Jason Gothard **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 01/08/2013 12:55:00 Equipment Type: N/A Action Taken: Informational mntr is at the location  
performing tests and forgot to take location off line. xing working as intended Operational Checks Performed

---

**Log#** [5661734](#) **Status** Closed **Entered** 06-24-2012 05:46:34 **by** Rockhill, Jerry **Type** Vehicle on Track

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 725.7 **Block** 2762

**Section** 3090-Ocean Springs **Asset** CRAWFORD ST - BILOXI MS **AssetNum** 340178L **Maintainer** Houck, B - ETA: 07:31

**Description** 06/24/2012 05:49:27 **by** Jerry Rockhill **Dept** Signals **IT+** Vehicle on Track  
0549 atl chief, aa disp, nm sub, vehicle stuck on the track at mp 000725.7 Crawford Street .....no further  
infomation given...aa disp protecting crossing with activation failure msg 22490..... Asset: CRAWFORD ST -  
BILOXI MS Status Changed To: Out Of Service PCC Notification Sent 06/24/2012 05:49:27

**Closed** 06/24/2012 07:37:54 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 06/24/2012 07:37:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as  
intended Suspected Reason: Outside party or vandalism

**Employee:** B. Houck

- Vehicle removed, No signal damage.

Did OP Checks, Back/released to AA disp. Watched NB train thru crossing, no exceptions.

Operational Checks Performed Asset: CRAWFORD ST - BILOXI MS Status Changed To: In Service PCC  
Notification Sent 06/24/2012 07:37:54

Page Execution Time: 005.37 seconds

**Dorries Street**

**DOT Crossing #: 340179T**

**RR Milepost #: 725.97**



## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 5

Status All AssetType All RootAssetType All Department Signals AssetNum 340179T

---

**Log#** [8005730](#) **Status** Closed **Entered** 02-16-2017 18:52:26 **by** Kondy, Rick **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.0 **Block** 2762  
**Section** 3090-7M16 **Asset** DORRIES ST **AssetNum** 340179T **Maintainer** Mannion, R - ETA: 20:28  
**Description** 02/16/2017 18:52:26 **by** Richard Kondy **Dept** Signals **IT+** Unknown  
**Updated** 02/16/2017 18:55:58 **by** Richard Kondy **Dept** Signals **IT+** .False or partial activation reported  
gates up and down , no trains . disp protecting crossing with false activation # 23043 . Asset: DORRIES ST Status Changed To: Out  
Of Service PCC Notification Sent 02/16/2017 18:55:58  
**Updated** 02/16/2017 19:19:34 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** 02-16-2017 19:18:00 **Agency** Biloxi Police Department **Contact Name** 3481 **Phone** 228-392-0641  
@ Allen St.  
**Updated** 02/16/2017 19:28:03 **by** Richard Kondy **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Roger Mannion ETA of: 20:28  
**Updated** 02/16/2017 20:30:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active  
**Updated** 02/16/2017 22:17:00 **by** Roger Mannion **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 02/16/2017 22:16:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced Track Card Unit was  
transferring from Main to Standby for no obvious reason, locked unit in main and tested crossing, watched NB train go through  
crossing with no exceptions. Could not locate new transfer module so unit remains functioning locked in main. Will need to replaced  
transfer module once one is located. Operational Checks Performed Asset: DORRIES ST Status Changed To: In Service PCC  
Notification Sent 02/16/2017 22:17:00  
**Closed** 02/16/2017 22:18:38 **by** Richard Kondy **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 02/16/2017 22:16:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced Track Card //  
Operational Checks Performed  
**Updated** 02/16/2017 22:46:12 **by** Emily Morton **Dept** PSCC **IT+**  
**Contacted On** 02-16-2017 22:45:00 **Agency** Biloxi Police Department **Contact Name** Brandy **Phone** 228-392-0641

---

**Log#** [7759487](#) **Status** Closed **Entered** 08-15-2016 00:04:59 **by** Buksar, Jake **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 726.0 **Block** 2762  
**Section** 3090-7M16 **Asset** DORRIES ST **AssetNum** 340179T **Maintainer** Stanfill, M O - ETA: 01:45  
**Description** 08/15/2016 00:04:59 **by** Jacob Buksar **Dept** Signals **IT+** Unknown  
**Updated** 08/15/2016 00:07:53 **by** Jacob Buksar **Dept** Signals **IT+** .False or partial activation reported  
Local PD reports the crossing is activated with no trains present. DOT# provided. Dispatcher protecting with a false partial.  
Asset: DORRIES ST Status Changed To: Out Of Service PCC Notification Sent 08/15/2016 00:07:53  
**Updated** 08/15/2016 00:07:57 **by** Jacob Buksar **Dept** Signals **IT+** .False or partial activation reported  
An email notification for (IRI) asset DORRIES ST (1) has been sent to the following:  
George James Jr  
**Updated** 08/15/2016 00:15:02 **by** David Mates **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 01:45  
**Updated** 08/15/2016 00:58:27 **by** Kiwana Tompkins **Dept** PSCC **IT+**

**Contacted On** Agency Biloxi PD **Contact Name** OPR 364 **Phone** 228-392-0641

Reporting party has been verified as the responsible law enforcement agency.

**Updated** 08/15/2016 01:50:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 08/15/2016 03:37:28 **by** Thomas Reed **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 08/15/2016 03:36:00 Equipment Type: Wiring/Protection Action Taken: Repaired/Replaced Protection mtr reported crossing found in high signal replaced lightning protection at crossing and adj crossings tested disp advised ok for service. Operational Checks Performed Asset: DORRIES ST Status Changed To: In Service PCC Notification Sent 08/15/2016 03:37:28

**Updated** 08/15/2016 04:02:42 **by** Alyson Trouba **Dept** PSCC **IT+**  
**Contacted On** 08-15-2016 04:02:00 **Agency** Biloxi PD **Contact Name** Brenda **Phone** 228-392-0641

---

**Log#** [7755665](#) **Status** Closed **Entered** 08-11-2016 12:27:06 **by** Wilburn, Marion **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.0 **Block** 2762

**Section** 3090-7M16 **Asset** DORRIES ST **AssetNum** 340179T **Maintainer** Broadway, J L - ETA: 14:51

**Description** 08/11/2016 12:27:06 **by** Marion Wilburn **Dept** Signals **IT+** Unknown

**Updated** 08/11/2016 12:32:16 **by** Marion Wilburn **Dept** Signals **IT+** .False or partial activation reported  
1228 Hrs. 911-center reports gates going up and down with no train present, AA-dispatcher has been notified to protect crossing as f/a Notification Sent to -Signal Control Center - Atlanta at 08/11/2016 12:32:16 Asset: DORRIES ST Status Changed To: Out Of Service PCC Notification Sent 08/11/2016 12:32:16

**Updated** 08/11/2016 12:33:33 **by** Michele Schwartz **Dept** PSCC **IT+**  
**Contacted On** **Agency** 911 **Contact Name** 376 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 08/11/2016 12:51:49 **by** Marion Wilburn **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Joshua Broadway ETA of: 14:51

**Updated** 08/11/2016 14:55:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 08/11/2016 15:33:20 **by** Joshua Broadway **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 08/11/2016 15:33:00 Equipment Type: N/A Action Taken: NTF - UTD crossing working as intended upon arrival. possible weather issue due to fact that unit had transferred to standby. reset to main and auto, no grounds , dc voltages all checked within specs, gate descent time 13 seconds. returned to service at 1528 SLE. Operational Checks Performed Asset: DORRIES ST Status Changed To: In Service PCC Notification Sent 08/11/2016 15:33:20

**Closed** 08/11/2016 15:35:47 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 08/11/2016 15:33:00 Equipment Type: N/A Action Taken: NTF - UTD Operational Checks Performed

**Updated** 08/11/2016 17:11:06 **by** Jerome Shepard **Dept** PSCC **IT+**  
**Contacted On** 08-11-2016 17:11:00 **Agency** Biloxi 911 **Contact Name** Operator 2292 **Phone** 228-392-0641

---

**Log#** [7528843](#) **Status** Closed **Entered** 02-21-2016 18:34:16 **by** Kite, Matt **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.0 **Block** 2762

**Section** 3090-7M16 **Asset** DORRIES ST **AssetNum** 340179T **Maintainer** Stanfill, M O - ETA: 20:08

**Description** 02/21/2016 18:34:16 **by** Matthew Kite **Dept** Signals **IT+** Unknown

**Updated** 02/21/2016 18:35:11 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Incident Type: TRK Dispatch incident Number: 70993 Incident Date: 21-FEB-16 Pri.Train ID: SubDivision Code: NM Left Mile Post:



000, 0723.1000 Right Mile Post: 000, 0723.2000 Asset: 2762 002, Asset Name: MAIN PTC Flag: N Incident Description: GATE BROKE HANGING ACROSS THE TRACK AT DORRIES ST MP 000725.7 Copied frm DIRT. Disp prot with A/F #21680. Asset: DORRIES ST Status Changed To: Out Of Service PCC Notification Sent 02/21/2016 18:35:11

**Updated** 02/21/2016 18:38:23 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 20:08

**Updated** 02/21/2016 18:54:33 **by** Shari Baron **Dept** PSCC **IT+**  
**Contacted On** 02-21-2016 18:53:00 **Agency** Biloxi Police Department **Contact Name** Jessica **Phone** 228-392-0641  
@Esters Blv

**Updated** 02/21/2016 20:10:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 02/21/2016 20:52:31 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 02/21/2016 20:52:00 Equipment Type: Gate Action Taken: Damaged gate or sections-replaced/repared  
Mntr replaced east gate. Performed op checks, turned crossing back over to disp.  
Operational Checks Performed Asset: DORRIES ST Status Changed To: In Service PCC Notification Sent 02/21/2016 20:52:31

**Updated** 02/21/2016 21:03:24 **by** Jodi Snyder **Dept** PSCC **IT+**  
**Contacted On** 02-21-2016 21:02:00 **Agency** Biloxi Police Department **Contact Name** Jennifer **Phone** 228-392-0641  
@Esters Blv

---

**Log#** [7282740](#) **Status** Closed **Entered** 08-18-2015 13:50:09 **by** Lewis, Wendell **Type** .False or partial activation reported

**Supv** Merritt, D **Reg SO** **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.0 **Block** 2762

**Section** 3090-7M16 **Asset** DORRIES ST **AssetNum** 340179T **Maintainer** Stanfill, M O - ETA: 14:17

**Description** 08/18/2015 13:50:09 **by** Wendell Lewis **Dept** Signals **IT+** Unknown

**Updated** 08/18/2015 13:54:24 **by** Wendell Lewis **Dept** Signals **IT+** .False or partial activation reported  
13:49 FLASHERS AND GATES ACTIVATED WITH NO TRAIN.....NOTIFIED AA-DISP. TO PROTECT F/P ACTIVATION.  
Notification Sent to -Signal Control Center - Atlanta at 08/18/2015 13:54:24 Asset: DORRIES ST Status Changed To: Out Of Service PCC Notification Sent 08/18/2015 13:54:24

**Updated** 08/18/2015 13:55:50 **by** Alyson Trouba **Dept** PSCC **IT+**  
**Contacted On** 08-18-2015 13:55:00 **Agency** BILOXI PD **Contact Name** DILLON **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 08/18/2015 14:02:15 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 14:17

**Updated** 08/18/2015 14:20:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 08/18/2015 15:29:51 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 08/18/2015 15:27:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced Termination Shunt

**The Signal Maintainer found and repaired a bad connection at the Southbound Termination Shunt. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: DORRIES ST Status Changed To: In Service PCC Notification Sent 08/18/2015 15:29:51

**Updated** 08/18/2015 15:47:29 **by** Alexis Romine **Dept** PSCC **IT+**  
**Contacted On** 08-18-2015 15:47:00 **Agency** BILOXI PD **Contact Name** Jackie **Phone** 228-392-0641

**Keller Avenue**

**DOT Crossing #: 340181U**

**RR Milepost #: 726.17**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 1

Status All AssetType All RootAssetType All Department Signals AssetNum 340181U

---

**Log#** [7805230](#) **Status** Closed **Entered** 09-17-2016 16:30:19 **by** Williams, Jack **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.2 **Block** 2762

**Section** 3090-7M16 **Asset** KELLER AVE **AssetNum** 340181U **Maintainer** Mannion, R - ETA: 18:22

**Description** 09/17/2016 16:30:19 **by** John Williams **Dept** Signals **IT+** Unknown

**Updated** 09/17/2016 16:35:27 **by** John Williams **Dept** Signals **IT+** .False or partial activation reported  
BPD reports lights flashing at crossing and no trains present. DOT # provided Disp protecting with F/P msg#29171 Asset:  
KELLER AVE Status Changed To: Out Of Service PCC Notification Sent 09/17/2016 16:35:27

**Updated** 09/17/2016 16:52:29 **by** John Williams **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Roger Mannion ETA of: 18:22

**Updated** 09/17/2016 17:09:03 **by** Deborah Anderson **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi Police Dept **Contact Name** 3241 **Phone** 2283920641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 09/17/2016 18:25:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 09/17/2016 19:28:16 **by** Roger Mannion **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 09/17/2016 19:28:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced/Reset CPU  
Replaced TRM module. Made adjustments as per prints, shunt tested crossing, watched southbound train over crossing at time  
table speed with 30 second warning time. Crossing is a lights and bell only crossing, bell working as intended. Back to  
dispatcher at 1713sle. Operational Checks Performed Asset: KELLER AVE Status Changed To: In Service PCC Notification  
Sent 09/17/2016 19:28:16

**Closed** 09/17/2016 19:33:23 **by** Andrew Stancil **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 09/17/2016 19:28:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced/Reset CPU  
Maintainer reports he replaced TRM module. Made adjustments as per prints, shunt tested crossing, watched southbound train  
over crossing at time table speed with 30 second warning time. Crossing is flasher only, maintainer tested w/ no exceptions  
taken. Back to dispatcher at 1713sle. Operational Checks Performed Operational Checks Performed

**Updated** 09/17/2016 21:50:20 **by** Jolene Woods **Dept** PSCC **IT+**  
**Contacted On** 09-17-2016 21:50:00 **Agency** Biloxi Police Dept **Contact Name** Brandy **Phone** 2283920641

Page Execution Time: 005.04 seconds

**Lee Street**

**DOT Crossing #: 340182B**

**RR Milepost #: 726.25**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 9

Status All AssetType All RootAssetType All Department Signals AssetNum 340182B

---

**Log#** [7103389](#) **Status** Closed **Entered** 04-17-2015 23:09:42 **by** Wood, Zach **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.3 **Block** 2762

**Section** 3090-7M16 **Asset** LEE ST **AssetNum** 340182B **Maintainer** Stanfill, M O - ETA: 01:38

**Description** 04/17/2015 23:09:42 **by** Zacchaeus Wood **Dept** Signals **IT+** Unknown

**Updated** 04/17/2015 23:12:25 **by** Zacchaeus Wood **Dept** Signals **IT+** .False or partial activation reported

Local PD reports crossing gates up and lights flashing w/ no trains present, DOT# provided. Crossing protected w/ F/P activation.

Notification Sent to -Signal Control Center - Atlanta at 04/17/2015 23:12:25 Asset: LEE ST Status Changed To: Out Of Service

PCC Notification Sent 04/17/2015 23:12:25

**Updated** 04/17/2015 23:24:51 **by** Jodi Snyder **Dept** PSCC **IT+**

**Contacted On** 04-17-2015 23:22:00 **Agency** Biloxi Police Department **Contact Name** April **Phone** 228-392-0641

Esters Blvd.

**Updated** 04/18/2015 00:08:34 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported

Status changed to Dispatched for Michael Stanfill ETA of: 01:38

**Updated** 04/18/2015 01:40:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported

ETA time reached Status changed to Active

**Closed** 04/18/2015 02:52:16 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported

Incident Resolved: 04/18/2015 02:51:00 Equipment Type: Gate Mechanism Action Taken: Repaired/Replaced Contacts 0250 mtr

reports clean and adj east gate mech power up contact....gft 14sec...op cks ok and crossing back in service with disp. Operational

Checks Performed Asset: LEE ST Status Changed To: In Service PCC Notification Sent 04/18/2015 02:52:16

**Updated** 04/18/2015 02:56:43 **by** Jodi Snyder **Dept** PSCC **IT+**

**Contacted On** 04-18-2015 02:56:00 **Agency** Biloxi Police Department **Contact Name** April **Phone** 228-392-0641

Esters Blvd.

---

**Log#** [6796888](#) **Status** Closed **Entered** 09-16-2014 03:33:06 **by** Belkot, Paul **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.3 **Block** 2762

**Section** 3090-7M16 **Asset** LEE ST **AssetNum** 340182B **Maintainer** Stanfill, M O - ETA: 05:14

**Description** 09/16/2014 03:33:06 **by** Paul Belkot **Dept** Signals **IT+** Unknown

**Updated** 09/16/2014 03:37:31 **by** Paul Belkot **Dept** Signals **IT+** .False or partial activation reported

GATES UP FLASHERS CONTINUOUS NO TRAIN IN AREA PER LOCAL PD. AA disp advised to protect crossing as a false partial

activation, disp initials ECB. Sent notification to ESS Atlanta div., please call mtr. Notification Sent to -Signal Control Center - Atlanta

at 09/16/2014 03:37:31 Asset: LEE ST Status Changed To: Out Of Service PCC Notification Sent 09/16/2014 03:37:31

**Updated** 09/16/2014 03:44:07 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Status changed to Dispatched for Michael Stanfill ETA of: 05:14

**Updated** 09/16/2014 04:58:09 **by** Kiwana Tompkins **Dept** PSCC **IT+**

**Contacted On** **Agency** BILOXI MS PD **Contact Name** OPERATOR 3411 **Phone** 228-392-0641

Reporting party has been verified as the responsible law enforcement agency.

**Updated** 09/16/2014 05:15:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported

ETA time reached Status changed to Active

**Updated** 09/16/2014 07:26:37 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported

NB Q602-10 is in the block.

**Closed** 09/16/2014 08:14:29 by Bruce McVey Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 09/16/2014 08:14:00 Equipment Type: Gate Mechanism Action Taken: Repaired/Replaced Contacts

**Employee:** M. Stanfill

- Crossing was clear when MTR arrived, could not duplicate the trouble. Crossing is working as intended. Cleaned and adjusted both contactes in gate mech

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: LEE ST Status Changed To: In Service PCC Notification Sent 09/16/2014 08:14:29

**Updated** 09/16/2014 08:16:51 by Marvin Smoot Dept PSCC IT+  
**Contacted On** Agency BILOXI MS PD **Contact Name** OPERATOR 3411 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

---

**Log#** [6329325](#) **Status** Closed **Entered** 10-16-2013 16:40:35 by Mercado, Wito **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.3 **Block** 2762

**Section** 3090-Ocean Springs **Asset** LEE ST **AssetNum** 340182B **Maintainer** Stanfill, M O - ETA: 17:37

**Description** 10/16/2013 16:40:35 by Jesuito Mercado Dept Signals IT+ Unknown

**Updated** 10/16/2013 16:46:07 by Jesuito Mercado Dept Signals IT+ .False or partial activation reported  
1641hr Local pd reports crossing gates are up, lights on with no trains present... Notification Sent to -Signal Control Center - Atlanta at 10/16/2013 16:46:07 Asset: LEE ST Status Changed To: Out Of Service PCC Notification Sent 10/16/2013 16:46:07

**Updated** 10/16/2013 16:51:47 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported

The AA Dispatcher is protecting the crossing with a **Type 2 False / Partial Activation Message# 19107**. LVR

**Updated** 10/16/2013 16:52:51 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 17:37

**Closed** 10/16/2013 17:31:45 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 10/16/2013 17:29:00 Equipment Type: Gate mechanism Action Taken: Cleaned

**The Signal Maintainer cleaned all the contacts in the East Gate Mechanism. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: LEE ST Status Changed To: In Service PCC Notification Sent 10/16/2013 17:31:45

**Updated** 10/16/2013 17:35:09 by Sean Reid Dept PSCC IT+  
**Contacted On** 10-16-2013 17:34:00 Agency Biloxi Police Department **Contact Name** 2317 **Phone** 228-392-0641

---

**Log#** [6064744](#) **Status** Closed **Entered** 04-06-2013 14:32:07 by Miller, Vern **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.3 **Block** 2762

**Section** 3090-Ocean Springs **Asset** LEE ST **AssetNum** 340182B **Maintainer** Brown, K L - ETA: 17:07

**Description** 04/06/2013 14:32:07 by Verlon Miller Dept Signals IT+ Unknown

**Updated** 04/06/2013 14:33:19 by Verlon Miller Dept Signals IT+ .False or partial activation reported  
crossing activated, no train around. dispatcher notified to protect with false/partial activation protection. vern Asset: LEE ST Status Changed To: Out Of Service PCC Notification Sent 04/06/2013 14:33:19

**Updated** 04/06/2013 14:33:30 by Verlon Miller Dept Signals IT+ .False or partial activation reported  
. Notification Sent to -Signal Control Center - Atlanta at 04/06/2013 14:33:30

**Updated** 04/06/2013 14:41:28 by Jerome Shepard Dept PSCC IT+

**Contacted On** Agency p.d. **Contact Name** angie **Phone** 228 392 0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 04/06/2013 15:07:06 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Kenneth Brown ETA of: 17:07

**Updated** 04/06/2013 17:10:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 04/06/2013 19:01:27 **by** Kenneth Brown **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 04/06/2013 19:00:00 Equipment Type: Power/batteries Action Taken: Other - explain mntr found east gate latching out to soon. mntr cleaned and checked batteries and up charger to 14.5 volts on the B-G. mntr then operated system about ten times and watched train thru with no problems. Operational Checks Performed Asset: LEE ST Status Changed To: In Service PCC Notification Sent 04/06/2013 19:01:27

**Updated** 04/06/2013 19:19:40 **by** Jesse Gansen **Dept** PSCC **IT+**  
**Contacted On** 04-06-2013 19:19:00 **Agency** p.d. **Contact Name** 1955 **Phone** 228 392 0641

---

**Log#** [5749675](#) **Status** Closed **Entered** 08-21-2012 14:45:44 **by** Hofer, Dave **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 726.3 **Block** 2762

**Section** 3090-Ocean Springs **Asset** LEE ST **AssetNum** 340182B **Maintainer** Stanfill, M O - ETA: 16:10 & Houck, B - ETA: 16:09

**Description** 08/21/2012 14:47:55 **by** David Hofer **Dept** Signals **IT+** .False or partial activation reported  
14:46 Local pd reported the crossing gates are up but the lights are flashing. Notified the AA dispatcher to protect the crossing as a F/P. Notification Sent to -Signal Control Center - Atlanta at 08/21/2012 14:47:55 Asset: LEE ST Status Changed To: Out Of Service PCC Notification Sent 08/21/2012 14:47:55

**Updated** 08/21/2012 14:50:11 **by** Raheem Roberts **Dept** PSCC **IT+**  
**Contacted On** **Agency** Dispatcher **Contact Name** Local PD **Phone** 228.392.0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 08/21/2012 14:50:48 **by** David Hofer **Dept** Signals **IT+** .False or partial activation reported

**Closed** 08/21/2012 15:33:21 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 08/21/2012 15:32:00 Equipment Type: Gate mechanism Action Taken: Adjusted/Cleaned/Repaired/Reset  
Suspected Reason: Equipment failure  
**The Signal Maintainer adjusted the East gate Power Up Contact. Operational Checks were performed. The Crossing is Back In Service with the Dispatcher. LVR**  
Operational Checks Performed Asset: LEE ST Status Changed To: In Service PCC Notification Sent 08/21/2012 15:33:21

**Updated** 08/21/2012 15:35:10 **by** Tanya Josen **Dept** PSCC **IT+**  
**Contacted On** 08-21-2012 15:35:00 **Agency** Local PD **Contact Name** Operator 2793 **Phone** 228.392.0641

---

**Log#** [5711447](#) **Status** Closed **Entered** 07-26-2012 09:50:01 **by** Jackson Jr, Marvin **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 726.3 **Block** 2762

**Section** 3090-Ocean Springs **Asset** LEE ST **AssetNum** 340182B **Maintainer** Brown, K L - ETA: 12:27

**Description** 07/26/2012 09:51:44 **by** Marv Jackson Jr **Dept** Signals **IT+** .False or partial activation reported  
LOCAL PD REPORTED FALSE ACTIVATION(XING ACTIVATED W/O TRAIN) AT LEE ST. Notification Sent to -Signal Control Center - Atlanta at 07/26/2012 09:51:44 Asset: LEE ST Status Changed To: Out Of Service PCC Notification Sent 07/26/2012 09:51:44

**Updated** 07/26/2012 09:53:55 **by** Deborah Anderson **Dept** PSCC **IT+**  
**Contacted On** **Agency** LOCAL PD **Contact Name** DISP #317 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Closed** 07/26/2012 15:22:40 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 07/26/2012 15:17:00 Equipment Type: N/A Action Taken: Issue cleared before cause identified Suspected Reason: Equipment failure



**The Signal Maintainer reported that the Crossing was Clear when he got there. He ran tests and watched a train through the Crossing. Everything was working as intended. The Crossing was placed Back In Service with the Dispatcher. LVR**  
Operational Checks Performed Asset: LEE ST Status Changed To: In Service PCC Notification Sent 07/26/2012 15:22:40

**Updated** 07/26/2012 15:40:30 **by** Sean Reid **Dept** PSCC **IT+**  
**Contacted On** 07-26-2012 15:39:00 **Agency** Biloxi Police Department **Contact Name** Disp # 386 **Phone** 228-392-0641  
@ Esters Blvd

---

**Log#** [5652187](#) **Status** Closed **Entered** 06-17-2012 02:20:37 **by** Tyo, Mark **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 726.3 **Block** 2762

**Section** 3090-Ocean Springs **Asset** LEE ST **AssetNum** 340182B **Maintainer** Broadway, J L - ETA: 05:08

**Description** 06/17/2012 02:28:30 **by** Mark Tyo **Dept** Signals **IT+** .False or partial activation reported  
Police report crossing lights are on but gates are up. DOT # was given. Disp is protecting. Notification Sent to -  
Signal Control Center - Atlanta at 06/17/2012 02:28:30 Asset: LEE ST Status Changed To: Out Of Service PCC  
Notification Sent 06/17/2012 02:28:30

**Updated** 06/17/2012 02:42:07 **by** Myrtie Hackney **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi PD **Contact Name** 1955 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Closed** 06/17/2012 06:21:14 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 06/17/2012 06:20:00 Equipment Type: Gate mechanism Action Taken: Cleaned Suspected  
Reason: N/A 0617 mtr reports cleaning the power up contact on both gate mechs...crossing was coa...check cams  
...op cks ok and crossing back in service with disp... Operational Checks Performed Asset: LEE ST Status Changed  
To: In Service PCC Notification Sent 06/17/2012 06:21:14

**Updated** 06/17/2012 06:26:56 **by** Daniel Johnson **Dept** PSCC **IT+**  
**Contacted On** 06-17-2012 06:26:00 **Agency** Biloxi PD **Contact Name** 1955 **Phone** 228-392-0641

---

**Log#** [5560180](#) **Status** Closed **Entered** 04-13-2012 19:35:43 **by** Mercado, Wito **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 726.3 **Block** 2762

**Section** 3090-Ocean Springs **Asset** LEE ST **AssetNum** 340182B **Maintainer** Stanfill, M O - ETA: 21:29

**Description** 04/13/2012 19:37:43 **by** Jesuito Mercado **Dept** Signals **IT+** .False or partial activation reported  
1936hr Local pd reports crossing gates up, lights on with no trains present... Notification Sent to -Signal Control Center -  
Atlanta at 04/13/2012 19:37:43 Asset: LEE ST Status Changed To: Out Of Service PCC Notification Sent 04/13/2012  
19:37:43

**Updated** 04/13/2012 19:40:40 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported

The AA Dispatcher is protecting the crossing with a **Type 2 False / Partial Activation Message# 41270**. LVR

**Updated** 04/13/2012 19:50:40 **by** Jerome Shepard **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi Pd **Contact Name** Oper 366 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Closed** 04/13/2012 23:00:29 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 04/13/2012 22:56:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended  
Suspected Reason: N/A COA. made all op checks, ret to disp. gate descent is 14sec. Operational Checks Performed  
Asset: LEE ST Status Changed To: In Service PCC Notification Sent 04/13/2012 23:00:29

**Updated** 04/13/2012 23:03:38 **by** Gloria Andino **Dept** PSCC **IT+**  
**Contacted On** 04-13-2012 23:02:00 **Agency** Biloxi Pd **Contact Name** 1955 **Phone** 228-392-0641

---

**Log#** [5511198](#) **Status** Closed **Entered** 03-09-2012 20:22:34 **by** Gaspar, Sean **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 726.3 **Block** 2762



**Section** 3090-Ocean Springs    **Asset** LEE ST    **AssetNum** 340182B    **Maintainer** Houck, B - *ETA*: 21:58

**Description** 03/09/2012 20:32:02    **by** Sean Gaspar    **Dept** Signals    **IT+** .False or partial activation reported  
xing is activated w/ no train. dot provided. disp protecting w/ f/p. disp reports he has a train stopped at that mp at this time.  
Notification Sent to -Signal Control Center - Atlanta at 03/09/2012 20:32:02 Asset: LEE ST Status Changed To: Out Of  
Service PCC Notification Sent 03/09/2012 20:32:02

**Updated** 03/09/2012 20:35:38    **by** Tanya Joson    **Dept** PSCC    **IT+**  
**Contacted On**    **Agency** local police    **Contact Name** jerromy    **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Closed** 03/09/2012 22:29:39    **by** Louis Rosenblatt    **Dept** Signals    **IT+** .False or partial activation reported  
Incident Resolved: 03/09/2012 22:29:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended  
Suspected Reason: Other department

**Mntr reports the crossing was not in trouble when he got there. He dropped the gates three times and checked for  
grounds. The lights were strong. Nothing was found to be wrong. The Dispatcher said a train was stopped on the  
crossing at the time of the report. The Crossing is Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: LEE ST Status Changed To: In Service PCC Notification Sent 03/09/2012 22:29:39

**Updated** 03/09/2012 22:32:57    **by** Gloria Andino    **Dept** PSCC    **IT+**  
**Contacted On** 03-09-2012 22:32:00 **Agency** Local Police    **Contact Name** Jennifer    **Phone** 228-392-0641

Page Execution Time: 005.61 seconds

**Nixon Street**

**DOT Crossing #: 340183H**

**RR Milepost #: 726.50**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 1

Status All AssetType All RootAssetType All Department Signals AssetNum 340183H

---

**Log#** [6909924](#)   **Status** Closed   **Entered** 12-04-2014 22:35:17   **by** Rosenblatt, Louis   **Type** Train-vehicle collision  
**Supv** Merritt, D   **Reg** SO   **Div** AT   **Sub** NM   **IRI** 0   **Milepost** 000 726.5   **Block** 2762  
**Section** 3090-7M16   **Asset** NIXON ST   **AssetNum** 340183H   **Maintainer** Stanfill, M O - ETA: 23:44  
**Description** 12/04/2014 22:35:17   **by** Louis Rosenblatt   **Dept** Signals   **IT+** Unknown  
**Updated** 12/04/2014 22:40:28   **by** Louis Rosenblatt   **Dept** Signals   **IT+** Train-vehicle collision

1. **Train involved:** Q18004
2. **Direction of travel:** North
3. **Estimated speed:** Unknown
4. **Subdivision:** NM - NO&M
5. **Timetable speed:** 45 MPH
6. **Number of occupants/injuries:** Unknown
7. **Number of fatalities:** Unknown
8. **Milepost:** 000 726.610   **DOT:** 340185W   **Name:** Main Street
9. **Crossing protection (gates, flashers, bells, cantilevers, etc.):** Flashers/Bell/Gates
10. **Crossing controller equipment (PMD3, GCP 4000, etc.):** GCP-3000
11. **Damage to crossing, if any:** Unknown
12. **Date last inspected (can be pulled from Raildocs):** 12/02/2014

The AA Dispatcher has not gotten a clear report as to which crossing the collision occurred at.

**Updated** 12/04/2014 22:40:29   **by** Louis Rosenblatt   **Dept** Signals   **IT+** Train-vehicle collision  
Notification has been sent to the following: George James Jr Danny McKenzie Jody Cox C Manager

**Updated** 12/04/2014 22:44:26   **by** Louis Rosenblatt   **Dept** Signals   **IT+** Train-vehicle collision  
Status changed to Dispatched for Michael Stanfill ETA of: 23:44

**Updated** 12/04/2014 22:46:40   **by** Louis Rosenblatt   **Dept** Signals   **IT+** Train-vehicle collision  
New Asset Added: 340183H - NIXON ST

**Updated** 12/04/2014 22:46:47   **by** Louis Rosenblatt   **Dept** Signals   **IT+** Train-vehicle collision  
Primary Asset changed from: 340185W - MAIN ST To: 340183H - NIXON ST

**Updated** 12/04/2014 22:56:09   **by** Jerry Rockhill   **Dept** Signals   **IT+** Train-vehicle collision  
2253 AA DISP REPORTS CONFIRM CROSSING ACCIDENT WAS AT NIXON ST...NOT MAIN ST...VEHICLE OCCUPANT ONLY MINOR INJURIES....MTR STILL ENROUTE TO CONFIRM NO OTHER DAMAGE TO SIGNAL CROSSINGS....

**Updated** 12/04/2014 23:45:00   **by** TCIS AUTOMATION   **Dept** Signals   **IT+** Train-vehicle collision  
ETA time reached Status changed to Active

**Updated** 12/05/2014 00:21:21   **by** Jerry Rockhill   **Dept** Signals   **IT+** Train-vehicle collision  
0020 informed mtr of current information on crossing change and nb train has moved out of area and now sb trains are lined thru area....

**Closed** 12/05/2014 00:27:10   **by** Jerry Rockhill   **Dept** Signals   **IT+** Train-vehicle collision  
Incident Resolved: 12/05/2014 00:27:00 Equipment Type: N/A Action Taken: NTF - UTD 0025 MTR REPORTS WATCHED TRAIN THRU AREA AND NO ISSUES FOUND...VEHICLE REMOVED FROM TRACKS AND TRAINS UNDER SIGNALS....OP CKS OK AND NO DAMAGE FOUND... Operational Checks Performed

**Main Street**

**DOT Crossing #: 340185W**

**RR Milepost #: 726.61**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 28

Status All AssetType All RootAssetType All Department Signals AssetNum 340185W

---

**Log#** [8029709](#) **Status** Closed **Entered** 03-07-2017 15:26:44 **by** Kondy, Rick **Type** Train-vehicle collision (Signals)

**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.6 **Block** 2762/2763

**Section** 3090-7M16 **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Stanfill, M O - ETA: 15:44

**Description** 03/07/2017 15:26:44 **by** Richard Kondy **Dept** Signals **IT+** Unknown

**Updated** 03/07/2017 15:27:44 **by** Richard Kondy **Dept** Signals **IT+** Train-vehicle collision (Signals)

Incident Type: TRK Dispatch incident Number: 94977 Incident Date: 07-MAR-17 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000, 0727.0000 Right Mile Post: 000, 0730.2851 Asset: 2763 003, Asset Name: MAIN PTC Flag: N Incident Description: Q60607 HIT A PASSENGER BUS AT MP 000726.6 MAIN ST. BUS HAD PASSENGERS. disp protecting crossing with activation failure # 12212 . Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 03/07/2017 15:27:44

**Updated** 03/07/2017 15:31:50 **by** Richard Kondy **Dept** Signals **IT+** Train-vehicle collision (Signals)  
noc mgr notified .

**Updated** 03/07/2017 15:43:05 **by** Richard Kondy **Dept** Signals **IT+** Train-vehicle collision (Signals)  
Status changed to Dispatched for Michael Stanfill ETA of: 15:44

**Updated** 03/07/2017 15:45:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Train-vehicle collision (Signals)  
ETA time reached Status changed to Active

**Updated** 03/07/2017 21:54:57 **by** John Williams **Dept** Signals **IT+** Train-vehicle collision (Signals)  
Waiting on update from maintainer

**Updated** 03/08/2017 00:00:40 **by** Zacchaeus Wood **Dept** Signals **IT+** Train-vehicle collision (Signals)  
Left msg for mtr to update.

**Updated** 03/08/2017 01:36:12 **by** Trent Burnham **Dept** -C and S **IT+** Train-vehicle collision (Signals)

**Updated** 03/08/2017 06:16:34 **by** Trent Burnham **Dept** -C and S **IT+** Train-vehicle collision (Signals)  
Gate Mech and foundation to be replaced on the east side. ETR 12:00 3/8.

**Closed** 03/10/2017 07:57:56 **by** Bruce McVey **Dept** Signals **IT+** Train-vehicle collision (Signals)  
Incident Resolved: 03/10/2017 07:56:00 Equipment Type: Cantilever/Mast Action Taken: Repaired/Replaced cantilever/mast

**Employee:** Sig Mgr James

- replaced gate mech with doll arm and kight, foundation...

Did ALL OP Checks , Back/released to AA disp.

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 03/10/2017 07:57:56

---

**Log#** [7949382](#) **Status** Closed **Entered** 01-05-2017 11:04:10 **by** McVey, Bruce **Type** Train-vehicle collision (Signals)

**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.6 **Block** 2762/2763

**Section** 3090-7M16 **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Stanfill, M O - ETA: 11:35

**Description** 01/05/2017 11:04:10 **by** Bruce McVey **Dept** Signals **IT+** Unknown

**Updated** 01/05/2017 11:04:33      **by** Bruce McVey      **Dept** Signals      **IT+** Train-vehicle collision (Signals)

**COPIED FROM DIRT Notification**

Incident Type: TRK Dispatch incident Number: 78802 Incident Date: 05-JAN-17 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000, 0723.1305 Right Mile Post: 000, 0727.0000 Asset: 2762 001, Asset Name: MAIN PTC Flag: N **Incident**

**Description: TRAIN HIT VEHICLE AT MAIN ST MP 000726.1. GATES DAMAGED ON WEST SIDE AND LOCAL POWER COMPANY NEEDED ON SITE**

Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 01/05/2017 11:04:33

**Updated** 01/05/2017 11:05:34      **by** Bruce McVey      **Dept** Signals      **IT+** Train-vehicle collision (Signals)  
Status changed to Dispatched for Michael Stanfill ETA of: 11:35

**Updated** 01/05/2017 11:06:09      **by** Bruce McVey      **Dept** Signals      **IT+** Train-vehicle collision (Signals)

The AA is protecting the Crossing with a **Type 1 Activation Failure Message# 35609**.

**Updated** 01/05/2017 11:06:42      **by** Bruce McVey      **Dept** Signals      **IT+** Train-vehicle collision (Signals)  
South bound Q619-03

**Updated** 01/05/2017 11:14:45      **by** Waltina Edwards      **Dept** PSCC      **IT+**  
**Contacted On** 01-05-2017 11:11:00 **Agency** . Police Department      **Contact Name** 2922 **Phone** 228-392-0641

**Updated** 01/05/2017 11:40:00      **by** TCIS AUTOMATION      **Dept** Signals      **IT+** Train-vehicle collision (Signals)  
ETA time reached Status changed to Active

**Updated** 01/05/2017 13:14:05      **by** Bruce McVey      **Dept** Signals      **IT+** Train-vehicle collision (Signals)  
South bound Q619-03 still on site

**Updated** 01/05/2017 14:12:35      **by** Bruce McVey      **Dept** Signals      **IT+** Train-vehicle collision (Signals)  
disp reports that vehicle was not occupied at time of incident.

**Updated** 01/05/2017 14:39:08      **by** Bruce McVey      **Dept** Signals      **IT+** Train-vehicle collision (Signals)  
WAITING ON PARTS , ARRIVE IN AM

**Updated** 01/05/2017 14:42:42      **by** Bruce McVey      **Dept** Signals      **IT+** Train-vehicle collision (Signals)  
applied Jumper Log # 7949670

**Updated** 01/05/2017 14:49:19      **by** Michael Stanfill      **Dept** Signals      **IT+** Train-vehicle collision (Signals)  
Q619-03 hit Pepsi truck that got stuck on crossing. Truck was pushed into west gate mech. Gate mech and all associated parts are destroyed. Parts have been ordered and should arrive 1-6-17 in the am. Maintainer applied jumper from gp1 to gp to stop lights from flashing continuously with jumper log# 7949670. East gate and lights will work as designed. Maintainer will leave activation failure message# 35609 on crossing till repairs are completed. Maintainer attached Hawk recorder logs to this file. Field report shows 33 seconds from crossing activation to Island drop.

**Updated** 01/05/2017 14:52:16      **by** Don Skidmore Jr      **Dept** -C and S      **IT+** Train-vehicle collision (Signals)  
WAITING ON PARTS , ARRIVE IN AM

**Updated** 01/06/2017 19:12:18      **by** Michael Stanfill      **Dept** Signals      **IT+** Train-vehicle collision (Signals)  
Incident Resolved: 01/06/2017 19:11:00 Equipment Type: Gate Mechanism Action Taken: Replaced component(s) Replaced west gate mast, mech, foundation and all lights. Tested with a 360 day test with no exceptions. Gate decent time is 14 seconds. Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 01/06/2017 19:12:18

**Closed** 01/06/2017 19:16:12      **by** Sean Gaspar      **Dept** Signals      **IT+** Train-vehicle collision (Signals)  
Incident Resolved: 01/06/2017 19:11:00 Equipment Type: Gate Mechanism Action Taken: Replaced component(s) . Operational Checks Performed

**Updated** 01/06/2017 20:36:53      **by** Shari Baron      **Dept** PSCC      **IT+**  
**Contacted On** 01-06-2017 20:36:00 **Agency** Biloxi Police Department **Contact Name** Eric **Phone** 228-392-0641

**Log#** [7945208](#) **Status** Closed **Entered** 01-02-2017 17:05:07 **by** Knotts, Patrick **Type** Vehicle on Track

**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.6 **Block** 2762/2763

**Section** 3090-7M16 **Asset** MAIN ST **AssetNum** 340185W **Maintainer** McCardle, B - *ETA*: 19:36

**Description** 01/02/2017 17:05:07 **by** Patrick Knotts **Dept** Signals **IT+** Unknown

**Updated** 01/02/2017 17:05:40 **by** Patrick Knotts **Dept** Signals **IT+** Vehicle on Track  
MAIN ST MP 000726.6. PSCC REPORTED SEMI TRUCK STUCK ON TRACKS. PROTECTED WITH MSG  
32182-SIGNALS AND 32183-MOW. Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent  
01/02/2017 17:05:40

**Updated** 01/02/2017 17:24:07 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** 01-02-2017 17:24:00 **Agency** NA **Contact Name** NA **Phone** NA  
PSCC Incident Report - #7945200

**Updated** 01/02/2017 17:36:10 **by** Patrick Knotts **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Brent McCardle ETA of: 19:36

**Updated** 01/02/2017 19:40:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Closed** 01/02/2017 20:31:31 **by** Carlos Betancourt **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 01/02/2017 20:30:00 Equipment Type: N/A Action Taken: NTF - UTD No Signal equipment  
damage, all op checks and wai. Operational Checks Performed Asset: MAIN ST Status Changed To: In Service  
PCC Notification Sent 01/02/2017 20:31:31

**Updated** 01/02/2017 20:49:12 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** 01-02-2017 20:48:00 **Agency** Biloxi Police Department **Contact Name** Eric **Phone** 228-392-0641

---

**Log#** [7853208](#) **Status** Closed **Entered** 10-21-2016 14:18:13 **by** Tyo, Mark **Type** Vehicle on Track

**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 726.6 **Block** 2762/2763

**Section** 3090-7M16 **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Stanfill, M O - *ETA*: 15:06

**Description** 10/21/2016 14:18:13 **by** Mark Tyo **Dept** Signals **IT+** Unknown

**Updated** 10/21/2016 14:18:56 **by** Mark Tyo **Dept** Signals **IT+** Vehicle on Track  
Incident Type: TRK Dispatch incident Number: 59747 Incident Date: 21-OCT-16 Pri.Train ID: SubDivision Code: NM Left  
Mile Post: 000, 0723.1305 Right Mile Post: 000, 0727.0000 Asset: 2762 001, Asset Name: MAIN PTC Flag: N Incident  
Description: SEMI STUCK ON TRACK AT MAIN ST 000726.6 Asset: MAIN ST Status Changed To: Out Of Service PCC  
Notification Sent 10/21/2016 14:18:56

**Updated** 10/21/2016 14:18:57 **by** Mark Tyo **Dept** Signals **IT+** Vehicle on Track  
An email notification for (IRI) asset MAIN ST (1) has been sent to the following:  
George James Jr

**Updated** 10/21/2016 14:21:23 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Michael Stanfill ETA of: 15:06

**Updated** 10/21/2016 15:10:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Updated** 10/21/2016 15:36:05 **by** Jerome Shepard **Dept** PSCC **IT+**  
**Contacted On** 10-21-2016 15:36:00 **Agency** Biloxi Police Department **Contact Name** Operator Angie **Phone** 228-392-0641  
PSCC Incident 7853190

**Closed** 10/21/2016 15:48:36 **by** Jake Carter **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 10/21/2016 15:48:00 Equipment Type: N/A Action Taken: Track Occupied no signal damage,gft 13  
sec;returned to disp Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent  
10/21/2016 15:48:36

**Updated** 10/21/2016 15:53:45 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** 10-21-2016 15:53:00 **Agency** Biloxi Police Department **Contact Name** 911 **Phone** 228-392-0641  
PSCC Incident 7853190

---

**Log#** [7847406](#) **Status** Closed **Entered** 10-17-2016 18:23:52 **by** Oglesby, Brad **Type** Vehicle on Track

**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.6 **Block** 2762/2763

**Section** 3090-7M16 **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Stanfill, M O - *ETA*: 20:57

**Description** 10/17/2016 18:23:52 **by** Brad Oglesby **Dept** Signals **IT+** Unknown

**Updated** 10/17/2016 18:25:33 **by** Brad Oglesby **Dept** Signals **IT+** Vehicle on Track

Last Update 10-17-2016 18:19 By DRT Type General Business Impact 3 Priority 3 Incident Type: TRK Dispatch  
incident Number: 58858 Incident Date: 17-OCT-16 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000,  
0723.1305 Right Mile Post: 000, 0727.0000 Asset: 2762 001, Asset Name: MAIN PTC Flag: N Incident  
Description: TRUCK STUCK ON THE TRACKS AT 000726.6 MAIN STREET, NEED MAINTAINER AND TRACK  
INSPECTOR 1824 ESS CONFIRMED THE AA DISPATCHER IS PROVIDING PROTECTION ON THE  
CROSSING AS PER ACTIVATION FAILURE STANDARD. Asset: MAIN ST Status Changed To: Out Of Service  
PCC Notification Sent 10/17/2016 18:25:33

**Updated** 10/17/2016 18:26:55 **by** Brad Oglesby **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Michael Stanfill ETA of: 19:56

**Updated** 10/17/2016 18:53:56 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** 10-17-2016 18:53:00 **Agency** NA **Contact Name** NA **Phone** NA  
PSCC Incident Report - #7847395 Biloxi Police Department 228-392-0641

**Updated** 10/17/2016 20:00:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Updated** 10/17/2016 21:55:52 **by** Michael Stanfill **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 10/17/2016 21:55:00 Equipment Type: Gate Action Taken: Replaced shear pin/rehung  
original gate Rehang east gate. No other damage. Operational Checks Performed Asset: MAIN ST Status  
Changed To: In Service PCC Notification Sent 10/17/2016 21:55:52

**Closed** 10/17/2016 21:56:24 **by** Brad Oglesby **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 10/17/2016 21:55:00 Equipment Type: Gate Action Taken: Replaced shear pin/rehung  
original gate . Operational Checks Performed

**Updated** 10/17/2016 21:56:43 **by** Kiwana Tompkins **Dept** PSCC **IT+**  
**Contacted On** 10-17-2016 21:56:00 **Agency** N/A **Contact Name** N/A **Phone** N/A

---

**Log#** [7810240](#) **Status** Closed **Entered** 09-21-2016 10:11:23 **by** McVey, Bruce **Type** Train-vehicle collision (Signals)

**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.6 **Block** 2762/2763

**Section** 3090-7M16 **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Stanfill, M O - *ETA*: 10:58

**Description** 09/21/2016 10:11:23 **by** Bruce McVey **Dept** Signals **IT+** Unknown

**Updated** 09/21/2016 10:11:51 **by** Bruce McVey **Dept** Signals **IT+** Train-vehicle collision (Signals)

**COPIED FROM DIRT Notification**

Incident Type: TRK Dispatch incident Number: 52348 Incident Date: 21-SEP-16 Pri.Train ID: SubDivision Code: NM Left  
Mile Post: 000, 0723.1305 Right Mile Post: 000, 0727.0000 Asset: 2762 001, Asset Name: MAIN PTC Flag: N **Incident**

**Description: Q61421 HIT CAR AT MP 000726.6, MAIN ST**

Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 09/21/2016 10:11:51

**Updated** 09/21/2016 10:12:27 **by** Bruce McVey **Dept** Signals **IT+** Train-vehicle collision (Signals)



The AA is protecting the Crossing with a **Type 1 Activation Failure Message# 35759.**

**Updated** 09/21/2016 10:13:40 **by** Bruce McVey **Dept** Signals **IT+** Train-vehicle collision (Signals)  
Status changed to Dispatched for Michael Stanfill ETA of: 10:58

**Updated** 09/21/2016 10:53:31 **by** Bruce McVey **Dept** Signals **IT+** Train-vehicle collision (Signals)  
mtr reports that incident happened at 340187K - DELAUNEY ST xing (cross buck xing....)

**Updated** 09/21/2016 11:34:06 **by** Michael Stanfill **Dept** Signals **IT+** Train-vehicle collision (Signals)  
Incident Resolved: 09/21/2016 11:30:00 Equipment Type: N/A Action Taken: NTF - UTD Collision occurred 2 crossings south of Main st, at 340187K - DELAUNEY ST. which is a cross-buck only crossing. Maintainer checked Main St. with no exceptions to operation of crossing. Remove crossing protection with message number 35850. Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 09/21/2016 11:34:06

**Updated** 09/21/2016 11:42:23 **by** Waltina Edwards **Dept** PSCC **IT+**  
**Contacted On** 09-21-2016 11:40:00 **Agency** [Police Department] **Contact Name** 352 **Phone** 228-392-0641  
Esters Boulevard

**Closed** 09/21/2016 11:53:48 **by** Bruce McVey **Dept** Signals **IT+** Train-vehicle collision (Signals)  
Incident Resolved: 09/21/2016 11:30:00 Equipment Type: N/A Action Taken: NTF - UTD  
**Incident Resolved. Operational Checks Performed**

---

**Log#** [7687076](#) **Status** Closed **Entered** 06-21-2016 13:32:04 **by** McVey, Bruce **Type** Vehicle on Track

**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.6 **Block** 2762/2763

**Section** 3090-7M16 **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Stanfill, M O - ETA: 14:05

**Description** 06/21/2016 13:32:04 **by** Bruce McVey **Dept** Signals **IT+** Unknown

**Updated** 06/21/2016 13:32:26 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track

**COPIED FROM DIRT Notification**

Incident Type: TRK Dispatch incident Number: 28769 Incident Date: 21-JUN-16 Pri.Train ID: SubDivision Code: NM  
Left Mile Post: 000, 0727.0000 Right Mile Post: 000, 0730.2851 Asset: 2763 003, Asset Name: MAIN PTC Flag: N

**Incident Description: ACTIVATION FAILURE TRACTOR TRAILER STUCK ON TRACKS 000726.6 MAIN STREET**

Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 06/21/2016 13:32:26

**Updated** 06/21/2016 13:32:55 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track

The AA is protecting the Crossing with a **Type 1 Activation Failure Message# 27090.**

**Updated** 06/21/2016 13:35:39 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Michael Stanfill ETA of: 14:05

**Updated** 06/21/2016 13:47:24 **by** Jackie McGuirt **Dept** PSCC **IT+**  
**Contacted On** 06-21-2016 13:47:00 **Agency** Biloxi Police Department **Contact Name** Oper: 308 **Phone** 228-392-0641  
PSCC Incident Report - Edit #7687054

**Updated** 06/21/2016 14:10:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Closed** 06/21/2016 14:27:45 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 06/21/2016 14:27:00 Equipment Type: N/A Action Taken: NTF - UTD

**Employee:** M. Stanfill

- Vehicle removed, No signal damage.

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 06/21/2016 14:27:45

**Updated** 06/21/2016 14:56:28 **by** Roland Knagge **Dept** PSCC **IT+**  
**Contacted On** 06-21-2016 14:54:00 **Agency** Biloxi Police Department **Contact Name** 3501 **Phone** 228-392-0641

---

**Log#** [7633152](#) **Status** Closed **Entered** 05-10-2016 13:58:37 **by** McVey, Bruce **Type** Vehicle on Track  
**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0.5 **Milepost** 000 726.6 **Block** 2762/2763  
**Section** 3090-7M16 **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Stanfill, M O - *ETA*: 15:02  
**Description** 05/10/2016 13:58:37 **by** Bruce McVey **Dept** Signals **IT+** Unknown  
**Updated** 05/10/2016 13:59:07 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track

**COPIED FROM DIRT Notification**

Incident Type: TRK Dispatch incident Number: 19563 Incident Date: 10-MAY-16 Pri.Train ID: SubDivision Code:  
NM Left Mile Post: 000, 0723.1305 Right Mile Post: 000, 0727.0000 Asset: 2762 001, Asset Name: MAIN PTC  
Flag: N **Incident Description: VEHIVLE STUCK ON TRACKS AT MAIN ST MP 000726.6**  
Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 05/10/2016 13:59:07

**Updated** 05/10/2016 13:59:09 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track  
An email notification for (IRI) asset MAIN ST (3) has been sent to the following:  
George James Jr  
Danny McKenzie

**Updated** 05/10/2016 13:59:39 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track

The AA is protecting the Crossing with a **Type 1 Activation Failure Message# 34645**.

**Updated** 05/10/2016 14:03:00 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Michael Stanfill *ETA* of: 15:02

**Updated** 05/10/2016 14:19:35 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** 05-10-2016 14:19:00 **Agency** NA **Contact Name** NA **Phone** NA  
PSCC Incident Report - Edit #7633121 Biloxi Police Department 228-392-0641

**Updated** 05/10/2016 15:05:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
*ETA* time reached Status changed to Active

**Closed** 05/10/2016 16:15:15 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 05/10/2016 16:14:00 Equipment Type: N/A Action Taken: NTF - UTD

**The Signal Maintainer reported that there was no signal damage. Gate Descent time is 13 Seconds.**  
**Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 05/10/2016  
16:15:15

**Updated** 05/10/2016 16:25:42 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** 05-10-2016 16:24:00 **Agency** Biloxi Police Department **Contact Name** 3501 **Phone** 228-392-0641

---

**Log#** [7622945](#) **Status** Closed **Entered** 05-02-2016 15:36:22 **by** Rosenblatt, Louis **Type** Vehicle on Track  
**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0.25 **Milepost** 000 726.6 **Block** 2762/2763  
**Section** 3090-7M16 **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Stanfill, M O - *ETA*: 16:01  
**Description** 05/02/2016 15:36:22 **by** Louis Rosenblatt **Dept** Signals **IT+** Unknown  
**Updated** 05/02/2016 15:38:25 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track

The AA Dispatcher received a report that a Tanker Truck is stuck on the tracks at Main Street, MP 000 726.61,

DOT# 340185W, NM Sub.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 20431**. LVR  
Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 05/02/2016 15:38:25

**Updated** 05/02/2016 15:38:27 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track  
An email notification for (IRI) asset MAIN ST (2) has been sent to the following:  
George James Jr

**Updated** 05/02/2016 15:41:27 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Michael Stanfill ETA of: 16:01

**Updated** 05/02/2016 16:05:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Updated** 05/02/2016 16:07:56 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** 05-02-2016 16:06:00 **Agency** Biloxi Police Department **Contact Name** 911 **Phone** 228-392-0641  
@ Easter Blvd.

**Closed** 05/02/2016 16:19:42 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 05/02/2016 16:19:00 Equipment Type: N/A Action Taken: NTF - UTD

**The Signal Maintainer reported that there was no signal damage. Operational Checks were performed.  
The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent  
05/02/2016 16:19:42

**Updated** 05/02/2016 16:29:57 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** 05-02-2016 16:28:00 **Agency** Biloxi Police Department **Contact Name** Eric **Phone** 228-392-0641  
@ Easter Blvd.

---

**Log#** [7611665](#) **Status** Closed **Entered** 04-23-2016 22:20:27 **by** Kite, Matt **Type** Vehicle on Track  
**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 726.6 **Block** 2762/2763  
**Section** 3090-7M16 **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Broadway, J L - *ETA: 00:43*  
**Description** 04/23/2016 22:20:27 **by** Matthew Kite **Dept** Signals **IT+** Unknown  
**Updated** 04/23/2016 22:21:21 **by** Matthew Kite **Dept** Signals **IT+** Vehicle on Track

Incident Type: TRK Dispatch incident Number: 16104 Incident Date: 23-APR-16 Pri.Train ID: SubDivision Code: NM  
Left Mile Post: 000, 0727.0000 Right Mile Post: 000, 0730.2851 Asset: 2763 003, Asset Name: MAIN PTC Flag: Y  
Incident Description: SEMI STUCK ON MAIN ST XING - 000 726.6 - NEED TRACK INSPECTION Copied frm DIRT.  
Disp prot with A/F #45854.  
Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 04/23/2016 22:21:21

**Updated** 04/23/2016 22:21:22 **by** Matthew Kite **Dept** Signals **IT+** Vehicle on Track  
An email notification for (IRI) asset MAIN ST (1) has been sent to the following:  
George James Jr

**Updated** 04/23/2016 22:24:19 **by** Kiwana Tompkins **Dept** PSCC **IT+**  
**Contacted On** 04-23-2016 22:23:00 **Agency** Biloxi Police Department **Contact Name** Brady **Phone** 228\*392\*0641  
PSCC #7611589

**Updated** 04/23/2016 23:13:07 **by** Jerry Rockhill **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Joshua Broadway ETA of: 00:43

**Updated** 04/24/2016 00:05:40 **by** Jerry Rockhill **Dept** Signals **IT+** Vehicle on Track  
Last Update 04-23-2016 23:33 By DRT Type General Business Impact 3 Priority 3 Incident Type: TRK Dispatch  
incident Number: 16119 Incident Date: 23-APR-16 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000,

0723.1305 Right Mile Post: 000, 0727.0000 Asset: 2762 001, Asset Name: MAIN PTC Flag: N Incident Description: SEMI STUCK ON TRACK, NEED SIGNALS AND TRACK INSPECTOR ....second notification sent by aa disp is a duplicate notification 6236521 is a duplicate .... confirmed by aa disp 3rd shift...

**Updated** 04/24/2016 00:45:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Updated** 04/24/2016 02:06:08 **by** Joshua Broadway **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 04/24/2016 02:05:00 Equipment Type: Track Action Taken: Removed debris Vehicle removed.  
no signal damage. 12 seconds gate descent time. Returned to service with anullment number 45917. Operational  
Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 04/24/2016 02:06:08

**Closed** 04/24/2016 02:07:29 **by** Jerry Rockhill **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 04/24/2016 02:05:00 Equipment Type: Track Action Taken: Removed debris . Operational  
Checks Performed

**Updated** 04/24/2016 02:09:13 **by** Kiwana Tompkins **Dept** PSCC **IT+**  
**Contacted On** 04-24-2016 02:09:00 **Agency** Biloxi Police Department **Contact Name** 1955 **Phone** 228\*392\*0641

---

**Log#** [7604659](#) **Status** Closed **Entered** 04-18-2016 16:32:31 **by** Rosenblatt, Louis **Type** Vehicle on Track

**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.6 **Block** 2762/2763

**Section** 3090-7M16 **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Mannion, R - ETA: 18:20

**Description** 04/18/2016 16:32:31 **by** Louis Rosenblatt **Dept** Signals **IT+** Unknown

**Updated** 04/18/2016 16:33:11 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track

The AA Dispatcher received a report from the PSCC that a Semi Truck is stuck on the track at Main Street, MP 000 726.61, DOT# 340185W, NM Sub.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 36059**. LVR  
Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 04/18/2016 16:33:11

**Updated** 04/18/2016 17:05:59 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Roger Mannion ETA of: 18:20

**Updated** 04/18/2016 18:25:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Updated** 04/18/2016 20:09:58 **by** Roger Mannion **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 04/18/2016 20:09:00 Equipment Type: N/A Action Taken: Track Occupied Truck removed, no  
signal damage Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification  
Sent 04/18/2016 20:09:58

**Closed** 04/18/2016 20:11:43 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 04/18/2016 20:09:00 Equipment Type: N/A Action Taken: Track Occupied Operational  
Checks Performed

---

**Log#** [7556283](#) **Status** Closed **Entered** 03-12-2016 15:55:50 **by** Kite, Matt **Type** Vehicle on Track

**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.6 **Block** 2762/2763

**Section** 3090-7M16 **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Broadway, J L - ETA: 17:59

**Description** 03/12/2016 15:55:50 **by** Matthew Kite **Dept** Signals **IT+** Unknown

**Updated** 03/12/2016 15:56:40 **by** Matthew Kite **Dept** Signals **IT+** Vehicle on Track

Incident Type: TRK Dispatch incident Number: 06489 Incident Date: 12-MAR-16 Pri.Train ID: SubDivision Code:  
NM Left Mile Post: 000, 0726.0000 Right Mile Post: 000, 0730.3000 Asset: 2763 003, Asset Name: MAIN PTC

Flag: N Incident Description: CAR STUCK ON THE TRACKS AT 000726.6 MAIN STREET, NEED MAINTAINER AND TRACK INSPECTOR Copied frm DIRT. Disp prot with A/F #15725.

Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 03/12/2016 15:56:40

**Updated** 03/12/2016 16:29:02 **by** Matthew Kite **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Joshua Broadway ETA of: 17:59

**Updated** 03/12/2016 18:00:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Closed** 03/12/2016 18:13:51 **by** Matthew Kite **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 03/12/2016 18:13:00 Equipment Type: N/A Action Taken: NTF - UTD  
Mntr reports bus removed frm trks. No damage to sig equip. Performed op checks, no exceptions noted to sig equip. Turned crossing back over to disp.  
Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 03/12/2016 18:13:51

---

**Log#** [7457210](#) **Status** Closed **Entered** 12-29-2015 14:12:16 **by** Williams, Joseph **Type** Vehicle on Track

**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 726.6 **Block** 2762/2763

**Section** 3090-7M16 **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Stanfill, M O - ETA: 15:18

**Description** 12/29/2015 14:12:16 **by** Joseph Williams **Dept** Signals **IT+** Unknown

**Updated** 12/29/2015 14:14:39 **by** Joseph Williams **Dept** Signals **IT+** Vehicle on Track  
1413:Hr outside party reported that there is a semi truck stuck on the tracks. 1413:Hr dispatcher was already protecting the crossing with an activation failure message. Notification Sent to -Signal Control Center - Atlanta at 12/29/2015 14:14:39  
Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 12/29/2015 14:14:39

**Updated** 12/29/2015 14:14:40 **by** Joseph Williams **Dept** Signals **IT+** Vehicle on Track  
An email notification for (IRI) asset MAIN ST (.125) has been sent to the following:  
George James Jr

**Updated** 12/29/2015 14:18:44 **by** Matthew Kite **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Michael Stanfill ETA of: 15:18

**Updated** 12/29/2015 14:25:56 **by** Deborah Anderson **Dept** PSCC **IT+**  
**Contacted On** 12-29-2015 14:23:00 **Agency** Biloxi Police Department **Contact Name** 376 **Phone** 228-392-0641  
TCIS # 7457207

**Updated** 12/29/2015 15:20:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Closed** 12/29/2015 16:11:02 **by** Jake Carter **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 12/29/2015 16:10:00 Equipment Type: N/A Action Taken: NTF - UTD No damage to sig equipment;returned to disp Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC  
Notification Sent 12/29/2015 16:11:02

**Updated** 12/29/2015 16:32:27 **by** Waltina Edwards **Dept** PSCC **IT+**  
**Contacted On** 12-29-2015 16:31:00 **Agency** Police Department **Contact Name** 2901 **Phone** Phone# 228-392-0641

---

**Log#** [7421701](#) **Status** Closed **Entered** 11-30-2015 06:06:40 **by** Rockhill, Jerry **Type** Vehicle on Track

**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.6 **Block** 2762/2763

**Section** 3090-7M16 **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Stanfill, M O - ETA: 07:40

**Description** 11/30/2015 06:06:40 **by** Jerry Rockhill **Dept** Signals **IT+** Unknown

**Updated** 11/30/2015 06:08:40 **by** Jerry Rockhill **Dept** Signals **IT+** Vehicle on Track  
0607 Last Update 11-30-2015 05:59 By DRT Type General Business Impact 3 Priority 3 Incident Type: TRK



Dispatch incident Number: 51756 Incident Date: 30-NOV-15 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000, 0726.0000 Right Mile Post: 000, 0730.3000 Asset: 2763 003, Asset Name: MAIN PTC Flag: N Incident Description: TRUCK STUCK ON TRACK AT MAIN ST. 726.6 .....af 31096 Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 11/30/2015 06:08:40

**Updated** 11/30/2015 06:10:11 **by** Jerry Rockhill **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Michael Stanfill ETA of: 07:40

**Updated** 11/30/2015 07:45:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Updated** 11/30/2015 09:48:48 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track

**Update** - The ESS texted a message requesting an update on the Signal Maintainers cell phone.

**Closed** 11/30/2015 09:51:09 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 11/30/2015 08:50:00 Equipment Type: N/A Action Taken: NTF - UTD

**Employee:** M. Stanfill

- Vehicle removed, No signal damage.

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 11/30/2015 09:51:09

---

**Log#** [7188341](#) **Status** Closed **Entered** 06-15-2015 15:12:04 **by** Rosenblatt, Louis **Type** Vehicle on Track

**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 726.6 **Block** 2762

**Section** 3090-7M16 **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Stanfill, M O - *ETA: 16:49*

**Description** 06/15/2015 15:12:04 **by** Louis Rosenblatt **Dept** Signals **IT+** Unknown

**Updated** 06/15/2015 15:12:41 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track

The AA Dispatcher reported that Main Street, MP 000 726.61, DOT# 340185W, NM Sub, has a tractor trailer stuck on the tracks.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 24259**. LVR  
Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 06/15/2015 15:12:41

**Updated** 06/15/2015 15:34:25 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Michael Stanfill ETA of: 16:49

**Updated** 06/15/2015 16:50:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Closed** 06/15/2015 17:32:50 **by** Robert Gibson **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 06/15/2015 17:22:00 Equipment Type: N/A Action Taken: NTF - UTD MTR REPORTED  
COA, NO DAMAGE TO THE XING, EZ/EX 100/85 Operational Checks Performed Asset: MAIN ST Status  
Changed To: In Service PCC Notification Sent 06/15/2015 17:32:50

---

**Log#** [7158402](#) **Status** Closed **Entered** 05-26-2015 11:27:21 **by** McVey, Bruce **Type** Vehicle on Track

**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.6 **Block** 2762

**Section** 3090-7M16 **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Stanfill, M O - *ETA: 13:07*

**Description** 05/26/2015 11:27:21 **by** Bruce McVey **Dept** Signals **IT+** Unknown

**Updated** 05/26/2015 11:27:44 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track

The AA Dispatcher reported that Main Street, MP 000 726.61, DOT# 340185W, NM Sub, has a truck stuck on the track.

The Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 26906**. BLM  
Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 05/26/2015 11:27:44

**Updated** 05/26/2015 11:28:42 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Michael Stanfill ETA of: 13:07

**Updated** 05/26/2015 11:44:06 **by** Waltina Edwards **Dept** PSCC **IT+**  
**Contacted On** 05-26-2015 11:42:00 **Agency** Biloxi Police Department **Contact Name** 347 **Phone** 228-392-0641  
esters Boulevard

**Updated** 05/26/2015 13:10:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Closed** 05/26/2015 15:01:54 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 05/26/2015 15:00:00 Equipment Type: N/A Action Taken: NTF - UTD

**The Signal Maintainer reported that there was no signal damage. Operational Checks were performed.  
The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 05/26/2015  
15:01:54

**Updated** 05/26/2015 15:11:03 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** 05-26-2015 15:07:00 **Agency** Biloxi Police Department **Contact Name** 2901 **Phone** 228-392-0641  
esters Boulevard

---

**Log#** [7078439](#) **Status** Closed **Entered** 03-31-2015 18:42:08 **by** Rosenblatt, Louis **Type** Vehicle on Track

**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 726.6 **Block** 2762

**Section** 3090-7M16 **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Mannion, R - *ETA: 21:29*

**Description** 03/31/2015 18:42:08 **by** Louis Rosenblatt **Dept** Signals **IT+** Unknown

**Updated** 03/31/2015 18:44:19 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track

The AA Dispatcher received a report from the PSCC that Main Street, MP 000 726.61, DOT# 340185W, NM Sub, has a tractor trailer stuck on the tracks.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 49296**. LVR  
Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 03/31/2015 18:44:19

**Updated** 03/31/2015 19:29:44 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Roger Mannion ETA of: 21:29

**Updated** 03/31/2015 21:30:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Updated** 03/31/2015 21:57:04 **by** Roger Mannion **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 03/31/2015 21:57:00 Equipment Type: N/A Action Taken: Track Occupied Truck removed from track,  
no signal damage, watched SB train through crossing with no exceptions. Returned to dispatcher @ 2156. Operational  
Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 03/31/2015 21:57:04

**Closed** 03/31/2015 22:01:23 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 03/31/2015 22:01:00 Equipment Type: N/A Action Taken: Track Occupied Resolved to close.  
Operational Checks Performed

**Updated** 03/31/2015 23:42:55 **by** Misty Hunter **Dept** PSCC **IT+**

---

**Log#** [7076463](#) **Status** Closed **Entered** 03-30-2015 15:49:29 **by** Rosenblatt, Louis **Type** Vehicle on Track  
**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.6 **Block** 2762  
**Section** 3090-7M16 **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Mannion, R - ETA: 19:15  
**Description** 03/30/2015 15:49:29 **by** Louis Rosenblatt **Dept** Signals **IT+** Unknown  
**Updated** 03/30/2015 15:49:57 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track

The AA Dispatcher received a report from the PSCC that Main Street, MP 000 726.61, DOT# 340185W, NM Sub, has a tractor trailer stuck on the tracks.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 45827**. LVR  
Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 03/30/2015 15:49:57

**Updated** 03/30/2015 16:15:46 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Roger Mannion ETA of: 19:15

**Updated** 03/30/2015 18:11:12 **by** Roger Mannion **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 03/30/2015 18:11:00 Equipment Type: N/A Action Taken: Track Occupied Truck removed prior to arrival, no signal damages, verified full operation of crossing with no exceptions. returned to dispatcher at 1806, WCJ. Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 03/30/2015 18:11:12

**Closed** 03/30/2015 18:12:54 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 03/30/2015 18:12:00 Equipment Type: N/A Action Taken: Track Occupied Resolved to close. Operational Checks Performed

---

**Log#** [6860473](#) **Status** Closed **Entered** 10-31-2014 10:45:13 **by** Kite, Matt **Type** Vehicle on Track  
**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 726.6 **Block** 2762  
**Section** 3090-7M16 **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Mannion, R - ETA: 12:50  
**Description** 10/31/2014 10:45:13 **by** Matthew Kite **Dept** Signals **IT+** Unknown  
**Updated** 10/31/2014 10:46:07 **by** Matthew Kite **Dept** Signals **IT+** Vehicle on Track

Disp reports truck on the trks at crossing. Disp prot with A/F #16860.  
Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 10/31/2014 10:46:07

**Updated** 10/31/2014 10:50:13 **by** Matthew Kite **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Roger Mannion ETA of: 12:50

**Updated** 10/31/2014 10:57:24 **by** Robert Clendening **Dept** PSCC **IT+**  
**Contacted On** 10-31-2014 10:56:00 Agency Biloxi Police Department **Contact Name** John **Phone** 228-392-0641  
@ Esters Boulevard

**Updated** 10/31/2014 11:07:30 **by** Matthew Kite **Dept** Signals **IT+** Vehicle on Track

ATL ACD, AA Disp, NM Sub, Loc 2762; PSCC reported vehicle stuck on tracks at mp 000726.6, Main Street - COPIED.

**Updated** 10/31/2014 12:55:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Updated** 10/31/2014 12:55:24 **by** Roger Mannion **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 10/31/2014 12:55:00 Equipment Type: N/A Action Taken: Track Occupied truck removed no signal damage. back to dispatcher @ 1254 with message number 16966 Operational Checks Performed Asset:



MAIN ST Status Changed To: In Service PCC Notification Sent 10/31/2014 12:55:24

**Closed** 10/31/2014 12:58:05 by Matthew Kite Dept Signals IT+ Vehicle on Track  
Incident Resolved: 10/31/2014 12:57:00 Equipment Type: N/A Action Taken: NTF - UTD  
Operational Checks Performed

---

**Log#** [6848453](#) **Status** Closed **Entered** 10-22-2014 17:34:32 **by** Rosenblatt, Louis **Type** Vehicle on Track  
**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.6 **Block** 2762  
**Section** 3090-7M16 **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Mannion, R - ETA: 19:49  
**Description** 10/22/2014 17:34:32 by Louis Rosenblatt Dept Signals IT+ Unknown  
**Updated** 10/22/2014 17:35:19 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track

The AA Dispatcher reported that Main Street, MP 000 726.61, DOT# 340185W, NM Sub, has a tractor trailer stuck on the tracks.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 39632**. LVR  
Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 10/22/2014 17:35:19

**Updated** 10/22/2014 17:49:10 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track  
Status changed to Dispatched for Roger Mannion ETA of: 19:49

**Updated** 10/22/2014 19:50:00 by TCIS AUTOMATION Dept Signals IT+ Vehicle on Track  
ETA time reached Status changed to Active

**Updated** 10/22/2014 20:08:52 by Roger Mannion Dept Signals IT+ Vehicle on Track  
Incident Resolved: 10/22/2014 20:08:00 Equipment Type: N/A Action Taken: Track Occupied vehicle removed,  
no signal damages. Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC  
Notification Sent 10/22/2014 20:08:52

**Closed** 10/22/2014 20:13:43 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track  
Incident Resolved: 10/22/2014 20:13:00 Equipment Type: N/A Action Taken: Track Occupied Resolved to close.  
Operational Checks Performed

---

**Log#** [6772574](#) **Status** Closed **Entered** 08-28-2014 22:29:53 **by** Rosenblatt, Louis **Type** Train-vehicle collision  
**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.6 **Block** 2762  
**Section** 3090-7M16 **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Stanfill, M O - ETA: 01:11 & Watson, T G - ETA: 05:30  
**Description** 08/28/2014 22:29:53 by Louis Rosenblatt Dept Signals IT+ Unknown  
**Updated** 08/28/2014 22:30:34 by Louis Rosenblatt Dept Signals IT+ Train-vehicle collision

The AA Dispatcher received a report from Q18028 Northbound that they struck a Tractor Trailer at Main Street,  
MP 000 726.61, DOT# 340185W, NM Sub.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 20224**. LVR  
Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 08/28/2014 22:30:34

**Updated** 08/28/2014 22:30:47 by Louis Rosenblatt Dept Signals IT+ Train-vehicle collision  
Notification has been sent to the following: George James Jr Danny McKenzie Jody Cox C Manager

**Updated** 08/28/2014 22:39:49 by Louis Rosenblatt Dept Signals IT+ Train-vehicle collision

1. **Train involved:** Q18028
2. **Direction of travel:** North
3. **Estimated speed:** unknown

4. **Subdivision:** NM - NO&M
5. **Timetable speed:** 45 MPH
6. **Number of occupants/injuries:** 0/0
7. **Number of fatalities:** 0
8. **Milepost:** 000 726.61 **DOT:** 340185W **Name:** Main Street
9. **Crossing protection (gates, flashers, bells, cantilevers, etc.):** Flashers/Bell/Gates
10. **Crossing controller equipment (PMD3, GCP 4000, etc.):** GCP-3000
11. **Damage to crossing, if any:** unknown
12. **Date last inspected (can be pulled from Raildocs):** 08/08/2014

**Updated** 08/28/2014 22:41:34      **by** Louis Rosenblatt      **Dept** Signals      **IT+** Train-vehicle collision

C&S Manager Briefed.

**Updated** 08/28/2014 22:43:12      **by** Louis Rosenblatt      **Dept** Signals      **IT+** Train-vehicle collision

**Update** - The AA Dispatcher reported that the train crew said they were going 40 mph and they are checking for signal damage. LVR

**Updated** 08/28/2014 23:11:59      **by** Jerry Rockhill      **Dept** Signals      **IT+** Train-vehicle collision  
Status changed to Dispatched for Michael Stanfill ETA of: 01:11

**Updated** 08/29/2014 01:15:00      **by** TCIS AUTOMATION      **Dept** Signals      **IT+** Train-vehicle collision  
ETA time reached Status changed to Active

**Updated** 08/29/2014 01:20:34      **by** Jerry Rockhill      **Dept** Signals      **IT+** Train-vehicle collision  
0114 mtr reports east gate and signal at crossing is on the ground....mtr onsite

**Updated** 08/29/2014 03:08:17      **by** Jerry Rockhill      **Dept** Signals      **IT+** Train-vehicle collision  
0300 mtr needs for crossing repairs: gate mech with 2 arms and gate keeper mast with double junction box base 18 ft gate with lights bell for top of mast doll arm 2 sets of back to back lights (8 lights)....led inserts are reusable onsite...xbucks and dot sign reusable...

**Updated** 08/29/2014 05:29:38      **by** Jerry Rockhill      **Dept** Signals      **IT+** Train-vehicle collision  
Status changed to Escalated, Tommy Watson ETA of: 05:30

**Closed** 08/29/2014 21:42:07      **by** Louis Rosenblatt      **Dept** Signals      **IT+** Train-vehicle collision  
Incident Resolved: 08/29/2014 21:39:00 Equipment Type: Gate Mechanism Action Taken: Replaced component(s)

**The Signal Maintainer reported that East Gate Mechanism Assembly was replaced. Operational Checks were performed. He watched a Southbound train operate through the crossing with no exceptions taken. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 08/29/2014 21:42:07

---

**Log#** [6740944](#)      **Status** Closed      **Entered** 08-07-2014 08:23:35      **by** Gothard, Jason      **Type** Vehicle on Track  
**Supv** James Jr, G H      **Reg** SO      **Div** AT      **Sub** NM      **IRI** 0      **Milepost** 000 726.6      **Block** 2762  
**Section** 3090-Ocean Springs      **Asset** MAIN ST      **AssetNum** 340185W      **Maintainer** Stanfill, M O - ETA: 09:24  
**Description** 08/07/2014 08:23:35      **by** Jason Gothard      **Dept** Signals      **IT+** Unknown  
**Updated** 08/07/2014 08:24:05      **by** Jason Gothard      **Dept** Signals      **IT+** Vehicle on Track  
atl acd, aa disp, nm sub, loc 2781" PSSC reported a tractor trailer stuck on the track at Main St, MP 000 726.61...Please send MOW and Signals to check Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 08/07/2014 08:24:05

**Updated** 08/07/2014 08:24:49 **by** Jason Gothard **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Michael Stanfill ETA of: 09:24

**Updated** 08/07/2014 08:40:16 **by** Brooks Clayton **Dept** PSCC **IT+**  
**Contacted On** 08-07-2014 08:40:00 **Agency** Biloxi Police Department **Contact Name** Tiffany **Phone** 228-392-0641

**Closed** 08/07/2014 09:20:44 **by** Jason Gothard **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 08/07/2014 09:20:00 Equipment Type: N/A Action Taken: Track Occupied truck cleared and no signal damage. made op checks and ret to disp Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 08/07/2014 09:20:44

**Updated** 08/07/2014 09:23:47 **by** Christina Martorano **Dept** PSCC **IT+**  
**Contacted On** 08-07-2014 09:22:00 **Agency** Biloxi Police **Contact Name** Tiffany **Phone** 228-392-0641

---

**Log#** [6646699](#) **Status** Closed **Entered** 06-03-2014 08:32:07 **by** Kite, Matt **Type** Vehicle on Track  
**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.6 **Block** 2762  
**Section** 3090-Ocean Springs **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Stanfill, M O - ETA: 09:34  
**Description** 06/03/2014 08:32:07 **by** Matthew Kite **Dept** Signals **IT+** Unknown  
**Updated** 06/03/2014 08:33:03 **by** Matthew Kite **Dept** Signals **IT+** Vehicle on Track

ATLANTA CHIEF, AA DISPATCHER, MM SUB, LOCATION 2762-001, PSCC REPORTS TRUCK ON TRACKS AT MAIN ST MP 000726.6 - Copied. Disp prot with A/F #47506.  
Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 06/03/2014 08:33:03

**Updated** 06/03/2014 08:34:18 **by** Matthew Kite **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Michael Stanfill ETA of: 09:34

**Updated** 06/03/2014 08:45:31 **by** Christina Martorano **Dept** PSCC **IT+**  
**Contacted On** 06-03-2014 08:35:00 **Agency** Biloxi Police **Contact Name** 347 **Phone** 228-392-0641  
PSCC incident #6646688

**Updated** 06/03/2014 09:39:04 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Closed** 06/03/2014 10:13:00 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 06/03/2014 10:12:00 Equipment Type: N/A Action Taken: NTF - UTD

**Employee:** M. Stanfill

- Vehicle removed, No signal damage.

Did OP Checks, Back/released to AA disp. Gate down time 14

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 06/03/2014 10:13:00

**Updated** 06/03/2014 10:42:40 **by** Alexis Romine **Dept** PSCC **IT+**  
**Contacted On** 06-03-2014 10:42:00 **Agency** Biloxi Police **Contact Name** Angie **Phone** 228-392-0641  
PSCC incident #6646688

---

**Log#** [6534225](#) **Status** Closed **Entered** 03-14-2014 17:29:57 **by** Rosenblatt, Louis **Type** Vehicle on Track  
**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.6 **Block** 2762  
**Section** 3090-Ocean Springs **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Richardson, G L - ETA: 19:48  
**Description** 03/14/2014 17:29:57 **by** Louis Rosenblatt **Dept** Signals **IT+** Unknown  
**Updated** 03/14/2014 17:31:25 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track

The AA Dispatcher received a report from the PSCC that Main Street, MP 000 726.61, DOT# 340185W, NM Sub, has a vehicle on the track.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 16663**. LVR  
Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 03/14/2014 17:31:25

**Updated** 03/14/2014 17:49:37 **by** Sean Reid **Dept** PSCC **IT+**  
**Contacted On** 03-14-2014 17:49:00 **Agency** Biloxi Police Department **Contact Name** Disp # Hamet **Phone** 228-392-0641  
@ Esters Blvd

**Updated** 03/14/2014 19:03:21 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Gregory Richardson ETA of: 19:48

**Updated** 03/14/2014 19:50:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Updated** 03/14/2014 19:50:10 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Closed** 03/14/2014 20:59:15 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 03/14/2014 20:56:00 Equipment Type: N/A Action Taken: NTF - UTD

**The Signal Maintainer reported that there was no signal damage. The vehicle has been removed. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 03/14/2014 20:59:15

**Updated** 03/14/2014 21:05:59 **by** Avie Saunders **Dept** PSCC **IT+**  
**Contacted On** 03-14-2014 21:05:00 **Agency** n/a **Contact Name** n/a **Phone** n/a  
PSCC Incident Report #6534196

---

**Log#** [6254591](#) **Status** Closed **Entered** 08-18-2013 07:52:45 **by** Kondy, Rick **Type** .False or partial activation reported

**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 726.6 **Block** 2762

**Section** 3090-Ocean Springs **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Stanfill, M O - ETA: 09:31

**Description** 08/18/2013 07:52:45 **by** Richard Kondy **Dept** Signals **IT+** Unknown

**Updated** 08/18/2013 07:55:00 **by** Richard Kondy **Dept** Signals **IT+** .False or partial activation reported  
gates down , no trains . disp protecting crossing with false activation # 29673 . Notification Sent to -Signal Control Center - Atlanta at 08/18/2013 07:55:00 Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 08/18/2013 07:55:00

**Updated** 08/18/2013 08:01:50 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 09:31

**Updated** 08/18/2013 08:03:30 **by** Deborah Anderson **Dept** PSCC **IT+**  
**Contacted On** **Agency** // **Contact Name** biloxi police **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 08/18/2013 09:35:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 08/18/2013 10:00:49 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
• Mtr/employee is on-site.

**Updated** 08/18/2013 11:21:55 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
SB Q579-17 in block

**Closed** 08/18/2013 11:46:44 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported

Incident Resolved: 08/18/2013 11:46:00 Equipment Type: Power/batteries Action Taken: Lightning protectors/arrestors replaced

**Employee:** M. Stanfill

- replaced 6 lighting arrestors at Lamse...

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 08/18/2013 11:46:44

**Updated** 08/18/2013 12:19:54 **by** Deborah Anderson **Dept** PSCC **IT+**  
**Contacted On** 08-18-2013 12:19:00 **Agency** biloxi police **Contact Name** 376 **Phone** 228-392-0641

---

**Log#** [6254121](#) **Status** Closed **Entered** 08-17-2013 14:55:47 **by** Williams, Joseph **Type** .False or partial activation reported

**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.6 **Block** 2762

**Section** 3090-Ocean Springs **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Houck, B - ETA: 16:30

**Description** 08/17/2013 14:55:47 **by** Joseph Williams **Dept** Signals **IT+** Unknown

**Updated** 08/17/2013 14:59:17 **by** Joseph Williams **Dept** Signals **IT+** .False or partial activation reported  
1456:HR Biloxi Police reported that the gates are down with lights flashing and no trains in sight. 1458:Hr dispatcher WJS notified.  
Notification Sent to -Signal Control Center - Atlanta at 08/17/2013 14:59:17 Asset: MAIN ST Status Changed To: Out Of Service PCC  
Notification Sent 08/17/2013 14:59:17

**Updated** 08/17/2013 15:07:44 **by** Sean Reid **Dept** PSCC **IT+**  
**Contacted On** 08-17-2013 15:07:00 **Agency** Biloxi Police Department **Contact Name** Disp # Eric **Phone** 228-392-0641

**Updated** 08/17/2013 15:30:56 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Bradley Houck ETA of: 16:30

**Updated** 08/17/2013 16:35:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 08/17/2013 17:56:48 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 08/17/2013 17:45:00 Equipment Type: Crossing case equipment Action Taken: Replaced card(s)  
Mntr found relay drive cd on nor side was bad, transferred to stand-by side, tested crossing. Operational checks were good, turned  
crossing backover to disp.  
Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 08/17/2013 17:56:48

**Updated** 08/17/2013 18:37:57 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** 08-17-2013 18:37:00 **Agency** Biloxi Police Department **Contact Name** operator **Phone** 228-392-0641

---

**Log#** [5884366](#) **Status** Closed **Entered** 12-01-2012 17:13:28 **by** Kite, Matt **Type** Vehicle on Track

**Supv** James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 726.6 **Block** 2762

**Section** 3090-Ocean Springs **Asset** MAIN ST **AssetNum** 340185W **Maintainer** Broadway, J L - ETA: 18:41

**Description** 12/01/2012 17:14:56 **by** Matthew Kite **Dept** Signals **IT+** Vehicle on Track

atl acc, aa disp, nm sub, loca: 000726.6 horse trailer bottomed out on the tracks, need mow and signals to  
inspect - COPIED. Train crew reports trailer is stuck on trks. Disp prot crossing with A/F #40581.  
Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 12/01/2012 17:14:56

**Closed** 12/01/2012 19:22:55 **by** Matthew Kite **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 12/01/2012 19:18:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as  
intended Suspected Reason: Outside party or vandalism  
Mntr reports trailer removed frm trk. No damage to sig equipment at crossing. Performed op checks, gate des  
time 13 sec. Turned crossing backover to disp.  
Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent  
12/01/2012 19:22:55

**Log#** [5789068](#)   **Status** Closed   **Entered** 09-19-2012 15:39:54   **by** Rosenblatt, Louis   **Type** Vehicle on Track

**Supv** James Jr, G H   **Reg** SO   **Div** AT   **Sub** NM   **IRI**   **Milepost** 000 726.6   **Block** 2762

**Section** 3090-Ocean Springs   **Asset** MAIN ST   **AssetNum** 340185W   **Maintainer** Stanfill, M O - *ETA*: 16:54

**Description** 09/19/2012 15:43:19   **by** Louis Rosenblatt   **Dept** Signals   **IT+** Vehicle on Track

The AA Dispatcher received a report from the PSCC that Main Street, MP 000 726.61, DOT# 340185W, has a vehicle stuck on the track.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 33399**. LVR  
Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 09/19/2012 15:43:19

**Updated** 09/19/2012 15:44:53

**by** Raheem Roberts

**Dept** PSCC

**IT+**

**Contacted On** 09-19-2012 15:44:00

**Agency** n/a

**Contact Name** n/a

**Phone** n/a

Ref PSCC Incident Report #5788977

**Closed** 09/19/2012 17:49:10

**by** Louis Rosenblatt

**Dept** Signals

**IT+** Vehicle on Track

Incident Resolved: 09/19/2012 17:47:00 Equipment Type: N/A Action Taken: Issue cleared before cause identified Suspected Reason: Equipment failure

**The Signal Maintainer tested the crossings with no issues found. The Crossing is Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 09/19/2012 17:49:10

**Updated** 09/19/2012 18:15:21

**by** Sean Reid

**Dept** PSCC

**IT+**

**Contacted On** 09-19-2012 18:15:00

**Agency** n/a

**Contact Name** n/a

**Phone** n/a

Ref PSCC Incident Report #5788977

Page Execution Time: 003.00 seconds

**Lameuse Street**

**DOT Crossing #: 340186D**

**RR Milepost #: 726.70**



## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 16

Status All AssetType All RootAssetType All Department Signals AssetNum 340186D

---

**Log#** [7389691](#) **Status** Closed **Entered** 11-04-2015 15:46:31 **by** Oglesby, Brad **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.7 **Block** 2762

**Section** 3090-7M16 **Asset** LAMEUSE ST. **AssetNum** 340186D **Maintainer**

**Description** 11/04/2015 15:46:31 **by** Brad Oglesby **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340186D). Fault detected - sigOStCsAlarm\_000-726.70-340186D-034 LIGHTING BATTERY (XB) GFT ALARM - TCIS:3 at Lameuse St. - (Bad CDMA) 10/26/2015 02:24:28 (MP:000-726.70, DOT:340186D) [ Count: 21 on Wed Nov 4 20:45:10 2015 ]

**Updated** 11/04/2015 15:47:33 **by** Brad Oglesby **Dept** Signals **IT+** .Other Failure

**Closed** 11/05/2015 10:55:21 **by** Bruce McVey **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 11/05/2015 10:55:00 Equipment Type: N/A Action Taken: NTF - UTD reset both GND fault tester box... Operational Checks Performed

---

**Log#** [7316618](#) **Status** Closed **Entered** 09-11-2015 12:38:33 **by** Lewis, Wendell **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 726.7 **Block** 2762

**Section** 3090-7M16 **Asset** LAMEUSE ST. **AssetNum** 340186D **Maintainer** Stanfill, M O - ETA: 14:45

**Description** 09/11/2015 12:38:33 **by** Wendell Lewis **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340186D). Fault detected - sigOStCsAlarm\_000-726.70-340186D-005 \*\*AC POWER OFF FOR 20 MINUTES - TCIS:4 at Lameuse St. - Biloxi, MS 09/11/2015 12:28:28 (MP:000-726.70, DOT:340186D) [ Count: 2 on Fri Sep 11 16:27:05 2015 ]

**Updated** 09/11/2015 12:39:17 **by** Wendell Lewis **Dept** Signals **IT+** .Other Failure  
. Notification Sent to -Signal Control Center - Atlanta at 09/11/2015 12:39:17

**Updated** 09/11/2015 12:45:45 **by** Matthew Kite **Dept** Signals **IT+** .Other Failure  
Status changed to Dispatched for Michael Stanfill ETA of: 14:45

**Updated** 09/11/2015 14:50:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .Other Failure  
ETA time reached Status changed to Active

**Closed** 09/11/2015 14:58:01 **by** Louis Rosenblatt **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 09/11/2015 14:57:00 Equipment Type: Power/Batteries Action Taken: Commercial Power Restored

**The Signal Maintainer reported that the Commercial Power is good at the location. LVR**

Operational Checks Performed

---

**Log#** [7310570](#) **Status** Closed **Entered** 09-07-2015 08:23:06 **by** Lewis, Wendell **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.7 **Block** 2762

**Section** 3090-7M16 **Asset** LAMEUSE ST. **AssetNum** 340186D **Maintainer**

**Description** 09/07/2015 08:23:06 **by** Wendell Lewis **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340186D). Fault detected - sigOStCsAlarm\_000-726.70-340186D-005 \*\*AC POWER OFF FOR 20 MINUTES - TCIS:4 at Lameuse St. - Biloxi, MS 09/07/2015 08:21:19 (MP:000-726.70, DOT:340186D) [ Count: 2 on Mon Sep 7 12:19:58 2015 ]

**Updated** 09/07/2015 08:25:54 **by** Wendell Lewis **Dept** Signals **IT+** .Other Failure  
PLEASE HAVE MNTR. CHECK PRIORITY 4 ALARM WHEN BACK ON DUTY.

**Updated** 09/07/2015 15:48:57 **by** Brad Oglesby **Dept** Signals **IT+** .Other Failure  
Smarts alert notification for njax-aserver-04.dmz.csxr(340186D). Fault detected - sigOStCsAlarm\_000-726.70-340186D-005 CLEARED:AC POWER BACK ON - TCIS:5 at Lameuse St. - Biloxi, MS 09/07/2015 11:21:57



(MP:000-726.70, DOT:340186D)

**Closed** 09/07/2015 15:49:19 by Brad Oglesby Dept Signals IT+ .Other Failure  
Incident Resolved: 09/07/2015 15:49:00 Equipment Type: N/A Action Taken: NTF - UTD . Operational Checks Performed

---

**Log#** [6981383](#) **Status** Closed **Entered** 01-28-2015 12:14:17 **by** Lewis, Wendell **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.7 **Block** 2762

**Section** 3090-7M16 **Asset** LAMEUSE ST. **AssetNum** 340186D **Maintainer** Stanfill, M O - *ETA*: 13:20

**Description** 01/28/2015 12:14:18 by Wendell Lewis Dept Signals IT+ Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340186D). Fault detected - sigOStCsAlarm\_000-726.70-340186D-005 \*\*AC POWER OFF FOR 20 MINUTES - TCIS:4 at Lameuse St. - Biloxi, MS 01/28/2015 12:13:54 (MP:000-726.70, DOT:340186D) [ Count: 2 on Wed Jan 28 17:13:17 2015 ]

**Updated** 01/28/2015 12:15:02 by Wendell Lewis Dept Signals IT+ .Other Failure  
. Notification Sent to -Signal Control Center - Atlanta at 01/28/2015 12:15:02

**Updated** 01/28/2015 12:20:52 by Jason Gothard Dept Signals IT+ .Other Failure  
Status changed to Dispatched for Michael Stanfill ETA of: 13:20

**Closed** 01/28/2015 13:21:32 by Bruce McVey Dept Signals IT+ .Other Failure  
Incident Resolved: 01/28/2015 13:21:00 Equipment Type: Other Equipment/Relays Action Taken: Reseated Relay

**Employee:** M. Stanfill

- Reseated potter brum relay, power restored in WAMS

Did OP Checks

Operational Checks Performed

---

**Log#** [6939971](#) **Status** Closed **Entered** 12-29-2014 11:22:03 **by** Lewis, Wendell **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 726.7 **Block** 2762

**Section** 3090-7M16 **Asset** LAMEUSE ST. **AssetNum** 340186D **Maintainer** Stanfill, M O - *ETA*: 12:57

**Description** 12/29/2014 11:22:04 by Wendell Lewis Dept Signals IT+ Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340186D). Fault detected - sigOStCsAlarm\_000-726.70-340186D-005 \*\*AC POWER OFF FOR 20 MINUTES - TCIS:4 at Lameuse St. - Biloxi, MS 12/29/2014 09:43:18 (MP:000-726.70, DOT:340186D) [ Count: 2 on Mon Dec 29 14:42:56 2014 ]

**Updated** 12/29/2014 11:22:33 by Wendell Lewis Dept Signals IT+ .Other Failure  
. Notification Sent to -Signal Control Center - Atlanta at 12/29/2014 11:22:33

**Updated** 12/29/2014 11:27:59 by Jason Gothard Dept Signals IT+ .Other Failure  
Status changed to Dispatched for Michael Stanfill ETA of: 12:57

**Updated** 12/29/2014 12:27:12 by Jason Gothard Dept Signals IT+ .Other Failure  
2014/12/29 11:37:23 AC POWER BACK ON - TCIS:5#5#0#5#5##

**Closed** 12/29/2014 12:40:54 by Jason Gothard Dept Signals IT+ .Other Failure  
Incident Resolved: 12/29/2014 12:40:00 Equipment Type: Power/Batteries Action Taken: Commercial Power Restored commercial power restored Operational Checks Performed

---

**Log#** [6932130](#) **Status** Closed **Entered** 12-21-2014 14:35:13 **by** Jackson Jr, Marv **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.7 **Block** 2762

**Section** 3090-7M16 **Asset** LAMEUSE ST. **AssetNum** 340186D **Maintainer**

**Description** 12/21/2014 14:35:14 by Marv Jackson Jr Dept Signals IT+ Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340186D). Fault detected - sigOStCsAlarm\_000-726.70-340186D-005 \*\*AC POWER OFF FOR 20 MINUTES - TCIS:4 at Lameuse St. - Biloxi, MS 12/21/2014 13:45:11 (MP:000-726.70, DOT:340186D) [ Count: 2 on Sun Dec 21 18:44:51 2014 ]

**Updated** 12/21/2014 14:38:19 **by** Marv Jackson Jr **Dept** Signals **IT+** .Other Failure  
AC POWER OFF FOR 20 MINUTES - TCIS:4 at Lameuse St. - Biloxi, MS 12/21/2014 13:45:11 (MP:000-726.70,  
DOT:340186D) [ Count: 2 on Sun Dec 21 18:44:51 2014 ] Notification Sent to -Signal Control Center - Atlanta at  
12/21/2014 14:38:19

**Updated** 12/27/2014 07:22:13 **by** Tommy Watson **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 12/27/2014 07:21:00 Equipment Type: Other Equipment/Relays Action Taken: Replace Relay  
Replaced the potter brumfield relay for POR Operational Checks Performed

**Closed** 12/27/2014 07:27:23 **by** Jason Gothard **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 12/27/2014 07:27:00 Equipment Type: Other Equipment/Relays Action Taken: Replace Relay  
Incident Resolved: 12/27/2014 07:21:00 Operational Checks Performed

---

**Log#** [6852610](#) **Status** Closed **Entered** 10-25-2014 23:34:13 **by** Oglesby, Brad **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 726.7 **Block** 2762

**Section** 3090-7M16 **Asset** LAMEUSE ST. **AssetNum** 340186D **Maintainer**

**Description** 10/25/2014 23:34:13 **by** Brad Oglesby **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340186D). Fault detected - sigOStCsAlarm\_000-726.70-  
340186D-005 \*\*AC POWER OFF FOR 20 MINUTES - TCIS:4 at Lameuse St. - Biloxi, MS 10/25/2014 20:59:07  
(MP:000-726.70, DOT:340186D) [ 6 at ]

**Updated** 10/25/2014 23:35:09 **by** Brad Oglesby **Dept** Signals **IT+** .Other Failure  
THERE ISN'T A POWER-OFF INDICATION SHOWING AT THE CONTROL POINT OR IN THE BLOCK.

**Updated** 10/26/2014 04:13:25 **by** Jerry Rockhill **Dept** Signals **IT+** .Other Failure  
0411 MTR REPORTS POWER IS ON BUT HAS A BAD POTTER BRUMFIELD RELAY...MTR WILL REPLACE  
MONDAY AM....CIS...

**Updated** 10/28/2014 06:56:11 **by** Tommy Watson **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 10/28/2014 06:55:00 Equipment Type: Other Equipment/Relays Action Taken: Replace Relay  
Replaced the relay Operational Checks Performed

**Closed** 10/28/2014 06:57:49 **by** Bruce McVey **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 10/28/2014 06:57:00 Equipment Type: Other Equipment/Relays Action Taken: Replace Relay  
**Operational Checks Performed**

---

**Log#** [6852374](#) **Status** Closed **Entered** 10-25-2014 17:11:06 **by** Lewis, Wendell **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.7 **Block** 2762

**Section** 3090-7M16 **Asset** LAMEUSE ST. **AssetNum** 340186D **Maintainer**

**Description** 10/25/2014 17:11:06 **by** Wendell Lewis **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340186D). Fault detected - sigOStCsAlarm\_000-726.70-  
340186D-005 \*\*AC POWER OFF FOR 20 MINUTES - TCIS:4 at Lameuse St. - Biloxi, MS 10/25/2014 17:09:45  
(MP:000-726.70, DOT:340186D) [ 2 at ]

**Updated** 10/25/2014 17:12:55 **by** Wendell Lewis **Dept** Signals **IT+** .Other Failure  
PLEASE HAVE MNTR. CHECK PRIORITY 4 ALARM WHEN BACK ON DUTY.

**Updated** 10/25/2014 19:50:06 **by** Brad Oglesby **Dept** Signals **IT+** .Other Failure  
Smarts alert notification for njax-aserver-04.dmz.csxr(340186D). Fault detected - sigOStCsAlarm\_000-726.70-  
340186D-005 CLEARED:AC POWER BACK ON - TCIS:5 at Lameuse St. - Biloxi, MS 10/25/2014 17:50:02  
(MP:000-726.70, DOT:340186D)

**Closed** 10/25/2014 19:50:25 **by** Brad Oglesby **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 10/25/2014 19:50:00 Equipment Type: N/A Action Taken: NTF - UTD . Operational Checks  
Performed

---

**Log#** [6570331](#) **Status** Closed **Entered** 04-09-2014 11:30:24 **by** McVey, Bruce **Type** Vehicle on Track

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.7 **Block** 2762

**Section** 3090-Ocean Springs **Asset** LAMEUSE ST. **AssetNum** 340186D **Maintainer** Stanfill, M O - ETA: 13:09

**Description** 04/09/2014 11:30:24      **by** Bruce McVey      **Dept** Signals      **IT+** Unknown  
**Updated** 04/09/2014 11:31:44      **by** Bruce McVey      **Dept** Signals      **IT+** Vehicle on Track

ATL CTD

- Notification:

atl acd, aa disp, nm sub, loc 2781: PSCC reported a vehicle on the track at Lameuse ST, mp 000 726.7...need MOW and Signals to respond.... :COPIED

Asset: LAMEUSE ST. Status Changed To: Out Of Service PCC Notification Sent 04/09/2014 11:31:44

**Updated** 04/09/2014 11:33:13      **by** Bruce McVey      **Dept** Signals      **IT+** Vehicle on Track  
The AA is protecting the Crossing with a **Type 1 Activation Failure Message#24491** .

**Updated** 04/09/2014 11:35:32      **by** Max Todd      **Dept** PSCC      **IT+**  
**Contacted On** 04-09-2014 11:35:00      **Agency** n/a      **Contact Name** n/a      **Phone** n/a  
vehicle on track

**Updated** 04/09/2014 11:39:21      **by** Bruce McVey      **Dept** Signals      **IT+** Vehicle on Track  
Status changed to Dispatched for Michael Stanfill ETA of: 13:09

**Updated** 04/09/2014 13:10:00      **by** TCIS AUTOMATION      **Dept** Signals      **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Closed** 04/09/2014 14:42:29      **by** Jason Gothard      **Dept** Signals      **IT+** Vehicle on Track  
Incident Resolved: 04/09/2014 14:42:00 Equipment Type: N/A Action Taken: NTF - UTD vehicle removed, no signal damage xing working as intended Operational Checks Performed Asset: LAMEUSE ST. Status Changed To: In Service PCC Notification Sent 04/09/2014 14:42:29

**Updated** 04/09/2014 14:44:09      **by** Max Todd      **Dept** PSCC      **IT+**  
**Contacted On** 04-09-2014 14:44:00      **Agency** n/a      **Contact Name** n/a      **Phone** n/a  
vehicle on track

---

**Log#** [6254868](#)      **Status** Closed      **Entered** 08-18-2013 15:34:35      **by** Oglesby, Brad      **Type** .Other Failure  
**Supv** Merritt, D      **Reg** SO      **Div** AT      **Sub** NM      **IRI** 0      **Milepost** 000 726.7      **Block** 2762  
**Section** 3090-Ocean Springs      **Asset** LAMEUSE ST.      **AssetNum** 340186D      **Maintainer** Stanfill, M O - *ETA*: 20:23

**Description** 08/18/2013 15:34:35      **by** Brad Oglesby      **Dept** Signals      **IT+** Unknown  
Smarts alert notification for nind2008app.dmz(340186D). Fault detected - sigOStCsAlarm\_000-726.70-340186D-005 \*\*AC POWER OFF FOR 20 MINUTES - TCIS:4 at Lameuse St. - Biloxi, MS 08/18/2013 15:33:59 (MP:000-726.70, DOT:340186D) [ 1 at ]

**Updated** 08/18/2013 15:35:26      **by** Brad Oglesby      **Dept** Signals      **IT+** .Other Failure  
THERE ISN'T A POWER-OFF INDICATION SHOWING AT THE CONTROL POINT NOR IN THE BLOCK.

**Updated** 08/18/2013 18:46:02      **by** Matthew Kite      **Dept** Signals      **IT+** .Other Failure

Notified Sig Sup James about multiple issues over territory. Bad storms throughout the day.

**Closed** 08/18/2013 20:23:27      **by** Matthew Kite      **Dept** Signals      **IT+** .Other Failure  
Incident Resolved: 08/18/2013 20:15:00 Equipment Type: Power/batteries Action Taken: Other electrical Mntr replaced PO relay at crossing. Bad storms in area. Performed op checks. 2013/08/18 20:10:22 AC POWER BACK ON - TCIS:5# - FRM WAMS.  
Operational Checks Performed

---

**Log#** [6152326](#)      **Status** Closed      **Entered** 06-03-2013 18:41:50      **by** Rosenblatt, Louis      **Type** Vehicle on Track  
**Supv** Merritt, D      **Reg** SO      **Div** AT      **Sub** NM      **IRI** 0      **Milepost** 000 726.7      **Block** 2762  
**Section** 3090-Ocean Springs      **Asset** LAMEUSE ST.      **AssetNum** 340186D      **Maintainer** Stanfill, M O - *ETA*: 20:00

**Description** 06/03/2013 18:41:50      **by** Louis Rosenblatt      **Dept** Signals      **IT+** Unknown

**Updated** 06/03/2013 18:42:29      **by** Louis Rosenblatt      **Dept** Signals      **IT+** Vehicle on Track

The AA Dispatcher received a report that Lamuse Street, MP 000 726.70, DOT# 340186D, has a vehicle stuck on the track.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 39984**. LVR  
Asset: LAMEUSE ST. Status Changed To: Out Of Service PCC Notification Sent 06/03/2013 18:42:29

**Updated** 06/03/2013 18:45:39 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track  
Status changed to Dispatched for Michael Stanfill ETA of: 20:00

**Updated** 06/03/2013 20:05:00 by TCIS AUTOMATION Dept Signals IT+ Vehicle on Track  
ETA time reached Status changed to Active

**Closed** 06/03/2013 21:45:42 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track  
Incident Resolved: 06/03/2013 21:37:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended

**The Signal Maintainer reported that there was no signal damage. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: LAMEUSE ST. Status Changed To: In Service PCC Notification Sent 06/03/2013 21:45:42

---

**Log#** [6030473](#) **Status** Closed **Entered** 03-14-2013 06:44:34 **by** Jackson Jr, Marvin **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.7 **Block** 2762

**Section** 3090-Ocean Springs **Asset** LAMEUSE ST. **AssetNum** 340186D **Maintainer** Stanfill, M O - ETA: 07:35

**Description** 03/14/2013 06:44:34 by Marv Jackson Jr Dept Signals IT+ Unknown  
Smarts alert notification for nind2008app.drmz(340186D). Fault detected - sigOStCsAlarm\_000-726.70-340186D-005 \*\*AC POWER OFF FOR 20 MINUTES - TCIS:4 at Lameuse St. - Biloxi, MS 03/13/2013 23:31:46 (MP:000-726.70, DOT:340186D) [ 1 at ]

**Updated** 03/14/2013 06:45:09 by Marv Jackson Jr Dept Signals IT+ .Other Failure  
smart alarm Notification Sent to -Signal Control Center - Atlanta at 03/14/2013 06:45:09

**Updated** 03/14/2013 07:05:13 by TCIS AUTOMATION Dept Signals IT+ .Other Failure  
Status changed to Dispatched for ETA of: 07:35

**Updated** 03/14/2013 07:40:00 by TCIS AUTOMATION Dept Signals IT+ .Other Failure  
ETA time reached Status changed to Active

**Closed** 03/14/2013 08:41:21 by Jason Gothard Dept Signals IT+ .Other Failure  
Incident Resolved: 03/14/2013 08:30:00 Equipment Type: Power/batteries Action Taken: Other electrical  
2013/03/14 08:37:15 AC POWER BACK ON - TCIS:5#5#0#5#5## replaced the OB pwr off relay Operational Checks Performed

---

**Log#** [5659422](#) **Status** Closed **Entered** 06-22-2012 06:36:06 **by** Jahay, Brian **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 726.7 **Block** 2762

**Section** 3090-Ocean Springs **Asset** LAMEUSE ST. **AssetNum** 340186D **Maintainer** Stanfill, M O - ETA: 07:44 & Patterson Jr, L D - ETA: 13:42

**Description** 06/22/2012 06:37:36 by Brian Jahay Dept Signals IT+ .False or partial activation reported  
Officer rpts crossings are activated with no train in sight.

**Updated** 06/22/2012 06:37:51 by Brian Jahay Dept Signals IT+ .False or partial activation reported  
New Asset Added: 340185W - MAIN ST

**Updated** 06/22/2012 06:38:05 by Brian Jahay Dept Signals IT+ .False or partial activation reported  
New Asset Added: 340186D - LAMEUSE ST.

**Updated** 06/22/2012 06:46:02 by Brian Jahay Dept Signals IT+ .False or partial activation reported  
Protecting with false partial message #'s 19663, 19667 WCJ Notification Sent to -Signal Control Center - Atlanta at 06/22/2012 06:46:02  
Asset: CAILLAVET ST Status Changed To: Out Of Service PCC Notification Sent 06/22/2012 06:46:02 Asset: MAIN ST  
Status Changed To: Out Of Service PCC Notification Sent 06/22/2012 06:46:02 Asset: LAMEUSE ST. Status Changed To: Out Of Service PCC Notification Sent 06/22/2012 06:46:02

**Updated** 06/22/2012 06:50:43 **by** Jesse Gansen **Dept** PSCC **IT+**  
**Contacted On** 06-22-2012 06:50:00 **Agency** Bollix PD **Contact Name** Freida **Phone** 1-228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 06/22/2012 09:04:27 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Mntr reports issue at Lameuse St. Had disp upgrade prot to A/F #19819. Applied jumper Log #5659609, for troubleshooting.

**Updated** 06/22/2012 15:04:19 **by** Brad Oglesby **Dept** Signals **IT+** .False or partial activation reported  
Smarts alert notification for njax-aserver-04.dmz(340186D). Fault detected - sigOStCsAlarm\_000-726.70-340186D-099  
CLEARED:GCP4K TRANSFER COMPLETED TCIS:5 at Lameuse St. - Biloxi, MS 06/22/2012 14:57:53 (MP:000-726.70, DOT:340186D)

**Updated** 06/22/2012 15:04:40 **by** Brad Oglesby **Dept** Signals **IT+** .False or partial activation reported  
Smarts alert notification for njax-aserver-04.dmz(340186D). Fault detected - sigOStCsAlarm\_000-726.70-340186D-006  
ESCALATED:FALSE ACT - GATES STAYED DOWN BEHIND TRAIN - TCIS:1 at Lameuse St. - Biloxi, MS 06/22/2012 14:57:56  
(MP:000-726.70, DOT:340186D)

**Updated** 06/22/2012 15:09:20 **by** Brad Oglesby **Dept** Signals **IT+** .False or partial activation reported  
1506 RECEIVED TCIS SMARTS PRIORITY 1 ALARM FOR LAMEUSE ST. AND NOTICED THAT PROTECTION HAD BEEN LIFTED FROM THE CROSSING. ADVISED THE AA DISPATCHER TO PROVIDE PROTECTION ON LAMEUSE ST. CROSSING AS PER FALSE ACTIVATION STANDARD. A SIGNAL MAINTAINER NEEDS DISPATCHED TO INVESTIGATE THE TCIS SMARTS PRIORITY 1 ALARM. THE GCP4K UNIT HAS DETECTED A FALSE ACTIVATION OCCURRENCE(GATES STAYED DOWN BEHIND A TRAIN) AT LAMEUSE ST. CROSSING. Notification Sent to -Signal Control Center - Atlanta at 06/22/2012 15:09:20

**Updated** 06/22/2012 15:20:35 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Primary Asset changed from: 340191A - CAILLAVET ST To: 340186D - LAMEUSE ST.

**Updated** 06/22/2012 16:10:17 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported

**Update** - The Technician said he took the unit offline for four hours at 14:45. It appears that the unit came back online when transferring the unit to the other side. LVR

**Closed** 06/22/2012 18:30:26 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 06/22/2012 18:25:00 Equipment Type: Track Action Taken: Repaired/replaced track/bond wire Suspected Reason: Equipment failure

**The Signal Maintainer and the Technician found a high resistance island wire connection in a sleeve for the South West bootleg. The connection was repaired. Oeprational Checks were performed. All three crossings are Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: LAMEUSE ST. Status Changed To: In Service PCC Notification Sent 06/22/2012 18:30:26  
Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 06/22/2012 18:30:26 Asset: CAILLAVET ST Status Changed To: In Service PCC Notification Sent 06/22/2012 18:30:26

**Updated** 06/22/2012 18:39:10 **by** Jerome Shepard **Dept** PSCC **IT+**  
**Contacted On** 06-22-2012 18:39:00 **Agency** Bollix PD **Contact Name** Operator Jennifer **Phone** -228-392-0641

---

**Log#** [5642330](#) **Status** Closed **Entered** 06-10-2012 10:08:07 **by** Lewis, Wendell **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 726.7 **Block** 2762

**Section** 3090-Ocean Springs **Asset** LAMEUSE ST. **AssetNum** 340186D **Maintainer**

**Description** 06/10/2012 10:08:07 **by** Wendell Lewis **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz(340186D). Fault detected - sigOStCsAlarm\_000-726.70-340186D-005 \*\*AC POWER OFF FOR 20 MINUTES - TCIS:4 at Lameuse St. - Biloxi, MS 06/10/2012 09:44:19 (MP:000-726.70, DOT:340186D) [ 1 at ]

**Updated** 06/10/2012 10:11:51 **by** Wendell Lewis **Dept** Signals **IT+** .Other Failure  
PLEASE HAVE MNTR. CHECK PRIORITY 4 ALARM WHEN BACK ON DUTY.

**Updated** 06/10/2012 11:19:08 **by** Bruce McVey **Dept** Signals **IT+** .Other Failure  
storms and high winds in area at time on incident

**Closed** 06/11/2012 13:57:32 **by** Bruce McVey **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 06/11/2012 13:56:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended Suspected Reason: Equipment failure reseated ob relay ion the base, power show on now at xing, did cks, OB has had relay base replaced all ready Operational Checks Performed



---

**Log#** [5544507](#) **Status** Closed **Entered** 04-03-2012 08:10:10 **by** Lewis, Wendell **Type** .Other Failure  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 726.7 **Block** 2762  
**Section** 3090-Ocean Springs **Asset** LAMEUSE ST. **AssetNum** 340186D **Maintainer** Stanfill, M O - ETA: 09:41  
**Description** 04/03/2012 08:10:10 **by** Wendell Lewis **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz(340186D). Fault detected - sigOStCsAlarm\_000-726.70-340186D-005 \*\*AC POWER OFF FOR 20 MINUTES - TCIS:4 at Lameuse St. - Biloxi, MS 04/03/2012 07:53:26 (MP:000-726.70, DOT:340186D) [ 1 at ]

**Updated** 04/03/2012 08:11:04 **by** Wendell Lewis **Dept** Signals **IT+** .Other Failure  
. Notification Sent to -Signal Control Center - Atlanta at 04/03/2012 08:11:04

**Updated** 04/03/2012 09:18:52 **by** Jason Gothard **Dept** Signals **IT+** .Other Failure  
2012/04/03 08:55:33 AC POWER BACK ON - TCIS:5#5#0#5#5##

**Closed** 04/03/2012 10:14:46 **by** Bruce McVey **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 04/03/2012 09:15:00 Equipment Type: Other - explain Action Taken: Other - explain  
Suspected Reason: Design/engineering

**Employee:** M. Stanfill

- Replaced bad relay and base for the power off

Did OP Checks

Operational Checks Performed

---

**Log#** [5511570](#) **Status** Closed **Entered** 03-10-2012 09:48:04 **by** Hofer, Dave **Type** .Other Failure  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 726.7 **Block** 2762  
**Section** 3090-Ocean Springs **Asset** LAMEUSE ST. **AssetNum** 340186D **Maintainer**  
**Description** 03/10/2012 09:48:04 **by** David Hofer **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz(340186D). Fault detected - sigOStCsAlarm\_000-726.70-340186D-005 \*\*AC POWER OFF FOR 20 MINUTES - TCIS:4 at Lameuse St. - Biloxi, MS 03/10/2012 09:48:24 (MP:000-726.70, DOT:340186D) [ 1 at ]

**Updated** 03/10/2012 09:50:40 **by** David Hofer **Dept** Signals **IT+** .Other Failure  
Smart alarm of AC power off for over twenty minutes. Yellow 4 Dispatch during business day (Monday - Friday 0700-1500). Resolve by the end of next business day. Should not involve overtime. Use deferment procedure after business hours. Maintainer must obtain protection if the crossing is not working as designed upon arrival.

**Updated** 03/10/2012 09:50:46 **by** David Hofer **Dept** Signals **IT+** .Other Failure  
A email notification for Multi Failure Count (MFC) asset LAMEUSE ST. (3) has been sent to the following:  
Terrence Smale II  
John Parr

**Closed** 03/12/2012 14:34:10 **by** Bruce McVey **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 03/12/2012 14:33:00 Equipment Type: Power/batteries Action Taken: Commercial Power Restored Suspected Reason: Outside party or vandalism power is on at location, did cks Operational Checks Performed

Page Execution Time: 002.69 seconds

**Magnolia Street**

**DOT Crossing #: 340189Y**

**RR Milepost #: 726.81**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 2

Status All AssetType All RootAssetType All AssetNum 340189Y

---

**Log#** [7511647](#)    **Status** Closed    **Entered** 02-09-2016 09:15:23    **by** Crews Jr, Aaron    **Type** Track & Time  
**Supv** Power, C    **Reg** SO    **Div** AT    **Sub** NM    **IRI** 0    **Milepost** 000 726.8    **Block** 2762  
**Section** 7660-NOandM SUB. TRACK INSPECTOR    **Asset** MAGNOLIA ST    **AssetNum** 340189Y    **Maintainer** May, J A - ETA: 09:16  
**Description** 02/09/2016 09:15:23    **by** Aaron Crews Jr    **Dept** Engineering    **IT+** Unknown  
**Updated** 02/09/2016 09:16:32    **by** Aaron Crews Jr    **Dept** Engineering    **IT+** Track & Time  
Sperry 950 is at MP 000 726.8 has 35mins track and time delay. Waiting on 1NB 2SB.  
**Updated** 02/09/2016 09:16:52    **by** Aaron Crews Jr    **Dept** Engineering    **IT+** Track & Time  
Status changed to Dispatched for Jeromy May ETA of: N/A  
**Updated** 02/09/2016 09:20:00    **by** TCIS AUTOMATION    **Dept** Engineering    **IT+** Track & Time  
ETA time reached Status changed to Active  
**Updated** 02/09/2016 09:53:58    **by** Aaron Crews Jr    **Dept** Engineering    **IT+** Track & Time  
Still waiting for track time.  
**Closed** 02/09/2016 17:19:15    **by** Angelo Donegan    **Dept** Engineering    **IT+** Track & Time  
Incident Resolved: 02/09/2016 17:19:00 Equipment Type: Track & Time Action Taken: Testing Day Complete  
TEST DAY COMPLETE Operational Checks Performed

---

**Log#** [7296076](#)    **Status** Closed    **Entered** 08-27-2015 11:52:42    **by** Bailey, Doug    **Type** Vehicle on Track  
**Supv** Power, C    **Reg** SO    **Div** AT    **Sub** NM    **IRI** 0    **Milepost** 000 726.8    **Block** 2762  
**Section** 7660-NOandM SUB. TRACK INSPECTOR    **Asset** MAGNOLIA ST    **AssetNum** 340189Y    **Maintainer** Barber, R - ETA: 12:02  
**Description** 08/27/2015 11:52:42    **by** Douglas Bailey    **Dept** Engineering    **IT+** Unknown  
**Updated** 08/27/2015 11:52:51    **by** Douglas Bailey    **Dept** Engineering    **IT+** Vehicle on Track  
TRUCK WAS STUCK ON TRACK AT MAGNOLIA ST 000726.8  
**Updated** 08/27/2015 12:02:55    **by** Douglas Bailey    **Dept** Engineering    **IT+** Vehicle on Track  
Status changed to Dispatched for Ryan Barber ETA of: N/A  
**Updated** 08/27/2015 12:05:00    **by** TCIS AUTOMATION    **Dept** Engineering    **IT+** Vehicle on Track  
ETA time reached Status changed to Active  
**Closed** 08/27/2015 15:14:15    **by** Douglas Bailey    **Dept** Engineering    **IT+** Vehicle on Track  
Incident Resolved: 08/27/2015 15:14:00 Equipment Type: Track Action Taken: Inspected - No Track Issues  
Track inspected, no damage Operational Checks Performed

Page Execution Time: 002.32 seconds



**Reynoir Street**

**DOT Crossing #: 340190T**

**RR Milepost #: 726.89**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 6

Status All AssetType All RootAssetType All Department Signals AssetNum 340190T

---

**Log#** [6564771](#) **Status** Closed **Entered** 04-05-2014 12:29:03 **by** Miller, Vern **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 726.9 **Block** 2762  
**Section** 3090-Ocean Springs **Asset** REYNOIR ST **AssetNum** 340190T **Maintainer** Houck, B - ETA: 13:53  
**Description** 04/05/2014 12:29:03 **by** Verlon Miller **Dept** Signals **IT+** Unknown  
**Updated** 04/05/2014 12:30:09 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
crossing activated, no train around. dispatcher notified to protect with false/partial activation protection. vern Asset: REYNOIR ST Status  
Changed To: Out Of Service PCC Notification Sent 04/05/2014 12:30:09  
**Updated** 04/05/2014 12:30:26 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
. Notification Sent to -Signal Control Center - Atlanta at 04/05/2014 12:30:26  
**Updated** 04/05/2014 12:38:06 **by** Alexis Romine **Dept** PSCC **IT+**  
**Contacted On** **Agency** p.d. **Contact Name** sara **Phone** 228 392 0641  
Reporting party has been verified as the responsible law enforcement agency.  
**Updated** 04/05/2014 12:53:55 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Bradley Houck ETA of: 13:53  
**Updated** 04/05/2014 13:55:02 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active  
**Updated** 04/05/2014 16:05:57 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Mntr on-site. MOW working in area, holding 707 over trk seg.  
**Closed** 04/05/2014 16:44:54 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 04/05/2014 16:34:00 Equipment Type: Gate Mechanism Action Taken: Replaced component(s)  
Mntr replaced D con cd in west gate mech. Performed op checks, turned crossing backover to disp.  
Operational Checks Performed Asset: REYNOIR ST Status Changed To: In Service PCC Notification Sent 04/05/2014 16:44:54  
**Updated** 04/05/2014 16:47:15 **by** Jesse Gansen **Dept** PSCC **IT+**  
**Contacted On** 04-05-2014 16:46:00 **Agency** Biloxi Polixce Department **Contact Name** Courtney **Phone** 228 392 0641

---

**Log#** [6554069](#) **Status** Closed **Entered** 03-29-2014 11:24:07 **by** Lewis, Wendell **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.9 **Block** 2762  
**Section** 3090-Ocean Springs **Asset** REYNOIR ST **AssetNum** 340190T **Maintainer** Patterson Jr, L D - ETA: 14:28  
**Description** 03/29/2014 11:24:07 **by** Wendell Lewis **Dept** Signals **IT+** Unknown  
**Updated** 03/29/2014 11:28:59 **by** Wendell Lewis **Dept** Signals **IT+** .False or partial activation reported  
11:20 X-ING FLASHERS ACTIVATED WITH THE N. SIDE GATE STUCK DOWN AND NO TRAIN....NOTIFIED AA-DISP.  
TO PROTECT F/P ACTIVATION. Notification Sent to -Signal Control Center - Atlanta at 03/29/2014 11:28:59 Asset:  
REYNOIR ST Status Changed To: Out Of Service PCC Notification Sent 03/29/2014 11:28:59  
**Updated** 03/29/2014 11:43:29 **by** Christina Martorano **Dept** PSCC **IT+**  
**Contacted On** 03-29-2014 11:41:00 **Agency** Biloxi Police **Contact Name** 315 **Phone** 228-392-0641  
@ Esters Blvd  
**Updated** 03/29/2014 12:58:31 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Leonard Patterson Jr ETA of: 14:28

**Updated** 03/29/2014 14:30:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 03/29/2014 17:30:58 **by** Leonard Patterson Jr **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 03/29/2014 17:30:00 Equipment Type: Gate Mechanism Action Taken: Repaired/Replaced Motor Control  
Replaced Gate Controller Module in southwest S-60 Gate Mechanism. Operational Checks Performed Asset: REYNOIR ST  
Status Changed To: In Service PCC Notification Sent 03/29/2014 17:30:58

**Updated** 03/29/2014 17:38:32 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** 03-29-2014 17:38:00 **Agency** Biloxi Police **Contact Name** Jennifer **Phone** 228-392-0641

---

**Log#** [6449471](#) **Status** Closed **Entered** 01-18-2014 11:51:56 **by** Jackson Jr, Marv **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.9 **Block** 2762

**Section** 3090-Ocean Springs **Asset** REYNOIR ST **AssetNum** 340190T **Maintainer** Houck, B - *ETA: 13:51*

**Description** 01/18/2014 11:51:56 **by** Marv Jackson Jr **Dept** Signals **IT+** Unknown

**Updated** 01/18/2014 11:54:02 **by** Marv Jackson Jr **Dept** Signals **IT+** .False or partial activation reported  
OSP REPORTED FALSE ACTIVATION AT REYNOIR ST... Notification Sent to -Signal Control Center - Atlanta at 01/18/2014  
11:54:02 Asset: REYNOIR ST Status Changed To: Out Of Service PCC Notification Sent 01/18/2014 11:54:02

**Updated** 01/18/2014 12:01:23 **by** Robert Clendening **Dept** PSCC **IT+**  
**Contacted On** 01-18-2014 12:00:00 **Agency** Biloxi Police Department **Contact Name** 315 **Phone** 228-392-0641  
@ Esters Blvd.

**Updated** 01/18/2014 12:12:04 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Bradley Houck ETA of: 13:51

**Closed** 01/18/2014 13:14:20 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 01/18/2014 13:13:00 Equipment Type: Gate Mechanism Action Taken: Repaired/Replaced Contacts

**Employee:** B. Houck

- high res gold nut on the west gate... test link for the slot...

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: REYNOIR ST Status Changed To: In Service PCC Notification Sent 01/18/2014 13:14:20

**Updated** 01/18/2014 13:17:54 **by** Robert Clendening **Dept** PSCC **IT+**  
**Contacted On** 01-18-2014 13:17:00 **Agency** Biloxi Police Department **Contact Name** 3289 **Phone** 228-392-0641  
@ Esters Blvd.

---

**Log#** [6266660](#) **Status** Closed **Entered** 08-27-2013 14:17:00 **by** Jackson Jr, Marvin **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.9 **Block** 2762

**Section** 3090-Ocean Springs **Asset** REYNOIR ST **AssetNum** 340190T **Maintainer** Stanfill, M O - *ETA: 14:41*

**Description** 08/27/2013 14:17:00 **by** Marv Jackson Jr **Dept** Signals **IT+** Unknown

**Updated** 08/27/2013 14:26:22 **by** Marv Jackson Jr **Dept** Signals **IT+** .False or partial activation reported  
CSX EMPLOYEE REPORTED AFTER S/B TRAIN CLEARED REYNOIR STREET....XING REACTIVATED FOR 1-MIN THEN  
CLEARED UP(POSSIBLE TAIL RING)..PROTECTING AS FALSE PARTIAL. Notification Sent to -Signal Control Center - Atlanta at  
08/27/2013 14:26:22 Asset: REYNOIR ST Status Changed To: Out Of Service PCC Notification Sent 08/27/2013 14:26:22

**Updated** 08/27/2013 14:27:06 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
NB Q57227 in the approach at time of report

**Updated** 08/27/2013 14:33:08 **by** Tanya Joson **Dept** PSCC **IT+**  
**Contacted On** 08-27-2013 14:33:00 **Agency** Biloxi Police Department **Contact Name** Jody 3289 **Phone** 228-392-0641

**Closed** 08/27/2013 14:39:51 by Jason Gothard Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 08/27/2013 14:39:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended mnter was performing tests at Lameuse street which caused this xing to activate. made op checks and ret to disp Operational Checks Performed  
Asset: REYNOIR ST Status Changed To: In Service PCC Notification Sent 08/27/2013 14:39:51

**Updated** 08/27/2013 14:46:26 by Kihron Bristol Dept PSCC IT+  
**Contacted On** 08-27-2013 14:46:00 Agency Biloxi Police Department Contact Name jody Phone 228-392-0641

---

**Log#** [6106559](#) **Status** Closed **Entered** 05-03-2013 10:01:52 **by** Kite, Matt **Type** Train-vehicle collision  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.9 **Block** 2762  
**Section** 3090-Ocean Springs **Asset** REYNOIR ST **AssetNum** 340190T **Maintainer** Stanfill, M O - ETA: 10:09  
**Description** 05/03/2013 10:01:52 **by** Matthew Kite **Dept** Signals **IT+** Unknown  
**Updated** 05/03/2013 10:07:50 **by** Matthew Kite **Dept** Signals **IT+** Train-vehicle collision

atl acd, aa disp, nm sub, loc 2762: Q57902 struck a vehicle at Reynoir St, mp 000 726.89 - COPIED.  
Asset: REYNOIR ST Status Changed To: Out Of Service PCC Notification Sent 05/03/2013 10:07:50

**Updated** 05/03/2013 10:07:53 **by** Matthew Kite **Dept** Signals **IT+** Train-vehicle collision  
Notification has been sent to the following: George James Jr Danny McKenzie Jody Cox C Manager

**Updated** 05/03/2013 10:09:56 **by** Matthew Kite **Dept** Signals **IT+** Train-vehicle collision  
Status changed to Dispatched for Michael Stanfill ETA of: N/A

**Updated** 05/03/2013 10:10:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Train-vehicle collision  
ETA time reached Status changed to Active

**Updated** 05/03/2013 10:11:55 **by** Matthew Kite **Dept** Signals **IT+** Train-vehicle collision

Mnter on-site, reports train struck trailer, wiped out west gate mech and cantilever. No report of any injuries.

**Updated** 05/03/2013 10:15:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Train-vehicle collision  
ETA time reached Status changed to Active

**Updated** 05/03/2013 10:18:56 **by** Matthew Kite **Dept** Signals **IT+** Train-vehicle collision

1. **Train involved:** Q57902
2. **Direction of travel:** South
3. **Estimated speed:** UNK
4. **Subdivision:** NM - NO&M
5. **Timetable speed:** 45 MPH
6. **Number of occupants/injuries:** 2 train crew, 1 driver - no injuries
7. **Number of fatalities:** 0
8. **Milepost:** 000 726.8 **DOT:** 340190T
9. **Crossing protection (gates, flashers, bells, cantilevers, etc.):** Bells, Flashers, and Gates
10. **Crossing controller equipment (PMD3, GCP 4000, etc.):** GCP-3000
11. **Damage to crossing, if any:** Wiped out west gate mech and cantilever
12. **Date last inspected (can be pulled from Raildocs):** 04-04-13

**Updated** 05/03/2013 10:23:39 **by** Matthew Kite **Dept** Signals **IT+** Train-vehicle collision

Disp prot with A/F #22942. Mnter on-site.

**Updated** 05/03/2013 14:44:08 **by** Matthew Kite **Dept** Signals **IT+** Train-vehicle collision

Mnter reports placing new gate and mast/lights at crossing. Should be BIS around 1900.

**Updated** 05/03/2013 16:49:57 **by** Louis Rosenblatt **Dept** Signals **IT+** Train-vehicle collision

**Update** - The Signal Maintainers are installing a new gate. They have about an hour more of work to be done.  
LVR

**Closed** 05/03/2013 17:47:05 **by** Louis Rosenblatt **Dept** Signals **IT+** Train-vehicle collision  
Incident Resolved: 05/03/2013 17:39:00 Equipment Type: Gate mechanism Action Taken: Replaced entire unit

**The Signal Maintainer reported completing the replacement of the West side Gate Mechanism Assembly. An annual test was performed at the crossing. The starts were confirmed as correct. The lamp voltages were checked. Everything on the crossing is working as intended. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: REYNOIR ST Status Changed To: In Service PCC Notification Sent  
05/03/2013 17:47:05

---

**Log#** [5960276](#) **Status** Closed **Entered** 01-26-2013 14:31:44 **by** Miller, Vern **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.9 **Block** 2762  
**Section** 3090-Ocean Springs **Asset** REYNOIR ST **AssetNum** 340190T **Maintainer** Houck, B - ETA: 15:43  
**Description** 01/26/2013 14:32:46 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
gates going up and down, no train around. dispatcher notified to protect with false/partial activation protection. vern Asset: REYNOIR ST  
Status Changed To: Out Of Service PCC Notification Sent 01/26/2013 14:32:46  
**Updated** 01/26/2013 14:32:58 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
. Notification Sent to -Signal Control Center - Atlanta at 01/26/2013 14:32:58  
**Updated** 01/26/2013 14:35:52 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for ETA of: 15:05  
**Updated** 01/26/2013 14:40:18 **by** Jerome Shepard **Dept** PSCC **IT+**  
**Contacted On** 01-26-2013 14:40:00 **Agency** Biloxi Police Department **Contact Name** Operator **Phone** 228-392-0641  
@ Esters Blvd  
**Updated** 01/26/2013 14:43:22 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for ETA of: 15:43  
**Updated** 01/26/2013 15:10:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active  
**Closed** 01/26/2013 15:43:32 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 01/26/2013 15:41:00 Equipment Type: Track Action Taken: Repaired/replaced track/bond wire  
Mntr repaired broken island wire, south end. MOW gang working in area. Performed op checks, turned crossing backover to disp.  
Operational Checks Performed Asset: REYNOIR ST Status Changed To: In Service PCC Notification Sent 01/26/2013 15:43:32  
**Updated** 01/26/2013 15:52:50 **by** Tanya Joson **Dept** PSCC **IT+**  
**Contacted On** 01-26-2013 15:52:00 **Agency** Biloxi Police Department **Contact Name** Operator Donna **Phone** 228-392-0641

Page Execution Time: 002.12 seconds

**Caillavet Street**

**DOT Crossing #: 340191A**

**RR Milepost #: 727.01**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 28

Status All AssetType All RootAssetType All Department Signals AssetNum 340191A

---

**Log#** [7898508](#) **Status** Closed **Entered** 11-24-2016 22:18:09 **by** Oglesby, Brad **Type** Vehicle on Track

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.0 **Block** 2763

**Section** 3090-7M16 **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Broadway, J L - *ETA*: 00:03

**Description** 11/24/2016 22:18:09 **by** Brad Oglesby **Dept** Signals **IT+** Unknown

**Updated** 11/24/2016 22:18:59 **by** Brad Oglesby **Dept** Signals **IT+** Vehicle on Track

Last Update 11-24-2016 22:15 By DRT Type General Business Impact 3 Priority 3 Incident Type: TRK Dispatch  
incident Number: 67973 Incident Date: 24-NOV-16 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000,  
0727.0000 Right Mile Post: 000, 0730.2851 Asset: 2763 003, Asset Name: MAIN PTC Flag: N Incident Description:  
CAR STUCK ON THE TRACK AT 000727.0 CAILLAVET STREET, NEED MAINTAINER AND TRACK INSPECTOR  
2218 ESS CONFIRMED THE AA DISPATCHER IS PROVIDING PROTECTION ON THE CROSSING AS PER  
ACTIVATION FAILURE STANDARD. Asset: CAILLAVET ST Status Changed To: Out Of Service PCC Notification  
Sent 11/24/2016 22:18:59

**Updated** 11/24/2016 22:23:41 **by** Emily Morton **Dept** PSCC **IT+**

**Contacted On** 11-24-2016 22:23:00 **Agency** Biloxi Police Department **Contact Name** Jennifer **Phone** 228-392-0641  
PSCC Incident Report - #7898498

**Updated** 11/24/2016 22:44:00 **by** Brad Oglesby **Dept** Signals **IT+** Vehicle on Track

Status changed to Dispatched for Joshua Broadway ETA of: 00:03

**Updated** 11/25/2016 00:05:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track

ETA time reached Status changed to Active

**Updated** 11/25/2016 00:16:31 **by** Joshua Broadway **Dept** Signals **IT+** Vehicle on Track

Incident Resolved: 11/25/2016 00:16:00 Equipment Type: Track Action Taken: Removed debris Vehicle removed  
from the crossing. No damage to signal equipment. Returned to service at 0014 dispatcher initial WCJ. Operational  
Checks Performed Asset: CAILLAVET ST Status Changed To: In Service PCC Notification Sent 11/25/2016 00:16:31

**Updated** 11/25/2016 00:17:38 **by** Sabrina Smith **Dept** PSCC **IT+**

**Contacted On** 11-25-2016 00:17:00 **Agency** Biloxi Police Department **Contact Name** Jennifer **Phone** 228-392-0641

**Closed** 11/25/2016 00:17:43 **by** David Mates **Dept** Signals **IT+** Vehicle on Track

Incident Resolved: 11/25/2016 00:16:00 Equipment Type: Track Action Taken: Removed debris Vehicle removed  
from the crossing. No damage to signal equipment. Returned to service at 0014 dispatcher initial WCJ. Operational  
Checks Performed

---

**Log#** [7773459](#) **Status** Closed **Entered** 08-24-2016 15:48:51 **by** Gaspar, Sean **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.0 **Block** 2763

**Section** 3090-7M16 **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Stanfill, M O - *ETA*: 17:23

**Description** 08/24/2016 15:48:51 **by** Sean Gaspar **Dept** Signals **IT+** Unknown

**Updated** 08/24/2016 15:52:37 **by** Sean Gaspar **Dept** Signals **IT+** .False or partial activation reported

gates up and lights flashing w/ no train. dot provided. disp protecting w/ f/p. Asset: CAILLAVET ST Status Changed To:  
Out Of Service PCC Notification Sent 08/24/2016 15:52:37



**Updated** 08/24/2016 16:02:54 **by** Waltina Edwards **Dept** PSCC **IT+**  
**Contacted On** **Agency** local police **Contact Name** eric **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 08/24/2016 16:08:30 **by** Gene Peaytt **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 17:23

**Updated** 08/24/2016 17:25:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 08/24/2016 17:46:43 **by** Michael Stanfill **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 08/24/2016 17:46:00 Equipment Type: Wiring/Protection Action Taken: Repaired/Replaced Protection  
Found 80013 relay drive module bad(lightning strike). Replaced module and replaced track lightning protection. Bad  
storms in area. Operational Checks Performed Asset: CAILLAVET ST Status Changed To: In Service PCC Notification  
Sent 08/24/2016 17:46:43

**Closed** 08/24/2016 17:48:25 **by** Richard Kondy **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 08/24/2016 17:46:00 Equipment Type: Wiring/Protection Action Taken: Repaired/Replaced Protection  
// Operational Checks Performed

**Closed** 08/24/2016 17:48:30 **by** Patrick Knotts **Dept** Signals **IT+** .False or partial activation reported  
Found 80013 relay drive module bad(lightning strike). Replaced module and replaced track lightning protection. Bad  
storms in area.

**Updated** 08/24/2016 17:52:15 **by** Waltina Edwards **Dept** PSCC **IT+**  
**Contacted On** 08-24-2016 17:51:00 **Agency** 911 **Contact Name** 2901 **Phone** 22839.20641

---

**Log#** [7641764](#) **Status** Closed **Entered** 05-17-2016 10:40:16 **by** Williams, Joseph **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.25 **Milepost** 000 727.0 **Block** 2763

**Section** 3090-7M16 **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Stanfill, M O - ETA: 12:25

**Description** 05/17/2016 10:40:16 **by** Joseph Williams **Dept** Signals **IT+** Unknown

**Updated** 05/17/2016 10:42:52 **by** Joseph Williams **Dept** Signals **IT+** .False or partial activation reported  
1040:Hr Biloxi Police reported that one of the gates are damaged at the crossing. 1041:Hr dispatcher notified. Notification  
Sent to -Signal Control Center - Atlanta at 05/17/2016 10:42:52 Asset: CAILLAVET ST Status Changed To: Out Of  
Service PCC Notification Sent 05/17/2016 10:42:52

**Updated** 05/17/2016 10:42:55 **by** Joseph Williams **Dept** Signals **IT+** .False or partial activation reported  
An email notification for (IRI) asset CAILLAVET ST (2) has been sent to the following:  
George James Jr

**Updated** 05/17/2016 10:46:10 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 12:25

**Updated** 05/17/2016 10:46:47 **by** Robert Clendening **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi Police **Contact Name** Sara **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 05/17/2016 12:30:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 05/17/2016 13:13:12 **by** Michael Stanfill **Dept** Signals **IT+** .False or partial activation reported

Incident Resolved: 05/17/2016 13:00:00 Equipment Type: Gate Action Taken: Repaired/replaced only gate light(s)  
UNABLE TO FIND REPORTED DAMAGE TIGHTEN SHEER PINS ON WEST GATE Operational Checks Performed  
Asset: CAILLAVET ST Status Changed To: In Service PCC Notification Sent 05/17/2016 13:13:12

**Updated** 05/17/2016 13:16:49 **by** Michael Stanfill **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 05/17/2016 13:15:00 Equipment Type: Gate Action Taken: Repaired/replaced only gate light(s)  
UNABLE TO FIND REPORTED DAMAGE / TIGHTEN SHEER PINS ON WEST GATE Operational Checks Performed

**Updated** 05/17/2016 13:17:40 **by** Christina Martorano **Dept** PSCC **IT+**  
**Contacted On** 05-17-2016 13:16:00 **Agency** Biloxi Police **Contact Name** 2292 **Phone** 228-392-0641

**Closed** 05/17/2016 13:20:40 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 05/17/2016 13:15:00 Equipment Type: Gate Action Taken: Repaired/replaced only gate light(s) closed  
Operational Checks Performed

---

**Log#** [7639067](#) **Status** Closed **Entered** 05-14-2016 21:49:57 **by** Kite, Matt **Type** .Other Failure

**Supv** Merritt, D **Reg SO** **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.0 **Block** 2763

**Section** 3090-7M16 **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Stanfill, M O - ETA: 23:38

**Description** 05/14/2016 21:49:57 **by** Matthew Kite **Dept** Signals **IT+** Unknown

**Updated** 05/14/2016 21:51:10 **by** Matthew Kite **Dept** Signals **IT+** .Other Failure

Incident Type: TRK Dispatch incident Number: 20579 Incident Date: 14-MAY-16 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000, 0727.0000  
Right Mile Post: 000, 0730.2851 Asset: 2763 003, Asset Name: MAIN PTC Flag: N Incident Description: SOUTHBOUND Q14513 HIT A  
PEDESTRIAN AT MP 000727.01 CAILLAVET STREET. NEED MAINTAINER AND TRACK INSPECTOR Copied frm DIRT. Disp prot with A/F  
#42414.

Asset: CAILLAVET ST Status Changed To: Out Of Service PCC Notification Sent 05/14/2016 21:51:10

**Updated** 05/14/2016 22:00:05 **by** Matthew Kite **Dept** Signals **IT+** .Other Failure

1. **Train involved:** Q14513
2. **Direction of travel:** South
3. **Estimated speed:** UNK
4. **Subdivision:** NM - NO&M
5. **Timetable speed:** 45 MPH
6. **Number of occupants/injuries:** 2 train crew no injuries/1 pedestrian struck
7. **Number of fatalities:** 1
8. **Milepost:** 000 727.01 **DOT:** 340191A **Name:** Caillavet St
9. **Crossing protection (gates, flashers, bells, cantilevers, etc.):** Bells, Flashers, and Gates
10. **Crossing controller equipment (PMD3, GCP 4000, etc.):** GCP-3000
11. **Damage to crossing, if any:** N/A
12. **Date last inspected (can be pulled from Raildocs):** NOT AVAILABLE

**Updated** 05/14/2016 22:04:32 **by** Matthew Kite **Dept** Signals **IT+** .Other Failure

Train crew took no exception to crossing. No vehicle involved, pedestrian appears to have walked out in-front of train.

**Updated** 05/14/2016 22:08:31 **by** Matthew Kite **Dept** Signals **IT+** .Other Failure  
Status changed to Dispatched for Michael Stanfill ETA of: 23:38

**Updated** 05/14/2016 22:13:46 **by** Matthew Kite **Dept** Signals **IT+** .Other Failure

Notified NOC C&S Manager, Sig Sup James, DE McKenzie and left VM for Asst Chief Eng Parr. Mntr en-route.

**Updated** 05/14/2016 22:17:39 **by** Jolene Woods **Dept** PSCC **IT+**  
**Contacted On** 05-14-2016 22:17:00 **Agency** Biloxi Police Department **Contact Name** PSCC Incident Report - Edit #7639035 **Phone** 228-392-0641

**Updated** 05/14/2016 23:40:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .Other Failure  
ETA time reached Status changed to Active

**Closed** 05/15/2016 01:02:31 **by** Jerry Rockhill **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 05/15/2016 00:59:00 Equipment Type: N/A Action Taken: NTF - UTD 0055 mtr reports downloaded all three ..deluxe report , field report and configuration report and sent to sig mgr g. james... 360 day inspection completed and no abnormalities or issues found... 12 gft... op cks ok and crossing back in service with disp.. Operational Checks Performed Asset: CAILLAVET ST Status Changed To: In Service PCC Notification Sent 05/15/2016 01:02:31

**Updated** 05/15/2016 01:10:58 **by** Thera Moore **Dept** PSCC **IT+**  
**Contacted On** 05-15-2016 01:10:00 **Agency** Biloxi Police Department **Contact Name** 3246 **Phone** 228-392-0641

---

**Log#** [7617413](#) **Status** Closed **Entered** 04-28-2016 11:13:52 **by** Meier, Jeremy **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 727.0 **Block** 2763

**Section** 3090-7M16 **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Stanfill, M O - ETA: 13:46

**Description** 04/28/2016 11:13:52 **by** Jeremy Meier **Dept** Signals **IT+** Unknown

**Updated** 04/28/2016 11:14:45 **by** Jeremy Meier **Dept** Signals **IT+** .False or partial activation reported  
DIRT: reports west gate broken AA Disp is protecting with an activation failure Asset: CAILLAVET ST Status Changed To: Out Of Service PCC Notification Sent 04/28/2016 11:14:45

**Updated** 04/28/2016 11:14:46 **by** Jeremy Meier **Dept** Signals **IT+** .False or partial activation reported  
An email notification for (IRI) asset CAILLAVET ST (1) has been sent to the following:  
George James Jr

**Updated** 04/28/2016 11:16:32 **by** Jeremy Meier **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 13:46

**Updated** 04/28/2016 11:34:53 **by** Waltina Edwards **Dept** PSCC **IT+**  
**Contacted On** 04-28-2016 11:33:00 **Agency** Biloxi police **Contact Name** 3 6 6 **Phone** 228-392-0641

**Updated** 04/28/2016 13:50:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 04/28/2016 16:02:39 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 04/28/2016 15:59:00 Equipment Type: Gate Action Taken: Damaged gate or sections-replaced/repared

**The Signal Maintainer replaced the second and third gate sections of the West gate. The Gate Descent time is 13 seconds. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: CAILLAVET ST Status Changed To: In Service PCC Notification Sent 04/28/2016 16:02:39

**Updated** 04/28/2016 16:39:47 **by** Waltina Edwards **Dept** PSCC **IT+**  
**Contacted On** 04-28-2016 16:37:00 **Agency** Police Department **Contact Name** 2901 **Phone** Phone# 228-392-0641

**Log# 7590646**    **Status Closed**    **Entered** 04-07-2016 13:33:22    **by** McClure, Dale    **Type** .False or partial activation reported  
**Supv** Merritt, D    **Reg** SO    **Div** AT    **Sub** NM    **IRI** 0    **Milepost** 000 727.0    **Block** 2763  
**Section** 3090-7M16    **Asset** CAILLAVET ST    **AssetNum** 340191A    **Maintainer** Stanfill, M O - ETA: 13:42  
**Description** 04/07/2016 13:33:22    **by** Dale McClure    **Dept** Signals    **IT+** Unknown  
**Updated** 04/07/2016 13:39:04    **by** Dale McClure    **Dept** Signals    **IT+** .False or partial activation reported  
POLICE REPORTING THESE 3 CROSSINGS ACTIVATED/ NO TRAINS PRESENT. TRACK DEPT. IN AREA. AA DISP. NOTIFIED  
AND INSTRUCTED TO PRTOECT ALL 3 AS FALSE/ PARTIAL ACTIVATION. Asset: CAILLAVET ST Status Changed To: Out Of  
Service PCC Notification Sent 04/07/2016 13:39:04  
**Updated** 04/07/2016 13:39:25    **by** Dale McClure    **Dept** Signals    **IT+** .False or partial activation reported  
New Asset Added: 340190T - REYNOIR ST  
**Updated** 04/07/2016 13:39:49    **by** Dale McClure    **Dept** Signals    **IT+** .False or partial activation reported  
New Asset Added: 340186D - LAMEUSE ST.  
**Updated** 04/07/2016 13:40:07    **by** Dale McClure    **Dept** Signals    **IT+** .False or partial activation reported  
PCC Notification Sent 04/07/2016 13:40:07 Asset: 340186D - LAMEUSE ST. Status Changed To: Out of Service  
**Updated** 04/07/2016 13:40:11    **by** Dale McClure    **Dept** Signals    **IT+** .False or partial activation reported  
PCC Notification Sent 04/07/2016 13:40:11 Asset: 340190T - REYNOIR ST Status Changed To: Out of Service  
**Updated** 04/07/2016 13:42:41    **by** Dale McClure    **Dept** Signals    **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: N/A  
**Updated** 04/07/2016 13:43:20    **by** Jolene Woods    **Dept** PSCC    **IT+**  
**Contacted On**    **Agency** BOLOXI    **Contact Name** BRENDA (POLICE) **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.  
**Updated** 04/07/2016 13:45:00    **by** TCIS AUTOMATION **Dept** Signals    **IT+** .False or partial activation reported  
ETA time reached Status changed to Active  
**Closed** 04/07/2016 15:08:38    **by** Louis Rosenblatt    **Dept** Signals    **IT+** .False or partial activation reported  
Incident Resolved: 04/07/2016 14:57:00 Equipment Type: N/A Action Taken: Track Occupied

**The Signal Maintainer reported that Welders were working on the Approach Circuit at Lameuse Street. Nothing was found to be wrong with the crossings. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: CAILLAVET ST Status Changed To: In Service PCC Notification Sent 04/07/2016 15:08:38 Asset: LAMEUSE ST. Status Changed To: In Service PCC Notification Sent 04/07/2016 15:08:38 Asset: REYNOIR ST Status Changed To: In Service PCC Notification Sent 04/07/2016 15:08:38

**Updated** 04/07/2016 15:25:49    **by** Alexis Romine    **Dept** PSCC    **IT+**  
**Contacted On** 04-07-2016 15:25:00 **Agency** BOLOXI    **Contact Name** KRISTIN    **Phone** 228-392-0641

**Log# 7464443**    **Status Closed**    **Entered** 01-05-2016 12:07:54    **by** McClure, Dale    **Type** .False or partial activation reported  
**Supv** Merritt, D    **Reg** SO    **Div** AT    **Sub** NM    **IRI** 0.25    **Milepost** 000 727.0    **Block** 2763  
**Section** 3090-7M16    **Asset** CAILLAVET ST    **AssetNum** 340191A    **Maintainer** Stanfill, M O - ETA: 13:21  
**Description** 01/05/2016 12:07:54    **by** Dale McClure    **Dept** Signals    **IT+** Unknown  
**Updated** 01/05/2016 12:12:44    **by** Dale McClure    **Dept** Signals    **IT+** .False or partial activation reported

POLICE REPORTING THIS CROSSING ACTIVATED/ NO TRAINS PRESENT. AA DISP. NOTIFIED AND INSTRUCTED TO PROTECT AS FALSE/ PARTIAL ACTIVATION. Asset: CAILLAVET ST Status Changed To: Out Of Service PCC Notification Sent 01/05/2016 12:12:44

**Updated** 01/05/2016 12:12:45 **by** Dale McClure **Dept** Signals **IT+** .False or partial activation reported  
An email notification for (IRI) asset CAILLAVET ST (.25) has been sent to the following:  
George James Jr

**Updated** 01/05/2016 12:14:40 **by** Avie Saunders **Dept** PSCC **IT+**  
**Contacted On** 01-05-2016 12:13:00 **Agency** Biloxi Police Department **Contact Name** 347 **Phone** 228-392-0641  
Esters Blvd

**Updated** 01/05/2016 12:21:53 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 13:21

**Updated** 01/05/2016 13:25:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 01/05/2016 13:54:03 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 01/05/2016 12:53:00 Equipment Type: N/A Action Taken: NTF - UTD

**Employee:** M. Stanfill

- mtr testing adjoining xing at time of incident....

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: CAILLAVET ST Status Changed To: In Service PCC Notification Sent 01/05/2016 13:54:03

**Updated** 01/05/2016 14:02:15 **by** Waltina Edwards **Dept** PSCC **IT+**  
**Contacted On** 01-05-2016 14:02:00 **Agency** Police Department **Contact Name** 308 **Phone** Phone# 228-392-0641

---

**Log#** [7456003](#) **Status** Closed **Entered** 12-28-2015 16:41:19 **by** Oglesby, Brad **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 727.0 **Block** 2763

**Section** 3090-7M16 **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Stanfill, M O - ETA: 17:44

**Description** 12/28/2015 16:41:19 **by** Brad Oglesby **Dept** Signals **IT+** Unknown

**Updated** 12/28/2015 16:43:56 **by** Brad Oglesby **Dept** Signals **IT+** .False or partial activation reported  
1641 AN OUTSIDE PARTY CLAIMED THE CROSSING IS ACTIVATED WITHOUT ANY TRAINS PRESENT(DOT NUMBER PROVIDED). 1642 ESS ADVISED THE AA DISPATCHER(INITIALS-WCJ) TO PROVIDE PROTECTION ON THE CROSSING AS PER FALSE ACTIVATION STANDARD. Notification Sent to -Signal Control Center - Atlanta at 12/28/2015 16:43:56 Asset: CAILLAVET ST Status Changed To: Out Of Service PCC Notification Sent 12/28/2015 16:43:56

**Updated** 12/28/2015 16:43:57 **by** Brad Oglesby **Dept** Signals **IT+** .False or partial activation reported  
An email notification for (IRI) asset CAILLAVET ST (.125) has been sent to the following:  
George James Jr

**Updated** 12/28/2015 16:59:02 **by** Kareem Battle **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 17:44

**Updated** 12/28/2015 17:45:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 12/28/2015 18:34:36 **by** Alyson Trouba **Dept** PSCC **IT+**

**Contacted On** 12-28-2015 18:33:00 **Agency** Biloxi Police Department **Contact Name** 3501 **Phone** 228-392-0641  
Esters Blvd

**Closed** 12/28/2015 18:46:39 **by** Kareem Battle **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 12/28/2015 18:45:00 Equipment Type: Gate Action Taken: Damaged gate or sections-replaced/repared mntr  
had to replace the west gate, descent time 14 sec. all op checks performed Operational Checks Performed Asset: CAILLAVET ST  
Status Changed To: In Service PCC Notification Sent 12/28/2015 18:46:39

**Updated** 12/28/2015 20:16:56 **by** Alexis Romine **Dept** PSCC **IT+**  
**Contacted On** 12-28-2015 20:16:00 **Agency** Biloxi Police Department **Contact Name** 3501 **Phone** 228-392-0641  
Esters Blvd

---

**Log#** [7449073](#) **Status** Closed **Entered** 12-21-2015 22:39:43 **by** Foster, George **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.0 **Block** 2763

**Section** 3090-7M16 **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Stanfill, M O - ETA: 00:38

**Description** 12/21/2015 22:39:43 **by** George Foster **Dept** Signals **IT+** Unknown

**Updated** 12/21/2015 22:43:22 **by** George Foster **Dept** Signals **IT+** .False or partial activation reported  
Crossing activated with no trains in sight. Notification Sent to -Signal Control Center - Atlanta at 12/21/2015 22:43:22  
Asset: CAILLAVET ST Status Changed To: Out Of Service PCC Notification Sent 12/21/2015 22:43:22

**Updated** 12/21/2015 22:45:11 **by** Kiwana Tompkins **Dept** PSCC **IT+**  
**Contacted On** **Agency** 911 **Contact Name** 3501 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 12/21/2015 23:08:36 **by** David Price **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 00:38

**Updated** 12/22/2015 00:40:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 12/22/2015 02:33:58 **by** Donald Schreiner **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 12/22/2015 02:30:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced Track  
Card Replaced the transceiver card and lightning protection at the crossing and the 727 signal. All ops checks made with  
no exceptions taken. Back to the Dispatcher in service. Operational Checks Performed Asset: CAILLAVET ST Status  
Changed To: In Service PCC Notification Sent 12/22/2015 02:33:58

**Updated** 12/22/2015 02:34:54 **by** Kiwana Tompkins **Dept** PSCC **IT+**  
**Contacted On** 12-22-2015 02:34:00 **Agency** 911 **Contact Name** April **Phone** 228-392-0641

---

**Log#** [7239664](#) **Status** Closed **Entered** 07-19-2015 19:06:25 **by** Buksar, Jake **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.0 **Block** 2763

**Section** 3090-7M16 **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Stanfill, M O - ETA: 20:49

**Description** 07/19/2015 19:06:25 **by** Jacob Buksar **Dept** Signals **IT+** Unknown

**Updated** 07/19/2015 19:11:49 **by** Jacob Buksar **Dept** Signals **IT+** .False or partial activation reported  
Local PD reports crossing is activated with no trains present. Dispatcher protecting with a false partial. Notification Sent to -  
Signal Control Center - Atlanta at 07/19/2015 19:11:49 Asset: CAILLAVET ST Status Changed To: Out Of Service PCC  
Notification Sent 07/19/2015 19:11:49

**Updated** 07/19/2015 19:19:09 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 20:49

**Updated** 07/19/2015 19:30:21 **by** Kiwana Tompkins **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi PD **Contact Name** opr 3471 **Phone** 228 392 0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 07/19/2015 20:50:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 07/19/2015 21:09:10 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 07/19/2015 21:08:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced Track Card  
Mntr replaced transceiver cd due to lightning strike. Performed op checks, turned crossing backover to disp.  
Operational Checks Performed Asset: CAILLAVET ST Status Changed To: In Service PCC Notification Sent 07/19/2015  
21:09:10

**Updated** 07/19/2015 21:24:21 **by** Robert Clendening **Dept** PSCC **IT+**  
**Contacted On** 07-19-2015 21:23:00 **Agency** Biloxi PD **Contact Name** 2292 **Phone** 228 392 0641

---

**Log#** [7042987](#) **Status** Closed **Entered** 03-07-2015 18:57:52 **by** Tyo, Mark **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.0 **Block** 2763

**Section** 3090-7M16 **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Broadway, J L - ETA: 21:48

**Description** 03/07/2015 18:57:52 **by** Mark Tyo **Dept** Signals **IT+** Unknown

**Updated** 03/07/2015 19:03:46 **by** Mark Tyo **Dept** Signals **IT+** .False or partial activation reported  
Reported gates up and lights are flashing. Disp is protecting. Notification Sent to -Signal Control Center - Atlanta at  
03/07/2015 19:03:46 Asset: CAILLAVET ST Status Changed To: Out Of Service PCC Notification Sent 03/07/2015  
19:03:46

**Updated** 03/07/2015 19:26:19 **by** Christopher Joson **Dept** PSCC **IT+**  
**Contacted On** 03-07-2015 19:24:00 **Agency** Biloxi PD **Contact Name** Jackie **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 03/07/2015 20:18:37 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Joshua Broadway ETA of: 21:48

**Closed** 03/07/2015 21:17:28 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 03/07/2015 21:16:00 Equipment Type: N/A Action Taken: NTF - UTD  
Mntr reports crossing COA. Performed op checks, took no exception to sig equip, turned crossing backover to disp.  
Operational Checks Performed Asset: CAILLAVET ST Status Changed To: In Service PCC Notification Sent 03/07/2015  
21:17:28

**Updated** 03/07/2015 21:21:02 **by** Michele Schwartz **Dept** PSCC **IT+**  
**Contacted On** 03-07-2015 21:20:00 **Agency** Biloxi PD **Contact Name** 3235 **Phone** 228-392-0641

---

**Log#** [6981797](#) **Status** Closed **Entered** 01-28-2015 15:30:46 **by** Oglesby, Brad **Type** -Informational

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.0 **Block** 2763

**Section** 3090-7M16 **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Stanfill, M O - ETA: 15:39

**Description** 01/28/2015 15:30:46 **by** Brad Oglesby **Dept** Signals **IT+** Unknown



**Updated** 01/28/2015 15:35:48 **by** Brad Oglesby **Dept** Signals **IT+** -Informational  
1530 TELLCSX REPORTED RECEIVING A NOTICE FROM AN OUTSIDE PARTY ALLEGING THAT ONE  
CROSSING ARM CAME DOWN ON THEIR VEHICLE EARLIER TODAY(APPROXIMATELY 1345) AS ROADWAY  
PERSONNEL WERE WORKING IN THE AREA(DOT NUMBER PROVIDED). TELLCSX REPORTED THAT  
OUTSIDE PARTY ALLEGED THE CROSSING ARM "MALFUNCTION" DAMAGED OUTSIDE PARTY'S VEHICLE.  
1533 ESS ADVISED THE AA DISPATCHER(INITIALS-WJS) TO PROVIDE PROTECTION ON THE CROSSING  
AS PER FALSE ACTIVATION STANDARD. Notification Sent to -Signal Control Center - Atlanta at 01/28/2015  
15:35:48 Asset: CAILLAVET ST Status Changed To: Out Of Service PCC Notification Sent 01/28/2015 15:35:48

**Updated** 01/28/2015 15:37:43 **by** Avie Saunders **Dept** PSCC **IT+**  
**Contacted On** 01-28-2015 15:36:00 **Agency** Biloxi Police Department **Contact Name** Eric **Phone** 228-392-0641  
Esters Blvd

**Updated** 01/28/2015 15:39:48 **by** Louis Rosenblatt **Dept** Signals **IT+** -Informational  
Status changed to Dispatched for Michael Stanfill ETA of: N/A

**Updated** 01/28/2015 15:40:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** -Informational  
ETA time reached Status changed to Active

**Closed** 01/28/2015 15:41:45 **by** Louis Rosenblatt **Dept** Signals **IT+** -Informational  
Incident Resolved: 01/28/2015 15:39:00 Equipment Type: N/A Action Taken: Track Occupied

**The Signal Maintainer reported that he was performing tests on the crossing at the time and that the  
Outside Party drove under the gate. He spoke to the outside party previously today. The Maintainer  
reported that the crossing is working properly. Operational Checks were performed. The Crossing was  
placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: CAILLAVET ST Status Changed To: In Service PCC Notification Sent  
01/28/2015 15:41:45

**Updated** 01/28/2015 15:56:38 **by** Waltina Edwards **Dept** PSCC **IT+**  
**Contacted On** 01-28-2015 15:56:00 **Agency** Biloxi Police Department **Contact Name** 3235. **Phone** 228-392-0641

---

**Log#** [6896451](#) **Status** Closed **Entered** 11-24-2014 13:47:07 **by** Wilburn, Marion **Type** .False or partial activation reported

**Supv** Merritt, D **Reg SO** **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.0 **Block** 2763

**Section** 3090-7M16 **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Stanfill, M O - ETA: 15:34

**Description** 11/24/2014 13:47:07 **by** Marion Wilburn **Dept** Signals **IT+** Unknown

**Updated** 11/24/2014 13:51:01 **by** Marion Wilburn **Dept** Signals **IT+** .False or partial activation reported  
1349 Hrs. 911-center reports crossing is activated with no train present, AA-dispatcher-ADS has been notified to protect crossing as  
f/a. Notification Sent to -Signal Control Center - Atlanta at 11/24/2014 13:51:01 Asset: CAILLAVET ST Status Changed To: Out Of  
Service PCC Notification Sent 11/24/2014 13:51:01

**Updated** 11/24/2014 13:53:02 **by** Marvin Smoot **Dept** PSCC **IT+**  
**Contacted On** **Agency** 911-center **Contact Name** Operator 352 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 11/24/2014 13:55:25 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 15:34

**Updated** 11/24/2014 15:35:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 11/24/2014 16:15:40 by Jason Gothard Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 11/24/2014 16:15:00 Equipment Type: Gate Mechanism Action Taken: Realigned gate mech west gate mech hit  
by outside party. re-aligned gate mech, made op checks and ret to disp Operational Checks Performed Asset: CAILLAVET ST Status  
Changed To: In Service PCC Notification Sent 11/24/2014 16:15:40

**Updated** 11/24/2014 16:21:12 by Kiwana Tompkins Dept PSCC IT+  
**Contacted On** 11-24-2014 16:20:00 Agency 911-center **Contact Name** Dispatcher 2901 **Phone** 228-392-0641

---

**Log#** [6535676](#) **Status** Closed **Entered** 03-16-2014 09:29:45 by McVey, Bruce **Type** Vehicle Collision On Crossing  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.0 **Block** 2763  
**Section** 3090-Ocean Springs **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Brown, K L - ETA: 15:34 & Lumpkin, K J - ETA: 15:35  
**Description** 03/16/2014 09:29:45 by Bruce McVey Dept Signals IT+ Unknown  
**Updated** 03/16/2014 09:30:30 by Bruce McVey Dept Signals IT+ Vehicle Collision On Crossing

ATL CTD

- Notification:

ATL ACD, AA Disp, NM Sub, Loc 2763; PSCC reported vehicle accident on tracks at mp 000727.0, Caillavet Street.  
:COPIED

Asset: CAILLAVET ST Status Changed To: Out Of Service PCC Notification Sent 03/16/2014 09:30:30

**Updated** 03/16/2014 09:43:45 by Bruce McVey Dept Signals IT+ Vehicle Collision On Crossing

Storms in area with heavy rains at time of incident (WIND WARNING also).

**Updated** 03/16/2014 10:07:29 by Bruce McVey Dept Signals IT+ Vehicle Collision On Crossing  
Several warning in area, will hold tix till weather breaks some(safer to travel to location)

**Updated** 03/16/2014 12:13:54 by Bruce McVey Dept Signals IT+ Vehicle Collision On Crossing  
Status changed to Dispatched for Claudell Wilson ETA of: 16:13

**Updated** 03/16/2014 15:35:01 by TCIS AUTOMATION Dept Signals IT+ Vehicle Collision On Crossing  
ETA time reached Status changed to Active

**Closed** 03/16/2014 15:43:49 by Richard Kondy Dept Signals IT+ Vehicle Collision On Crossing  
Incident Resolved: 03/16/2014 15:43:00 Equipment Type: N/A Action Taken: NTF - UTD no signal damage . made all op  
checks . Operational Checks Performed Asset: CAILLAVET ST Status Changed To: In Service PCC Notification Sent  
03/16/2014 15:43:49

**Updated** 03/16/2014 16:24:26 by Misty Hunter Dept PSCC IT+  
**Contacted On** 03-16-2014 16:23:00 Agency Biloxi Police Department **Contact Name** 366 **Phone** 228-392-0641  
Esters Blvd

---

**Log#** [6511462](#) **Status** Closed **Entered** 02-27-2014 15:11:37 by Kondy, Rick **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.5 **Milepost** 000 727.0 **Block** 2763  
**Section** 3090-Ocean Springs **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Stanfill, M O - ETA: 15:26  
**Description** 02/27/2014 15:11:37 by Richard Kondy Dept Signals IT+ Unknown

**Updated** 02/27/2014 15:14:14 **by** Richard Kondy **Dept** Signals **IT+** .False or partial activation reported  
gates down , no trains . disp protecting crossing with false activation # 28255 . Notification Sent to -Signal Control Center - Atlanta at  
02/27/2014 15:14:14 Asset: CAILLAVET ST Status Changed To: Out Of Service PCC Notification Sent 02/27/2014 15:14:14

**Updated** 02/27/2014 15:14:17 **by** Richard Kondy **Dept** Signals **IT+** .False or partial activation reported  
An email notification for Multi Failure Count (MFC) asset CAILLAVET ST (3) has been sent to the following:  
George James Jr  
Danny McKenzie

**Updated** 02/27/2014 15:26:10 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: N/A

**Updated** 02/27/2014 15:30:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 02/27/2014 15:33:12 **by** Avie Saunders **Dept** PSCC **IT+**  
**Contacted On** 02-27-2014 15:33:00 **Agency** 228-392-0641 **Contact Name** \\  
**Phone** Biloxi Police Depart

**Closed** 02/27/2014 15:46:54 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 02/27/2014 15:46:00 Equipment Type: N/A Action Taken: NTF - UTD  
Mntr reports crossing COA. Performed op checks, took no exception to sig equip. Turned crossing backover to disp.  
Operational Checks Performed Asset: CAILLAVET ST Status Changed To: In Service PCC Notification Sent 02/27/2014 15:46:54

**Updated** 02/27/2014 17:07:05 **by** Jerome Shepard **Dept** PSCC **IT+**  
**Contacted On** 02-27-2014 17:07:00 **Agency** Biloxi Police Depart **Contact Name** Operator Kayla **Phone** 228-392-0641

---

**Log#** [6502057](#) **Status** Closed **Entered** 02-21-2014 06:06:05 **by** Rockhill, Jerry **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.25 **Milepost** 000 727.0 **Block** 2763

**Section** 3090-Ocean Springs **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Houck, B - ETA: 06:21

**Description** 02/21/2014 06:06:05 **by** Jerry Rockhill **Dept** Signals **IT+** Unknown

**Updated** 02/21/2014 06:08:14 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
0606 atl chief, aa disp, nm sub, gates broken off of Caillavet Street at mp 000727.0 disp msg 17473 Asset: CAILLAVET ST Status  
Changed To: Out Of Service PCC Notification Sent 02/21/2014 06:08:14

**Updated** 02/21/2014 06:20:12 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Bradley Houck ETA of: 06:21

**Updated** 02/21/2014 06:21:51 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
0621 mtr reports searching for parts....

**Updated** 02/21/2014 06:25:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 02/21/2014 06:27:41 **by** Alexis Romine **Dept** PSCC **IT+**  
**Contacted On** 02-21-2014 06:26:00 **Agency** Biloxi Police Department **Contact Name** Operator 364 **Phone** 228-392-0641  
@ Esters Blvd

**Closed** 02/21/2014 09:35:01 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 02/21/2014 09:35:00 Equipment Type: Gate Action Taken: Damaged gate or sections-replaced/repared broken gate  
and wind guard and flasher arm. replaced all and made op checks, ret to disp. Operational Checks Performed Asset: CAILLAVET ST  
Status Changed To: In Service PCC Notification Sent 02/21/2014 09:35:01

**Updated** 02/21/2014 09:37:21 **by** Max Todd **Dept** PSCC **IT+**  
**Contacted On** 02-21-2014 09:36:00 **Agency** Biloxi Police Department **Contact Name** 347 **Phone** 228-392-0641  
at Esters Blvd.

---

**Log#** [6470482](#) **Status** Closed **Entered** 01-31-2014 14:08:51 **by** Jackson Jr, Marv **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 727.0 **Block** 2763

**Section** 3090-Ocean Springs **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Stanfill, M O - ETA: 14:43

**Description** 01/31/2014 14:08:51 **by** Marv Jackson Jr **Dept** Signals **IT+** Unknown

**Updated** 01/31/2014 14:11:10 **by** Marv Jackson Jr **Dept** Signals **IT+** .False or partial activation reported  
OSP REPORTED FALSE ACTIVATION AT CAILLAVET STREET..... Notification Sent to -Signal Control Center - Atlanta at  
01/31/2014 14:11:10 Asset: CAILLAVET ST Status Changed To: Out Of Service PCC Notification Sent 01/31/2014 14:11:10

**Updated** 01/31/2014 14:13:26 **by** Max Todd **Dept** PSCC **IT+**  
**Contacted On** **Agency** LOCAL PD **Contact Name** LOCAL PD **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 01/31/2014 14:13:49 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 14:43

**Updated** 01/31/2014 14:45:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 01/31/2014 16:13:55 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 01/31/2014 16:13:00 Equipment Type: N/A Action Taken: Track Occupied

**The Signal Maintainer reported that Maintenance of Way was working on the approach circuit at the time of the report. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: CAILLAVET ST Status Changed To: In Service PCC Notification Sent 01/31/2014  
16:13:55

**Updated** 01/31/2014 16:22:25 **by** Max Todd **Dept** PSCC **IT+**  
**Contacted On** 01-31-2014 16:21:00 **Agency** LOCAL PD **Contact Name** 2922 **Phone** 228-392-0641  
at Esters Blvd.

---

**Log#** [6452513](#) **Status** Closed **Entered** 01-21-2014 00:49:59 **by** Foster, George **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.0 **Block** 2763

**Section** 3090-Ocean Springs **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** James Jr, G H - ETA: 02:24

**Description** 01/21/2014 00:49:59 **by** George Foster **Dept** Signals **IT+** Unknown

**Updated** 01/21/2014 00:53:00 **by** George Foster **Dept** Signals **IT+** .False or partial activation reported  
Crossing activated with no trains in sight. Dispatcher protecting with false partial activation MSG# 44347. Notification Sent to -Signal Control  
Center - Atlanta at 01/21/2014 00:53:00 Asset: CAILLAVET ST Status Changed To: Out Of Service PCC Notification Sent 01/21/2014  
00:53:00

**Updated** 01/21/2014 00:56:21 **by** Thera Moore **Dept** PSCC **IT+**  
**Contacted On** **Agency** 911 **Contact Name** 392 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 01/21/2014 02:23:38 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Call list exhausted. Notified Sig Sup James and NOC C&S Manager.

**Updated** 01/21/2014 02:24:04 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Status changed to Escalated, George James Jr ETA of: N/A

**Closed** 01/21/2014 09:52:57 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported

Incident Resolved: 01/21/2014 09:52:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced Termination Shunt DAX unit was down, vandals had cut the wires at the termination shunts. repaired wire, made op checks and ret to disp. Operational Checks Performed Asset: CAILLAVET ST Status Changed To: In Service PCC Notification Sent 01/21/2014 09:52:57

**Updated** 01/21/2014 10:02:47 **by** Alexis Romine **Dept** PSCC **IT+**

**Contacted On** 01-21-2014 10:02:00 **Agency** Biloxi Police Department **Contact Name** Operator 3312 **Phone** 228-392-0641  
@ Esters Blvd

---

**Log#** [6206318](#) **Status** Closed **Entered** 07-11-2013 13:39:23 **by** Williams, Joseph **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.0 **Block** 2763

**Section** 3090-Ocean Springs **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Stanfill, M O - ETA: 14:58

**Description** 07/11/2013 13:39:23 **by** Joseph Williams **Dept** Signals **IT+** Unknown

**Updated** 07/11/2013 13:43:59 **by** Joseph Williams **Dept** Signals **IT+** .False or partial activation reported

1340:Hr outside party reported that the gates are down with lights flashing and no trains in sight. 1341:Hr dispatcher MSC notified. Notification Sent to -Signal Control Center - Atlanta at 07/11/2013 13:43:59 Asset: CAILLAVET ST Status Changed To: Out Of Service PCC Notification Sent 07/11/2013 13:43:59

**Updated** 07/11/2013 13:56:13 **by** Kihron Bristol **Dept** PSCC **IT+**

**Contacted On** 07-11-2013 13:55:00 **Agency** Biloxi Police Department **Contact Name** Moffett **Phone** 228-392-0641  
Esters Blvd

**Updated** 07/11/2013 13:57:47 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported

MOW EC1 in block at time of report

**Updated** 07/11/2013 13:58:41 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported

Status changed to Dispatched for Michael Stanfill ETA of: 14:58

**Updated** 07/11/2013 13:59:22 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported

mntr reports severe weather in area

**Updated** 07/11/2013 15:00:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported

ETA time reached Status changed to Active

**Closed** 07/11/2013 15:21:07 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported

Incident Resolved: 07/11/2013 15:19:00 Equipment Type: Crossing case equipment Action Taken: Repaired/adjusted island circuit

**The Signal Maintainer reset the IPI. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: CAILLAVET ST Status Changed To: In Service PCC Notification Sent 07/11/2013 15:21:07

**Updated** 07/11/2013 15:23:43 **by** Kihron Bristol **Dept** PSCC **IT+**

**Contacted On** 07-11-2013 15:23:00 **Agency** Biloxi Police Department **Contact Name** Aaron **Phone** 228-392-0641

**Log#** [6093510](#) **Status** Closed **Entered** 04-24-2013 15:57:41 **by** Tyo, Mark **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.0 **Block** 2763  
**Section** 3090-Ocean Springs **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** McKibbon, R L - ETA: 17:45  
**Description** 04/24/2013 15:57:41 **by** Mark Tyo **Dept** Signals **IT+** Unknown  
**Updated** 04/24/2013 16:05:00 **by** Mark Tyo **Dept** Signals **IT+** .False or partial activation reported  
 Police report gate damaged during storm. DOT # was given. Disp is protecting. Notification Sent to -Signal Control Center - Atlanta at 04/24/2013 16:05:00 Asset: CAILLAVET ST Status Changed To: Out Of Service PCC Notification Sent 04/24/2013 16:05:00  
**Updated** 04/24/2013 16:17:23 **by** Max Todd **Dept** PSCC **IT+**  
**Contacted On** 04-24-2013 16:17:00 **Agency** Biloxi PD **Contact Name** SARA **Phone** 228-392-0641  
 Reporting party has been verified as the responsible law enforcement agency.  
**Updated** 04/24/2013 16:30:10 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
 Status changed to Dispatched for Richard McKibbon ETA of: 19:00  
**Updated** 04/24/2013 17:50:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
 ETA time reached Status changed to Active  
**Closed** 04/24/2013 18:45:51 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
 Incident Resolved: 04/24/2013 18:42:00 Equipment Type: Gate Action Taken: Replaced shear pin/rehung original gate  
**The Signal Maintainer found that a broken shear pin bolt was causing the gate to lean up against the cantilever. He installed new bolts in it. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**  
 Operational Checks Performed Asset: CAILLAVET ST Status Changed To: In Service PCC Notification Sent 04/24/2013 18:45:51  
**Updated** 04/24/2013 19:18:18 **by** Jerome Shepard **Dept** PSCC **IT+**  
**Contacted On** 04-24-2013 19:18:00 **Agency** Biloxi PD **Contact Name** Operator Moffit **Phone** 228-392-0641

---

**Log#** [5960157](#) **Status** Closed **Entered** 01-26-2013 12:01:21 **by** Miller, Vern **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.0 **Block** 2763  
**Section** 3090-Ocean Springs **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Houck, B - ETA: 13:26  
**Description** 01/26/2013 12:02:42 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
 crossing activated, no train around. dispatcher notified to protect with false/partial activation protection. vern Asset: CAILLAVET ST Status Changed To: Out Of Service PCC Notification Sent 01/26/2013 12:02:42  
**Updated** 01/26/2013 12:02:55 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
 . Notification Sent to -Signal Control Center - Atlanta at 01/26/2013 12:02:55  
**Updated** 01/26/2013 12:09:47 **by** Sheri Sheppard **Dept** PSCC **IT+**  
**Contacted On** 01-26-2013 12:08:00 **Agency** Biloxi Police Department **Contact Name** 347 **Phone** 228-392-0641  
 @ Esters Blvd  
**Updated** 01/26/2013 12:23:36 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
 707 in area of xing. (Summer)  
**Updated** 01/26/2013 12:26:56 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported

Status changed to Dispatched for ETA of: 13:26

**Updated** 01/26/2013 13:30:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 01/26/2013 13:32:33 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 01/26/2013 13:31:00 Equipment Type: Track Action Taken: Other - explain

**Employee:** B. Houck

- MoW working caused crossing to activate,

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: CAILLAVET ST Status Changed To: In Service PCC Notification Sent 01/26/2013 13:32:33

**Updated** 01/26/2013 13:37:42 **by** Brooks Clayton **Dept** PSCC **IT+**  
**Contacted On** 01-26-2013 13:37:00 **Agency** Biloxi Police Department **Contact Name** 2292 **Phone** 228-392-0641

---

**Log#** [5919628](#) **Status** Closed **Entered** 12-28-2012 22:00:23 **by** Carter, Jake **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 727.0 **Block** 2763

**Section** 3090-Ocean Springs **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Wilson, C E - ETA: 05:34 & Smith, K E - ETA: 05:37 & Benton, R E - ETA: 23:59 & White, R - ETA: 01:42

**Description** 12/28/2012 22:03:34 **by** Jake Carter **Dept** Signals **IT+** .False or partial activation reported  
OSP reports lights are flashing, w/no train present;disp is protecting as f/p Notification Sent to -Signal Control Center - Atlanta at 12/28/2012 22:03:34  
Asset: CAILLAVET ST Status Changed To: Out Of Service PCC Notification Sent 12/28/2012 22:03:34

**Updated** 12/28/2012 22:11:57 **by** Terry Lloyd **Dept** PSCC **IT+**  
**Contacted On** 12-28-2012 22:11:00 **Agency** Biloxi Pd **Contact Name** Kirk **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 12/29/2012 00:00:15 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Call list exhausted. Left message with Sig Sup White. Notified Wkd Duty Mngr Benton and NOC C&S Manager.

**Updated** 12/29/2012 01:42:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for ETA of: N/A

**Updated** 12/29/2012 01:42:30 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Sig Sup White returned call, notified of incident.

**Updated** 12/29/2012 04:07:09 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for ETA of: 05:37

**Updated** 12/29/2012 05:34:30 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for ETA of: N/A

**Updated** 12/29/2012 05:35:35 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Mntr's assisting each other at Caillavet crossing and 3 Mile Creek DB.

**Closed** 12/29/2012 07:13:57 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 12/29/2012 07:13:00 Equipment Type: Gate Action Taken: Damaged gate or sections-replaced/repared broken gate, replaced 2 sections. made op checks and ret to disp. no error codes. Operational Checks Performed Asset: CAILLAVET ST Status Changed To: In Service PCC



**Updated** 12/29/2012 07:33:02 **by** Jesse Gansen **Dept** PSCC **IT+**  
**Contacted On** 12-29-2012 07:32:00 **Agency** 28-2012 22:11 **By** Terry Lloyd - PSCC **Contact Name** Stephanie **Phone** 228-392-0641

---

**Log#** [5916828](#) **Status** Closed **Entered** 12-26-2012 19:41:03 **by** Tyo, Mark **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 727.0 **Block** 2763

**Section** 3090-Ocean Springs **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Brown, K L - *ETA*: 21:11

**Description** 12/26/2012 19:53:45 **by** Mark Tyo **Dept** Signals **IT+** .False or partial activation reported  
Police report gate broke. DOT # was given. Disp is protecting. Notification Sent to -Signal Control Center - Atlanta at 12/26/2012 19:53:45 **Asset**: CAILLAVET ST **Status Changed To**: Out Of Service **PCC Notification Sent** 12/26/2012 19:53:45

**Updated** 12/26/2012 19:58:20 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi PD **Contact Name** 3235 **Phone** 228-392-0641

Reporting party has been verified as the responsible law enforcement agency.

**Closed** 12/26/2012 21:11:20 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 12/26/2012 21:00:00 **Equipment Type**: Gate **Action Taken**: Damaged gate or sections-replaced/repaired  
Mntr replaced middle sec of gate. Performed op checks, 12 sec gate des time. Turned crossing backover to disp.  
Operational Checks Performed **Asset**: CAILLAVET ST **Status Changed To**: In Service **PCC Notification Sent** 12/26/2012 21:11:20

**Updated** 12/26/2012 21:11:37 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
**Status changed to** Dispatched for *ETA* of: N/A

**Updated** 12/26/2012 21:21:24 **by** Richard Fields **Dept** PSCC **IT+**  
**Contacted On** 12-26-2012 21:17:00 **Agency** Biloxi PD **Contact Name** Operator Jennifer **Phone** 228-392-0641

---

**Log#** [5877753](#) **Status** Closed **Entered** 11-26-2012 19:58:05 **by** Rosenblatt, Louis **Type** Vehicle Collision On Crossing

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 727.0 **Block** 2763

**Section** 3090-Ocean Springs **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Stanfill, M O - *ETA*: 21:13

**Description** 11/26/2012 20:02:38 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle Collision On Crossing

The AA Dispatcher received a report from the PSCC that Caillavet Street, MP 000 727.01, DOT# 340191A, had a vehicle collision on the track.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 32640**. LVR  
**Asset**: CAILLAVET ST **Status Changed To**: Out Of Service **PCC Notification Sent** 11/26/2012 20:02:38

**Closed** 11/26/2012 21:55:06 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle Collision On Crossing  
Incident Resolved: 11/26/2012 21:41:00 **Equipment Type**: N/A **Action Taken**: Eqpt tested & fnd working as intended  
**Suspected Reason**: Outside party or vandalism

**The Signal Maintainer reported that there was no signal damage. Gate Descent time was 14.7 seconds. Operational Checks were performed. The Crossing is Back In Service with the Dispatcher. LVR**  
Operational Checks Performed **Asset**: CAILLAVET ST **Status Changed To**: In Service **PCC Notification Sent** 11/26/2012 21:55:06

---

**Log#** [5708264](#) **Status** Closed **Entered** 07-24-2012 12:01:34 **by** Miller, Vern **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 727.0 **Block** 2763

**Section** 3090-Ocean Springs **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Stanfill, M O - ETA: 12:56

**Description** 07/24/2012 12:03:01 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
crossing activated, no train around. dispatcher notified to protect with false/partial activation protection. vern Asset:  
CAILLAVET ST Status Changed To: Out Of Service PCC Notification Sent 07/24/2012 12:03:01

**Updated** 07/24/2012 12:03:12 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
. Notification Sent to -Signal Control Center - Atlanta at 07/24/2012 12:03:12

**Updated** 07/24/2012 12:05:28 **by** Brooks Clayton **Dept** PSCC **IT+**  
**Contacted On** **Agency** p.d. **Contact Name** opr.#347 **Phone** 228 392 0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 07/24/2012 12:10:32 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
MOW has EC1 in area

**Updated** 07/24/2012 12:11:54 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
MNTR reports rail car in area

**Closed** 07/24/2012 14:30:38 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 07/24/2012 14:29:00 Equipment Type: N/A Action Taken: MoW equipment cleared ckt Suspected Reason:  
Other department

**Employee:** M. Stanfill

- MoW on-track equipment trammng thu crossing.

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: CAILLAVET ST Status Changed To: In Service PCC Notification Sent 07/24/2012  
14:30:38

**Updated** 07/24/2012 15:41:06 **by** Jerome Shepard **Dept** PSCC **IT+**  
**Contacted On** 07-24-2012 15:41:00 **Agency** Biloxi Police **Contact Name** Ms Operator **Phone** 228 392 0641

---

**Log#** [5642309](#) **Status** Closed **Entered** 06-10-2012 09:33:14 **by** Hofer, Dave **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 727.0 **Block** 2763

**Section** 3090-Ocean Springs **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Houck, B - ETA: 11:08

**Description** 06/10/2012 09:36:13 **by** David Hofer **Dept** Signals **IT+** .False or partial activation reported  
09:33 Local pd reported a broken gate at DOT# 340191A. Notified the AA dispatcher to protect the crossing as a F/P.  
Notification Sent to -Signal Control Center - Atlanta at 06/10/2012 09:36:13 Asset: CAILLAVET ST Status Changed To:  
Out Of Service PCC Notification Sent 06/10/2012 09:36:13

**Updated** 06/10/2012 09:38:17 **by** Daniel Johnson **Dept** PSCC **IT+**  
**Contacted On** **Agency** Dispatcher **Contact Name** Local PD **Phone** 228-392.0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 06/10/2012 09:40:28 **by** David Hofer **Dept** Signals **IT+** .False or partial activation reported  
.

**Updated** 06/10/2012 11:19:36 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
storms and high winds in area at time on incident

**Closed** 06/10/2012 11:54:07 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 06/10/2012 11:52:00 Equipment Type: Gate Action Taken: Damaged gate or sections-

replaced/repared Suspected Reason: N/A

**Employee:** B. Houck

- Replaced broken gate at crossing (west gate) middle section.

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: CAILLAVET ST Status Changed To: In Service PCC Notification Sent 06/10/2012 11:54:07

**Updated** 06/10/2012 12:02:22 **by** Jesse Gansen **Dept** PSCC **IT+**  
**Contacted On** 06-10-2012 12:01:00 **Agency** Local PD **Contact Name** 308 **Phone** 228-392.0641

---

**Log#** [5526200](#) **Status** Closed **Entered** 03-20-2012 22:43:13 **by** Rosenblatt, Louis **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 727.0 **Block** 2763  
**Section** 3090-Ocean Springs **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Houck, B - ETA: 00:13  
**Description** 03/20/2012 22:43:50 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported

The AA Dispatcher received a report from K87621 Northbound that Caillavet Street, MP 000 727.01, DOT# 340191A, one of the gates did not come down because it is a long gate and it was caught in the wire.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 34472**. LVR  
Asset: CAILLAVET ST Status Changed To: Out Of Service PCC Notification Sent 03/20/2012 22:43:50

**Updated** 03/20/2012 22:43:52 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
A email notification for Multi Failure Count (MFC) asset CAILLAVET ST (3) has been sent to the following:  
Terrence Smale II  
John Parr

**Updated** 03/20/2012 22:50:01 **by** Christopher Horman **Dept** PSCC **IT+**  
**Contacted On** 03-20-2012 22:48:00 **Agency** Biloxi Police Department **Contact Name** Disp. 364 **Phone** 228-392-0641  
@ Esters Boulevard

**Closed** 03/21/2012 00:36:41 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 03/21/2012 00:34:00 Equipment Type: Gate Action Taken: Replaced shear pin/rehung original gate Suspected Reason: Other weather  
Mntr rehung gate, replaced shear pins. Watched train over crossing, no exceptions noted. Turned crossing backover to disp.  
Operational Checks Performed Asset: CAILLAVET ST Status Changed To: In Service PCC Notification Sent 03/21/2012 00:36:41

**Updated** 03/21/2012 00:38:24 **by** Myrtie Hackney **Dept** PSCC **IT+**  
**Contacted On** 03-21-2012 00:37:00 **Agency** Biloxi Police Department **Contact Name** Sarah **Phone** 228-392-0641  
@ Esters Boulevard

---

**Log#** [5498777](#) **Status** Closed **Entered** 03-01-2012 13:46:04 **by** Gothard, Jason **Type** Train-vehicle collision  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 727.0 **Block** 2763  
**Section** 3090-Ocean Springs **Asset** CAILLAVET ST **AssetNum** 340191A **Maintainer** Stanfill, M O - ETA: 13:58  
**Description** 03/01/2012 13:47:49 **by** Jason Gothard **Dept** Signals **IT+** Train-vehicle collision  
Q57925 reports striking piece of outside party equipment at/near xing. no injuries to either train crew or vehicle occupants. Asset: CAILLAVET ST Status Changed To: Out Of Service PCC Notification Sent 03/01/2012 13:47:49

**Updated** 03/01/2012 13:47:55      **by** Jason Gothard      **Dept** Signals      **IT+** Train-vehicle collision  
Notification has been sent to the following: Terrence Smale II John Parr J Orlandi C Manager

**Updated** 03/01/2012 14:07:53      **by** Sean Reid      **Dept** PSCC      **IT+**  
**Contacted On** 03-01-2012 14:06:00      **Agency** n/a      **Contact Name** n/a      **Phone** n/a  
refer to PSCC incident 5498737

**Closed** 03/01/2012 14:52:33      **by** Michael Houston      **Dept** Signals      **IT+** Train-vehicle collision  
Incident Resolved: 03/01/2012 14:52:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as  
intended Suspected Reason: Outside party or vandalism no damage to crossing. all applicable tests performed  
and crossing returned to dispatcher. Operational Checks Performed Asset: CAILLAVET ST Status Changed To:  
In Service PCC Notification Sent 03/01/2012 14:52:33

**Updated** 03/01/2012 15:25:01      **by** Emily Morton      **Dept** PSCC      **IT+**  
**Contacted On** 03-01-2012 15:24:00      **Agency** na      **Contact Name** na      **Phone** na  
refer to PSCC incident 5498737

Page Execution Time: 006.14 seconds

**Bohn Street**

**DOT Crossing #: 340193N**

**RR Milepost #: 727.11**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 14

Status All AssetType All RootAssetType All Department Signals AssetNum 340193N

---

**Log#** [7868296](#) **Status** Closed **Entered** 11-02-2016 06:19:25 **by** Haselden, Thomas **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.1 **Block** 2763

**Section** 3090-7M16 **Asset** BOHN ST **AssetNum** 340193N **Maintainer** Stanfill, M O - ETA: 07:52

**Description** 11/02/2016 06:19:25 **by** Thomas Haselden **Dept** Signals **IT+** Unknown

**Updated** 11/02/2016 06:22:06 **by** Thomas Haselden **Dept** Signals **IT+** .False or partial activation reported

Gates up and lights flashing, dot# provided, dispatcher protecting with false partial message. Asset: BOHN ST Status Changed To: Out Of Service PCC Notification Sent 11/02/2016 06:22:06

**Updated** 11/02/2016 06:22:58 **by** Thomas Haselden **Dept** Signals **IT+** .False or partial activation reported

Status changed to Dispatched for Michael Stanfill ETA of: 07:52

**Updated** 11/02/2016 06:34:18 **by** Terry Lloyd **Dept** PSCC **IT+**

**Contacted On** 11-02-2016 06:33:00 **Agency** biloxi pd **Contact Name** badge # 3312 **Phone** 228-392-0641

Reporting party has been verified as the responsible law enforcement agency.

**Updated** 11/02/2016 07:55:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported

ETA time reached Status changed to Active

**Updated** 11/02/2016 09:37:16 **by** Michael Stanfill **Dept** Signals **IT+** .False or partial activation reported

Incident Resolved: 11/02/2016 09:37:00 Equipment Type: Gate Action Taken: Damaged gate or sections-replaced/repared Maintainer found west gate bent and hanging up in lights. Replace gate and all gate lights. Time both gates to 13.5 seconds. Operational Checks Performed Asset: BOHN ST Status Changed To: In Service PCC Notification Sent 11/02/2016 09:37:16

**Closed** 11/02/2016 09:39:30 **by** Marion Wilburn **Dept** Signals **IT+** .False or partial activation reported

Incident Resolved: 11/02/2016 09:37:00 Equipment Type: Gate Action Taken: Damaged gate or sections-replaced/repared Maintainer found west gate bent and hanging up in lights. Replace gate and all gate lights. Time both gates to 13.5 seconds. Operational Checks Performed Operational Checks Performed

**Updated** 11/02/2016 09:46:09 **by** Avie Saunders **Dept** PSCC **IT+**

**Contacted On** 11-02-2016 09:45:00 **Agency** biloxi pd **Contact Name** Anthony **Phone** 228-392-0641

---

**Log#** [7464746](#) **Status** Closed **Entered** 01-05-2016 14:32:54 **by** Jackson Jr, Marv **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.1 **Block** 2763

**Section** 3090-7M16 **Asset** BOHN ST **AssetNum** 340193N **Maintainer** Stanfill, M O - ETA: 15:37

**Description** 01/05/2016 14:32:54 **by** Marv Jackson Jr **Dept** Signals **IT+** Unknown

**Updated** 01/05/2016 14:35:03 **by** Marv Jackson Jr **Dept** Signals **IT+** .False or partial activation reported

LOCAL PD REPORTS FALSE ACTIVATION AT BOHN ST Notification Sent to -Signal Control Center - Atlanta at 01/05/2016 14:35:03 Asset: BOHN ST Status Changed To: Out Of Service PCC Notification Sent 01/05/2016 14:35:03

**Updated** 01/05/2016 14:37:42 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported

Status changed to Dispatched for Michael Stanfill ETA of: 15:37

**Updated** 01/05/2016 14:44:34 **by** Brad Oglesby **Dept** Signals **IT+** .False or partial activation reported

1444 ADVISED THE AA DISPATCHER(INITIALS-DC) TO PROVIDE PROTECTION ON THE CROSSING AS PER FALSE ACTIVATION STANDARD.

**Updated** 01/05/2016 14:53:55 **by** Waltina Edwards **Dept** PSCC **IT+**

**Contacted On** **Agency** LOCAL PD **Contact Name** BRENDA **Phone** 228-392-0641

Reporting party has been verified as the responsible law enforcement agency.

**Updated** 01/05/2016 15:40:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 01/05/2016 16:11:12 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 01/05/2016 15:28:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced Track Card

**The Signal Maintainer replaced the RYD Module. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: BOHN ST Status Changed To: In Service PCC Notification Sent 01/05/2016 16:11:12

**Updated** 01/05/2016 16:18:38 **by** Waltina Edwards **Dept** PSCC **IT+**  
**Contacted On** 01-05-2016 16:18:00 **Agency** Police Department to **Contact Name** 3500 **Phone** Phone# 228-392-0641

---

**Log#** [7206904](#) **Status** Closed **Entered** 06-27-2015 01:04:23 **by** Hillard, James **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.1 **Block** 2763

**Section** 3090-7M16 **Asset** BOHN ST **AssetNum** 340193N **Maintainer** Mannion, R - ETA: 07:28 & Broadway, J L - ETA: 03:56

**Description** 06/27/2015 01:04:23 **by** James Hillard **Dept** Signals **IT+** Unknown

**Updated** 06/27/2015 01:08:57 **by** James Hillard **Dept** Signals **IT+** .False or partial activation reported  
Local Pd reports that the crossing is activated with no trains present. Dot# provided dispatcher protecting with false/partial activation message# 48716 Notification Sent to -Signal Control Center - Atlanta at 06/27/2015 01:08:57 Asset: BOHN ST Status Changed To: Out Of Service PCC Notification Sent 06/27/2015 01:08:57

**Updated** 06/27/2015 01:29:10 **by** Jesse Gansen **Dept** PSCC **IT+**  
**Contacted On** 06-27-2015 01:28:00 **Agency** Biloxi Police Department **Contact Name** Operator 3458 **Phone** 228-392-0641

**Updated** 06/27/2015 01:56:43 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Joshua Broadway ETA of: 03:56

**Updated** 06/27/2015 04:00:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 06/27/2015 05:39:27 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
0535 mtr reports the dax unit at the intermediate signal, mp 000 727.3 approx...unit has been hit by lightning... and will have to be replaced....

**Updated** 06/27/2015 06:25:04 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
0623 JUMPER LOG APPLIED ...

**Updated** 06/27/2015 06:30:16 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
0625 bohn st and Hopkins blvd affected the intermediate 000 727.3 dax unit....

**Updated** 06/27/2015 08:26:22 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Jumper Log # 7207061

**Closed** 06/27/2015 11:32:33 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 06/27/2015 11:32:00 Equipment Type: Wiring/Protection Action Taken: Repaired/Replaced Protection

**Employee:** J. Broadway

- Replaced GCP unit in the dax house...

Did OP Checks, Back/released to AA disp. Watched train thru block, no exceptions.

Operational Checks Performed Asset: BOHN ST Status Changed To: In Service PCC Notification Sent 06/27/2015 11:32:33

**Updated** 06/27/2015 11:46:05 **by** Michele Schwartz **Dept** PSCC **IT+**  
**Contacted On** 06-27-2015 11:45:00 **Agency** Biloxi Police Department **Contact Name** 2292 **Phone** 228-392-0641

---

**Log#** [6836323](#) **Status** Closed **Entered** 10-14-2014 09:35:42 **by** Williams, Joseph **Type** .False or partial activation reported



Supv Merritt, D Reg SO Div AT Sub NM IRI 0 Milepost 000 727.1 Block 2763

Section 3090-7M16 Asset BOHN ST AssetNum 340193N Maintainer Stanfill, M O - ETA: 10:42

Description 10/14/2014 09:35:42 by Joseph Williams Dept Signals IT+ Unknown

Updated 10/14/2014 09:40:00 by Joseph Williams Dept Signals IT+ .False or partial activation reported  
0936:Hr Biloxi Police reported that a concrete block was hit at the tracks by a semi truck. 0937:Hr dispatcher DC notified to protect as an activation failure. Notification Sent to -Signal Control Center - Atlanta at 10/14/2014 09:40:00 Asset: BOHN ST Status Changed To: Out Of Service PCC Notification Sent 10/14/2014 09:40:00

Updated 10/14/2014 09:42:29 by Bruce McVey Dept Signals IT+ .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 10:42

Updated 10/14/2014 09:43:00 by Marvin Smoot Dept PSCC IT+  
Contacted On 10-14-2014 09:43:00 Agency Biloxi Police Department Contact Name John Phone 228-392-0641  
@ Esters Blvd

Updated 10/14/2014 10:45:00 by TCIS AUTOMATION Dept Signals IT+ .False or partial activation reported  
ETA time reached Status changed to Active

Closed 10/14/2014 10:57:09 by Jason Gothard Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 10/14/2014 10:57:00 Equipment Type: N/A Action Taken: NTF - UTD truck did hit a signal barricade, not causing any signals issues and not in th eway of train or auto traffic. Operational Checks Performed Asset: BOHN ST Status Changed To: In Service PCC Notification Sent 10/14/2014 10:57:09

Updated 10/14/2014 10:59:10 by Marvin Smoot Dept PSCC IT+  
Contacted On 10-14-2014 10:59:00 Agency Biloxi Police Department Contact Name John Phone 228-392-0641  
@ Esters Blvd

---

Log# [6746606](#) Status Closed Entered 08-11-2014 14:46:23 by Kondy, Rick Type .False or partial activation reported

Supv Merritt, D Reg SO Div AT Sub NM IRI 0 Milepost 000 727.1 Block 2763

Section 3090-Ocean Springs Asset BOHN ST AssetNum 340193N Maintainer Stanfill, M O - ETA: 16:59

Description 08/11/2014 14:46:23 by Richard Kondy Dept Signals IT+ Unknown

Updated 08/11/2014 14:48:09 by Richard Kondy Dept Signals IT+ .False or partial activation reported  
gates up and down , no trains . disp protecting crossing with false activation # 228959 . Notification Sent to -Signal Control Center - Atlanta at 08/11/2014 14:48:09 Asset: BOHN ST Status Changed To: Out Of Service PCC Notification Sent 08/11/2014 14:48:09

Updated 08/11/2014 14:50:24 by Jackie McGuirt Dept PSCC IT+  
Contacted On Agency // Contact Name biloxi police Phone 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

Updated 08/11/2014 14:59:01 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 16:59

Closed 08/11/2014 16:00:52 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 08/11/2014 15:58:00 Equipment Type: N/A Action Taken: Track Occupied

**The Signal Maintainer reported that a Rail Test Car was operating on the approach at the time of the report. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: BOHN ST Status Changed To: In Service PCC Notification Sent 08/11/2014 16:00:52

Updated 08/11/2014 16:11:31 by Jackie McGuirt Dept PSCC IT+  
Contacted On 08-11-2014 16:11:00 Agency biloxi police Contact Name Oper: Jennifer Phone 228-392-0641

---

Log# [6644932](#) Status Closed Entered 06-02-2014 08:41:20 by Lewis, Wendell Type .Other Failure

**Supv** Merritt, D **Reg SO** **Div AT** **Sub NM** **IRI 0** **Milepost** 000 727.1 **Block** 2762  
**Section** 3090-Ocean Springs **Asset** BOHN ST **AssetNum** 340193N **Maintainer** Stanfill, M O - ETA: 09:48  
**Description** 06/02/2014 08:41:20 **by** Wendell Lewis **Dept** Signals **IT+** Unknown  
**Updated** 06/02/2014 08:45:58 **by** Wendell Lewis **Dept** Signals **IT+** .Other Failure  
08:41 POLICE REPORTED BROKEN X-ING GATE AT BOHN ST.....AA-DISP. PROTECTING WITH A/F MSG.  
Notification Sent to -Signal Control Center - Atlanta at 06/02/2014 08:45:58 Asset: BOHN ST Status Changed  
To: Out Of Service PCC Notification Sent 06/02/2014 08:45:58

**Updated** 06/02/2014 08:48:54 **by** Jerry Rockhill **Dept** Signals **IT+** .Other Failure  
Status changed to Dispatched for Michael Stanfill ETA of: 09:48

**Updated** 06/02/2014 08:59:53 **by** Roland Knagge **Dept** PSCC **IT+**  
**Contacted On** 06-02-2014 08:59:00 **Agency** BILOXI PD **Contact Name** ANGIE **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 06/02/2014 09:50:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .Other Failure  
ETA time reached Status changed to Active

**Updated** 06/02/2014 12:44:17 **by** Bruce McVey **Dept** Signals **IT+** .Other Failure

**Update** - The ESS texted a message requesting an update on the Signal Maintainers cell phone.

**Closed** 06/02/2014 13:29:41 **by** Bruce McVey **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 06/02/2014 13:29:00 Equipment Type: Gate Action Taken: Damaged gate or sections-  
replaced/repared

**Employee:** M. Stanfill

- Replaced broken gate at crossing (west side) with new gate and gate light. Broken back to back light,  
replaed elbow...

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: BOHN ST Status Changed To: In Service PCC Notification Sent  
06/02/2014 13:29:41

**Updated** 06/02/2014 13:36:36 **by** Robert Clendening **Dept** PSCC **IT+**  
**Contacted On** 06-02-2014 13:35:00 **Agency** BILOXI PD **Contact Name** Romia **Phone** 228-392-0641

---

**Log#** [6640166](#) **Status** Closed **Entered** 05-29-2014 13:17:08 **by** Gothard, Jason **Type** .False or partial activation reported

**Supv** Merritt, D **Reg SO** **Div AT** **Sub NM** **IRI 0** **Milepost** 000 727.1 **Block** 2762  
**Section** 3090-Ocean Springs **Asset** BOHN ST **AssetNum** 340193N **Maintainer** Stanfill, M O - ETA: 14:44

**Description** 05/29/2014 13:17:08 **by** Jason Gothard **Dept** Signals **IT+** Unknown

**Updated** 05/29/2014 13:17:40 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
gate knocked off Asset: BOHN ST Status Changed To: Out Of Service PCC Notification Sent 05/29/2014 13:17:40

**Updated** 05/29/2014 13:22:53 **by** Robert Clendening **Dept** PSCC **IT+**  
**Contacted On** 05-29-2014 13:21:00 **Agency** Biloxi Police Department **Contact Name** Dispatcher **Phone** 228-392-0641  
@ Esters BLVD.

**Updated** 05/29/2014 13:23:24 **by** Dale McClure **Dept** Signals **IT+** .False or partial activation reported  
POLICE DEPT. CASE #14-010796 BILOXI PD.

**Updated** 05/29/2014 13:44:20 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 14:44

**Closed** 05/29/2014 14:31:53 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 05/29/2014 14:31:00 Equipment Type: Gate Action Taken: Damaged gate or sections-replaced/repared replaced

2nd section east gate, made op checks and ret to disp Operational Checks Performed Asset: BOHN ST Status Changed To: In Service  
PCC Notification Sent 05/29/2014 14:31:53

**Updated** 05/29/2014 14:34:36 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** 05-29-2014 14:34:00 **Agency** Biloxi Police Department **Contact Name** Angie **Phone** 228-392-0641

---

**Log#** [6313730](#) **Status** Closed **Entered** 10-04-2013 15:09:18 **by** Tyo, Mark **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 1 **Milepost** 000 727.1 **Block** 2762

**Section** 3090-Ocean Springs **Asset** BOHN ST **AssetNum** 340193N **Maintainer** Houck, B - ETA: 16:27

**Description** 10/04/2013 15:09:18 **by** Mark Tyo **Dept** Signals **IT+** Unknown

**Updated** 10/04/2013 15:12:29 **by** Mark Tyo **Dept** Signals **IT+** .False or partial activation reported  
Police report crossing activated no trains. DOT # was given. Disp is protecting. Notification Sent to -Signal Control Center - Atlanta at 10/04/2013 15:12:29 Asset: BOHN ST Status Changed To: Out Of Service PCC Notification Sent 10/04/2013 15:12:29

**Updated** 10/04/2013 15:13:44 **by** Max Todd **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi PD **Contact Name** 3293 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 10/04/2013 15:27:25 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Bradley Houck ETA of: 16:27

**Updated** 10/04/2013 16:30:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 10/04/2013 17:10:41 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Mntr reports crossing COA. Found error code C623 on unit, gates dwn to long after train clears (not a tail ring), unit transferred to standby under train - RX value shows below 76 on trans/pwr up and indicates error. Mntr looking for TLM cd to replace in unit.

**Closed** 10/04/2013 20:00:27 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 10/04/2013 19:30:00 Equipment Type: Crossing case equipment Action Taken: Replaced card(s)  
Mntr replaced TLM cd. Performed op checks, turned crossing backover to disp.  
Operational Checks Performed Asset: BOHN ST Status Changed To: In Service PCC Notification Sent 10/04/2013 20:00:27

**Updated** 10/04/2013 20:18:29 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** 10-04-2013 20:18:00 **Agency** Biloxi PD **Contact Name** april **Phone** 228-392-0641

---

**Log#** [6279874](#) **Status** Closed **Entered** 09-07-2013 04:57:46 **by** Belkot, Paul **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.5 **Milepost** 000 727.1 **Block** 2763

**Section** 3090-Ocean Springs **Asset** BOHN ST **AssetNum** 340193N **Maintainer** Houck, B - ETA: 07:05 & Broadway, J L - ETA: 08:28

**Description** 09/07/2013 04:57:46 **by** Paul Belkot **Dept** Signals **IT+** Unknown

**Updated** 09/07/2013 05:01:18 **by** Paul Belkot **Dept** Signals **IT+** .False or partial activation reported  
GATES UP FLASHERS CONTINUOUS NO TRAIN IN AREA PER LOCAL PD. AA DISP ADVISED TO PROTECT CROSSING AS A FALSE PARTIAL ACTIVATION. SENT NOTIFICATION TO ESS ATLANTA DIV., PLEASE CALL MTR. Notification Sent to -Signal Control Center - Atlanta at 09/07/2013 05:01:18 Asset: BOHN ST Status Changed To: Out Of Service PCC Notification Sent 09/07/2013 05:01:18

**Updated** 09/07/2013 05:01:20 **by** Paul Belkot **Dept** Signals **IT+** .False or partial activation reported  
An email notification for Multi Failure Count (MFC) asset BOHN ST (4) has been sent to the following:  
George James Jr  
Danny McKenzie

**Updated** 09/07/2013 05:04:58 **by** Alison Obrien **Dept** PSCC **IT+**

**Contacted On** Agency BILOXI MS PD **Contact Name** OPERATOR 3289 **Phone** 228-392-0641

Reporting party has been verified as the responsible law enforcement agency.

**Updated** 09/07/2013 05:35:32 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Bradley Houck ETA of: 07:05

**Updated** 09/07/2013 06:40:26 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
0638 mtr reports vehicle has struck the mech arm with weights...also damaged flasher light and elbow ...maintainer will need help....

**Updated** 09/07/2013 07:10:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 09/07/2013 09:06:03 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
on site

**Closed** 09/07/2013 11:27:33 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 09/07/2013 09:30:00 Equipment Type: Other - explain Action Taken: Other - explain Replaced gate mech arm, flasher arm, op cks and BTD Operational Checks Performed Asset: BOHN ST Status Changed To: In Service PCC Notification Sent 09/07/2013 11:27:33

**Updated** 09/07/2013 11:52:35 **by** Christina Martorano **Dept** PSCC **IT+**  
**Contacted On** 09-07-2013 11:51:00 **Agency** BILOXI PD **Contact Name** Sarah **Phone** 228-392-0641

---

**Log#** [6272908](#) **Status** Closed **Entered** 09-01-2013 19:01:54 **by** Filarski Jr, John **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.25 **Milepost** 000 727.1 **Block** 2763

**Section** 3090-Ocean Springs **Asset** BOHN ST **AssetNum** 340193N **Maintainer** Stanfill, M O - ETA: 21:30

**Description** 09/01/2013 19:01:54 **by** John Filarski Jr **Dept** Signals **IT+** Unknown

**Updated** 09/01/2013 19:04:47 **by** John Filarski Jr **Dept** Signals **IT+** .False or partial activation reported  
BILOXI pd gave dot # and reports gates stayed down after train Notification Sent to -Signal Control Center - Atlanta at 09/01/2013 19:04:47 Asset: BOHN ST Status Changed To: Out Of Service PCC Notification Sent 09/01/2013 19:04:47

**Updated** 09/01/2013 19:04:48 **by** John Filarski Jr **Dept** Signals **IT+** .False or partial activation reported  
An email notification for Multi Failure Count (MFC) asset BOHN ST (3) has been sent to the following:  
George James Jr  
Danny McKenzie

**Updated** 09/01/2013 19:15:02 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 21:30

**Updated** 09/01/2013 19:33:29 **by** Thera Moore **Dept** PSCC **IT+**  
**Contacted On** **Agency** 2922 **Contact Name** BILOXI pd **Phone** 228 392 0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 09/01/2013 21:30:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 09/02/2013 00:17:52 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 09/02/2013 00:17:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended 0014 mtr reports coa and found 623 error codes on crossing unit...tested nb and sb starts ok shunted approaches watched 3 trains thru ok ...op cks ok and crossing back in service with disp...storms were in area at time of call... Operational Checks Performed Asset: BOHN ST Status Changed To: In Service PCC Notification Sent 09/02/2013 00:17:52

**Updated** 09/02/2013 00:29:28 **by** Christopher Horman **Dept** PSCC **IT+**  
**Contacted On** 09-02-2013 00:28:00 **Agency** BILOXI pd **Contact Name** Disp. Ramona **Phone** 228 392 0641

---

**Log#** [6266653](#) **Status** Closed **Entered** 08-27-2013 14:11:20 **by** McClure, Dale **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 727.1 **Block** 2763

**Section** 3090-Ocean Springs **Asset** BOHN ST **AssetNum** 340193N **Maintainer** Stanfill, M O - ETA: 14:41

**Description** 08/27/2013 14:11:20 **by** Dale McClure **Dept** Signals **IT+** Unknown

**Updated** 08/27/2013 14:16:34 **by** Dale McClure **Dept** Signals **IT+** .False or partial activation reported  
LOCAL CITIZEN REPORTING THIS CROSSING IS REACTIVATING INTERMITTENTLY FOR SEVERAL MINUTES AFTER A TRAIN PASSES. AA DISP. NOTIFIED AND INSTRUCTED TO PROTECT AS FALSE/ PARTIAL ACTIVATION UNTIL CHECKED.  
Asset: BOHN ST Status Changed To: Out Of Service PCC Notification Sent 08/27/2013 14:16:34

**Updated** 08/27/2013 14:26:52 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
NB Q57227 in the approach at time of report

**Updated** 08/27/2013 14:34:36 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** 08-27-2013 14:32:00 **Agency** Biloxi Police Department **Contact Name** 3289 **Phone** 228-392-0641  
@ Esters Blvd.

**Closed** 08/27/2013 14:40:15 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 08/27/2013 14:40:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended mntr was performing tests at Lameuse street which caused this xing to activate. made op checks and ret to disp Operational Checks Performed Asset: BOHN ST Status Changed To: In Service PCC Notification Sent 08/27/2013 14:40:15

**Updated** 08/27/2013 14:45:42 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** 08-27-2013 14:45:00 **Agency** Biloxi Police Department **Contact Name** Angie **Phone** 228-392-0641

---

**Log#** [6254880](#) **Status** Closed **Entered** 08-18-2013 15:41:57 **by** Kondy, Rick **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.1 **Block** 2763

**Section** 3090-Ocean Springs **Asset** BOHN ST **AssetNum** 340193N **Maintainer** Stanfill, M O - ETA: 17:17

**Description** 08/18/2013 15:41:57 **by** Richard Kondy **Dept** Signals **IT+** Unknown

**Updated** 08/18/2013 15:44:21 **by** Richard Kondy **Dept** Signals **IT+** .False or partial activation reported  
gate knocked off . disp protecting crossing with false activation # 29914 . Notification Sent to -Signal Control Center - Atlanta at 08/18/2013 15:44:21 Asset: BOHN ST Status Changed To: Out Of Service PCC Notification Sent 08/18/2013 15:44:21

**Updated** 08/18/2013 15:46:08 **by** Jesse Gansen **Dept** PSCC **IT+**  
**Contacted On** 08-18-2013 15:45:00 **Agency** Biloxi Police Department **Contact Name** 366 **Phone** 228-392-0641  
At Esters Boulevard

**Updated** 08/18/2013 15:47:52 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 17:17

**Updated** 08/18/2013 16:34:42 **by** Richard Kondy **Dept** Signals **IT+** .False or partial activation reported  
New Asset Added: 340191A - CAILLAVET ST

**Updated** 08/18/2013 16:38:17 **by** Richard Kondy **Dept** Signals **IT+** .False or partial activation reported  
gate knocked off at callivat st . disp protecting crossing with false activation # 29971 . Notification Sent to -Signal Control Center - Atlanta at 08/18/2013 16:38:17 Asset: CAILLAVET ST Status Changed To: Out Of Service PCC Notification Sent 08/18/2013 16:38:17

**Updated** 08/18/2013 16:43:10 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Notified Sig Mntr Stanfill about gate issue at Caillavet St. Mntr will handle repair. Mntr is working repairs at three (3) crossing's and an incident at the Biloxi Bay DB.

**Updated** 08/18/2013 17:19:04 **by** Jesse Gansen **Dept** PSCC **IT+**  
**Contacted On** 08-18-2013 17:18:00 **Agency** Biloxi Police Department **Contact Name** Sara **Phone** 228-392-0641

**Updated** 08/18/2013 17:20:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 08/18/2013 18:45:05 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Notified Sig Sup James about multiple issues over territory. Bad storms throughout the day.



**Closed** 08/18/2013 20:21:16 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 08/18/2013 20:14:00 Equipment Type: Gate Action Taken: Damaged gate or sections-replaced/repared  
Mntr replaced one sec on east gate at Bohn St and all three gate lights. Refocused lights, performed op checks. Mntr replaced west gate and gate lights, adjusted torque and performed op checks, 14 sec gate descent time at Caillavet St. Mntr turned both crossings backover to disp, ready for timetable speed.  
Operational Checks Performed Asset: BOHN ST Status Changed To: In Service PCC Notification Sent 08/18/2013 20:21:16 Asset: CAILLAVET ST Status Changed To: In Service PCC Notification Sent 08/18/2013 20:21:16

**Updated** 08/18/2013 20:32:20 **by** Sean Reid **Dept** PSCC **IT+**  
**Contacted On** 08-18-2013 20:28:00 **Agency** Biloxi Police Department **Contact Name** Disp # Sara 2922 **Phone** 228-392-0641  
At Esters Boulevard

---

**Log#** [6215011](#) **Status** Closed **Entered** 07-18-2013 06:56:40 **by** Williams, Joseph **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.1 **Block** 2763  
**Section** 3090-Ocean Springs **Asset** BOHN ST **AssetNum** 340193N **Maintainer** Houck, B - ETA: 08:11  
**Description** 07/18/2013 06:56:40 **by** Joseph Williams **Dept** Signals **IT+** Unknown

**Updated** 07/18/2013 06:59:32 **by** Joseph Williams **Dept** Signals **IT+** .False or partial activation reported  
0657:Hr Biloxi Police reported that the gates are down with lights flashing and no trains in sight. 0657:Hr DRG notified.  
Notification Sent to -Signal Control Center - Atlanta at 07/18/2013 06:59:32 Asset: BOHN ST Status Changed To: Out Of Service  
PCC Notification Sent 07/18/2013 06:59:32

**Updated** 07/18/2013 07:11:51 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Bradley Houck ETA of: 08:11

**Updated** 07/18/2013 07:31:08 **by** Louis Van Deusen **Dept** PSCC **IT+**  
**Contacted On** 07-18-2013 07:28:00 **Agency** Biloxi Police Department **Contact Name** 12 **Phone** 228-392-0641  
@ North of W Howard Ave

**Updated** 07/18/2013 08:15:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 07/18/2013 08:41:56 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 07/18/2013 08:41:00 Equipment Type: Gate mechanism Action Taken: Adjusted/Cleaned/Repaired/Reset  
mntr reports east gate pwr up contact adjusted. made op checks and ret to disp. Operational Checks Performed Asset: BOHN ST  
Status Changed To: In Service PCC Notification Sent 07/18/2013 08:41:56

**Updated** 07/18/2013 08:48:00 **by** Myrtie Hackney **Dept** PSCC **IT+**  
**Contacted On** 07-18-2013 08:47:00 **Agency** Biloxi Police Department **Contact Name** 315 **Phone** 228-392-0641  
@ North of W Howard Ave

---

**Log#** [5820809](#) **Status** Closed **Entered** 10-12-2012 20:41:19 **by** Kondy, Rick **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 727.1 **Block** 2763  
**Section** 3090-Ocean Springs **Asset** BOHN ST **AssetNum** 340193N **Maintainer** Houck, B - ETA: 21:51  
**Description** 10/12/2012 20:43:02 **by** Richard Kondy **Dept** Signals **IT+** .False or partial activation reported  
gates down , no trains . disp protecting crossing with false activation # 39097 . Notification Sent to -Signal Control Center -  
Atlanta at 10/12/2012 20:43:02 Asset: BOHN ST Status Changed To: Out Of Service PCC Notification Sent 10/12/2012  
20:43:02

**Updated** 10/12/2012 21:00:42 **by** Sean Reid **Dept** PSCC **IT+**  
**Contacted On** 10-12-2012 21:00:00 **Agency** // **Contact Name** biloxi police **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Closed** 10/13/2012 00:59:18 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 10/13/2012 00:58:00 Equipment Type: Crossing case equipment Action Taken:  
Repaired/adjusted/replaced other Suspected Reason: Lightning 0054 mtr reports making repairs to dax to bohn st (12 dax) at  
the 727.36 interdemiate signal...watched one nb train thru ok ....op cks ok and crossing back in service with disp...mtr

changed out lightning arrestor in case.... Operational Checks Performed Asset: BOHN ST Status Changed To: In Service PCC  
Notification Sent 10/13/2012 00:59:18

**Updated** 10/13/2012 01:06:06      **by** Gloria Andino      **Dept** PSCC      **IT+**  
**Contacted On** 10-13-2012 01:06:00 **Agency** biloxi police      **Contact Name** eric      **Phone** 228-392-0641

Page Execution Time: 002.93 seconds



**Hopkins Boulevard**

**DOT Crossing #: 340194V**

**RR Milepost #: 727.19**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 4

Status All AssetType All RootAssetType All Department Signals AssetNum 340194V

---

**Log#** [7801580](#) **Status** Closed **Entered** 09-14-2016 21:27:01 **by** Rosenblatt, Louis **Type** Vehicle on Track

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.2 **Block** 2763

**Section** 3090-7M16 **Asset** HOPKINS BLVD **AssetNum** 340194V **Maintainer** Stanfill, M O - ETA: 23:07

**Description** 09/14/2016 21:27:01 **by** Louis Rosenblatt **Dept** Signals **IT+** Unknown

**Updated** 09/14/2016 21:29:28 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track

The AA Dispatcher reported a vehicle on the track at Hopkins Boulevard, MP 000 727.19, DOT# 340194V, NM Sub.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 25249**. LVR Asset: HOPKINS BLVD Status Changed To: Out Of Service PCC Notification Sent 09/14/2016 21:29:28

**Updated** 09/14/2016 21:37:15 **by** Patrick Knotts **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Michael Stanfill ETA of: 23:07

**Updated** 09/14/2016 23:10:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Updated** 09/15/2016 00:36:14 **by** Michael Stanfill **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 09/15/2016 00:35:00 Equipment Type: Track Action Taken: Removed debris Vehicle removed from track. NO SIGNAL DAMAGE. Maintainer was able to watch one n.b. train through crossing with no exceptions. Operational Checks Performed Asset: HOPKINS BLVD Status Changed To: In Service PCC Notification Sent 09/15/2016 00:36:14

**Closed** 09/15/2016 00:37:25 **by** Matthew Kite **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 09/15/2016 00:35:00 Equipment Type: N/A Action Taken: NTF - UTD  
Operational Checks Performed

---

**Log#** [7528957](#) **Status** Closed **Entered** 02-21-2016 20:49:55 **by** Kite, Matt **Type** Vehicle on Track

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.2 **Block** 2763

**Section** 3090-7M16 **Asset** HOPKINS BLVD **AssetNum** 340194V **Maintainer** Stanfill, M O - ETA: 21:32

**Description** 02/21/2016 20:49:55 **by** Matthew Kite **Dept** Signals **IT+** Unknown

**Updated** 02/21/2016 20:50:48 **by** Matthew Kite **Dept** Signals **IT+** Vehicle on Track

Incident Type: TRK Dispatch incident Number: 71013 Incident Date: 21-FEB-16 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000, 0723.2000 Right Mile Post: 000, 0726.0000 Asset: 2762 001, Asset Name: MAIN PTC Flag: N Incident Description: CAR WAS STUCK ON THE TRACK AT 727.19 HOPKINS BLVD, PLEASE SEND A SIGNAL MAINTAINER AND A TRACK INSPECTOR Copied frm DIRT. Disp prot with A/F #21938. Asset: HOPKINS BLVD Status Changed To: Out Of Service PCC Notification Sent 02/21/2016 20:50:48

**Updated** 02/21/2016 20:52:54 **by** Matthew Kite **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Michael Stanfill ETA of: 21:32

**Updated** 02/21/2016 21:05:44 **by** Jodi Snyder **Dept** PSCC **IT+**  
**Contacted On** 02-21-2016 21:04:00 **Agency** Biloxi Police Department **Contact Name** Kayla **Phone** 228-392-0641  
PSCC Incident Report - Edit #7528915

**Closed** 02/21/2016 21:15:11 **by** Matthew Kite **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 02/21/2016 21:15:00 Equipment Type: N/A Action Taken: NTF - UTD  
Mntr reports vehicle removed frm trks, no damage to sig equip at crossing. Performed op checks, turned crossing

back over to disp.

Operational Checks Performed Asset: HOPKINS BLVD Status Changed To: In Service PCC Notification Sent  
02/21/2016 21:15:11

**Updated** 02/21/2016 21:19:55 **by** Alyson Trouba **Dept** PSCC **IT+**  
**Contacted On** 02-21-2016 21:19:00 **Agency** Biloxi Police Department **Contact Name** Eric **Phone** 228-392-0641  
PSCC Incident Report - Edit #7528915

---

**Log#** [7206900](#) **Status** Closed **Entered** 06-27-2015 00:59:28 **by** Belkot, Paul **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.2 **Block** 2763  
**Section** 3090-7M16 **Asset** HOPKINS BLVD **AssetNum** 340194V **Maintainer** Mannion, R - ETA: 07:28 & Broadway, J L - ETA: 03:26  
**Description** 06/27/2015 00:59:28 **by** Paul Belkot **Dept** Signals **IT+** Unknown

**Updated** 06/27/2015 01:03:18 **by** Paul Belkot **Dept** Signals **IT+** .False or partial activation reported  
gates down flashers continuous no train in area per local pd. AA disp advised to protect crossing as a false partial activation. Sent notification to ESS Atlanta div., please call mtr. Notification Sent to -Signal Control Center - Atlanta at 06/27/2015 01:03:18 Asset: HOPKINS BLVD Status Changed To: Out Of Service PCC Notification Sent 06/27/2015 01:03:18

**Updated** 06/27/2015 01:28:10 **by** Jesse Gansen **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi ms pd **Contact Name** OPERATOR 3458 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 06/27/2015 01:56:08 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Joshua Broadway ETA of: 03:26

**Updated** 06/27/2015 03:30:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 06/27/2015 05:38:56 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
0535 mtr reports the dax unit at the intermediate signal, mp 000 727.3 approx...unit has been hit by lightning... and will have to be replaced....

**Updated** 06/27/2015 06:24:22 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
0623 JUMPER LOG APPLIED ...

**Updated** 06/27/2015 06:30:33 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
0625 bohn st and Hopkins blvd affected the intermediate 000 727.3 dax unit....

**Updated** 06/27/2015 08:26:40 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Jumper Log # 7207059

**Closed** 06/27/2015 11:32:09 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 06/27/2015 11:31:00 Equipment Type: Wiring/Protection Action Taken: Repaired/Replaced Protection

**Employee:** J. Broadway

- Replaced GCP unit in the dax house...

Did OP Checks, Back/released to AA disp. Watched train thru block, no exceptions.

Operational Checks Performed Asset: HOPKINS BLVD Status Changed To: In Service PCC Notification Sent 06/27/2015 11:32:09

**Updated** 06/27/2015 11:42:50 **by** Michele Schwartz **Dept** PSCC **IT+**  
**Contacted On** 06-27-2015 11:42:00 **Agency** Biloxi ms pd **Contact Name** 2292 **Phone** 228-392-0641

---

**Log#** [6347747](#) **Status** Closed **Entered** 10-31-2013 11:11:15 **by** Miller, Vern **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.2 **Block** 2763  
**Section** 3090-Ocean Springs **Asset** HOPKINS BLVD **AssetNum** 340194V **Maintainer** Stanfill, M O - ETA: 13:17

**Description** 10/31/2013 11:11:15 **by** Verlon Miller **Dept** Signals **IT+** Unknown

**Updated** 10/31/2013 11:12:33 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
biloxi p.d. reports crossing activated, no train around. dispatcher notified to protect with false/partial activation protection.  
vern Asset: HOPKINS BLVD Status Changed To: Out Of Service PCC Notification Sent 10/31/2013 11:12:33

**Updated** 10/31/2013 11:12:48 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
. Notification Sent to -Signal Control Center - Atlanta at 10/31/2013 11:12:48

**Updated** 10/31/2013 11:15:16 **by** Christopher Joson **Dept** PSCC **IT+**  
**Contacted On** **Agency** p.d. **Contact Name** haley **Phone** 228 392 0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 10/31/2013 11:17:05 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 13:17

**Closed** 10/31/2013 11:41:23 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 10/31/2013 11:41:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended  
transportation was making op tests. xing was working as intended. made op checks and ret to disp Operational Checks  
Performed Asset: HOPKINS BLVD Status Changed To: In Service PCC Notification Sent 10/31/2013 11:41:23

**Updated** 10/31/2013 11:47:12 **by** Christopher Joson **Dept** PSCC **IT+**  
**Contacted On** 10-31-2013 11:46:00 **Agency** p.d **Contact Name** Deseree **Phone** 228 392 0641

Page Execution Time: 001.97 seconds

**Seal Avenue**

**DOT Crossing #: 340195C**

**RR Milepost #: 727.30**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 1

Status All AssetType All RootAssetType All AssetNum 340195C

---

**Log#** [5540548](#) **Status** Closed **Entered** 03-30-2012 17:31:43 **by** Bailey, Doug **Type** OUTSIDE PARTY REPORT

**Supv** Power, C **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 727.3 **Block** 2763

**Section** 7660-NOandM SUB. TRACK INSPECTOR **Asset** SEAL AVE **AssetNum** 340195C **Maintainer** LaFONTAINE, L J - *ETA*: 18:18

**Description** 03/30/2012 17:31:54 **by** Douglas Bailey **Dept** Engineering **IT+** OUTSIDE PARTY REPORT  
atl acd, aa disp, nm sub, loc 2781: PSCC reported an outside party called in a very large rock/boulder placed on  
the track at mp 000 727.3...need mow to check for possible damage

**Closed** 03/30/2012 19:23:20 **by** Douglas Bailey **Dept** Engineering **IT+** OUTSIDE PARTY REPORT  
Incident Resolved: 03/30/2012 19:23:00 Equipment Type: Track Action Taken: Inspected - No Track Issues  
Suspected Reason: Outside party or vandalism Track inspected both directions, nothing found. Operational  
Checks Performed

Page Execution Time: 007.34 seconds

**Iroquois Street**

**DOT Crossing #: 340196J**

**RR Milepost #: 727.36**



## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 1

Status All AssetType All RootAssetType All Department Signals AssetNum 340196J

---

**Log#** [7469973](#)   **Status** Closed   **Entered** 01-09-2016 00:15:18   **by** Rockhill, Jerry   **Type** Train-vehicle collision (Signals)  
**Supv** Merritt, D   **Reg** SO   **Div** AT   **Sub** NM   **IRI** 0   **Milepost** 000 727.4   **Block** 2763  
**Section** 3090-7M16   **Asset** IROQUOIS AVE   **AssetNum** 340196J   **Maintainer** Stanfill, M O - ETA: 01:54  
**Description** 01/09/2016 00:15:18   **by** Jerry Rockhill   **Dept** Signals   **IT+** Unknown

**Updated** 01/09/2016 00:17:36   **by** Jerry Rockhill   **Dept** Signals   **IT+** Train-vehicle collision (Signals)  
0016 Last Update 01-09-2016 00:01 By DRT Type General Business Impact 3 Priority 3 Incident Type: TRK Dispatch incident  
Number: 59996 Incident Date: 09-JAN-16 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000, 0726.0000 Right Mile Post: 000,  
0730.3000 Asset: 2763 003, Asset Name: MAIN PTC Flag: N Incident Description: I57907 STRUCK TRAIN AT HOPKINS RD AT  
727.19 ..... DISP PROTECTING WITH MESSAGE 39246... Asset: HOPKINS BLVD Status Changed To: Out Of Service PCC  
Notification Sent 01/09/2016 00:17:36

**Updated** 01/09/2016 00:24:22   **by** Jerry Rockhill   **Dept** Signals   **IT+** Train-vehicle collision (Signals)  
Status changed to Dispatched for Michael Stanfill ETA of: 01:54

**Updated** 01/09/2016 00:24:24   **by** Sabrina Smith   **Dept** PSCC   **IT+**  
**Contacted On** 01-09-2016 00:22:00 **Agency** Biloxi Police Department   **Contact Name** Ramona   **Phone** 228-392-0641  
PSCC Incident Report - #7469962

**Updated** 01/09/2016 01:49:53   **by** Jerry Rockhill   **Dept** Signals   **IT+** Train-vehicle collision (Signals)  
New Asset Added: 340196J - IROQUOIS AVE

**Updated** 01/09/2016 01:50:04   **by** Jerry Rockhill   **Dept** Signals   **IT+** Train-vehicle collision (Signals)  
Primary Asset changed from: 340194V - HOPKINS BLVD To: 340196J - IROQUOIS AVE

**Updated** 01/09/2016 01:52:40   **by** Jerry Rockhill   **Dept** Signals   **IT+** Train-vehicle collision (Signals)  
340196J - IROQUOIS AVE Master Asset Key 422905 AssetID 164300 Department Engineering Team Maintenance of Way Status  
In Service asset added as mow crossing... mtr will verify crossing... and then check Hopkins blvd ...

**Updated** 01/09/2016 01:53:26   **by** Jerry Rockhill   **Dept** Signals   **IT+** Train-vehicle collision (Signals)  
Last Update 01-09-2016 00:35 By DRT Type General Business Impact 3 Priority 3 Incident Type: TRK Dispatch incident Number:  
60001 Incident Date: 09-JAN-16 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000, 0726.0000 Right Mile Post: 000,  
0730.3000 Asset: 2763 003, Asset Name: MAIN PTC Flag: N Incident Description: I57907 STRUCK OCCUPIED VEHICLE AT  
IROQUOIS AVE AT 727.36

**Updated** 01/09/2016 01:55:00   **by** TCIS AUTOMATION   **Dept** Signals   **IT+** Train-vehicle collision (Signals)  
ETA time reached Status changed to Active

**Closed** 01/09/2016 02:12:59   **by** Jerry Rockhill   **Dept** Signals   **IT+** Train-vehicle collision (Signals)  
Incident Resolved: 01/09/2016 02:12:00 Equipment Type: N/A Action Taken: NTF - UTD 0208 mtr reports vehicle removed from  
xbuck xing and no damage to xbucks. mtr reports no evidence of accident was found at crossing but local pd was contacted by AA  
disp to confirm accident location was Iroquois ave xbuck xing....mtr called to to Hopkins rd prior to determining that vehicle accident  
was at Iroquois ave..... Hopkins rd ...no damage no issues found... op cks ok and crossing crossing back in service with disp.  
Operational Checks Performed Asset: HOPKINS BLVD Status Changed To: In Service PCC Notification Sent 01/09/2016 02:12:59

**Updated** 01/09/2016 02:17:51   **by** Kiwana Tompkins   **Dept** PSCC   **IT+**  
**Contacted On** 01-09-2016 02:17:00 **Agency** Biloxi Police Department   **Contact Name** Kristen   **Phone** 228-392-0641

**Benachi Avenue**

**DOT Crossing #: 340197R**

**RR Milepost #: 727.48**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 7

Status All AssetType All RootAssetType All Department Signals AssetNum 340197R

---

**Log#** [7990288](#) **Status** Closed **Entered** 02-04-2017 22:30:14 **by** Todd, Lee **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.5 **Block** 2763

**Section** 3090-7M16 **Asset** BENACHI AVE **AssetNum** 340197R **Maintainer** McCardle, B - ETA: 01:45

**Description** 02/04/2017 22:30:14 **by** Lee Todd **Dept** Signals **IT+** Unknown

**Updated** 02/04/2017 22:31:21 **by** Lee Todd **Dept** Signals **IT+** Unknown  
New Asset Added: 340199E - PORTER AVE

**Updated** 02/04/2017 22:42:03 **by** Lee Todd **Dept** Signals **IT+** .False or partial activation reported  
Local PD reports both crossings activated with no train in sight. DOT provided. Dispatcher protecting with false partial #41933/41934  
Asset: BENACHI AVE Status Changed To: Out Of Service PCC Notification Sent 02/04/2017 22:42:03 Asset: PORTER AVE Status  
Changed To: Out Of Service PCC Notification Sent 02/04/2017 22:42:03

**Updated** 02/04/2017 22:42:51 **by** Emily Morton **Dept** PSCC **IT+**  
**Contacted On** **Agency** Local PD **Contact Name** Local PD **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 02/04/2017 23:35:21 **by** David Mahan **Dept** Signals **IT+** .False or partial activation reported  
Call list exhausted, Signal supervisor will dispatch.

**Updated** 02/04/2017 23:36:02 **by** David Mahan **Dept** Signals **IT+** .False or partial activation reported

**Updated** 02/05/2017 00:45:19 **by** Charles Sydney **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Brent McCardle ETA of: 01:45

**Updated** 02/05/2017 01:50:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 02/05/2017 03:06:26 **by** Charles Sydney **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 02/05/2017 03:06:00 Equipment Type: N/A Action Taken: NTF - UTD MNTR reports: Both crossings were C.O.A.  
Unable to duplicate problem. Performed operational checks on both crossings. Crossings are working as intended. Released protection  
on both crossings. Crossings are in service. Operational Checks Performed Asset: BENACHI AVE Status Changed To: In Service PCC  
Notification Sent 02/05/2017 03:06:26 Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent 02/05/2017  
03:06:26

**Updated** 02/05/2017 03:17:40 **by** Alyson Trouba **Dept** PSCC **IT+**  
**Contacted On** 02-05-2017 03:17:00 **Agency** Biloxi Police Department **Contact Name** Shelby **Phone** 228-392-0641

---

**Log#** [7944968](#) **Status** Closed **Entered** 01-02-2017 11:48:08 **by** Hudson, Travis **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.5 **Block** 2763

**Section** 3090-7M16 **Asset** BENACHI AVE **AssetNum** 340197R **Maintainer** McCardle, B - ETA: 14:37

**Description** 01/02/2017 11:48:08 **by** Travis Hudson **Dept** Signals **IT+** Unknown

**Updated** 01/02/2017 12:02:19 **by** Travis Hudson **Dept** Signals **IT+** .False or partial activation reported  
PD reports: Crossing activating with NO train. DOT provided. **Crossing is being protected with a false/partial activation type  
message #31963.** Asset: BENACHI AVE Status Changed To: Out Of Service PCC Notification Sent 01/02/2017 12:02:19

**Updated** 01/02/2017 12:03:24 **by** Brooks Clayton **Dept** PSCC **IT+**  
**Contacted On** **Agency** PD **Contact Name** Lola **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 01/02/2017 12:38:04 **by** Travis Hudson **Dept** Signals **IT+** .False or partial activation reported  
Exhausted call list. Supervisor notified. The incident handed over to the Supervisor of the territory for further handling.

**Updated** 01/02/2017 13:37:04 **by** Jesuito Mercado **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Brent McCardle ETA of: 14:37

**Updated** 01/02/2017 14:40:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 01/02/2017 16:43:44 **by** David Price **Dept** Signals **IT+** .False or partial activation reported  
mtr jumpered the crossing and is getting some parts.

**Updated** 01/02/2017 18:48:50 **by** Andrew Stancil **Dept** Signals **IT+** .False or partial activation reported  
SENT MAINTAINER A MESSAGE REQUESTING UPDATE

**Closed** 01/02/2017 20:26:39 **by** Carlos Betancourt **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 01/02/2017 20:26:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced Termination  
Shunt Replaced sb start, narrow band shunt. Operational Checks Performed Asset: BENACHI AVE Status Changed To: In Service  
PCC Notification Sent 01/02/2017 20:26:39

**Updated** 01/02/2017 21:34:43 **by** Kiwana Tompkins **Dept** PSCC **IT+**  
**Contacted On** 01-02-2017 21:34:00 **Agency** Biloxi Police Department **Contact Name** Lola **Phone** 228-392-0641

---

**Log#** [7724634](#) **Status** Closed **Entered** 07-19-2016 12:49:17 **by** Jackson Jr, Marv **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.5 **Block** 2763

**Section** 3090-7M16 **Asset** BENACHI AVE **AssetNum** 340197R **Maintainer** Stanfill, M O - ETA: 13:58

**Description** 07/19/2016 12:49:17 **by** Marv Jackson Jr **Dept** Signals **IT+** Unknown

**Updated** 07/19/2016 12:51:41 **by** Marv Jackson Jr **Dept** Signals **IT+** .False or partial activation reported  
OSP REPORTS FALSE ACTIVATION AT BENACHI AVE. Notification Sent to -Signal Control Center - Atlanta at  
07/19/2016 12:51:41 Asset: BENACHI AVE Status Changed To: Out Of Service PCC Notification Sent 07/19/2016 12:51:41

**Updated** 07/19/2016 12:58:58 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 13:58

**Updated** 07/19/2016 13:06:31 **by** Christina Martorano **Dept** PSCC **IT+**  
**Contacted On** 07-19-2016 13:04:00 **Agency** Biloxi Police **Contact Name** 3474 **Phone** 228-392-0641  
Howard Ave

**Updated** 07/19/2016 14:00:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 07/19/2016 15:12:12 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 07/19/2016 15:10:00 Equipment Type: Wiring/Protection Action Taken: Repaired/Replaced Protection

**The Signal Maintainer replaced the lightning protection. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: BENACHI AVE Status Changed To: In Service PCC Notification Sent 07/19/2016 15:12:12

**Updated** 07/19/2016 17:19:21 **by** Alexis Romine **Dept** PSCC **IT+**  
**Contacted On** 07-19-2016 17:19:00 **Agency** Biloxi Police **Contact Name** Jackie **Phone** 228-392-0641  
Howard Ave

---

**Log#** [7683041](#) **Status** Closed **Entered** 06-17-2016 23:44:47 **by** Rowe, Christopher **Type** .False or partial activation reported

Supv Merritt, D Reg SO Div AT Sub NM IRI 0 Milepost 000 727.5 Block 2763

Section 3090-7M16 Asset BENACHI AVE AssetNum 340197R Maintainer Stanfill, M O - ETA: 04:23

Description 06/17/2016 23:44:47 by Christopher Rowe Dept Signals IT+ Unknown

Updated 06/18/2016 00:00:14 by Christopher Rowe Dept Signals IT+ .False or partial activation reported  
CROSSING ACTIVATED NO TRAINS IN THE VICINITY. Notification Sent to -Signal Control Center - Atlanta at 06/18/2016  
00:00:14 Asset: BENACHI AVE Status Changed To: Out Of Service PCC Notification Sent 06/18/2016 00:00:14

Updated 06/18/2016 00:13:11 by Kiwana Tompkins Dept PSCC IT+  
Contacted On Agency BILOXI PD Contact Name DISPATCHER` Phone 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

Updated 06/18/2016 02:23:46 by Jerry Rockhill Dept Signals IT+ .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 04:23

Updated 06/18/2016 04:25:00 by TCIS AUTOMATION Dept Signals IT+ .False or partial activation reported  
ETA time reached Status changed to Active

Closed 06/18/2016 04:57:59 by Jerry Rockhill Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 06/18/2016 04:57:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced Track Card 0456  
MTR REPORTS REPLACED TRANSIEVER CARD DUE TO LIGHTNING ... OP CKS OK AND BACK IN SERVICE WITH DISP...  
Operational Checks Performed Asset: BENACHI AVE Status Changed To: In Service PCC Notification Sent 06/18/2016 04:57:59

Updated 06/18/2016 05:03:48 by Thera Moore Dept PSCC IT+  
Contacted On 06-18-2016 05:03:00 Agency BILOXI PD Contact Name 1955 Phone 228-392-0641

---

Log# [6903068](#) Status Closed Entered 11-30-2014 13:54:29 by Foster, George Type .False or partial activation reported

Supv Merritt, D Reg SO Div AT Sub NM IRI 0 Milepost 000 727.5 Block 2763

Section 3090-7M16 Asset BENACHI AVE AssetNum 340197R Maintainer Wilson, C E - ETA: 16:21

Description 11/30/2014 13:54:29 by George Foster Dept Signals IT+ Unknown

Updated 11/30/2014 13:58:11 by George Foster Dept Signals IT+ .False or partial activation reported  
After trains go through the crossing the crossing remains activated for about 10 minutes while the crossing near by has already  
recovered. Notification Sent to -Signal Control Center - Atlanta at 11/30/2014 13:58:11 Asset: BENACHI AVE Status Changed To:  
Out Of Service PCC Notification Sent 11/30/2014 13:58:11

Updated 11/30/2014 14:13:14 by Jodi Snyder Dept PSCC IT+  
Contacted On 11-30-2014 13:59:00 Agency Biloxi Police Department Contact Name 3411 Phone 228-392-0641  
Howard Ave

Updated 11/30/2014 14:19:34 by Jason Gothard Dept Signals IT+ .False or partial activation reported  
Status changed to Dispatched for Joshua Broadway ETA of: 16:19

Updated 11/30/2014 16:20:00 by TCIS AUTOMATION Dept Signals IT+ .False or partial activation reported  
ETA time reached Status changed to Active

Closed 11/30/2014 17:11:02 by Matthew Kite Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 11/30/2014 17:09:00 Equipment Type: N/A Action Taken: NTF - UTD  
Mntr reports crossing COA. Performed op checks, EZ:95 EX:88, mntr saw sig contr tm working in area at another crossing. Turned  
crossing backover to disp.  
Operational Checks Performed Asset: BENACHI AVE Status Changed To: In Service PCC Notification Sent 11/30/2014 17:11:02

Updated 11/30/2014 17:20:49 by Avie Saunders Dept PSCC IT+  
Contacted On 11-30-2014 17:20:00 Agency Biloxi Police Department Contact Name John Phone 228-392-0641

---

Log# [5765513](#) Status Closed Entered 09-02-2012 11:46:03 by Kondy, Rick Type .False or partial activation reported

Supv Merritt, D Reg SO Div AT Sub NM IRI Milepost 000 727.5 Block 2763

Section 3090-Ocean Springs Asset BENACHI AVE AssetNum 340197R Maintainer Houck, B - ETA: 19:17

Description 09/02/2012 11:47:05 by Richard Kondy Dept Signals IT+ .False or partial activation reported  
GATES DOWN , NO TRAINS . DISP PROTECTING CROSSING WITH FALSE ACTIVATION # 39991 . Notification Sent to -Signal Control Center - Atlanta at 09/02/2012 11:47:05 Asset: BENACHI AVE Status Changed To: Out Of Service PCC Notification Sent 09/02/2012 11:47:05

Updated 09/02/2012 12:05:37 by Deborah Anderson Dept PSCC IT+  
Contacted On Agency // Contact Name BILOXI POLICE Phone 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

Updated 09/02/2012 13:50:45 by Bruce McVey Dept Signals IT+ .False or partial activation reported  
• Exhausted the call list, escalated to sig mgr Smale. he stated that he will get someone to cover call.

Updated 09/02/2012 14:27:16 by Bruce McVey Dept Signals IT+ .False or partial activation reported  
• Briefed JAX duty mgr call list exhausted.

Closed 09/02/2012 19:17:04 by Matthew Kite Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 09/02/2012 19:09:00 Equipment Type: Power/batteries Action Taken: Other electrical Suspected Reason: Other weather  
Mntr reports open test nut on OB battery bank, tightened dwn. Performed op checks, turned crossing backover to disp. Crossing had been OOS due to Hurricane Issac, sig construction tms placing assets BIS.  
Operational Checks Performed Asset: BENACHI AVE Status Changed To: In Service PCC Notification Sent 09/02/2012 19:17:04

Updated 09/02/2012 19:22:32 by Emily Morton Dept PSCC IT+  
Contacted On 09-02-2012 19:22:00 Agency BILOXI POLICE Contact Name Sara Phone 228-392-0641

---

Log# [5576611](#) Status Closed Entered 04-25-2012 17:27:57 by Mercado, Wito Type .False or partial activation reported

Supv Merritt, D Reg SO Div AT Sub NM IRI Milepost 000 727.5 Block 2763

Section 3090-Ocean Springs Asset BENACHI AVE AssetNum 340197R Maintainer Houck, B - ETA: 18:14

Description 04/25/2012 17:30:12 by Jesuito Mercado Dept Signals IT+ .False or partial activation reported  
1728hr Local pd reports crossing is activated with no trains present... Notification Sent to -Signal Control Center - Atlanta at 04/25/2012 17:30:12 Asset: BENACHI AVE Status Changed To: Out Of Service PCC Notification Sent 04/25/2012 17:30:12

Updated 04/25/2012 17:40:52 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported

The AA Dispatcher is protecting the crossing with a **Type 2 False / Partial Activation Message# 24991**. LVR

Updated 04/25/2012 17:44:01 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported  
A email notification for Multi Failure Count (MFC) asset PORTER AVE (4) has been sent to the following:  
Terrence Smale II  
John Parr

Updated 04/25/2012 17:44:01 by Brad Oglesby Dept Signals IT+ .False or partial activation reported  
New Asset Added: 340199E - PORTER AVE

Updated 04/25/2012 17:46:05 by Kihron Bristol Dept PSCC IT+  
Contacted On Agency BILOXI,PD Contact Name Oper Miller Phone 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

Updated 04/25/2012 17:46:45 by Brad Oglesby Dept Signals IT+ .False or partial activation reported  
1744 THE LOCAL PD REPORTED THAT PORTER AVE. CROSSING IS ALSO ACTIVATED WITHOUT ANY TRAINS PRESENT(DOT NUMBER PROVIDED). 1745 ADVISED THE AA DISPATCHER TO PROVIDE PROTECTION ON PORTER AVE. CROSSING AS PER FALSE ACTIVATION STANDARD. Notification Sent to -Signal Control Center - Atlanta at 04/25/2012 17:46:45 Asset: PORTER AVE Status Changed To: Out Of Service PCC Notification Sent 04/25/2012 17:46:45

Updated 04/25/2012 18:14:34 by Kihron Bristol Dept PSCC IT+  
Contacted On Agency BILOXI,PD Contact Name Oper Miller Phone 228-392-0641

Reporting party has been verified as the responsible law enforcement agency.

**Updated** 04/25/2012 19:37:52      **by** Louis Rosenblatt **Dept** Signals      **IT+** .False or partial activation reported

**Update** - The Signal Maintainer reports finding a bad 211 hz Multishunt. He is looking for a replacement Multishunt as the start requires a dummyload. LVR

**Closed** 04/25/2012 23:18:02      **by** Jerry Rockhill      **Dept** Signals      **IT+** .False or partial activation reported  
Incident Resolved: 04/25/2012 23:15:00 Equipment Type: Track Action Taken: Termination shunt-repaired/replaced Suspected Reason: N/A 2314 mtr reports replacing 211 start at the dax unit at intermediate signal 727...op cks ok and both crossings back in service with disp... Operational Checks Performed Asset: BENACHI AVE Status Changed To: In Service PCC Notification Sent 04/25/2012 23:18:02 Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent 04/25/2012 23:18:02

**Updated** 04/25/2012 23:25:33      **by** Terry Lloyd      **Dept** PSCC      **IT+**  
**Contacted On** 04-25-2012 23:24:00 **Agency** BILOXI PD **Contact Name** Operator Porter **Phone** 228-392-0641

Page Execution Time: 002.21 seconds



**Querens Avenue**

**DOT Crossing #: 340198X**

**RR Milepost #: 727.53**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 1

Status All AssetType All RootAssetType All Department Signals AssetNum 340198X

---

**Log#** [7378435](#) **Status** Closed **Entered** 10-27-2015 15:15:30 **by** Gaspar, Sean **Type** -Informational

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.5 **Block** 2763

**Section** 3090-7M16 **Asset** QUERENS ST **AssetNum** 340198X **Maintainer**

**Description** 10/27/2015 15:15:30 **by** Sean Gaspar **Dept** Signals **IT+** Unknown

**Updated** 10/27/2015 15:20:01 **by** Sean Gaspar **Dept** Signals **IT+** -Informational  
one hood on one flasher has fallen off. dot provided. otherwise xing is operating normally. please have mtr check in am. briefed c&s manager.

**Closed** 10/28/2015 11:14:15 **by** Bruce McVey **Dept** Signals **IT+** -Informational  
Incident Resolved: 10/28/2015 11:13:00 Equipment Type: Cantilever/Mast Action Taken: Repaired/Replaced  
Lamp/Roundel replaced 1 hood on flasher... Operational Checks Performed

Page Execution Time: 001.69 seconds

**Porter Avenue**

**DOT Crossing #: 340199E**

**RR Milepost #: 727.58**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 22

Status All AssetType All RootAssetType All Department Signals AssetNum 340199E

---

**Log#** [7982224](#) **Status** Closed **Entered** 01-30-2017 04:00:47 **by** Johnstone, Terry **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 727.6 **Block** 2763

**Section** 3090-7M16 **Asset** PORTER AVE **AssetNum** 340199E **Maintainer**

**Description** 01/30/2017 04:00:47 **by** Terry Johnstone **Dept** Signals **IT+** Unknown

**Updated** 01/30/2017 04:04:09 **by** Terry Johnstone **Dept** Signals **IT+** .False or partial activation reported  
Local PD reports crossing activated with no trains. DOT # provided Dispatcher protecting with message # 32198 Asset: PORTER AVE Status Changed To: Out Of Service PCC Notification Sent 01/30/2017 04:04:09

**Updated** 01/30/2017 04:04:12 **by** Terry Johnstone **Dept** Signals **IT+** .False or partial activation reported  
An email notification for (IRI) asset PORTER AVE (1) has been sent to the following:  
George James Jr

**Updated** 01/30/2017 04:11:06 **by** Emily Morton **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi PD **Contact Name** OP 3631 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 01/30/2017 04:14:57 **by** Thomas Haselden **Dept** Signals **IT+** .False or partial activation reported  
New Asset Added: 340197R - BENACHI AVE

**Updated** 01/30/2017 04:14:57 **by** Thomas Haselden **Dept** Signals **IT+** .False or partial activation reported  
New Asset Added: 340198X - QUERENS ST

**Updated** 01/30/2017 04:20:19 **by** Thomas Haselden **Dept** Signals **IT+** .False or partial activation reported  
Officer called back and reported two more crossings activated with dot# provided Dispatcher protecting Benachi with f/p msg # 32201 Querens with f/p msg # 32204 Asset: BENACHI AVE Status Changed To: Out Of Service PCC Notification Sent 01/30/2017 04:20:19 Asset: QUERENS ST Status Changed To: Out Of Service PCC Notification Sent 01/30/2017 04:20:19

**Updated** 01/30/2017 04:21:01 **by** Alyson Trouba **Dept** PSCC **IT+**  
**Contacted On** 01-30-2017 04:20:00 **Agency** Biloxi PD **Contact Name** OP 3631 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 01/30/2017 05:19:35 **by** Terry Johnstone **Dept** Signals **IT+** .False or partial activation reported  
Ran list twice. List exhausted...

**Updated** 01/30/2017 05:21:58 **by** Terry Johnstone **Dept** Signals **IT+** .False or partial activation reported  
Manager notified, will handle.

**Updated** 01/30/2017 07:57:25 **by** Hess Branch **Dept** Signals **IT+** .False or partial activation reported  
Manager will resolve

**Updated** 01/30/2017 09:01:23 **by** Joseph Williams **Dept** Signals **IT+** .False or partial activation reported  
Dispatcher is protecting Porter Ave with message #32603.

**Closed** 01/30/2017 10:11:25 **by** Marion Wilburn **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 01/30/2017 10:11:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced Track Card 1009 Hrs. Supv. replaced 80016 card at 727-intermediate signal Operational Checks Performed Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent 01/30/2017 10:11:25 Asset: BENACHI AVE Status Changed To: In Service PCC Notification Sent 01/30/2017 10:11:25 Asset: QUERENS ST Status Changed To: In Service PCC Notification Sent 01/30/2017 10:11:25

**Updated** 01/30/2017 10:19:06 **by** Sabrina Smith **Dept** PSCC **IT+**  
**Contacted On** 01-30-2017 10:17:00 **Agency** Biloxi PD **Contact Name** angie **Phone** 228-392-0641

---

**Log#** [7945358](#) **Status** Closed **Entered** 01-02-2017 19:09:22 **by** Carter, Jake **Type** .False or partial activation reported

Supv Merritt, D Reg SO Div AT Sub NM IRI 0 Milepost 000 727.6 Block 2763

Section 3090-7M16 Asset PORTER AVE AssetNum 340199E Maintainer McCardle, B - ETA: 20:28

Description 01/02/2017 19:09:22 by Jake Carter Dept Signals IT+ Unknown

Updated 01/02/2017 19:14:26 by Jake Carter Dept Signals IT+ .False or partial activation reported  
Local Pd reports xng is activated, w/no train;disp is protecting as f/p Asset: PORTER AVE Status Changed To: Out Of Service PCC Notification Sent 01/02/2017 19:14:26

Updated 01/02/2017 19:32:24 by Jake Carter Dept Signals IT+ .False or partial activation reported  
call list exh'd; Sig Mgr James notified and He asked to be esc'd to Him

Updated 01/02/2017 19:58:05 by Byron Tinsley Dept PSCC IT+  
Contacted On Agency Biloxi Pd Contact Name Eric Phone 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

Updated 01/02/2017 20:28:23 by Carlos Betancourt Dept Signals IT+ .False or partial activation reported  
Status changed to Dispatched for Brent McCardle ETA of: N/A

Closed 01/02/2017 20:29:30 by Carlos Betancourt Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 01/02/2017 20:29:00 Equipment Type: N/A Action Taken: NTF - UTD Mntr Mccardle was replacing a sb start at BENACHI AVE, op checks made and wai. Operational Checks Performed Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent 01/02/2017 20:29:30

Updated 01/02/2017 20:46:13 by Byron Tinsley Dept PSCC IT+  
Contacted On 01-02-2017 20:45:00 Agency Biloxi Pd Contact Name 911 Phone 228-392-0641

---

Log# [7559097](#) Status Closed Entered 03-15-2016 03:41:31 by Kite, Matt Type .False or partial activation reported

Supv Merritt, D Reg SO Div AT Sub NM IRI 0.125 Milepost 000 727.6 Block 2763

Section 3090-7M16 Asset PORTER AVE AssetNum 340199E Maintainer Broadway, J L - ETA: 05:28

Description 03/15/2016 03:41:31 by Matthew Kite Dept Signals IT+ Unknown

Updated 03/15/2016 03:44:45 by Matthew Kite Dept Signals IT+ .False or partial activation reported

Mntr was clearing up area preparing to leave crossing after work and noted DAX unit went back into high signal after train cleared and crossing re-activated. Disp prot crossing with F/P #18543. Mntr Richardson is now HSL, notified Sig Sup James. ESS re-running call list.  
Asset: PORTER AVE Status Changed To: Out Of Service PCC Notification Sent 03/15/2016 03:44:45

Updated 03/15/2016 03:44:46 by Matthew Kite Dept Signals IT+ .False or partial activation reported  
An email notification for (IRI) asset PORTER AVE (1) has been sent to the following:  
George James Jr

Updated 03/15/2016 03:56:50 by Kiwana Tompkins Dept PSCC IT+  
Contacted On 03-15-2016 03:55:00 Agency Biloxi Police Department Contact Name 3501 Phone 228-392-0641  
E Howard Ave

Updated 03/15/2016 03:58:47 by Matthew Kite Dept Signals IT+ .False or partial activation reported  
Status changed to Dispatched for Joshua Broadway ETA of: 05:28

Updated 03/15/2016 05:30:00 by TCIS AUTOMATION Dept Signals IT+ .False or partial activation reported  
ETA time reached Status changed to Active

Closed 03/15/2016 07:39:29 by Bruce McVey Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 03/15/2016 07:39:00 Equipment Type: Wiring/Protection Action Taken: Repaired/Replaced Island Circuit Wiring

Employee: J. Broadway

- replaced track connections and found hy-res wires under rails. at 727 sig repaired all

Did OP Checks, Back/released to AA disp. Watched train thru crossing, no exceptions.

Operational Checks Performed Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent 03/15/2016 07:39:29

**Updated** 03/15/2016 07:40:51 **by** Avie Saunders **Dept** PSCC **IT+**  
**Contacted On** 03-15-2016 07:40:00 **Agency** Biloxi Police Department **Contact Name** 1955 **Phone** 228-392-0641

---

**Log#** [7558876](#) **Status** Closed **Entered** 03-14-2016 20:26:30 **by** Foster, George **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.6 **Block** 2763

**Section** 3090-7M16 **Asset** PORTER AVE **AssetNum** 340199E **Maintainer** Richardson, G L - *ETA*: 22:36

**Description** 03/14/2016 20:26:30 **by** George Foster **Dept** Signals **IT+** Unknown

**Updated** 03/14/2016 20:30:02 **by** George Foster **Dept** Signals **IT+** .False or partial activation reported  
Crossing activated with no trains. DOT was given. Notification Sent to -Signal Control Center - Atlanta at 03/14/2016  
20:30:02 **Asset**: PORTER AVE **Status Changed To**: Out Of Service **PCC Notification Sent** 03/14/2016 20:30:02

**Updated** 03/14/2016 20:59:56 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** **Agency** 911 **Contact Name** 3497 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 03/14/2016 21:36:25 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
**Status changed to** Dispatched for Gregory Richardson *ETA* of: 22:36

**Updated** 03/14/2016 22:40:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
**ETA time reached** **Status changed to** Active

**Updated** 03/15/2016 02:12:57 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Mntr reports DAX unit at 727 in high signal, 348hz start bad, replaced. Mntr reports another issue effecting crossing also has 3 daxed crossings dwn. Notified Sig Sup, mntr is going HSL. Re-running call list.

**Closed** 03/15/2016 03:01:50 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
**Incident Resolved**: 03/15/2016 03:01:00 **Equipment Type**: Crossing Controller **Action Taken**: Repaired/Replaced  
Termination Shunt

Mntr found complicating issues in field. Replaced lightning arrestors for 48 Dax unit at 727 mp. At Denachi St, replaced lightning arrestors in bungalow. At Porter St, replaced lightning arrestors in bungalow and transceiver cd in 3k unit, then recalibrated. Performed op checks, all crossings operating as intended. Turned back over to disp.  
**Operational Checks Performed** **Asset**: PORTER AVE **Status Changed To**: In Service **PCC Notification Sent** 03/15/2016 03:01:50

**Updated** 03/15/2016 03:05:36 **by** Alyson Trouba **Dept** PSCC **IT+**  
**Contacted On** 03-15-2016 03:05:00 **Agency** 911 **Contact Name** Walton **Phone** 228-392-0641

---

**Log#** [7506990](#) **Status** Closed **Entered** 02-05-2016 08:55:00 **by** Miller, Vern **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.6 **Block** 2763

**Section** 3090-7M16 **Asset** PORTER AVE **AssetNum** 340199E **Maintainer** Stanfill, M O - *ETA*: 09:44

**Description** 02/05/2016 08:55:00 **by** Verlon Miller **Dept** Signals **IT+** Unknown

**Updated** 02/05/2016 08:56:30 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
crossing activated, no train around. dispatcher notified to protect with false/partial activation protection. vern **Asset**: PORTER AVE  
**Status Changed To**: Out Of Service **PCC Notification Sent** 02/05/2016 08:56:30

**Updated** 02/05/2016 08:56:46 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
. **Notification Sent to** -Signal Control Center - Atlanta at 02/05/2016 08:56:46

**Updated** 02/05/2016 08:59:43 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
**Status changed to** Dispatched for Michael Stanfill *ETA* of: 09:44

**Updated** 02/05/2016 09:03:57 **by** Terry Lloyd **Dept** PSCC **IT+**  
**Contacted On** 02-05-2016 09:01:00 **Agency** Biloxi Police Department **Contact Name** 2317 **Phone** 228-392-0641  
@ W Howard Ave

**Updated** 02/05/2016 09:45:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
**ETA time reached** **Status changed to** Active

**Closed** 02/05/2016 10:56:36 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 02/05/2016 10:55:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced/Reset CPU  
Mntr reports unit in high signal, trk conditions changed, recalibrated unit. Performed op checks, turned crossing back over to disp.  
Operational Checks Performed Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent 02/05/2016 10:56:36

**Updated** 02/05/2016 11:07:26 **by** Terry Lloyd **Dept** PSCC **IT+**  
**Contacted On** 02-05-2016 11:06:00 **Agency** Biloxi Police Department **Contact Name** 2317 **Phone** 228-392-0641

---

**Log#** [7409217](#) **Status** Closed **Entered** 11-19-2015 05:55:52 **by** Wood, Zach **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.6 **Block** 2763

**Section** 3090-7M16 **Asset** PORTER AVE **AssetNum** 340199E **Maintainer** Stanfill, M O - *ETA: 08:53*

**Description** 11/19/2015 05:55:52 **by** Zacchaeus Wood **Dept** Signals **IT+** Unknown

**Updated** 11/19/2015 05:59:03 **by** Zacchaeus Wood **Dept** Signals **IT+** .False or partial activation reported  
Local PD reports crossing activated w/ no trains present, DOT# provided. Crossing protected w/ F/P activation. Notification  
Sent to -Signal Control Center - Atlanta at 11/19/2015 05:59:03 Asset: PORTER AVE Status Changed To: Out Of Service  
PCC Notification Sent 11/19/2015 05:59:03

**Updated** 11/19/2015 06:11:08 **by** Brooks Clayton **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi City PD **Contact Name** Megan **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 11/19/2015 06:53:39 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 08:53

**Updated** 11/19/2015 08:55:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 11/19/2015 09:15:30 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 11/19/2015 09:14:00 Equipment Type: N/A Action Taken: NTF - UTD

**Employee:** M. Stanfill

- Crossing was clear when MTR arrived, could not duplicate the trouble. Crossing is working as intended.

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent 11/19/2015  
09:15:30

**Updated** 11/19/2015 09:22:37 **by** Terry Lloyd **Dept** PSCC **IT+**  
**Contacted On** 11-19-2015 09:21:00 **Agency** Biloxi City PD **Contact Name** Jackie **Phone** 228-392-0641

---

**Log#** [6643177](#) **Status** Closed **Entered** 05-31-2014 14:49:55 **by** McClure, Dale **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 727.6 **Block** 2763

**Section** 3090-Ocean Springs **Asset** PORTER AVE **AssetNum** 340199E **Maintainer** Lumpkin, K J - *ETA: 18:04* & James Jr, G H - *ETA: 16:31*

**Description** 05/31/2014 14:49:55 **by** Dale McClure **Dept** Signals **IT+** Unknown

**Updated** 05/31/2014 14:52:40 **by** Dale McClure **Dept** Signals **IT+** .False or partial activation reported  
POLICE REPORTING THIS CROSSING IS ACTIVATED/ NO TRAINS PRESENT. AA DISP. NOTIFIED AND INSTRUCTED TO  
PROTECT AS FALSE/ PARTIAL ACTIVATION UNTIL CHECKED. Asset: PORTER AVE Status Changed To: Out Of Service PCC  
Notification Sent 05/31/2014 14:52:40

**Updated** 05/31/2014 15:06:06 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 16:36

**Updated** 05/31/2014 15:07:56 **by** Avie Saunders **Dept** PSCC **IT+**  
**Contacted On** 05-31-2014 15:07:00 **Agency** Biloxi Police Department **Contact Name** Lola **Phone** 228-392-0641

**Updated** 05/31/2014 16:31:29 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Escalated, George James Jr ETA of: N/A



**Updated** 05/31/2014 16:32:09 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Call list exhausted. Notified Sig Sup James and NOC C&S Manager.

**Updated** 05/31/2014 16:34:31 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Kevin Lumpkin ETA of: 18:04

**Updated** 05/31/2014 16:35:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 05/31/2014 16:36:26 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Changed status. Sup informed.

**Closed** 05/31/2014 20:25:54 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 05/31/2014 20:22:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced Track Card  
Sig Sup reports 812 cd replaced at crossing. Performed op checks, turned crossing backover to disp.  
Operational Checks Performed Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent 05/31/2014 20:25:54

**Updated** 05/31/2014 20:49:28 **by** Misty Hunter **Dept** PSCC **IT+**  
**Contacted On** 05-31-2014 20:49:00 **Agency** Biloxi Police Department **Contact Name** Donna **Phone** 228-392-0641

---

**Log#** [6642161](#) **Status** Closed **Entered** 05-30-2014 16:06:23 **by** Tyo, Mark **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.6 **Block** 2763  
**Section** 3090-Ocean Springs **Asset** PORTER AVE **AssetNum** 340199E **Maintainer** Lumpkin, K J - ETA: 18:49 & James Jr, G H - ETA: 17:01  
**Description** 05/30/2014 16:06:23 **by** Mark Tyo **Dept** Signals **IT+** Unknown

**Updated** 05/30/2014 16:09:16 **by** Mark Tyo **Dept** Signals **IT+** .False or partial activation reported  
Reported crossing activated no trains. Disp is protecting.....OSP reported he could not read Numbers off our signs..... Notification  
Sent to -Signal Control Center - Atlanta at 05/30/2014 16:09:16 Asset: PORTER AVE Status Changed To: Out Of Service PCC  
Notification Sent 05/30/2014 16:09:16

**Updated** 05/30/2014 16:13:30 **by** Avie Saunders **Dept** PSCC **IT+**  
**Contacted On** 05-30-2014 16:10:00 **Agency** Biloxi Police Department **Contact Name** Jackie **Phone** 228-392-0641  
Howard Ave

**Updated** 05/30/2014 17:01:34 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Escalated, George James Jr ETA of: N/A

**Updated** 05/30/2014 17:07:20 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
C&S Manager Briefed.

**Updated** 05/30/2014 17:19:09 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Kevin Lumpkin ETA of: 18:49

**Updated** 05/30/2014 17:20:01 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 05/30/2014 18:49:47 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 05/30/2014 18:48:00 Equipment Type: N/A Action Taken: NTF - UTD

**The Signal Maintainer reported that the Crossing was working when he got there. He watched a Southbound train through the crossing with twenty-seven seconds of Warning Time. The crossing cleared as it is supposed to. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent 05/30/2014 18:49:47

**Updated** 05/30/2014 18:55:02 **by** Sean Reid **Dept** PSCC **IT+**  
**Contacted On** 05-30-2014 18:53:00 **Agency** Biloxi Police Department **Contact Name** Eric **Phone** 228-392-0641  
Howard Ave

---

**Log#** [6560335](#) **Status** Closed **Entered** 04-02-2014 14:08:52 **by** ORegan, Terrence **Type** .False or partial activation reported

Supv Merritt, D Reg SO Div AT Sub NM IRI 0 Milepost 000 727.6 Block 2763

Section 3090-Ocean Springs Asset PORTER AVE AssetNum 340199E Maintainer Stanfill, M O - ETA: 15:18

Description 04/02/2014 14:08:52 by Terrence ORegan Dept Signals IT+ Unknown

Updated 04/02/2014 14:11:41 by Terrence ORegan Dept Signals IT+ .False or partial activation reported  
Local police reports that the crossing is activated with no trains in the area. Dispatcher is protecting with a false partial type of protection. Notification Sent to -Signal Control Center - Atlanta at 04/02/2014 14:11:41 Asset: PORTER AVE Status Changed To: Out Of Service PCC Notification Sent 04/02/2014 14:11:41

Updated 04/02/2014 14:13:00 by Max Todd Dept PSCC IT+  
Contacted On Agency Local pd Contact Name 347 Phone 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

Updated 04/02/2014 14:18:32 by Jason Gothard Dept Signals IT+ .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 15:18

Updated 04/02/2014 15:20:12 by TCIS AUTOMATION Dept Signals IT+ .False or partial activation reported  
ETA time reached Status changed to Active

Closed 04/02/2014 15:32:20 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 04/02/2014 15:29:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced Track Card

**The Signal Maintainers replaced the transceiver module on the Main side with the transceiver module from the Standby side. Operational Checks were performed. He will return later with a new card. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent 04/02/2014 15:32:20

Updated 04/02/2014 15:35:01 by Max Todd Dept PSCC IT+  
Contacted On 04-02-2014 15:34:00 Agency Biloxi Police Department Contact Name 3235 Phone 228-392-0641  
at E. Howard Ave.

---

Log# [6483975](#) Status Closed Entered 02-09-2014 19:15:19 by Tyo, Mark Type .False or partial activation reported

Supv Merritt, D Reg SO Div AT Sub NM IRI 0.125 Milepost 000 727.6 Block 2763

Section 3090-Ocean Springs Asset PORTER AVE AssetNum 340199E Maintainer Houck, B - ETA: 20:59

Description 02/09/2014 19:15:19 by Mark Tyo Dept Signals IT+ Unknown

Updated 02/09/2014 19:21:30 by Mark Tyo Dept Signals IT+ .False or partial activation reported  
Reported crossing activated no trains. DOT # was given. Disp is protecting. Notification Sent to -Signal Control Center - Atlanta at 02/09/2014 19:21:30 Asset: PORTER AVE Status Changed To: Out Of Service PCC Notification Sent 02/09/2014 19:21:30

Updated 02/09/2014 19:22:26 by Avie Saunders Dept PSCC IT+  
Contacted On Agency Biloxi PD Contact Name Jennifer Phone 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

Updated 02/09/2014 19:59:06 by Matthew Kite Dept Signals IT+ .False or partial activation reported  
Status changed to Dispatched for Bradley Houck ETA of: 20:59

Updated 02/09/2014 21:00:00 by TCIS AUTOMATION Dept Signals IT+ .False or partial activation reported  
ETA time reached Status changed to Active

Closed 02/09/2014 22:05:23 by Matthew Kite Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 02/09/2014 21:54:00 Equipment Type: Wiring/Protection Action Taken: Repaired/Replaced Protection  
Mntr reports crossing in-trouble upon arrival, also found Benachi Rd crossing activated. Replaced bad lightning arrestor on unit at Porter Ave. Mntr found shared DAX unit between Porter and Benachi was putting out code to int sig at MP: 000 727, but unit was not reporting back. Mntr states crossings cleared after surge prot was replaced and additional op checks were made. Crossings both operating as intended. Mntr turned Porter Ave backover to disp. Will notify Sig Sup James and territory mntr in AM about incident.  
Operational Checks Performed Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent 02/09/2014 22:05:23

Updated 02/09/2014 22:13:50 by Christopher Horman Dept PSCC IT+

**Log#** [6482660](#) **Status** Closed **Entered** 02-08-2014 14:15:29 **by** Miller, Vern **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.6 **Block** 2763

**Section** 3090-Ocean Springs **Asset** PORTER AVE **AssetNum** 340199E **Maintainer** James Jr, G H - ETA: 16:10

**Description** 02/08/2014 14:15:29 **by** Verlon Miller **Dept** Signals **IT+** Unknown

**Updated** 02/08/2014 14:16:44 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
crossing activated, no train around. dispatcher notified to protect with false/partial active action protection. vern  
Asset: PORTER AVE Status Changed To: Out Of Service PCC Notification Sent 02/08/2014 14:16:44

**Updated** 02/08/2014 14:20:44 **by** Sean Reid **Dept** PSCC **IT+**  
**Contacted On** **Agency** p.d. **Contact Name** sara **Phone** 228 392 0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 02/08/2014 16:10:45 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Escalated, George James Jr ETA of: N/A

**Updated** 02/08/2014 16:11:19 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Call list exhausted. Notified Sig Sup James and NOC C&S Manager.

**Closed** 02/08/2014 19:05:00 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 02/08/2014 18:30:00 Equipment Type: Case equipment Action Taken: Repaired/Replaced  
Case Wiring - Not Track Related  
Sup reports Dax Unit was down, lightning arrestor shorted out on neg side, replaced lightning arrestor. Performed  
op checks, turned crossing backover to disp.  
Operational Checks Performed Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent  
02/08/2014 19:05:00

**Updated** 02/08/2014 19:21:09 **by** Jesse Gansen **Dept** PSCC **IT+**  
**Contacted On** 02-08-2014 19:20:00 **Agency** p.d. **Contact Name** 315 **Phone** 228 392 0641

**Log#** [6405412](#) **Status** Closed **Entered** 12-16-2013 08:01:27 **by** Lewis, Wendell **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.6 **Block** 2763

**Section** 3090-Ocean Springs **Asset** PORTER AVE **AssetNum** 340199E **Maintainer** Stanfill, M O - ETA: 09:08

**Description** 12/16/2013 08:01:27 **by** Wendell Lewis **Dept** Signals **IT+** Unknown

**Updated** 12/16/2013 08:04:35 **by** Wendell Lewis **Dept** Signals **IT+** .False or partial activation reported  
07:59 FLASHERS AND GATES ACTIVATED WITH NO TRAIN...AA-DISP. (DRG) NOTIFIED TO PROTECT WITH F/P MSG.  
Notification Sent to -Signal Control Center - Atlanta at 12/16/2013 08:04:35 Asset: PORTER AVE Status Changed To: Out Of  
Service PCC Notification Sent 12/16/2013 08:04:35

**Updated** 12/16/2013 08:06:13 **by** Max Todd **Dept** PSCC **IT+**  
**Contacted On** **Agency** BILOXI PD **Contact Name** LOLA **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 12/16/2013 08:08:09 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 09:08

**Updated** 12/16/2013 09:10:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 12/16/2013 11:01:58 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 12/16/2013 10:01:00 Equipment Type: Power/Batteries Action Taken: Lightning protectors/arrestors replaced  
Mntr found burnt lightning arrestors at crossing, replaced. Performed op checks, turned crossing backover to disp.  
Operational Checks Performed Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent 12/16/2013 11:01:58

**Updated** 12/16/2013 11:06:41 **by** Max Todd **Dept** PSCC **IT+**  
**Contacted On** 12-16-2013 11:06:00 **Agency** Biloxi Police Department **Contact Name** 376 **Phone** 228-392-0641  
at E. Howard Ave.

---

**Log#** [6359051](#) **Status** Closed **Entered** 11-09-2013 04:39:45 **by** Rowe, Christopher **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 727.6 **Block** 2763

**Section** 3090-Ocean Springs **Asset** PORTER AVE **AssetNum** 340199E **Maintainer** Stanfill, M O - ETA: 06:16

**Description** 11/09/2013 04:39:45 **by** Christopher Rowe **Dept** Signals **IT+** Unknown

**Updated** 11/09/2013 04:42:35 **by** Christopher Rowe **Dept** Signals **IT+** .False or partial activation reported  
CROSSING ACTIVATED NO TRAINS IN THE VICINITY Notification Sent to -Signal Control Center - Atlanta at 11/09/2013  
04:42:35 Asset: PORTER AVE Status Changed To: Out Of Service PCC Notification Sent 11/09/2013 04:42:35

**Updated** 11/09/2013 04:46:23 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 06:16

**Updated** 11/09/2013 04:55:35 **by** Christopher Horman **Dept** PSCC **IT+**  
**Contacted On** **Agency** BILOXI PD **Contact Name** DISPATCHER **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 11/09/2013 06:20:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 11/09/2013 08:23:31 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported

Mtr/employee is on-site.

**Closed** 11/09/2013 09:01:58 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 11/09/2013 09:01:00 Equipment Type: Other - explain Action Taken: Other - explain

**Employee:** M. Stanfill

- Replace 1000'DTL in southbound shunt...

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent 11/09/2013 09:01:58

**Updated** 11/09/2013 09:08:02 **by** Deborah Anderson **Dept** PSCC **IT+**  
**Contacted On** 11-09-2013 09:07:00 **Agency** BILOXI PD **Contact Name** 308 **Phone** 228-392-0641

---

**Log#** [6338077](#) **Status** Closed **Entered** 10-23-2013 13:17:35 **by** Jackson Jr, Marv **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.6 **Block** 2763

**Section** 3090-Ocean Springs **Asset** PORTER AVE **AssetNum** 340199E **Maintainer** Houck, B - ETA: 14:26

**Description** 10/23/2013 13:17:35 **by** Marv Jackson Jr **Dept** Signals **IT+** Unknown

**Updated** 10/23/2013 13:19:36 **by** Marv Jackson Jr **Dept** Signals **IT+** .False or partial activation reported  
LOCAL PD REPORTED FALSE ACTIVATION AT PORTER AVE..... Notification Sent to -Signal Control Center - Atlanta at  
10/23/2013 13:19:36 Asset: PORTER AVE Status Changed To: Out Of Service PCC Notification Sent 10/23/2013 13:19:36

**Updated** 10/23/2013 13:26:29 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Bradley Houck ETA of: 14:26

**Updated** 10/23/2013 13:26:34 **by** Virgil Adkins **Dept** PSCC **IT+**  
**Contacted On** 10-23-2013 13:22:00 **Agency** Biloxi Police Depart **Contact Name** stella **Phone** 228-392-0641

**Updated** 10/23/2013 14:30:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 10/23/2013 14:39:12 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 10/23/2013 14:39:00 Equipment Type: Track Action Taken: Repaired/replaced track/bond wire track  
connection at the 727 signal replaced. made op checks and ret to disp, and watched SB train Operational Checks Performed  
Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent 10/23/2013 14:39:12

**Updated** 10/23/2013 14:46:11 **by** Kihron Bristol **Dept** PSCC **IT+**

Contacted On 10-23-2013 14:46:00 Agency LOCAL PD

Contact Name paula Phone [REDACTED]

**Log#** [6176026](#) **Status** Closed **Entered** 06-19-2013 10:26:31 **by** Gothard, Jason **Type** Vehicle on Track

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.6 **Block** 2763

**Section** 3090-Ocean Springs **Asset** PORTER AVE **AssetNum** 340199E **Maintainer** Stanfill, M O - ETA: 11:13

**Description** 06/19/2013 10:26:31 **by** Jason Gothard **Dept** Signals **IT+** Unknown

**Updated** 06/19/2013 10:27:07 **by** Jason Gothard **Dept** Signals **IT+** Vehicle on Track  
ACD ATL BILOXI BAY PSCC NOTIFIED THAT A SEMI HAS DROPPED HIS TRAILOR ON THE TRACK AT MP 000727.6 IN THE PROCESS OF REMOVING Asset: PORTER AVE Status Changed To: Out Of Service PCC Notification Sent 06/19/2013 10:27:07

**Updated** 06/19/2013 10:28:02 **by** Jason Gothard **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Michael Stanfill ETA of: 11:13

**Updated** 06/19/2013 10:29:06 **by** Max Todd **Dept** PSCC **IT+**  
**Contacted On** 06-19-2013 10:29:00 Agency n/a **Contact Name** n/a **Phone** n/a  
vehicle on track

**Updated** 06/19/2013 11:15:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Updated** 06/19/2013 13:53:29 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track  
Texted employee reminder that tix was still open/if any updates

**Closed** 06/19/2013 14:10:01 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 06/19/2013 12:10:00 Equipment Type: Other - explain Action Taken: Other - explain

**Employee:** M. Stanfill

- Vehicle removed, No signal damage.

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent 06/19/2013 14:10:01

**Updated** 06/19/2013 14:13:00 **by** Max Todd **Dept** PSCC **IT+**  
**Contacted On** 06-19-2013 14:11:00 Agency Biloxi Police Department **Contact Name** 366 **Phone** 228-392-0641  
at Howard Ave.

**Log#** [6057267](#) **Status** Closed **Entered** 04-01-2013 18:09:53 **by** Mercado, Wito **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.6 **Block** 2763

**Section** 3090-Ocean Springs **Asset** PORTER AVE **AssetNum** 340199E **Maintainer** Houck, B - ETA: 19:38

**Description** 04/01/2013 18:09:53 **by** Jesuito Mercado **Dept** Signals **IT+** Unknown

**Updated** 04/01/2013 18:12:14 **by** Jesuito Mercado **Dept** Signals **IT+** .False or partial activation reported  
1810hr Local pd reports crossing is activated with no trains present... Notification Sent to -Signal Control Center - Atlanta at 04/01/2013 18:12:14 Asset: PORTER AVE Status Changed To: Out Of Service PCC Notification Sent 04/01/2013 18:12:14

**Updated** 04/01/2013 18:13:52 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported

The AA Dispatcher is protecting the crossing with a **Type 2 False / Partial Activation Message# 38804**. LVR

**Updated** 04/01/2013 18:37:45 **by** Jesse Gansen **Dept** PSCC **IT+**  
**Contacted On** 04-01-2013 18:37:00 Agency Biloxi Police Department **Contact Name** 3248 **Phone** 228-392-0641

**Updated** 04/01/2013 18:38:37 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Bradley Houck ETA of: 19:38

**Updated** 04/01/2013 19:40:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active



**Closed** 04/01/2013 20:37:49 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 04/01/2013 20:33:00 Equipment Type: N/A Action Taken: Issue cleared before cause identified

The Signal Maintainer reported that the crossing was working when he arrived. He found the GCP-3000 unit to be on the Standby side. EZ was 106 and the unit had been in High Signal. There were no error codes. He transferred the unit back to the Normal Side and was able to get the EZ down to 102 and 103. He checked the Insulated Joints at the Intermediate Signal at MP 727.0. The insulation was good. He checked all the track connections. He made sure all the gold nuts were tight in the bungalow. All the arrestors were checked in the Faraday cage. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR

Operational Checks Performed Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent 04/01/2013 20:37:49

**Updated** 04/01/2013 20:47:43 by Tanya Josen Dept PSCC IT+  
**Contacted On** 04-01-2013 20:47:00 Agency Biloxi Police Department Contact Name Marta Phone 228-392-0641

---

**Log#** [5760072](#) **Status** Closed **Entered** 08-29-2012 09:22:05 by Wilburn, Marion **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 727.6 **Block** 2763

**Section** 3090-Ocean Springs **Asset** PORTER AVE **AssetNum** 340199E **Maintainer**

**Description** 08/29/2012 09:28:10 by Marion Wilburn Dept Signals IT+ .False or partial activation reported  
0922 HRS POLICE DEPT REPORTED GATES ARE DOWN AND BLOCKING ROADWAY, LIGHTS ARE NOT FLASHING.  
DISPATCHER IS PROTECTING LOCATION UNDER BLANKET ORDER #30593. Asset: PORTER AVE Status Changed To: Out Of Service PCC Notification Sent 08/29/2012 09:28:10

**Updated** 08/29/2012 09:30:02 by Deborah Anderson Dept PSCC IT+  
**Contacted On** Agency POLICE DEPT Contact Name OPERATOR -229 Phone 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 08/29/2012 09:34:07 by Marion Wilburn Dept Signals IT+ .False or partial activation reported  
0933 HRS LEFT MESSAGE ON CELL PHONE FOR ASST CHIEF ENGR-COX

**Updated** 08/31/2012 04:45:39 by Jerry Rockhill Dept Signals IT+ .False or partial activation reported  
0436 MTR REPORTS CROSSING WORKING AS INTENDED....PORTER AVE NO LONGER HAS JUMPERS INSTALLED AT CROSSING...AND CAN BE REMOVED FROM JUMPER LOG WHEN JUMPER LOG IS CLOSED...THIS TICKET LEFT DEFERRED UNTIL JUMPER LOG READY TO BE CLOSED FOR ALL OTHER CROSSINGS ON THAT LIST...OP CKS OK AND READY FOR TRAIN TRAFFIC...

**Closed** 09/01/2012 13:02:18 by Terrence Smale II Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 09/01/2012 13:02:00 Equipment Type: N/A Action Taken: Eqpt tested & frnd working as intended Suspected Reason: Other weather crossing in service Operational Checks Performed Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent 09/01/2012 13:02:18

**Updated** 09/01/2012 13:11:17 by Deborah Anderson Dept PSCC IT+  
**Contacted On** 09-01-2012 13:10:00 Agency POLICE DEPT Contact Name 308 Phone 228-392-0641

---

**Log#** [5578618](#) **Status** Closed **Entered** 04-26-2012 19:07:57 by Tyo, Mark **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 727.6 **Block** 2763

**Section** 3090-Ocean Springs **Asset** PORTER AVE **AssetNum** 340199E **Maintainer** Stanfill, M O - ETA: 22:17

**Description** 04/26/2012 19:10:15 by Mark Tyo Dept Signals IT+ .False or partial activation reported  
Police report crossing activated no trains. DOT # was given. Disp is protecting. Notification Sent to -Signal Control Center - Atlanta at 04/26/2012 19:10:15 Asset: PORTER AVE Status Changed To: Out Of Service PCC Notification Sent 04/26/2012 19:10:15

**Updated** 04/26/2012 19:10:17 by Mark Tyo Dept Signals IT+ .False or partial activation reported  
A email notification for Multi Failure Count (MFC) asset PORTER AVE (5) has been sent to the following:  
Terrence Smale II  
John Parr

**Updated** 04/26/2012 19:17:20 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported

The AA Dispatcher is protecting the crossing with a **Type 2 False / Partial Activation Message# 27544**. LVR

**Updated** 04/26/2012 19:19:40 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi PD **Contact Name** Jennifer **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Closed** 04/27/2012 02:40:05 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 04/27/2012 02:38:00 Equipment Type: Power/batteries Action Taken: AC protectors replaced  
Suspected Reason: Lightning 0236 mtr reports sb start for porter ave was hi resistance connection...and bad lightning  
arrestors at the porter house....mtr replaced chicken head and lightning arrestors...op cks ok and crossing back in service  
with disp.... Operational Checks Performed Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent  
04/27/2012 02:40:05

**Updated** 04/27/2012 02:51:44 **by** Robert Clendening **Dept** PSCC **IT+**  
**Contacted On** 04-27-2012 02:50:00 **Agency** Biloxi PD **Contact Name** 366 **Phone** 228-392-0641

---

**Log#** [5572932](#) **Status** Closed **Entered** 04-23-2012 14:12:41 **by** McVey, Bruce **Type** Vehicle on Track

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 727.6 **Block** 2763

**Section** 3090-Ocean Springs **Asset** PORTER AVE **AssetNum** 340199E **Maintainer** Stanfill, M O - ETA: 14:43

**Description** 04/23/2012 14:13:25 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track  
notification: atl chief nm sub aa disp loc 2763 003 PSCC reports vehicle on the track at Porter AVE. 000727.5  
dispatcher protecting tm 18558 activation failure Asset: PORTER AVE Status Changed To: Out Of Service PCC  
Notification Sent 04/23/2012 14:13:25

**Updated** 04/23/2012 14:13:26 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track  
A email notification for Multi Failure Count (MFC) asset PORTER AVE (3) has been sent to the following:  
Terrence Smale II  
John Parr

**Updated** 04/23/2012 14:14:32 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** 04-23-2012 14:14:00 **Agency** N/A **Contact Name** N/A **Phone** N/A  
Event # 4458228

**Closed** 04/23/2012 15:19:11 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 04/23/2012 15:00:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as  
intended Suspected Reason: N/A  
**The Signal Maintainer reported that the vehicle was gone when he got there. There was no signal  
damage. For Operational Checks he watched a train through the crossing. The Crossing is Back In  
Service with the Dispatcher. LVR**  
Operational Checks Performed Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent  
04/23/2012 15:19:11

**Updated** 04/23/2012 15:21:00 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** 04-23-2012 15:20:00 **Agency** N/a **Contact Name** N/a **Phone** N/a

---

**Log#** [5570641](#) **Status** Closed **Entered** 04-21-2012 22:47:35 **by** Gaspar, Sean **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 727.6 **Block** 2763

**Section** 3090-Ocean Springs **Asset** PORTER AVE **AssetNum** 340199E **Maintainer** Patterson Jr, L D - ETA: 02:30

**Description** 04/21/2012 22:49:21 **by** Sean Gaspar **Dept** Signals **IT+** .False or partial activation reported  
xing is activated w/ no train. dot provided. disp protecting w/ f/p. Notification Sent to -Signal Control Center - Atlanta at  
04/21/2012 22:49:21 Asset: PORTER AVE Status Changed To: Out Of Service PCC Notification Sent 04/21/2012  
22:49:21

**Updated** 04/21/2012 22:55:41 **by** Christopher Horman **Dept** PSCC **IT+**  
**Contacted On** **Agency** local police **Contact Name** sara **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 04/22/2012 00:56:49 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
0055 sig tech l. patterson was called ...tcis was down at that time and unable to update the response....left msg..

**Updated** 04/22/2012 01:02:04 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
0100 sig tech l. patterson accepted...eta 90 min...0230.



**Updated** 04/22/2012 01:02:38 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported

**Closed** 04/22/2012 04:44:27 **by** Leonard Patterson Jr **Dept** Signals **IT+** .False or partial activation reported

Incident Resolved: 04/22/2012 04:30:00 Equipment Type: N/A Action Taken: Issue cleared before cause identified  
Suspected Reason: N/A G.C.W.D. clear upon arrival. No error codes, all voltages (+ & -) in cabinet no exceptions, EZ-100 & EX-87 good & stable. DAX input 15 VDC & stable. Watched 1 north & 1 south bound train by with no exceptions.  
Unable to duplicate any trouble. Operational Checks Performed Asset: PORTER AVE Status Changed To: In Service  
PCC Notification Sent 04/22/2012 04:44:27

**Updated** 04/22/2012 04:48:01 **by** Gloria Andino **Dept** PSCC **IT+**  
**Contacted On** 04-22-2012 04:47:00 **Agency** Local Police **Contact Name** 2317 **Phone** 228-392-0641

---

**Log#** [5563794](#) **Status** Closed **Entered** 04-17-2012 07:09:36 **by** Miller, Vern **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 727.6 **Block** 2763

**Section** 3090-Ocean Springs **Asset** PORTER AVE **AssetNum** 340199E **Maintainer** Stanfill, M O - ETA: 08:40

**Description** 04/17/2012 07:10:55 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
crossing activated, no train around. dispatcher notified to protect with false/partial activation protection. vern Asset: PORTER AVE Status  
Changed To: Out Of Service PCC Notification Sent 04/17/2012 07:10:55

**Updated** 04/17/2012 07:11:10 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
. Notification Sent to -Signal Control Center - Atlanta at 04/17/2012 07:11:10

**Updated** 04/17/2012 07:12:29 **by** Brooks Clayton **Dept** PSCC **IT+**  
**Contacted On** **Agency** p.d. **Contact Name** romona **Phone** 228 392 0641  
Reporting party has been verified as the responsible law enforcement agency.

**Closed** 04/17/2012 09:52:26 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 04/17/2012 09:51:00 Equipment Type: Other - explain Action Taken: Other - explain Suspected Reason: N/A

**Employee:** M. Stanfill

- high EZ (109) , found hi res connection at the southbound start, repaired

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent 04/17/2012 09:52:26

**Updated** 04/17/2012 09:59:07 **by** Clifford Keen **Dept** PSCC **IT+**  
**Contacted On** 04-17-2012 09:58:00 **Agency** Biloxi Police Department **Contact Name** DISP 3162 **Phone** 228-392-0641

---

**Log#** [5515405](#) **Status** Closed **Entered** 03-13-2012 11:21:35 **by** McClure, Dale **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 727.6 **Block** 2763

**Section** 3090-Ocean Springs **Asset** PORTER AVE **AssetNum** 340199E **Maintainer** Stanfill, M O - ETA: 12:38

**Description** 03/13/2012 11:24:53 **by** Dale McClure **Dept** Signals **IT+** .False or partial activation reported  
POLICE REPORTED CROSSING ACTIVATED/ NO TRAINS PRESENT. AA DISP. NOTIFIED AND INSTRUCTED TO PROTECT AS  
FALSE/ PARTIAL ACTIVATION UNTIL CHECKED. Asset: PORTER AVE Status Changed To: Out Of Service PCC Notification Sent  
03/13/2012 11:24:53

**Updated** 03/13/2012 11:42:51 **by** Virgil Adkins **Dept** PSCC **IT+**  
**Contacted On** **Agency** BILOXI, MS **Contact Name** RAMONA (POLICE) **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Closed** 03/13/2012 15:48:15 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 03/13/2012 14:30:00 Equipment Type: Track Action Taken: Repaired/replaced track/bond wire Suspected Reason:  
Other department

**Mntr reports a Regulator broke the wires at the northbound and southbound starts. He repaired the wires and performed  
Operational Checks. LVR**

Operational Checks Performed Asset: PORTER AVE Status Changed To: In Service PCC Notification Sent 03/13/2012 15:48:15

**Updated** 03/13/2012 15:52:09 **by** Tanya Joson **Dept** PSCC **IT+**



**Gill Avenue**

**DOT Crossing #: 340200W**

**RR Milepost #: 727.69**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 3

Status All AssetType All RootAssetType All Department Signals AssetNum 340200W

---

**Log#** [7463048](#) **Status** Closed **Entered** 01-04-2016 16:42:47 **by** Gaspar, Sean **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 727.7 **Block** 2763

**Section** 3090-7M16 **Asset** GILL AVE **AssetNum** 340200W **Maintainer** Stanfill, M O - ETA: 19:12

**Description** 01/04/2016 16:42:47 **by** Sean Gaspar **Dept** Signals **IT+** Unknown

**Updated** 01/04/2016 16:45:04 **by** Sean Gaspar **Dept** Signals **IT+** .False or partial activation reported  
gates up and lights flashing w/ no train. dot provided. disp protecting w/ f/p. Notification Sent to -Signal Control Center - Atlanta at 01/04/2016 16:45:04 Asset: GILL AVE Status Changed To: Out Of Service PCC Notification Sent 01/04/2016 16:45:04

**Updated** 01/04/2016 16:45:06 **by** Sean Gaspar **Dept** Signals **IT+** .False or partial activation reported  
An email notification for (IRI) asset GILL AVE (.125) has been sent to the following:  
George James Jr

**Updated** 01/04/2016 16:55:40 **by** Waltina Edwards **Dept** PSCC **IT+**  
**Contacted On** **Agency** local police **Contact Name** megan **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 01/04/2016 17:12:13 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 19:12

**Closed** 01/04/2016 18:20:46 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 01/04/2016 18:19:00 Equipment Type: N/A Action Taken: NTF - UTD

**The Signal Maintainer reported that the Crossing was working when he got there. There are no gates at this crossing. The lights are working properly. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: GILL AVE Status Changed To: In Service PCC Notification Sent 01/04/2016 18:20:46

**Updated** 01/04/2016 18:43:06 **by** Alyson Trouba **Dept** PSCC **IT+**  
**Contacted On** 01-04-2016 18:42:00 **Agency** local police **Contact Name** Meghan **Phone** 228-392-0641

---

**Log#** [7460756](#) **Status** Closed **Entered** 01-02-2016 08:50:06 **by** Wilburn, Marion **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.7 **Block** 2763

**Section** 3090-7M16 **Asset** GILL AVE **AssetNum** 340200W **Maintainer** Mannion, R - ETA: 10:09

**Description** 01/02/2016 08:50:06 **by** Marion Wilburn **Dept** Signals **IT+** Unknown

**Updated** 01/02/2016 08:54:31 **by** Marion Wilburn **Dept** Signals **IT+** .False or partial activation reported  
0852 Hrs. Police dept. reports crossing is activated with no train present, AA-dispatcher-JMR has been notified to protect crossing as F/P (Also states no gates at this crossing) Notification Sent to -Signal Control Center - Atlanta at 01/02/2016 08:54:31 Asset: GILL AVE Status Changed To: Out Of Service PCC Notification Sent 01/02/2016 08:54:31

**Updated** 01/02/2016 08:55:41 **by** Avie Saunders **Dept** PSCC **IT+**  
**Contacted On** **Agency** Police dept. **Contact Name** Operator 3246 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 01/02/2016 09:09:04 **by** Michael Houston **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Roger Mannion ETA of: 10:09

**Updated** 01/02/2016 10:10:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 01/02/2016 12:05:49 **by** Roger Mannion **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 01/02/2016 12:05:00 Equipment Type: N/A Action Taken: NTF - UTD Crossing was CoA, checked approaches and verified NBS to be in good order, shunted track to verify good operation of starts and crossing, no issues noted. Verified equipment in case to be in good order, no exceptions noted. Operational Checks Performed Asset: GILL AVE Status Changed To: In Service PCC Notification Sent 01/02/2016 12:05:49

**Closed** 01/02/2016 12:06:53 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 01/02/2016 12:05:00 Equipment Type: N/A Action Taken: NTF - UTD Resolved to close. Operational Checks Performed

**Updated** 01/02/2016 12:11:38 **by** Avie Saunders **Dept** PSCC **IT+**  
**Contacted On** 01-02-2016 12:11:00 **Agency** Police dept. **Contact Name** Brenda **Phone** 228-392-0641

---

**Log#** [6900827](#) **Status** Closed **Entered** 11-27-2014 17:29:51 **by** Carter, Jake **Type** .False or partial activation reported

**Supv** Merritt, D **Reg SO** **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 727.7 **Block** 2763

**Section** 3090-7M16 **Asset** GILL AVE **AssetNum** 340200W **Maintainer** Shelley, J - *ETA: 19:44*

**Description** 11/27/2014 17:29:51 **by** Jake Carter **Dept** Signals **IT+** Unknown

**Updated** 11/27/2014 17:40:09 **by** Jake Carter **Dept** Signals **IT+** .False or partial activation reported  
Local Pd reports xng is activated, w/no trains present;AtlCh is to protect as f/p Notification Sent to -Signal Control Center - Atlanta at 11/27/2014 17:40:09 Asset: GILL AVE Status Changed To: Out Of Service PCC Notification Sent 11/27/2014 17:40:09

**Updated** 11/27/2014 17:46:53 **by** Jodi Snyder **Dept** PSCC **IT+**  
**Contacted On** 11-27-2014 17:46:00 **Agency** Biloxi Pd **Contact Name** Eric **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 11/27/2014 18:14:37 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Jacob Shelley ETA of: N/A

**Updated** 11/27/2014 19:45:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 11/28/2014 00:11:19 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
MTR ONSITE WORKING...

**Closed** 11/28/2014 01:13:16 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 11/28/2014 01:13:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced Track Card 0112 MTR REPORTS REPLACED BAD TRM CARD....OP CKS OK AND WATCHED TRAIN THRU CROSSING OK...CROSSING BACK IN SERVICE WITH DISP Operational Checks Performed Asset: GILL AVE Status Changed To: In Service PCC Notification Sent 11/28/2014 01:13:16

**Updated** 11/28/2014 01:17:15 **by** Alison Obrien **Dept** PSCC **IT+**  
**Contacted On** 11-28-2014 01:16:00 **Agency** Biloxi Pd **Contact Name** 3246 **Phone** 228-392-0641

**White Avenue**

**DOT Crossing #: 340202K**

**RR Milepost #: 728.14**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 19

Status All AssetType All RootAssetType All Department Signals AssetNum 340202K

---

**Log#** [7776756](#) **Status** Closed **Entered** 08-26-2016 19:29:56 **by** Kondy, Rick **Type** Train-vehicle collision (Signals)

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 728.1 **Block** 2763

**Section** 3090-7M16 **Asset** WHITE AVE **AssetNum** 340202K **Maintainer** James Jr, G H - ETA: 20:03

**Description** 08/26/2016 19:29:56 **by** Richard Kondy **Dept** Signals **IT+** Unknown

**Updated** 08/26/2016 19:31:12 **by** Richard Kondy **Dept** Signals **IT+** Train-vehicle collision (Signals)  
Incident Type: TRK Dispatch incident Number: 45739 Incident Date: 26-AUG-16 Pri.Train ID: SubDivision Code:  
NM Left Mile Post: 000, 0727.0000 Right Mile Post: 000, 0730.2851 Asset: 2763 003, Asset Name: MAIN PTC  
Flag: N Incident Description: SOUTHBOUND Q57925 STATES THAT THEY STRUCK A VEHICLE AT 000727.6,  
GILL AVENUE THE ENTRANCE TO THE AIRFORCE BASE. NEED SIGNAL MAINTAINER AND TRACK  
INSPECTOR disp says crossing is at white ave . disp protecting crossing with activation failure # 31215 . Asset:  
WHITE AVE Status Changed To: Out Of Service PCC Notification Sent 08/26/2016 19:31:12

**Updated** 08/26/2016 20:02:39 **by** Richard Kondy **Dept** Signals **IT+** Train-vehicle collision (Signals)  
Status changed to Escalated, George James Jr ETA of: 20:03

**Closed** 08/26/2016 23:41:16 **by** Zacchaeus Wood **Dept** Signals **IT+** Train-vehicle collision (Signals)  
Incident Resolved: 08/26/2016 23:41:00 Equipment Type: N/A Action Taken: Track Occupied Mtr reports no  
physical damage done to crossing, made annual crossing test and gate fall time of 12 secs. Made all OP checks.  
Operational Checks Performed Asset: WHITE AVE Status Changed To: In Service PCC Notification Sent  
08/26/2016 23:41:16

---

**Log#** [7621577](#) **Status** Closed **Entered** 05-01-2016 19:57:33 **by** Wood, Zach **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 728.1 **Block** 2763

**Section** 3090-7M16 **Asset** WHITE AVE **AssetNum** 340202K **Maintainer** Mannion, R - ETA: 22:48 & James Jr, G H - ETA: 23:12

**Description** 05/01/2016 19:57:33 **by** Zacchaeus Wood **Dept** Signals **IT+** Unknown

**Updated** 05/01/2016 20:06:51 **by** Zacchaeus Wood **Dept** Signals **IT+** .False or partial activation reported  
Local PD reports crossing activated w/ no trains present, DOT# provided. Crossing protected w/ F/P activation Notification  
Sent to -Signal Control Center - Atlanta at 05/01/2016 20:06:51 Asset: WHITE AVE Status Changed To: Out Of Service  
PCC Notification Sent 05/01/2016 20:06:51

**Updated** 05/01/2016 20:06:53 **by** Zacchaeus Wood **Dept** Signals **IT+** .False or partial activation reported  
An email notification for (IRI) asset WHITE AVE (1) has been sent to the following:  
George James Jr

**Updated** 05/01/2016 20:25:40 **by** Roland Knagge **Dept** PSCC **IT+**  
**Contacted On** 05-01-2016 20:22:00 **Agency** Biloxi PD **Contact Name** Megan **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 05/01/2016 21:12:04 **by** Kelly Tucker **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Escalated, George James Jr ETA of: 23:12

**Updated** 05/01/2016 21:18:30 **by** Roger Mannion **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Roger Mannion ETA of: 22:48

**Updated** 05/01/2016 22:50:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 05/01/2016 23:34:09 **by** Roger Mannion **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 05/01/2016 23:34:00 Equipment Type: Gate Action Taken: Damaged gate or sections-replaced/repared  
Security Police on Air Force Base informed me the wind was blowing hard and gate got caught up under cantilever, next  
train caused gate to drop away from cant, and clear up correctly, had to replace two shear pins that broke, but gate did not  
fall from holder, back to dispatcher with message 19414. Operational Checks Performed Asset: WHITE AVE Status  
Changed To: In Service PCC Notification Sent 05/01/2016 23:34:09

**Closed** 05/01/2016 23:36:08 **by** Reed Dawley **Dept** Signals **IT+** .False or partial activation reported



Incident Resolved: 05/01/2016 23:34:00 Equipment Type: Gate Action Taken: Damaged gate or sections-replaced/repaired  
. Operational Checks Performed

**Updated** 05/01/2016 23:52:00 **by** Sabrina Smith **Dept** PSCC **IT+**  
**Contacted On** 05-01-2016 23:51:00 **Agency** Biloxi PD **Contact Name** Donna **Phone** 228-392-0641

---

**Log#** [7618166](#) **Status** Closed **Entered** 04-28-2016 22:19:35 **by** Tyo, Mark **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 728.1 **Block** 2763

**Section** 3090-7M16 **Asset** WHITE AVE **AssetNum** 340202K **Maintainer** Stanfill, M O - ETA: 00:45

**Description** 04/28/2016 22:19:35 **by** Mark Tyo **Dept** Signals **IT+** Unknown

**Updated** 04/28/2016 22:31:59 **by** Mark Tyo **Dept** Signals **IT+** .False or partial activation reported  
Reported gates going up and down no trains. Disp is protecting. Notification Sent to -Signal Control Center - Atlanta at 04/28/2016 22:31:59 Asset:  
WHITE AVE Status Changed To: Out Of Service PCC Notification Sent 04/28/2016 22:31:59

**Updated** 04/28/2016 22:45:19 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 00:45

**Updated** 04/28/2016 22:47:29 **by** Sabrina Smith **Dept** PSCC **IT+**  
**Contacted On** 04-28-2016 22:45:00 **Agency** Keesler Air Force Base Security Forces **Contact Name** Traynor **Phone** [REDACTED]  
@ Irish Hill Dr

**Updated** 04/29/2016 00:50:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 04/29/2016 02:55:45 **by** David Mates **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 04/29/2016 02:51:00 Equipment Type: Wiring/Protection Action Taken: Repaired/Replaced Protection Mtr replaced RYD card  
and some lightning arrestors made op checks released protection with dispatcher and crossing WAI Operational Checks Performed Asset: WHITE  
AVE Status Changed To: In Service PCC Notification Sent 04/29/2016 02:55:45

**Updated** 04/29/2016 04:12:53 **by** Sabrina Smith **Dept** PSCC **IT+**  
**Contacted On** 04-29-2016 04:11:00 **Agency** Biloxi PD **Contact Name** Traynor **Phone** [REDACTED]

---

**Log#** [7531963](#) **Status** Closed **Entered** 02-23-2016 18:22:23 **by** Foster, George **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 728.1 **Block** 2763

**Section** 3090-7M16 **Asset** WHITE AVE **AssetNum** 340202K **Maintainer** Richardson, G L - ETA: 01:16 & James Jr, G H - ETA: 19:15

**Description** 02/23/2016 18:22:23 **by** George Foster **Dept** Signals **IT+** Unknown

**Updated** 02/23/2016 18:27:08 **by** George Foster **Dept** Signals **IT+** .False or partial activation reported  
One of the gates is part way down with no trains. Notification Sent to -Signal Control Center - Atlanta at 02/23/2016 18:27:08  
Asset: WHITE AVE Status Changed To: Out Of Service PCC Notification Sent 02/23/2016 18:27:08

**Updated** 02/23/2016 18:45:24 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** **Agency** 911 **Contact Name** Operator Hall **Phone** [REDACTED]  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 02/23/2016 19:15:58 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Escalated, George James Jr ETA of: N/A

**Updated** 02/23/2016 19:17:22 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported

**Update** - The Supervisor reported that a Maintainer should not be dispatched right now as there have been 3 tornados that have  
touched down in the area so far. LVR

**Updated** 02/23/2016 22:20:34 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Gregory Richardson ETA of: 01:20

**Updated** 02/23/2016 22:25:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 02/23/2016 23:18:24 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Severe storms in area, call out held to allow weather to pass. Mntr en-route, Sig Sup notified.

**Updated** 02/23/2016 23:42:19 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 03:12

**Updated** 02/23/2016 23:45:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 02/23/2016 23:46:40 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

**Closed** 02/24/2016 02:21:50 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 02/24/2016 02:21:00 Equipment Type: Gate Action Taken: Damaged gate or sections-replaced/repair  
Mntr had to replace tip section of gate. Performed op checks, turned crossing back over to disp.  
Operational Checks Performed Asset: WHITE AVE Status Changed To: In Service PCC Notification Sent 02/24/2016 02:21:50

**Updated** 02/24/2016 03:25:57 **by** Kiwana Tompkins **Dept** PSCC **IT+**  
**Contacted On** 02-24-2016 02:37:00 **Agency** 911 **Contact Name** Williams **Phone** [REDACTED]

---

**Log#** [7376691](#) **Status** Closed **Entered** 10-26-2015 12:48:36 **by** McClure, Dale **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 728.1 **Block** 2763

**Section** 3090-7M16 **Asset** WHITE AVE **AssetNum** 340202K **Maintainer** Stanfill, M O - ETA: 14:38

**Description** 10/26/2015 12:48:36 **by** Dale McClure **Dept** Signals **IT+** Unknown

**Updated** 10/26/2015 12:54:05 **by** Dale McClure **Dept** Signals **IT+** .False or partial activation reported  
LOCAL REPORTING ONE GATE HUNG UP IN WIRES ON ONE SIDE OF THIS CROSSING AND NOT COMING DOWN.....WHEN ASKED IF  
FLASHERS ACTIVATED, SAID THEY DID.....IN THE INTEREST OF PUBLIC SAFETY, INSTRUCTED AA DISP. TO PROTECT AS A/F STOP  
AND FLAG UNTIL CHECKED. Asset: WHITE AVE Status Changed To: Out Of Service PCC Notification Sent 10/26/2015 12:54:05

**Updated** 10/26/2015 12:58:52 **by** Nikole Ross **Dept** PSCC **IT+**  
**Contacted On** 10-26-2015 12:58:00 **Agency** Keesler Air Force Base Security Forces **Contact Name** Gilliard **Phone** [REDACTED]  
@ Irish Hill Dr

**Updated** 10/26/2015 12:59:25 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 14:38

**Updated** 10/26/2015 14:40:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 10/26/2015 14:53:35 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 10/26/2015 14:53:00 Equipment Type: Gate Mechanism Action Taken: Realigned gate mech

**Employee:** M. Stanfill

- freed gate, realign gate mech

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: WHITE AVE Status Changed To: In Service PCC Notification Sent 10/26/2015 14:53:35

**Updated** 10/26/2015 15:22:56 **by** Alexis Romine **Dept** PSCC **IT+**  
**Contacted On** 10-26-2015 15:21:00 **Agency** Keesler Air Force Base Security Forces **Contact Name** Csemiozi **Phone** [REDACTED]  
@ Irish Hill Dr

---

**Log#** [7052751](#) **Status** Closed **Entered** 03-13-2015 23:51:13 **by** Rockhill, Jerry **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 728.1 **Block** 2763

**Section** 3090-7M16 **Asset** WHITE AVE **AssetNum** 340202K **Maintainer** Richardson, G L - ETA: 02:37

**Description** 03/13/2015 23:51:13 **by** Jerry Rockhill **Dept** Signals **IT+** Unknown

**Updated** 03/13/2015 23:52:26 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
2352 ATLANTA CHIEF, AA DISPATCHER, NM SUB, LOCATION 2763-003, NB Q61213 REPORTS GATES DID NOT COME DOWN AT WHITE AVE MP  
000728.1. ....af 18172 Asset: WHITE AVE Status Changed To: Out Of Service PCC Notification Sent 03/13/2015 23:52:26

**Updated** 03/13/2015 23:56:09 **by** Jodi Snyder **Dept** PSCC **IT+**  
**Contacted On** 03-13-2015 23:53:00 **Agency** Keesler Air Force Base Security Forces **Contact Name** A1C Schmeffel **Phone** [REDACTED]

Irish Hill Dr

**Updated** 03/14/2015 00:37:44 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Gregory Richardson ETA of: 02:37

**Closed** 03/14/2015 02:34:07 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 03/14/2015 02:32:00 Equipment Type: Gate Action Taken: Freed gate - no gate mech realignment 0231 mtr reports east gate light wiring caught on mast keeping gate from coming down...mtr secured gate light wires...op cks ok and crossing back in service with disp ...watched train thru ok...  
Operational Checks Performed Asset: WHITE AVE Status Changed To: In Service PCC Notification Sent 03/14/2015 02:34:07

---

**Log#** [6861586](#) **Status** Closed **Entered** 11-01-2014 04:08:14 **by** Wood, Zach **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 728.1 **Block** 2763

**Section** 3090-7M16 **Asset** WHITE AVE **AssetNum** 340202K **Maintainer** Richardson, G L - ETA: 07:37

**Description** 11/01/2014 04:08:14 **by** Zacchaeus Wood **Dept** Signals **IT+** Unknown

**Updated** 11/01/2014 04:10:40 **by** Zacchaeus Wood **Dept** Signals **IT+** .False or partial activation reported  
Local PD reports gate laying across track, DOT# provided. Crossing protected w/ F/P activation. Notification Sent to -Signal Control Center - Atlanta at 11/01/2014 04:10:40 Asset: WHITE AVE Status Changed To: Out Of Service PCC Notification Sent 11/01/2014 04:10:40

**Updated** 11/01/2014 04:15:54 **by** Alison Obrien **Dept** PSCC **IT+**  
**Contacted On** 11-01-2014 04:12:00 **Agency** Keesler Air Force Base Security Forces **Contact Name** Mathas **Phone** [REDACTED]  
@ Irish Hill Dr

**Updated** 11/01/2014 06:07:24 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Gregory Richardson ETA of: 07:37

**Updated** 11/01/2014 07:40:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 11/01/2014 08:44:25 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 11/01/2014 08:44:00 Equipment Type: Gate Action Taken: Damaged gate or sections-replaced/repairred

**Employee:** G.Richardson

- Replaced middle section, and hung gate...

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: WHITE AVE Status Changed To: In Service PCC Notification Sent 11/01/2014 08:44:25

**Updated** 11/01/2014 08:58:56 **by** Alexis Romine **Dept** PSCC **IT+**  
**Contacted On** 11-01-2014 08:58:00 **Agency** Keesler Air Force Base Security Forces **Contact Name** Turner **Phone** [REDACTED]  
@ Irish Hill Dr

**Closed** 11/01/2014 12:23:51 **by** Leonard Patterson Jr **Dept** Signals **IT+** .False or partial activation reported  
Signal 713...Stick Circuit activated, Adjusted Track Currents (conditions dry) = North, was 1.36A, now 1.24A...South was 1.56A, now 1.23A....loose wire on found on cabinet, tightened, (tested with wire off, only down graded South Gautier to a Yellow (code 2 out to left). Reseated all modules.

---

**Log#** [6477805](#) **Status** Closed **Entered** 02-05-2014 13:09:06 **by** Miller, Vern **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 728.1 **Block** 2763

**Section** 3090-Ocean Springs **Asset** WHITE AVE **AssetNum** 340202K **Maintainer** Stanfill, M O - ETA: 14:58

**Description** 02/05/2014 13:09:06 **by** Verlon Miller **Dept** Signals **IT+** Unknown

**Updated** 02/05/2014 13:10:46 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
gates going up and down, no train around. dispatcher notified to protect with false/partial activation protection. vern Asset: WHITE AVE Status Changed To: Out Of Service PCC Notification Sent 02/05/2014 13:10:46

**Updated** 02/05/2014 13:11:00 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
. Notification Sent to -Signal Control Center - Atlanta at 02/05/2014 13:11:00

**Updated** 02/05/2014 13:13:06 **by** Max Todd **Dept** PSCC **IT+**  
**Contacted On** 02-05-2014 13:12:00 **Agency** Keesler Air Force Base Security Forces **Contact Name** 1976 **Phone** [REDACTED]  
at Irish Hill Dr.

**Updated** 02/05/2014 13:28:41 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 14:58

**Updated** 02/05/2014 13:29:25 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
MOW has truck picking up rail causing the xing to activate

**Closed** 02/05/2014 14:07:32 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 02/05/2014 14:07:00 Equipment Type: N/A Action Taken: Track Occupied xing working as intended. MOW cleared and trouble cleared Operational Checks Performed Asset: WHITE AVE Status Changed To: In Service PCC Notification Sent 02/05/2014 14:07:32

**Updated** 02/05/2014 14:10:56 **by** Max Todd **Dept** PSCC **IT+**  
**Contacted On** 02-05-2014 14:10:00 **Agency** Keesler Air Force Base Security Forces **Contact Name** peterman **Phone** [REDACTED]  
at Irish Hill Dr.

---

**Log#** [6234827](#) **Status** Closed **Entered** 08-01-2013 23:36:41 **by** Foster, George **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 728.1 **Block** 2763

**Section** 3090-Ocean Springs **Asset** WHITE AVE **AssetNum** 340202K **Maintainer** Houck, B - ETA: 03:12

**Description** 08/01/2013 23:36:41 **by** George Foster **Dept** Signals **IT+** Unknown

**Updated** 08/01/2013 23:38:34 **by** George Foster **Dept** Signals **IT+** .False or partial activation reported  
Crossing activated with no trains in sight. Dispatcher protecting with false partial activation MSG# 38712 MES. Notification Sent to - Signal Control Center - Atlanta at 08/01/2013 23:38:34 Asset: WHITE AVE Status Changed To: Out Of Service PCC Notification Sent 08/01/2013 23:38:34

**Updated** 08/02/2013 00:01:34 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 01:01

**Updated** 08/02/2013 00:03:50 **by** Gloria Andino **Dept** PSCC **IT+**  
**Contacted On** **Agency** 911 **Contact Name** Rebels **Phone** [REDACTED]  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 08/02/2013 01:05:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 08/02/2013 03:12:40 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 08/02/2013 03:00:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended COA. mntr watched NB and SB trains. checked bonds, grds, gold nuts, made op checks and ret to disp Operational Checks Performed Asset: WHITE AVE Status Changed To: In Service PCC Notification Sent 08/02/2013 03:12:40

**Updated** 08/02/2013 03:18:53 **by** Gloria Andino **Dept** PSCC **IT+**  
**Contacted On** 08-02-2013 03:18:00 **Agency** 911 **Contact Name** Dispatcher Rebels **Phone** [REDACTED]

---

**Log#** [6128283](#) **Status** Closed **Entered** 05-18-2013 09:46:42 **by** Miller, Vern **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.25 **Milepost** 000 728.1 **Block** 2763

**Section** 3090-Ocean Springs **Asset** WHITE AVE **AssetNum** 340202K **Maintainer** Stanfill, M O - ETA: 15:04 & James Jr, G H - ETA: 12:05

**Description** 05/18/2013 09:46:42 **by** Verlon Miller **Dept** Signals **IT+** Unknown

**Updated** 05/18/2013 09:48:16 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
crossing activated, no train around. dispatcher notified to protect with false/partial activation protection. vern Asset: WHITE AVE Status Changed To: Out Of Service PCC Notification Sent 05/18/2013 09:48:16

**Updated** 05/18/2013 09:49:41 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
. Notification Sent to -Signal Control Center - Atlanta at 05/18/2013 09:49:41

**Updated** 05/18/2013 09:50:14 **by** Christina Martorano **Dept** PSCC **IT+**  
**Contacted On** 05-18-2013 09:49:00 **Agency** p.d. **Contact Name** barb **Phone** 228 392 0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 05/18/2013 10:35:07 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Escalated, George James Jr ETA of: 12:05

**Updated** 05/18/2013 14:04:54 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 15:04

**Updated** 05/18/2013 14:05:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 05/18/2013 15:25:40 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 05/18/2013 15:24:00 Equipment Type: Gate mechanism Action Taken: Adjusted/Cleaned/Repaired/Reset  
Mntr cleaned west gate pwr up contact. Performed op checks, turned crossing backover to disp.  
Operational Checks Performed Asset: WHITE AVE Status Changed To: In Service PCC Notification Sent 05/18/2013  
15:25:40

**Updated** 05/18/2013 15:33:12 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** 05-18-2013 15:32:00 **Agency** p.d. **Contact Name** Operator **Phone** 228 392 0641

---

**Log#** [6086395](#) **Status** Closed **Entered** 04-19-2013 18:58:49 **by** Carter, Jake **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 728.1 **Block** 2763

**Section** 3090-Ocean Springs **Asset** WHITE AVE **AssetNum** 340202K **Maintainer** Stanfill, M O - ETA: 20:44

**Description** 04/19/2013 18:58:49 **by** Jake Carter **Dept** Signals **IT+** Unknown

**Updated** 04/19/2013 19:02:27 **by** Jake Carter **Dept** Signals **IT+** .False or partial activation reported  
Local Pd reports xng is activated, w/no trains present;disp is protecting as f/p Notification Sent to -Signal Control Center -  
Atlanta at 04/19/2013 19:02:27 Asset: WHITE AVE Status Changed To: Out Of Service PCC Notification Sent 04/19/2013  
19:02:27

**Updated** 04/19/2013 19:09:00 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi Pd **Contact Name** Jackie **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 04/19/2013 19:14:25 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 20:44

**Updated** 04/19/2013 20:35:21 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported

**Update** - The Signal Maintainer's new ETA is 20:45. LVR

**Updated** 04/19/2013 20:45:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 04/19/2013 22:12:05 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported

**Update** - The Signal Maintainer reported that the Commercial Power is out. He is waiting on Mississippi Power to arrive. LVR

**Updated** 04/20/2013 00:12:58 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
STILL WAITING.

**Closed** 04/20/2013 00:20:23 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 04/20/2013 00:19:00 Equipment Type: Power/batteries Action Taken: Commercial Power Restored 0019  
mtr reports commercial power back on....op cks ok and crossing back in service with disp....due to weather... Operational  
Checks Performed Asset: WHITE AVE Status Changed To: In Service PCC Notification Sent 04/20/2013 00:20:23

**Updated** 04/20/2013 00:26:52 **by** Alison Obrien **Dept** PSCC **IT+**  
**Contacted On** 04-20-2013 00:26:00 **Agency** Biloxi Pd **Contact Name** Stephany **Phone** 228-392-0641

---

**Log#** [6076571](#) **Status** Closed **Entered** 04-14-2013 10:08:23 **by** Kondy, Rick **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 728.1 **Block** 2763

**Section** 3090-Ocean Springs **Asset** WHITE AVE **AssetNum** 340202K **Maintainer** Stanfill, M O - ETA: 14:43

**Description** 04/14/2013 10:08:23 **by** Richard Kondy **Dept** Signals **IT+** Unknown

**Updated** 04/14/2013 10:10:10 **by** Richard Kondy **Dept** Signals **IT+** .False or partial activation reported  
gate broken . disp protecting crossing with false activation # 24238 . Notification Sent to -Signal Control Center - Atlanta at  
04/14/2013 10:10:10 Asset: WHITE AVE Status Changed To: Out Of Service PCC Notification Sent 04/14/2013 10:10:10

**Updated** 04/14/2013 10:15:33 **by** Christina Martorano **Dept** PSCC **IT+**  
**Contacted On** 04-14-2013 10:14:00 **Agency** // **Contact Name** biloxi police **Phone** 228-392-0641



Reporting party has been verified as the responsible law enforcement agency.

**Updated** 04/14/2013 10:16:32 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported

- Storms in area (heavy rains and lightning) at time of incident:

**Updated** 04/14/2013 10:17:20 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported

WIND WARNING 1168 FOR CSX CONDITIONS: WIND START TIME: 04-14-2013, 10:00AM EDT EXPIRE TIME: 04-14-2013, 10:45AM EDT COMMENTS: EXPECT WESTERLY WIND GUSTS AS HIGH AS 60 MPH TO OCCUR ACROSS THIS AREA AS A LINE OF STORMS MOVES EAST QUICKLY.

**Updated** 04/14/2013 13:04:32 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported

**Updated** 04/14/2013 13:13:22 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported

Status changed to Dispatched for Michael Stanfill ETA of: 14:43

**Updated** 04/14/2013 14:45:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported

ETA time reached Status changed to Active

**Closed** 04/14/2013 16:16:39 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Incident Resolved: 04/14/2013 16:14:00 Equipment Type: Gate Action Taken: Damaged gate or sections-replaced/repared Mntr replaced 2nd sec of west gate; damaged from storms in area earlier. Performed op checks, turned crossing backover to disp.

Operational Checks Performed Asset: WHITE AVE Status Changed To: In Service PCC Notification Sent 04/14/2013 16:16:39

**Updated** 04/14/2013 16:23:02 **by** Tanya Joson **Dept** PSCC **IT+**

**Contacted On** 04-14-2013 16:23:00 **Agency** biloxi police **Contact Name** Marta **Phone** 228-392-0641

---

**Log#** [5808710](#) **Status** Closed **Entered** 10-04-2012 03:30:47 **by** Belkot, Paul **Type** -Activation failure reported

**Supv** Merritt, D **Reg SO** **Div** AT **Sub** NM **IRI** **Milepost** 000 728.1 **Block** 2763

**Section** 3090-Ocean Springs **Asset** WHITE AVE **AssetNum** 340202K **Maintainer** Houck, B - ETA: 05:22

**Description** 10/04/2012 03:45:35 **by** Paul Belkot **Dept** Signals **IT+** -Activation failure reported

local pd reports crossing did not activate for train traversing crossing at White Ave...time of occurrence 0330....local pd also reported that trains were stopped in area due to vehicle in pursuit at Iberville dr. see incident 5808676. AA disp advised to protect crossing as a activation failure, disp initials WCJ. Last train in area was WB Q57903 that was stopped due to stop and flag at Iberville Dr. per AA disp. Noc manager advised. Atlanta CTD advised, initials TSM. Sent notification to ess Atlanta div., please call mtr. Notification Sent to -Signal Control Center - Atlanta at 10/04/2012 03:45:35 Asset: WHITE AVE Status Changed To: Out Of Service PCC Notification Sent 10/04/2012 03:45:35

**Updated** 10/04/2012 03:45:36 **by** Paul Belkot **Dept** Signals **IT+** -Activation failure reported

Notification has been sent to the following: Terrence Smale II Danny McKenzie Jody Cox C Manager

**Updated** 10/04/2012 03:51:53 **by** Paul Belkot **Dept** Signals **IT+** -Activation failure reported

ess Atlanta updated and advised sig supvr T.Smale

**Updated** 10/04/2012 03:52:27 **by** Jerry Rockhill **Dept** Signals **IT+** -Activation failure reported

0350 signal mgr t. smale informed of activation failure at white ave

**Updated** 10/04/2012 03:58:35 **by** Roland Knagge **Dept** PSCC **IT+**

**Contacted On** 10-04-2012 03:57:00 **Agency** na **Contact Name** na **Phone** na  
reference PSCC 4665362

**Closed** 10/04/2012 04:44:54 **by** Jerry Rockhill **Dept** Signals **IT+** -Activation failure reported

Incident Resolved: 10/04/2012 04:43:00 Equipment Type: Gate Action Taken: Freed gate - no gate mech realignment Suspected Reason: 0439 mtr reports the light wire on the west gate were hung up in the wind guard...mtr corrected and secured wiring...op cks ok and crossing was placed back in service with disp...all lights were functioning except west gate light and east gate functioned properly...no other issues were found at crossing... Operational Checks Performed Asset: WHITE AVE Status Changed To: In Service PCC Notification Sent 10/04/2012 04:44:54

**Updated** 10/04/2012 04:50:41 **by** Terry Lloyd **Dept** PSCC **IT+**

**Contacted On** 10-04-2012 04:50:00 **Agency** N/A **Contact Name** N/A **Phone** N/A

**Log#** [5760254](#) **Status** Closed **Entered** 08-29-2012 10:49:00 **by** Wi burn, Marion **Type** .False or partial activation reported

**Supv** Merritt, D **Reg SO** **Div** AT **Sub** NM **IRI** **Milepost** 000 728.1 **Block** 2763

**Section** 3090-Ocean Springs **Asset** WHITE AVE **AssetNum** 340202K **Maintainer**

**Description** 08/29/2012 10:54:12 **by** Marion Wi burn **Dept** Signals **IT+** .False or partial activation reported  
1049 HRS POLICE DEPT REPORTED ONE OF THE GATES IS BROKEN IN HALF AND THE OTHER ONE IS MISSING.  
CROSSING IS BEING PROTECTED UNDER BLANKET MESSAGE #30593 Asset: WHITE AVE Status Changed To: Out Of Service  
PCC Notification Sent 08/29/2012 10:54:12

**Updated** 08/29/2012 11:01:23 **by** Brooks Clayton **Dept** PSCC **IT+**

**Contacted On** **Agency** POLICE DEPT **Contact Name** OPERATOR 315 **Phone** 228-392-0641

Reporting party has been verified as the responsible law enforcement agency.

**Closed** 09/01/2012 13:05:33 **by** Terrence Smale II **Dept** Signals **IT+** .False or partial activation reported

Incident Resolved: 09/01/2012 13:05:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended Suspected Reason: Other weather crossing in service Operational Checks Performed Asset: WHITE AVE Status Changed To: In Service PCC Notification Sent 09/01/2012 13:05:33

**Updated** 09/01/2012 13:11:06 **by** Deborah Anderson **Dept** PSCC **IT+**

**Contacted On** 09-01-2012 13:10:00 **Agency** POLICE DEPT **Contact Name** 308 **Phone** 228-392-0641

---

**Log#** [5698766](#) **Status** Closed **Entered** 07-18-2012 02:32:59 **by** Kite, Matt **Type** .False or partial activation reported

**Supv** Merritt, D **Reg SO** **Div** AT **Sub** NM **IRI** **Milepost** 000 728.1 **Block** 2763

**Section** 3090-Ocean Springs **Asset** WHITE AVE **AssetNum** 340202K **Maintainer** Brown, K L - ETA: 03:54

**Description** 07/18/2012 02:35:02 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

NB Q18017 reported to disp that one gate at crossing, White Ave., did not come dwn. Flashers were working. Disp prot with A/F #28373.  
Asset: WHITE AVE Status Changed To: Out Of Service PCC Notification Sent 07/18/2012 02:35:02

**Updated** 07/18/2012 02:35:17 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

**Updated** 07/18/2012 03:01:36 **by** Kihron Bristol **Dept** PSCC **IT+**

**Contacted On** 07-18-2012 02:58:00 **Agency** Biloxi Police Department **Contact Name** 366 **Phone** 228-392-0641

Irish Hill Dr

**Closed** 07/18/2012 06:04:37 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Incident Resolved: 07/18/2012 05:58:00 Equipment Type: Gate Action Taken: Freed gate - no gate mech realignment Suspected Reason: Other weather

Mntr reports gate light cable wrapped around signal post. Missing cable clips, mntr unwrapped, replaced clips. Performed ops check, adjusted gate descent time to 13 sec. Watched SB train through crossing with 30 sec warning time and a NB train through with 32 sec warning time. Turned backover to disp.

Operational Checks Performed Asset: WHITE AVE Status Changed To: In Service PCC Notification Sent 07/18/2012 06:04:37

**Updated** 07/18/2012 06:34:03 **by** Clifford Keen **Dept** PSCC **IT+**

**Contacted On** 07-18-2012 06:33:00 **Agency** Biloxi Police Department **Contact Name** DISP APRIL **Phone** 228-392-0641

---

**Log#** [5686236](#) **Status** Closed **Entered** 07-10-2012 07:42:27 **by** Miller, Vern **Type** .False or partial activation reported

**Supv** Merritt, D **Reg SO** **Div** AT **Sub** NM **IRI** **Milepost** 000 728.1 **Block** 2763

**Section** 3090-Ocean Springs **Asset** WHITE AVE **AssetNum** 340202K **Maintainer** Stanfill, M O - ETA: 08:34

**Description** 07/10/2012 07:43:53 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported

crossing activated, no train around. dispatcher notified to protect with false/partial activation protection. vern

Asset: WHITE AVE Status Changed To: Out Of Service PCC Notification Sent 07/10/2012 07:43:53

**Updated** 07/10/2012 07:44:04 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported

. Notification Sent to -Signal Control Center - Atlanta at 07/10/2012 07:44:04

**Updated** 07/10/2012 07:44:51 **by** Clifford Keen **Dept** PSCC **IT+**

**Contacted On** **Agency** p.d. **Contact Name** susan **Phone** 228 392 0641

Reporting party has been verified as the responsible law enforcement agency.

**Closed** 07/10/2012 11:24:04 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported

Incident Resolved: 07/10/2012 10:23:00 Equipment Type: N/A Action Taken: Issue cleared before cause



identified Suspected Reason: N/A

**Employee:** M. Stanfill

- Crossing was clear when MTR arrived, could not duplicate the trouble. Crossing is working as intended.

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: WHITE AVE Status Changed To: In Service PCC Notification Sent  
07/10/2012 11:24:04

---

**Log#** [5642325](#) **Status** Closed **Entered** 06-10-2012 09:53:05 **by** Kondy, Rick **Type** .False or partial activation reported

**Supv** Merritt, D **Reg SO** **Div** AT **Sub** NM **IRI** **Milepost** 000 728.1 **Block** 2763

**Section** 3090-Ocean Springs **Asset** WHITE AVE **AssetNum** 340202K **Maintainer** Houck, B - ETA: 11:08

**Description** 06/10/2012 09:54:20 **by** Richard Kondy **Dept** Signals **IT+** .False or partial activation reported  
police reports gate damaged . disp protecting crossing with false activation # 33854 . Notification Sent to -Signal Control  
Center - Atlanta at 06/10/2012 09:54:20 Asset: WHITE AVE Status Changed To: Out Of Service PCC Notification Sent  
06/10/2012 09:54:20

**Updated** 06/10/2012 09:59:50 **by** Daniel Johnson **Dept** PSCC **IT+**  
**Contacted On** **Agency** // **Contact Name** biloxi police **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 06/10/2012 11:19:18 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
storms and high winds in area at time on incident

**Closed** 06/10/2012 11:54:58 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 06/10/2012 11:54:00 Equipment Type: Gate Action Taken: Damaged gate or sections-replaced/repai  
red  
Suspected Reason: Other weather Employee: B. Houck - Replaced broken gate at crossing (west gate) middle section. Did  
OP Checks, Back/released to AA disp. Operational Checks Performed Asset: WHITE AVE Status Changed To: In Service  
PCC Notification Sent 06/10/2012 11:54:58

**Updated** 06/10/2012 12:06:32 **by** Daniel Johnson **Dept** PSCC **IT+**  
**Contacted On** 06-10-2012 12:06:00 **Agency** biloxi police **Contact Name** 308 **Phone** 228-392-0641

---

**Log#** [5560691](#) **Status** Closed **Entered** 04-14-2012 12:48:21 **by** Hofer, Dave **Type** .False or partial activation reported

**Supv** Merritt, D **Reg SO** **Div** AT **Sub** NM **IRI** **Milepost** 000 728.1 **Block** 2763

**Section** 3090-Ocean Springs **Asset** WHITE AVE **AssetNum** 340202K **Maintainer** Houck, B - ETA: 14:15

**Description** 04/14/2012 12:53:24 **by** David Hofer **Dept** Signals **IT+** .False or partial activation reported  
12:50 Local pd reported a caller called in an reported the lights were slow to come on and the gates did not come down at DOT #  
340202K. Notified the AA dispatcher to protect the crossing as an activation failure. Train Q60512 reported the crossing gates and lights  
worked for them. Notification Sent to -Signal Control Center - Atlanta at 04/14/2012 12:53:24 Asset: WHITE AVE Status Changed To: Out  
Of Service PCC Notification Sent 04/14/2012 12:53:24

**Updated** 04/14/2012 12:56:00 **by** Daniel Johnson **Dept** PSCC **IT+**  
**Contacted On** **Agency** Dispatcher **Contact Name** Local Pd **Phone** 228.392.0641  
Reporting party has been verified as the responsible law enforcement agency.

**Closed** 04/14/2012 14:34:19 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 04/14/2012 14:33:00 Equipment Type: Other - explain Action Taken: Other - explain Suspected Reason: Other  
department

**Employee:** B. Houck

- no errors in the unit, shunted approaches and island no exceptions, replaced blown bu b ion the west cant., crossing woking as  
intended

Did OP Checks, Back/released to AA disp. RX/PH 100/69

Operational Checks Performed Asset: WHITE AVE Status Changed To: In Service PCC Notification Sent 04/14/2012 14:34:19

**Updated** 04/14/2012 14:51:19 **by** Sean Reid **Dept** PSCC **IT+**  
**Contacted On** 04-14-2012 14:50:00 **Agency** Biloxi Police Department **Contact Name** Disp # 3162 **Phone** 228-392-0641

**Log#** [5546198](#) **Status** Closed **Entered** 04-04-2012 02:57:11 **by** Kite, Matt **Type** .False or partial activation reported

**Supv** Merritt, D **Reg SO** **Div** AT **Sub** NM **IRI** **Milepost** 000 728.1 **Block** 2763

**Section** 3090-Ocean Springs **Asset** WHITE AVE **AssetNum** 340202K **Maintainer** Brown, K L - *ETA*: 05:22

**Description** 04/04/2012 03:00:03 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

PSCC reported to disp that gate arm was broken at crossing. Disp prot crossing with A/F #23013.  
Asset: WHITE AVE Status Changed To: Out Of Service PCC Notification Sent 04/04/2012 03:00:03

**Updated** 04/04/2012 03:04:23 **by** Myrtie Hackney **Dept** PSCC **IT+**

**Contacted On** 04-04-2012 03:02:00 **Agency** Biloxi Police Department **Contact Name** 366 **Phone** 228-392-0641  
@ Irish Hill Drive

**Updated** 04/04/2012 03:23:13 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Heavy storms in area. As a safety precaution mntr will delay start time to give weather a chance to pass/calm.

**Updated** 04/04/2012 05:07:35 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Mntr on-site, lighting extremely bad. Mntr reports it is unsafe to work in current weather condition. Mntr will wait at crossing until it is safe to work.

**Closed** 04/04/2012 07:06:55 **by** Kenneth Brown **Dept** Signals **IT+** .False or partial activation reported

Incident Resolved: 04/04/2012 07:06:00 Equipment Type: Gate Action Taken: Damaged gate or sections-replaced/repared  
Suspected Reason: Lightning mntr had to replaced west gate. made op checks and back in service with dispatcher. gate down time was 11 seconds. mntr watched two south bounds thru with no problems. Operational Checks Performed Asset: WHITE AVE  
Status Changed To: In Service PCC Notification Sent 04/04/2012 07:06:55

**Updated** 04/04/2012 07:12:33 **by** Keith Datema **Dept** PSCC **IT+**

**Contacted On** 04-04-2012 07:11:00 **Agency** Biloxi Police Department **Contact Name** oper **Phone** 228-392-0641

**Iberville Drive**

**DOT Crossing #: 340204Y**

**RR Milepost #: 729.53**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 18

Status All AssetType All RootAssetType All Department Signals AssetNum 340204Y

---

**Log#** [7967675](#) **Status** Closed **Entered** 01-18-2017 14:20:23 **by** Lewis, Wendell **Type** Vehicle on Track

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 729.5 **Block** 2763

**Section** 3090-7M16 **Asset** IBERVILLE DR **AssetNum** 340204Y **Maintainer** James Jr, G H - *ETA*: 14:44

**Description** 01/18/2017 14:20:23 **by** Wendell Lewis **Dept** Signals **IT+** Unknown

**Updated** 01/18/2017 14:22:01 **by** Wendell Lewis **Dept** Signals **IT+** Vehicle on Track

Last Update 01-18-2017 14:16 By DRT Type General Business Impact 3 Priority 3 Incident Type: TRK Dispatch  
incident Number: 82818 Incident Date: 18-JAN-17 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000,  
0727.0000 Right Mile Post: 000, 0730.2851 Asset: 2763 003, Asset Name: MAIN PTC Flag: N Incident Description:  
TRUCK WAS STUCK ON TRACK AT IBERVILLE DR MP 000729.53 Asset: IBERVILLE DR Status Changed To:  
Out Of Service PCC Notification Sent 01/18/2017 14:22:01

**Updated** 01/18/2017 14:25:06 **by** Byron Tinsley

**Dept** PSCC **IT+**

**Contacted On** 01-18-2017 14:25:00 **Agency** NA

**Contact Name** NA **Phone** NA

PSCC Incident Report - #7967652

**Updated** 01/18/2017 14:44:30 **by** Wendell Lewis

**Dept** Signals **IT+** Vehicle on Track

Status changed to Escalated, George James Jr ETA of: N/A

**Updated** 01/18/2017 15:29:09 **by** Allen Rose

**Dept** Signals **IT+** Vehicle on Track

Incident Resolved: 01/18/2017 15:27:00 Equipment Type: Track Action Taken: Removed debris Clear on arrival, did  
operational checks. Operational Checks Performed Asset: IBERVILLE DR Status Changed To: In Service PCC  
Notification Sent 01/18/2017 15:29:09

**Updated** 01/18/2017 15:30:42 **by** Patrick Knotts

**Dept** Signals **IT+** Vehicle on Track

Incident Resolved: 01/18/2017 15:27:00 Equipment Type: N/A Action Taken: NTF - UTD Clear on arrival, did  
operational checks. Operational Checks Performed

**Closed** 01/18/2017 15:31:05 **by** Patrick Knotts

**Dept** Signals **IT+** Vehicle on Track

Incident Resolved: 01/18/2017 15:27:00 Equipment Type: N/A Action Taken: NTF - UTD . Operational Checks  
Performed

**Updated** 01/18/2017 15:32:27 **by** Misty Hunter

**Dept** PSCC **IT+**

**Contacted On** 01-18-2017 15:32:00 **Agency** Biloxi Police Department **Contact Name** Kristin **Phone** 228-392-0641

---

**Log#** [7902722](#) **Status** Closed **Entered** 11-29-2016 10:28:23 **by** Williams, Joseph **Type** Vehicle on Track

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 729.5 **Block** 2763

**Section** 3090-7M16 **Asset** IBERVILLE DR **AssetNum** 340204Y **Maintainer** Mannion, R - *ETA*: 11:20

**Description** 11/29/2016 10:28:23 **by** Joseph Williams **Dept** Signals **IT+** Unknown

**Updated** 11/29/2016 10:29:39 **by** Joseph Williams **Dept** Signals **IT+** Vehicle on Track

Incident Type: TRK Dispatch incident Number: 68907 Incident Date: 29-NOV-16 Pri.Train ID: SubDivision Code: NM  
Left Mile Post: 000, 0727.0000 Right Mile Post: 000, 0730.2851 Asset: 2763 003, Asset Name: MAIN PTC Flag: N  
Incident Description: TRUCK STUCK ON TRACKS Dispatcher reported that the truck is at Iberville Drive 000 729.5.  
Asset: IBERVILLE DR Status Changed To: Out Of Service PCC Notification Sent 11/29/2016 10:29:39

**Updated** 11/29/2016 10:30:30 **by** Kiwana Tompkins

**Dept** PSCC **IT+**

**Contacted On** 11-29-2016 10:30:00 **Agency** Biloxi Police Department **Contact Name** sarah **Phone** 228-392-0641

PSCC #7902693

**Updated** 11/29/2016 10:35:13 **by** Joseph Williams

**Dept** Signals **IT+** Vehicle on Track

Status changed to Dispatched for Roger Mannion ETA of: 11:20

**Updated** 11/29/2016 11:25:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Updated** 11/29/2016 11:40:44 **by** Roger Mannion **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 11/29/2016 11:40:00 Equipment Type: N/A Action Taken: Track Occupied Vehicle was gone when I got to crossing. No signal damages, returned to dispatcher DC at 1140 with message number 29284.  
Operational Checks Performed Asset: IBERVILLE DR Status Changed To: In Service PCC Notification Sent 11/29/2016 11:40:44

**Updated** 11/29/2016 11:44:32 **by** Kiwana Tompkins **Dept** PSCC **IT+**  
**Contacted On** 11-29-2016 11:44:00 **Agency** Biloxi Police Department **Contact Name** Sarah **Phone** 228-392-0641

**Closed** 11/29/2016 11:55:04 **by** David Price **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 11/29/2016 11:40:00 Equipment Type: N/A Action Taken: NTF - UTD CLOSED Operational Checks Performed

---

**Log#** [7705122](#) **Status** Closed **Entered** 07-05-2016 13:53:42 **by** Wilburn, Marion **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 729.5 **Block** 2763

**Section** 3090-7M16 **Asset** IBERVILLE DR **AssetNum** 340204Y **Maintainer** Stanfill, M O - ETA: 15:01

**Description** 07/05/2016 13:53:42 **by** Marion Wilburn **Dept** Signals **IT+** Unknown

**Updated** 07/05/2016 13:57:23 **by** Marion Wilburn **Dept** Signals **IT+** .False or partial activation reported  
1356 Hrs. Police dept. reports crossing is activated with no train present, AA-dispatcher has been notified to protect crossing as false activation . Notification Sent to -Signal Control Center - Atlanta at 07/05/2016 13:57:23 Asset: IBERVILLE DR Status Changed To: Out Of Service PCC Notification Sent 07/05/2016 13:57:23

**Updated** 07/05/2016 14:01:15 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 15:01

**Updated** 07/05/2016 14:18:42 **by** Jerome Shepard **Dept** PSCC **IT+**  
**Contacted On** **Agency** Police dept. **Contact Name** Operator 376 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 07/05/2016 15:05:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 07/05/2016 15:40:37 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 07/05/2016 15:38:00 Equipment Type: Wiring/Protection Action Taken: Repaired/Replaced Protection

**The Signal Maintainer found a burnt AGE-1 Arrestor at the adjoining crossing due to weather. He replaced it. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: IBERVILLE DR Status Changed To: In Service PCC Notification Sent 07/05/2016 15:40:37

**Updated** 07/05/2016 15:54:56 **by** Jackie McGuirt **Dept** PSCC **IT+**  
**Contacted On** **Agency** Police dept. **Contact Name** Operator 376 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

---

**Log#** [7642515](#) **Status** Closed **Entered** 05-17-2016 20:01:28 **by** Oglesby, Brad **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 729.5 **Block** 2763

**Section** 3090-7M16 **Asset** IBERVILLE DR **AssetNum** 340204Y **Maintainer** Mannion, R - ETA: 21:56

**Description** 05/17/2016 20:01:28 **by** Brad Oglesby **Dept** Signals **IT+** Unknown

**Updated** 05/17/2016 20:05:10 **by** Brad Oglesby **Dept** Signals **IT+** .False or partial activation reported  
2001 THE LOCAL PD REPORTED RECEIVING A NOTICE FROM AN OUTSIDE PARTY(NO CONTACT INFORMATION AVAILABLE) CLAIMING SHE ALMOST GOT HIT AT THE CROSSING; THE CALLER CLAIMED THE GATES AND LIGHTS

DIDN'T WORK ON ONE SIDE OF THE CROSSING AS A TRAIN WAS "RIGHT UP ON IT"(DOT NUMBER PROVIDED). THERE WASN'T ANY SPECIFICATION AS TO WHAT DIRECTION AND/OR SPEED THE TRAIN WAS TRAVELING WHEN THIS ALLEGED INCIDENT OCCURRED. 2002 ESS ADVISED THE AA DISPATCHER(INITIALS-WCJ) TO PROVIDE PROTECTION ON THE CROSSING AS PER ACTIVATION FAILURE STANDARD. Notification Sent to -Signal Control Center - Atlanta at 05/17/2016 20:05:10 Asset: IBERVILLE DR Status Changed To: Out Of Service PCC Notification Sent 05/17/2016 20:05:10

**Updated** 05/17/2016 20:26:30 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Roger Mannion ETA of: 21:56

**Updated** 05/17/2016 20:30:27 **by** Roland Knagge **Dept** PSCC **IT+**  
**Contacted On** 05-17-2016 20:30:00 **Agency** BILOXI PD **Contact Name** MONTANA **Phone** 228 392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 05/17/2016 22:00:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 05/17/2016 22:17:02 **by** Roger Mannion **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 05/17/2016 22:17:00 Equipment Type: N/A Action Taken: NTF - UTD Tested crossing and activated crossing in every way possible from my understanding of signals, verified gate activation as well as lights working by shunting island, approach, dropping gates individually, dropping XR relay, swapping from main to stand-by on cabinet and then doing it all again on DC power only. Never failed, activated every time. Also, verified gate mechs. to be in good order, no shear pins broken, hold clear devices working freely and properly, not even one single light was out, or unilluminated, (yep, made that word up). Back to dispatcher at 1012 wcj Operational Checks Performed Asset: IBERVILLE DR Status Changed To: In Service PCC Notification Sent 05/17/2016 22:17:02

**Closed** 05/17/2016 22:19:15 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 05/17/2016 22:17:00 Equipment Type: N/A Action Taken: NTF - UTD Operational Checks Performed

**Updated** 05/17/2016 22:31:15 **by** Kiwana Tompkins **Dept** PSCC **IT+**  
**Contacted On** 05-17-2016 22:28:00 **Agency** BILOXI PD **Contact Name** Jennifer **Phone** 228 392-0641

---

**Log#** [7532154](#) **Status** Closed **Entered** 02-23-2016 23:10:41 **by** Kite, Matt **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 729.5 **Block** 2763

**Section** 3090-7M16 **Asset** IBERVILLE DR **AssetNum** 340204Y **Maintainer** Stanfill, M O - ETA: 00:46 & Richardson, G L - ETA: 02:22

**Description** 02/23/2016 23:10:41 **by** Matthew Kite **Dept** Signals **IT+** Unknown

**Updated** 02/23/2016 23:11:32 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Incident Type: TRK Dispatch incident Number: 74061 Incident Date: 23-FEB-16 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000, 0726.0000 Right Mile Post: 000, 0730.3000 Asset: 2763 003, Asset Name: MAIN PTC Flag: N Incident Description: GATE BROKEN AT IBERVILLE DRIVE 729.53 REPORTED BY Q61722 Copied frm DIRT. Disp prot with A/F #26087.  
Asset: IBERVILLE DR Status Changed To: Out Of Service PCC Notification Sent 02/23/2016 23:11:32

**Updated** 02/23/2016 23:11:34 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
An email notification for (IRI) asset IBERVILLE DR (1) has been sent to the following:  
George James Jr

**Updated** 02/23/2016 23:16:37 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 00:46

**Updated** 02/23/2016 23:57:54 **by** Alyson Trouba **Dept** PSCC **IT+**  
**Contacted On** 02-23-2016 23:57:00 **Agency** Biloxi Police Department **Contact Name** Courtney **Phone** 228-392-0641  
Irish Hill Dr

**Updated** 02/24/2016 00:50:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 02/24/2016 01:10:35 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Severe storm passed through area. Mntr is working 3-4 separate crossing issues. Will move to crossings as quickly and safely as time

and weather permit.

**Updated** 02/24/2016 02:23:43 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Mntr Richardson in area working on White Ave. Finished work and mntr is now assisting Mntr Stanfill with repairs to multiple crossings in area.

**Closed** 02/24/2016 02:35:36 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Incident Resolved: 02/24/2016 02:35:00 Equipment Type: Gate Action Taken: Replaced shear pin/rehung original gate Mntr rehung west gate, repaired gate wires. Damaged due to severe storms in area. Performed op checks, turned crossing back over to disp.

Operational Checks Performed Asset: IBERVILLE DR Status Changed To: In Service PCC Notification Sent 02/24/2016 02:35:36

**Updated** 02/24/2016 02:43:10 **by** Misty Hunter **Dept** PSCC **IT+**

**Contacted On** 02-24-2016 02:43:00 **Agency** Biloxi Police Department **Contact Name** Mossel **Phone** 228-392-0641

---

**Log#** [7530593](#) **Status** Closed **Entered** 02-22-2016 21:37:42 **by** Foster, George **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 729.5 **Block** 2763

**Section** 3090-7M16 **Asset** IBERVILLE DR **AssetNum** 340204Y **Maintainer** Stanfill, M O - ETA: 23:40

**Description** 02/22/2016 21:37:42 **by** George Foster **Dept** Signals **IT+** Unknown

**Updated** 02/22/2016 21:40:42 **by** George Foster **Dept** Signals **IT+** .False or partial activation reported

Crossing activated with no trains. Notification Sent to -Signal Control Center - Atlanta at 02/22/2016 21:40:42 Asset:

IBERVILLE DR Status Changed To: Out Of Service PCC Notification Sent 02/22/2016 21:40:42

**Updated** 02/22/2016 22:40:46 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported

Status changed to Dispatched for Michael Stanfill ETA of: 00:40

**Updated** 02/22/2016 22:44:41 **by** Sabrina Smith **Dept** PSCC **IT+**

**Contacted On** 02-22-2016 22:44:00 **Agency** 911 **Contact Name** 3500 **Phone** 228-392-0641

Reporting party has been verified as the responsible law enforcement agency.

**Updated** 02/22/2016 23:45:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported

ETA time reached Status changed to Active

**Closed** 02/23/2016 02:53:39 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Incident Resolved: 02/23/2016 02:53:00 Equipment Type: Wiring/Protection Action Taken: Repaired/Replaced Protection Mntr replaced 2 lightning arrestors, replaced transceiver cd and calibrated unit and repaired wiring on east gate. Bad storms in area. Performed op checks, watched a NB and SB train through crossing, no exceptions noted. Turned crossing back over to disp.

Operational Checks Performed Asset: IBERVILLE DR Status Changed To: In Service PCC Notification Sent 02/23/2016 02:53:39

**Updated** 02/23/2016 02:59:06 **by** Alyson Trouba **Dept** PSCC **IT+**

**Contacted On** 02-23-2016 02:58:00 **Agency** 911 **Contact Name** Kristin **Phone** 228-392-0641

---

**Log#** [7356440](#) **Status** Closed **Entered** 10-10-2015 13:00:55 **by** Lewis, Wendell **Type** -Activation failure reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 729.5 **Block** 2763

**Section** 3090-7M16 **Asset** IBERVILLE DR **AssetNum** 340204Y **Maintainer** Mannion, R - ETA: 15:21

**Description** 10/10/2015 13:00:55 **by** Wendell Lewis **Dept** Signals **IT+** Unknown

**Updated** 10/10/2015 13:08:09 **by** Wendell Lewis **Dept** Signals **IT+** -Activation failure reported

12:58 PD REPORTS PER OUTSIDE PARTY X-ING FLASHERS AND GATES DID NOT ACTIVATE FOR TRAIN MOVEMENT THRU X-ING AT 11:49.....NOTIFIED AA-DISP. TO PROTECT WITH A/F MSG.....DISP. STATED NO TRAINS HAVE REPORTED ANY EXCEPTION TO X-ING OPERATION. Notification Sent to -Signal Control Center - Atlanta at 10/10/2015 13:08:09 Asset: IBERVILLE DR Status Changed To: Out Of Service PCC Notification Sent

10/10/2015 13:08:09



**Updated** 10/10/2015 13:08:10 **by** Wendell Lewis **Dept** Signals **IT+** -Activation failure reported  
Notification has been sent to the following: George James Jr Danny McKenzie Jody Cox C Manager

**Updated** 10/10/2015 13:12:51 **by** Avie Saunders **Dept** PSCC **IT+**  
**Contacted On** **Agency** BILOXI PD **Contact Name** BRENDA **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 10/10/2015 13:21:53 **by** Bruce McVey **Dept** Signals **IT+** -Activation failure reported  
Status changed to Dispatched for Roger Mannion ETA of: 15:21

**Updated** 10/10/2015 15:25:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** -Activation failure reported  
ETA time reached Status changed to Active

**Closed** 10/10/2015 17:10:52 **by** Matthew Kite **Dept** Signals **IT+** -Activation failure reported  
Incident Resolved: 10/10/2015 17:08:00 Equipment Type: N/A Action Taken: NTF - UTD  
Mntr reports crossing COA. Watched NB through flagging, equip operational. Mntr shunted through crossing and watched a train through on timetable speed with no exceptions noted. 29 sec warning time at crossing for train. Mntr turned crossing backover to disp.  
Operational Checks Performed Asset: IBERVILLE DR Status Changed To: In Service PCC Notification Sent 10/10/2015 17:10:52

**Updated** 10/10/2015 17:11:56 **by** Jodi Snyder **Dept** PSCC **IT+**  
**Contacted On** 10-10-2015 17:11:00 **Agency** BILOXI PD **Contact Name** Brandi **Phone** 228-392-0641

---

**Log#** [7247473](#) **Status** Closed **Entered** 07-24-2015 13:10:07 **by** Jackson Jr, Marv **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 729.5 **Block** 2763

**Section** 3090-7M16 **Asset** IBERVILLE DR **AssetNum** 340204Y **Maintainer** Stanfill, M O - ETA: 13:20

**Description** 07/24/2015 13:10:07 **by** Marv Jackson Jr **Dept** Signals **IT+** Unknown

**Updated** 07/24/2015 13:11:35 **by** Marv Jackson Jr **Dept** Signals **IT+** .False or partial activation reported  
CSX-PCC REPORTS BROKEN GATE AT IBERVILLE DR....DISP PROTECTING W/ACTIVATION FAILURE MESSAGE. Notification Sent to -Signal Control Center - Atlanta at 07/24/2015 13:11:35 Asset: IBERVILLE DR Status Changed To: Out Of Service PCC Notification Sent 07/24/2015 13:11:35

**Updated** 07/24/2015 13:20:49 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: N/A

**Updated** 07/24/2015 13:25:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 07/24/2015 13:31:05 **by** Nikole Ross **Dept** PSCC **IT+**  
**Contacted On** 07-24-2015 13:31:00 **Agency** Biloxi Police Department **Contact Name** OP **Phone** 228-392-0641  
PSCC Incident Report - Edit #7247446

**Updated** 07/24/2015 15:27:59 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported

**Update** - The ESS left a message requesting an update on the Signal Maintainer's cell phone. LVR

**Closed** 07/24/2015 15:31:01 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 07/24/2015 14:30:00 Equipment Type: Gate Action Taken: Damaged gate or sections-replaced/repaird

**The Signal Maintainer replaced the East gate. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: IBERVILLE DR Status Changed To: In Service PCC Notification Sent 07/24/2015 15:31:01

**Updated** 07/24/2015 15:36:30 **by** Misty Hunter **Dept** PSCC **IT+**  
**Contacted On** 07-24-2015 15:33:00 **Agency** Biloxi Police Department **Contact Name** Courtney **Phone** 228-392-0641

**Log# 7080213**    **Status Closed**    **Entered** 04-01-2015 19:08:30    **by** Rosenblatt, Louis    **Type** Vehicle on Track  
**Supv** Merritt, D    **Reg** SO    **Div** AT    **Sub** NM    **IRI** 0    **Milepost** 000 729.5    **Block** 2763  
**Section** 3090-7M16    **Asset** IBERVILLE DR    **AssetNum** 340204Y    **Maintainer** Mannion, R - *ETA*: 21:46  
**Description** 04/01/2015 19:08:30    **by** Louis Rosenblatt    **Dept** Signals    **IT+** Unknown  
**Updated** 04/01/2015 19:08:58    **by** Louis Rosenblatt    **Dept** Signals    **IT+** Vehicle on Track

The AA Dispatcher received a report from the PSCC that Iberville Drive, MP 000 729.53, DOT# 340204Y, NM Sub, has a vehicle on the tracks.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 12065**. LVR  
Asset: IBERVILLE DR Status Changed To: Out Of Service PCC Notification Sent 04/01/2015 19:08:58

**Updated** 04/01/2015 19:11:16    **by** Avie Saunders    **Dept** PSCC    **IT+**  
**Contacted On** 04-01-2015 19:10:00 **Agency** Biloxi Police Department    **Contact Name** Jackie    **Phone** 228-392-0641  
PSCC Incident Report - Edit #7080180

**Updated** 04/01/2015 19:46:37    **by** Louis Rosenblatt    **Dept** Signals    **IT+** Vehicle on Track  
Status changed to Dispatched for Roger Mannion ETA of: 21:46

**Updated** 04/01/2015 21:50:00    **by** TCIS AUTOMATION    **Dept** Signals    **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Closed** 04/01/2015 22:23:52    **by** Louis Rosenblatt    **Dept** Signals    **IT+** Vehicle on Track  
Incident Resolved: 04/01/2015 22:18:00 Equipment Type: N/A Action Taken: NTF - UTD

**The Signal Maintainer reported that there was no signal damage. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: IBERVILLE DR Status Changed To: In Service PCC Notification Sent  
04/01/2015 22:23:52

**Updated** 04/01/2015 22:30:35    **by** Jodi Snyder    **Dept** PSCC    **IT+**  
**Contacted On** 04-01-2015 22:29:00 **Agency** Biloxi Police Department    **Contact Name** Dillon    **Phone** 228-392-0641  
PSCC Incident Report - Edit #7080180

---

**Log# 6789052**    **Status Closed**    **Entered** 09-10-2014 08:45:30    **by** McVey, Bruce    **Type** Vehicle on Track  
**Supv** Merritt, D    **Reg** SO    **Div** AT    **Sub** NM    **IRI** 0    **Milepost** 000 729.5    **Block** 2763  
**Section** 3090-7M16    **Asset** IBERVILLE DR    **AssetNum** 340204Y    **Maintainer** Mannion, R - *ETA*: 10:32  
**Description** 09/10/2014 08:45:30    **by** Bruce McVey    **Dept** Signals    **IT+** Unknown  
**Updated** 09/10/2014 08:46:58    **by** Bruce McVey    **Dept** Signals    **IT+** Vehicle on Track

**ATL CTD :Notification**

ATL ACD, AA DISP, NM SUB, LOC 2762: PSCC reported a vehicle on the track at Iberville RD, mo 000 729.5...need MOW and Signals to respond...:**COPIED**  
Asset: IBERVILLE DR Status Changed To: Out Of Service PCC Notification Sent 09/10/2014 08:46:58

**Updated** 09/10/2014 08:48:17    **by** Bruce McVey    **Dept** Signals    **IT+** Vehicle on Track

The AA is protecting the Crossing with a **Type 1 Activation Failure Message# 40403** .

**Updated** 09/10/2014 08:53:30    **by** Bruce McVey    **Dept** Signals    **IT+** Vehicle on Track  
Status changed to Dispatched for Roger Mannion ETA of: 10:32

**Updated** 09/10/2014 09:03:24    **by** Christina Martorano    **Dept** PSCC    **IT+**  
**Contacted On** 09-10-2014 08:53:00    **Agency** Biloxi Police    **Contact Name** Desire    **Phone** 228-392-0641

**Updated** 09/10/2014 10:35:00    **by** TCIS AUTOMATION    **Dept** Signals    **IT+** Vehicle on Track

ETA time reached Status changed to Active

**Updated** 09/10/2014 11:11:17 **by** Roger Mannion **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 09/10/2014 11:10:00 Equipment Type: N/A Action Taken: Track Occupied Vehicle not on crossing upon arrival. Checked crossing, no exception are found as far as signals are concerned. Gave back to dispatcher with message number 40639. Operational Checks Performed Asset: IBERVILLE DR Status Changed To: In Service PCC Notification Sent 09/10/2014 11:11:17

**Closed** 09/10/2014 11:13:23 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 09/10/2014 11:12:00 Equipment Type: N/A Action Taken: Track Occupied Closed  
Operational Checks Performed

**Updated** 09/10/2014 11:17:06 **by** Michele Schwartz **Dept** PSCC **IT+**  
**Contacted On** 09-10-2014 11:16:00 **Agency** Biloxi Police **Contact Name** 347 **Phone** 228-392-0641

---

**Log#** [6631435](#) **Status** Closed **Entered** 05-22-2014 16:39:16 **by** Rosenblatt, Louis **Type** Vehicle on Track

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 729.5 **Block** 2763

**Section** 3090-Ocean Springs **Asset** IBERVILLE DR **AssetNum** 340204Y **Maintainer** Houck, B - ETA: 21:03

**Description** 05/22/2014 16:39:16 **by** Louis Rosenblatt **Dept** Signals **IT+** Unknown

**Updated** 05/22/2014 16:39:47 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track

The AA Dispatcher received a report from the PSCC that Iberville Drive, MP 000 729.53, DOT# 340204Y, NM Sub, has a vehicle stuck on the track.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 27336**. LVR  
Asset: IBERVILLE DR Status Changed To: Out Of Service PCC Notification Sent 05/22/2014 16:39:47

**Updated** 05/22/2014 17:12:42 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Bradley Houck ETA of: 18:42

**Updated** 05/22/2014 18:45:06 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Updated** 05/22/2014 21:04:27 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track

**Update** - The ESS left a message requesting an update on the Signal Maintainer's cell phone. LVR

**Closed** 05/22/2014 21:07:46 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 05/22/2014 21:07:00 Equipment Type: N/A Action Taken: NTF - UTD

**The Signal Maintainer reported that there was no signal damage. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: IBERVILLE DR Status Changed To: In Service PCC Notification Sent 05/22/2014 21:07:46

---

**Log#** [6495894](#) **Status** Closed **Entered** 02-17-2014 13:17:19 **by** McVey, Bruce **Type** Vehicle on Track

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 729.5 **Block** 2763

**Section** 3090-Ocean Springs **Asset** IBERVILLE DR **AssetNum** 340204Y **Maintainer** Stanfill, M O - ETA: 13:51

**Description** 02/17/2014 13:17:19 **by** Bruce McVey **Dept** Signals **IT+** Unknown

**Updated** 02/17/2014 13:20:21 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track

ATL CTD

- Notification:

ATLANTA CHIEF, AA DISPATCHER, NM SUB, LOCATION 2763-003, PSCC REPORTS TRUCK ON THE TRACKS AT IBERVILLE DR MP 000729.5. :COPIED

Asset: IBERVILLE DR Status Changed To: Out Of Service PCC Notification Sent 02/17/2014 13:20:21

**Updated** 02/17/2014 13:21:28 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Michael Stanfill ETA of: 13:51

**Updated** 02/17/2014 13:24:56 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track  
The AA is protecting the Crossing with a **Type 1 Activation Failure Message# 49470**.

**Closed** 02/17/2014 13:44:19 **by** Jason Gothard **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 02/17/2014 13:44:00 Equipment Type: N/A Action Taken: NTF - UTD removed truck and no signal damage. made op checks and ret to disp Operational Checks Performed Asset: IBERVILLE DR Status Changed To: In Service PCC Notification Sent 02/17/2014 13:44:19

---

**Log#** [6393211](#) **Status** Closed **Entered** 12-06-2013 18:41:27 **by** Gothard, Jason **Type** Vehicle on Track  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 729.5 **Block** 2763  
**Section** 3090-Ocean Springs **Asset** IBERVILLE DR **AssetNum** 340204Y **Maintainer** Stanfill, M O - ETA: 20:17

**Description** 12/06/2013 18:41:27 **by** Jason Gothard **Dept** Signals **IT+** Unknown

**Updated** 12/06/2013 18:41:57 **by** Jason Gothard **Dept** Signals **IT+** Vehicle on Track  
ATL ACD, AA Disp, NM Sub, Loc 2763; PSCC reported vehicle stuck on tracks at mp 000729.5, Iberville Drive. Asset: IBERVILLE DR Status Changed To: Out Of Service PCC Notification Sent 12/06/2013 18:41:57

**Updated** 12/06/2013 18:47:49 **by** Jason Gothard **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Michael Stanfill ETA of: 20:17

**Updated** 12/06/2013 19:00:26 **by** Sheri Sheppard **Dept** PSCC **IT+**  
**Contacted On** 12-06-2013 19:00:00 **Agency** na **Contact Name** na **Phone** na  
REf PSCC incident 6393199

**Updated** 12/06/2013 20:20:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Closed** 12/06/2013 21:37:21 **by** Jason Gothard **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 12/06/2013 21:36:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended mntr reports vehicle removed, no damage, made op checks and ret to disp Operational Checks Performed Asset: IBERVILLE DR Status Changed To: In Service PCC Notification Sent 12/06/2013 21:37:21

**Updated** 12/06/2013 21:42:43 **by** Sheri Sheppard **Dept** PSCC **IT+**  
**Contacted On** 12-06-2013 21:42:00 **Agency** na **Contact Name** na **Phone** na

---

**Log#** [6377993](#) **Status** Closed **Entered** 11-23-2013 23:38:35 **by** Rockhill, Jerry **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 729.5 **Block** 2763

**Section** 3090-Ocean Springs **Asset** IBERVILLE DR **AssetNum** 340204Y **Maintainer** Richardson, G L - ETA: 02:30

**Description** 11/23/2013 23:38:35 **by** Jerry Rockhill **Dept** Signals **IT+** Unknown

**Updated** 11/23/2013 23:41:38 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
2341 atl chief, aa disp, nm sub, lights not working on the gates at Iberville Drive mp 000729.5 .....disp protecting crossing with activation failure msg 47161..... Asset: IBERVILLE DR Status Changed To: Out Of Service PCC Notification Sent 11/23/2013 23:41:38

**Updated** 11/23/2013 23:46:59 **by** Christopher Horman **Dept** PSCC **IT+**  
**Contacted On** 11-23-2013 23:45:00 **Agency** Biloxi Police Department **Contact Name** Disp. Ramona **Phone** 228-392-0641  
@ Irish Hill Drive

**Updated** 11/24/2013 01:00:56 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Gregory Richardson ETA of: 02:30

**Updated** 11/24/2013 02:35:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 11/24/2013 02:49:44 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 11/24/2013 02:41:00 Equipment Type: Gate Action Taken: Repaired/replaced only gate light(s) 0239 mtr reports east side gate lights had bad connection ...mtr repaired....op cks ok and crossing back in service with disp.... Operational Checks Performed  
Asset: IBERVILLE DR Status Changed To: In Service PCC Notification Sent 11/24/2013 02:49:44

**Updated** 11/24/2013 02:56:35 **by** Thera Moore **Dept** PSCC **IT+**  
**Contacted On** 11-24-2013 02:56:00 **Agency** Biloxi Police Department **Contact Name** eric **Phone** 228-392-0641

---

**Log#** [6362778](#) **Status** Closed **Entered** 11-12-2013 13:10:51 **by** Lewis, Wendell **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 729.5 **Block** 2763

**Section** 3090-Ocean Springs **Asset** IBERVILLE DR **AssetNum** 340204Y **Maintainer** Stanfill, M O - ETA: 14:27

**Description** 11/12/2013 13:10:51 **by** Wendell Lewis **Dept** Signals **IT+** Unknown

**Updated** 11/12/2013 13:24:08 **by** Wendell Lewis **Dept** Signals **IT+** .False or partial activation reported  
13:05 CALLERS REPORTS SHE WAS PASSING IBERVILLE DR WHEN SHE LOOKED UP AND SAW A TRAIN HEADING TOWARD NEW ORLEANS COMING AT HER AND THE X-ING FLASHERS AND GATES DID NOT ACTIVATE UNTIL AFTER SHE HAD CROSSED OVER THE TRACKS, FLASHERS AND GATES WERE ACTIVATED WHEN TRAIN GOT TO AND PASSED OVER X-ING, CALLER FELT X-ING SHOULD HAVE BEEN ACTIVATED SOONER.....AA-DISP. NOTIFIED TO PROTECT WITH A/F MSG....DISP. REPORTS SB Q57911 LINED INTO THE SIDING AT N.E. OF BEAUVOIR MEETING NB Q57212 REPORTED NO EXCEPTION TO X-ING OPERATION. Notification Sent to -Signal Control Center - Atlanta at 11/12/2013 13:24:08 Asset: IBERVILLE DR Status Changed To: Out Of Service PCC Notification Sent 11/12/2013 13:24:08

**Updated** 11/12/2013 13:27:46 **by** Brooks Clayton **Dept** PSCC **IT+**  
**Contacted On** 11-12-2013 13:27:00 **Agency** Biloxi Police Department **Contact Name** Sarah **Phone** 228-392-0641

**Updated** 11/12/2013 13:27:59 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 14:27

**Updated** 11/12/2013 14:30:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 11/12/2013 16:26:43 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 11/12/2013 16:24:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended

**The Signal Maintainer reported that the Crossing is working properly. There are no issues or error codes. All Warning Times are above thirty seconds. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: IBERVILLE DR Status Changed To: In Service PCC Notification Sent 11/12/2013 16:26:43

**Updated** 11/12/2013 16:37:52 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** 11-12-2013 16:37:00 **Agency** Biloxi Police Department **Contact Name** jennifer **Phone** 228-392-0641

---

**Log#** [6279556](#) **Status** Closed **Entered** 09-06-2013 17:59:03 **by** Rosenblatt, Louis **Type** Vehicle on Track

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 729.5 **Block** 2763

**Section** 3090-Ocean Springs **Asset** IBERVILLE DR **AssetNum** 340204Y **Maintainer** Houck, B - ETA: 19:56

**Description** 09/06/2013 17:59:03 **by** Louis Rosenblatt **Dept** Signals **IT+** Unknown

**Updated** 09/06/2013 17:59:42 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track

The AA Dispatcher reported that Iberville Drive, MP 000 729.53, DOT# 340204Y, has a semi on the track.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 26307**. LVR  
Asset: IBERVILLE DR Status Changed To: Out Of Service PCC Notification Sent 09/06/2013 17:59:42



**Updated** 09/06/2013 18:03:40 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** 09-06-2013 18:03:00 **Agency** N/a **Contact Name** N/a **Phone** N/a  
PSCC Incident Report - Edit #6279547

**Updated** 09/06/2013 18:26:11 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Bradley Houck ETA of: 19:56

**Closed** 09/06/2013 19:30:11 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 09/06/2013 19:25:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended

**The Signal Maintainer reported that there was no signal damage. All Operational Checks were performed. There were no grounds. He watched a Northbound train operate through the crossing with no exceptions taken. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: IBERVILLE DR Status Changed To: In Service PCC Notification Sent 09/06/2013 19:30:11

**Updated** 09/06/2013 19:41:15 **by** Sean Reid **Dept** PSCC **IT+**  
**Contacted On** 09-06-2013 19:40:00 **Agency** n/a **Contact Name** n/a **Phone** n/a  
PSCC Incident Report - Edit #6279547

---

**Log#** [5808676](#) **Status** Closed **Entered** 10-04-2012 02:22:45 **by** Rockhill, Jerry **Type** Vehicle on Track  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 729.5 **Block** 2763  
**Section** 3090-Ocean Springs **Asset** IBERVILLE DR **AssetNum** 340204Y **Maintainer** Houck, B - ETA: 04:10  
**Description** 10/04/2012 02:25:21 **by** Jerry Rockhill **Dept** Signals **IT+** Vehicle on Track  
0224 atl chief, aa disp, nm sub, vehicle on fire on the tracks at Iberville Drive mp 000729.5. Vehicle slid across the tracks and burst into flames. Possible track damage in the area. ....disp protecting crossing with activation failure msg 22107... Asset: IBERVILLE DR Status Changed To: Out Of Service PCC Notification Sent 10/04/2012 02:25:21

**Closed** 10/04/2012 04:36:54 **by** Jerry Rockhill **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 10/04/2012 04:36:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended Suspected Reason: Outside party or vandalism 0435 mtr reports vehicle was not at crossing...no crossing damage or signal damage...op cks ok and crossing back in service with disp... Operational Checks Performed Asset: IBERVILLE DR Status Changed To: In Service PCC Notification Sent 10/04/2012 04:36:54

**Updated** 10/04/2012 04:49:53 **by** Terry Lloyd **Dept** PSCC **IT+**  
**Contacted On** 10-04-2012 04:49:00 **Agency** N/A **Contact Name** N/A **Phone** N/A

---

**Log#** [5805270](#) **Status** Closed **Entered** 10-01-2012 20:32:58 **by** Rosenblatt, Louis **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 729.5 **Block** 2763  
**Section** 3090-Ocean Springs **Asset** IBERVILLE DR **AssetNum** 340204Y **Maintainer** Brown, K L - ETA: 22:34  
**Description** 10/01/2012 20:33:27 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported

The AA Dispatcher received a report from Q61730 Southbound that Iberville Drive, MP 000 729.53, DOT# 340204Y, has a broken East gate.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 16855**. LVR  
Asset: IBERVILLE DR Status Changed To: Out Of Service PCC Notification Sent 10/01/2012 20:33:27

**Updated** 10/01/2012 21:03:45 **by** Tanya Joson **Dept** PSCC **IT+**  
**Contacted On** 10-01-2012 21:03:00 **Agency** Biloxi Police Department **Contact Name** Jennifer **Phone** 228-392-0641  
@ Irish Hill Drive

**Closed** 10/01/2012 23:10:39 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 10/01/2012 23:10:00 Equipment Type: Gate Action Taken: Damaged gate or sections-replaced/repared Suspected

Reason: Outside party or vandalism replaced east gate and flasher kit. descent time 14sec, made op checks and ret to disp  
Operational Checks Performed Asset: IBERVILLE DR Status Changed To: In Service PCC Notification Sent 10/01/2012 23:10:39

**Updated** 10/01/2012 23:12:58      **by** Alison Obrien      **Dept** PSCC      **IT+**  
**Contacted On** 10-01-2012 23:12:00 **Agency** Biloxi Police Department **Contact Name** Eric      **Phone** 228-392-0641

Page Execution Time: 002.11 seconds



**Rodenberg Avenue**

**DOT Crossing #: 340205F**

**RR Milepost #: 729.78**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 11

Status All AssetType All RootAssetType All Department Signals AssetNum 340205F

---

**Log#** [7993699](#) **Status** Closed **Entered** 02-07-2017 15:59:21 **by** Carter, Jake **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 729.8 **Block** 2763

**Section** 3090-7M16 **Asset** RODENBERG AVE **AssetNum** 340205F **Maintainer**

**Description** 02/07/2017 15:59:21 **by** Jake Carter **Dept** Signals **IT+** Unknown

**Updated** 02/07/2017 16:07:16 **by** Jake Carter **Dept** Signals **IT+** .False or partial activation reported  
OSP reports xng is activated, w/no trains;disp is protecting as f/p Asset: RODENBERG AVE Status Changed To: Out Of Service  
PCC Notification Sent 02/07/2017 16:07:16

**Updated** 02/07/2017 16:10:34 **by** Jake Carter **Dept** Signals **IT+** .False or partial activation reported  
Mntr reports Mntrs tied up with production teams;Sig Mgr Geo James asked to esc to Him

**Updated** 02/07/2017 16:13:26 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** 02-07-2017 16:12:00 **Agency** Biloxi Police Department **Contact Name** Eric **Phone** 228-392-0641  
@ Irish Hill Dr.

**Updated** 02/07/2017 16:13:37 **by** Michele Schwartz **Dept** PSCC **IT+**  
**Contacted On** 02-07-2017 16:13:00 **Agency** Biloxi Police Department **Contact Name** . **Phone** 228-392-0641  
@ Irish Hill Dr

**Updated** 02/08/2017 06:42:03 **by** David Mates **Dept** Signals **IT+** .False or partial activation reported  
Gulfport Bus Authority crossing still activated no trains.

**Updated** 02/08/2017 08:07:03 **by** Michael Stanfill **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 02/08/2017 08:05:00 Equipment Type: Wiring/Protection Action Taken: Repaired/Replaced Protection Remove  
burnt lightning protection. Replace and test TRM Module in PMD3 unit. Operational Checks Performed Asset: RODENBERG AVE  
Status Changed To: In Service PCC Notification Sent 02/08/2017 08:07:03

**Closed** 02/08/2017 08:08:27 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 02/08/2017 08:05:00 Equipment Type: Wiring/Protection Action Taken: Repaired/Replaced Protection  
**Incident Resolved. Operational Checks Performed**

---

**Log#** [7351579](#) **Status** Closed **Entered** 10-07-2015 05:34:21 **by** Rowe, Christopher **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 729.8 **Block** 2763

**Section** 3090-7M16 **Asset** RODENBERG AVE **AssetNum** 340205F **Maintainer** Stanfill, M O - ETA: 07:13

**Description** 10/07/2015 05:34:21 **by** Christopher Rowe **Dept** Signals **IT+** Unknown

**Updated** 10/07/2015 05:38:15 **by** Christopher Rowe **Dept** Signals **IT+** .False or partial activation reported  
CROSSING ACTIVATED NO TRAINS IN THE VICINITY Notification Sent to -Signal Control Center - Atlanta at 10/07/2015  
05:38:15 Asset: RODENBERG AVE Status Changed To: Out Of Service PCC Notification Sent 10/07/2015 05:38:15

**Updated** 10/07/2015 05:43:17 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 07:13

**Updated** 10/07/2015 05:54:59 **by** Avie Saunders **Dept** PSCC **IT+**  
**Contacted On** **Agency** BILOXI PD **Contact Name** DISPATCHER **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 10/07/2015 07:15:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 10/07/2015 08:48:07 by Bruce McVey Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 10/07/2015 08:44:00 Equipment Type: N/A Action Taken: NTF - UTD

**Employee:** M. Stanfill

- Crossing was clear when MTR arrived, could not duplicate the trouble. Crossing is working as intended.

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: RODENBERG AVE Status Changed To: In Service PCC Notification Sent 10/07/2015 08:48:07

**Updated** 10/07/2015 08:50:28 by Byron Tinsley Dept PSCC IT+  
**Contacted On** Agency BILOXI PD Contact Name DISPATCHER Phone 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

---

**Log#** [7158403](#) **Status** Closed **Entered** 05-26-2015 11:27:21 by Miller, Vern **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 729.8 **Block** 2763

**Section** 3090-7M16 **Asset** RODENBERG AVE **AssetNum** 340205F **Maintainer** Stanfill, M O - ETA: 13:09

**Description** 05/26/2015 11:27:21 by Verlon Miller Dept Signals IT+ Unknown

**Updated** 05/26/2015 11:28:40 by Verlon Miller Dept Signals IT+ .False or partial activation reported  
crossing activated, no train around. dispatcher was already protecting with false/partial activation protection. vern Asset:  
RODENBERG AVE Status Changed To: Out Of Service PCC Notification Sent 05/26/2015 11:28:40

**Updated** 05/26/2015 11:28:50 by Verlon Miller Dept Signals IT+ .False or partial activation reported  
. Notification Sent to -Signal Control Center - Atlanta at 05/26/2015 11:28:50

**Updated** 05/26/2015 11:30:03 by Bruce McVey Dept Signals IT+ .False or partial activation reported  
mtr getting parts for xing... storms in area

**Updated** 05/26/2015 11:30:10 by Bruce McVey Dept Signals IT+ .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 13:09

**Updated** 05/26/2015 11:42:32 by Terry Lloyd Dept PSCC IT+  
**Contacted On** 05-26-2015 11:38:00 Agency Biloxi Police Department Contact Name 347 Phone 228-392-0641  
@ Irish Hill Drive

**Updated** 05/26/2015 13:10:00 by TCIS AUTOMATION Dept Signals IT+ .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 05/26/2015 15:09:24 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported

**Update** - The Maintainer is en route back to the crossing. LVR

**Closed** 05/26/2015 18:46:55 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 05/26/2015 18:46:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced/Reset CPU

**The Signal Maintainer replaced the PMD-3 Cabinet. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: RODENBERG AVE Status Changed To: In Service PCC Notification Sent 05/26/2015 18:46:55

**Updated** 05/26/2015 18:49:47 by Emily Morton Dept PSCC IT+  
**Contacted On** 05-26-2015 18:49:00 Agency Biloxi Police Department Contact Name 2901 Phone 228-392-0641

---

**Log#** [7000731](#) **Status** Closed **Entered** 02-10-2015 17:53:38 by Tyo, Mark **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 729.8 **Block** 2763

**Section** 3090-7M16 **Asset** RODENBERG AVE **AssetNum** 340205F **Maintainer** Mannion, R - ETA: 21:10  
**Description** 02/10/2015 17:53:38 **by** Mark Tyo **Dept** Signals **IT+** Unknown

**Updated** 02/10/2015 17:59:36 **by** Mark Tyo **Dept** Signals **IT+** .False or partial activation reported  
 Reported gates did not come down for train movement, Lights were working. Disp is protecting. Train Q-57210 had no exception with crossing. Notification Sent to -Signal Control Center - Atlanta at 02/10/2015 17:59:36 Asset: RODENBERG AVE Status Changed To: Out Of Service PCC Notification Sent 02/10/2015 17:59:36

**Updated** 02/10/2015 18:06:58 **by** Myrtie Hackney **Dept** PSCC **IT+**  
**Contacted On** 02-10-2015 18:06:00 **Agency** Biloxi Police Department **Contact Name** Kayla **Phone** 228-392-0641  
 @ Irish Hill Dr

**Updated** 02/10/2015 18:40:32 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
 Status changed to Dispatched for Roger Mannion ETA of: 21:10

**Updated** 02/10/2015 21:00:00 **by** Roger Mannion **Dept** Signals **IT+** .False or partial activation reported  
 Incident Resolved: 02/10/2015 20:59:00 Equipment Type: N/A Action Taken: NTF - UTD Crossing does not have gates. Checked crossing and watched NB train go through crossing before giving it back to dispatcher @ 2059 wcj. Operational Checks Performed Asset: RODENBERG AVE Status Changed To: In Service PCC Notification Sent 02/10/2015 21:00:00

**Updated** 02/10/2015 21:01:48 **by** Avie Saunders **Dept** PSCC **IT+**  
**Contacted On** 02-10-2015 21:01:00 **Agency** Biloxi Police Department **Contact Name** Kayla **Phone** 228-392-0641

**Closed** 02/10/2015 21:13:48 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
 Incident Resolved: 02/10/2015 21:13:00 Equipment Type: N/A Action Taken: NTF - UTD Resolved to close. Operational Checks Performed

---

**Log#** [6440699](#) **Status** Closed **Entered** 01-12-2014 09:30:39 **by** Gaspar, Sean **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 729.8 **Block** 2763

**Section** 3090-Ocean Springs **Asset** RODENBERG AVE **AssetNum** 340205F **Maintainer** Houck, B - ETA: 11:08  
**Description** 01/12/2014 09:30:39 **by** Sean Gaspar **Dept** Signals **IT+** Unknown

**Updated** 01/12/2014 09:31:37 **by** Sean Gaspar **Dept** Signals **IT+** .False or partial activation reported  
 xings at jody and Rosenberg are activated w/ no train. dots provided.

**Updated** 01/12/2014 09:33:02 **by** Sean Gaspar **Dept** Signals **IT+** .False or partial activation reported  
 New Asset Added: 340206M - MCDONNEL AVE

**Updated** 01/12/2014 09:37:45 **by** Sean Gaspar **Dept** Signals **IT+** .False or partial activation reported  
 correction on xing names as mcdonnel and rosenburg, dots provided. disp protecting w/ f/ps. Notification Sent to -Signal Control Center - Atlanta at 01/12/2014 09:37:45 Asset: RODENBERG AVE Status Changed To: Out Of Service PCC Notification Sent 01/12/2014 09:37:45 Asset: MCDONNEL AVE Status Changed To: Out Of Service PCC Notification Sent 01/12/2014 09:37:45

**Updated** 01/12/2014 09:44:04 **by** Christina Martorano **Dept** PSCC **IT+**  
**Contacted On** 01-12-2014 09:43:00 **Agency** local police **Contact Name** jody **Phone** 228-392-0641  
 Reporting party has been verified as the responsible law enforcement agency.

**Updated** 01/12/2014 10:08:56 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
 Status changed to Dispatched for Bradley Houck ETA of: 11:08

**Updated** 01/12/2014 11:10:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
 ETA time reached Status changed to Active

**Closed** 01/12/2014 11:48:06 **by** William OConnell **Dept** Signals **IT+** .False or partial activation reported  
 Incident Resolved: 01/12/2014 11:47:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced Track Card maintainer (MDSA board took a lightning hit, lightning protection bypassed) (Rodenburg)...Maintainer found a TRM card changed at the other crossing...Both crossings tested, checked and BIS... Operational Checks Performed Asset: RODENBERG AVE Status Changed To: In Service PCC Notification Sent 01/12/2014 11:48:06 Asset: MCDONNEL AVE

Status Changed To: In Service PCC Notification Sent 01/12/2014 11:48:06

Updated 01/12/2014 11:58:13 by Christina Martorano Dept PSCC IT+  
Contacted On 01-12-2014 11:57:00 Agency BILOXI PD Contact Name 347 Phone 228-392-0641

---

Log# [6388649](#) Status Closed Entered 12-03-2013 14:06:58 by Lewis, Wendell Type .Other Failure  
Supv Merritt, D Reg SO Div AT Sub NM IRI 0 Milepost 000 729.8 Block 2763  
Section 3090-Ocean Springs Asset RODENBERG AVE AssetNum 340205F Maintainer Stanfill, M O - ETA: 15:39  
Description 12/03/2013 14:06:58 by Wendell Lewis Dept Signals IT+ Unknown  
Updated 12/03/2013 14:15:06 by Wendell Lewis Dept Signals IT+ .Other Failure  
14:00 PD REPORTS X-ING EQUIP. HAS BEEN STRUCK BY A VEHICLE IT DOESN'T APPEAR TO BE  
DAMAGED BUT SHOULD BE CHECKED.....AA-DISP. (DRG) NOTIFIED TO PROTECT WITH A/F MSG.  
Notification Sent to -Signal Control Center - Atlanta at 12/03/2013 14:15:06 Asset: RODENBERG AVE Status  
Changed To: Out Of Service PCC Notification Sent 12/03/2013 14:15:06

Updated 12/03/2013 14:22:08 by Alexis Romine Dept PSCC IT+  
Contacted On 12-03-2013 14:21:00 Agency Biloxi Police Department Contact Name Sarah Phone 228-392-0641  
@ Irish Hill Drive

Updated 12/03/2013 14:24:25 by Bruce McVey Dept Signals IT+ .Other Failure  
Status changed to Dispatched for Michael Stanfill ETA of: 15:39

Updated 12/03/2013 15:40:00 by TCIS AUTOMATION Dept Signals IT+ .Other Failure  
ETA time reached Status changed to Active

Closed 12/03/2013 16:13:58 by Louis Rosenblatt Dept Signals IT+ .Other Failure  
Incident Resolved: 12/03/2013 16:12:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as  
intended

The Signal Maintainer reported that there was no signal damage. Operational Checks were performed. The  
Crossing was placed Back In Service with the Dispatcher. LVR

Operational Checks Performed Asset: RODENBERG AVE Status Changed To: In Service PCC Notification Sent  
12/03/2013 16:13:58

Updated 12/03/2013 16:41:29 by Robert Clendening Dept PSCC IT+  
Contacted On 12-03-2013 16:40:00 Agency Biloxi Police Department Contact Name 3289 Phone 228-392-0641  
@ Irish Hill Drive

---

Log# [6249307](#) Status Closed Entered 08-13-2013 19:09:33 by Tyo, Mark Type -Activation failure reported  
Supv Merritt, D Reg SO Div AT Sub NM IRI 0 Milepost 000 729.8 Block 2763  
Section 3090-Ocean Springs Asset RODENBERG AVE AssetNum 340205F Maintainer Stanfill, M O - ETA: 20:59  
Description 08/13/2013 19:09:33 by Mark Tyo Dept Signals IT+ Unknown  
Updated 08/13/2013 19:22:08 by Mark Tyo Dept Signals IT+ -Activation failure reported  
Police recieved a call from OSP that the gates did not come down at all. Unsure if lights worked. Tried to reach OSP  
[REDACTED] and got answering machine. Disp is protecting with a Act/Fail mess. NOC Manager Skidmore, Signal  
Supervisor James and DTO all notified. Notification Sent to -Signal Control Center - Atlanta at 08/13/2013 19:22:08  
Asset: RODENBERG AVE Status Changed To: Out Of Service PCC Notification Sent 08/13/2013 19:22:08

Updated 08/13/2013 19:22:10 by Mark Tyo Dept Signals IT+ -Activation failure reported  
Notification has been sent to the following: George James Jr Danny McKenzie Jody Cox C Manager

Updated 08/13/2013 19:29:23 by Louis Rosenblatt Dept Signals IT+ -Activation failure reported  
Status changed to Dispatched for Michael Stanfill ETA of: 20:59

**Updated** 08/13/2013 19:38:43 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi PD **Contact Name** Jennifer **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 08/13/2013 21:00:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** -Activation failure reported  
ETA time reached Status changed to Active

**Updated** 08/13/2013 21:27:40 **by** Louis Rosenblatt **Dept** Signals **IT+** -Activation failure reported

**Update** - The Signal Maintainer contacted the reporting party. The reporting party told the Signal Maintainer that the incident occurred at 8:30 AM local time. She stated that the gates did not come down and she was not sure if the lights were flashing. The Signal Maintainer informed the reporting party that there are no gates at the crossing. The Signal Maintainer is in the process of performing an Annual Test at the Crossing. LVR

**Updated** 08/13/2013 23:31:02 **by** Matthew Kite **Dept** Signals **IT+** -Activation failure reported

Mntr verifying crossing operation.

**Closed** 08/14/2013 00:39:07 **by** Matthew Kite **Dept** Signals **IT+** -Activation failure reported  
Incident Resolved: 08/14/2013 00:37:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended  
Mntr reports crossing COA. Created an A/F report, performed a 360 day crossing test. Phase:68 RX:100. Mntr took no exception to crossing operation. Turned crossing backover to disp.  
Operational Checks Performed Asset: RODENBERG AVE Status Changed To: In Service PCC Notification Sent 08/14/2013 00:39:07

**Updated** 08/14/2013 00:47:58 **by** Christopher Horman **Dept** PSCC **IT+**  
**Contacted On** 08-14-2013 00:47:00 **Agency** Biloxi PD **Contact Name** Disp. 392 **Phone** 228-392-0641

---

**Log#** [5889675](#) **Status** Closed **Entered** 12-05-2012 10:10:44 **by** Jackson Jr, Marvin **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 729.8 **Block** 2763

**Section** 3090-Ocean Springs **Asset** RODENBERG AVE **AssetNum** 340205F **Maintainer** Houck, B - ETA: 11:04

**Description** 12/05/2012 10:12:08 **by** Marv Jackson Jr **Dept** Signals **IT+** .False or partial activation reported  
OSP REPORTED FALSE ACTIVATION AT RODENBERG AVE. Notification Sent to -Signal Control Center - Atlanta at 12/05/2012 10:12:08 Asset: RODENBERG AVE Status Changed To: Out Of Service PCC Notification Sent 12/05/2012 10:12:08

**Updated** 12/05/2012 10:15:09 **by** Clifford Keen **Dept** PSCC **IT+**  
**Contacted On** 12-05-2012 10:14:00 **Agency** BILOXI PD **Contact Name** DISP 308 **Phone** 228-392-0641

**Closed** 12/05/2012 17:02:29 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 12/05/2012 16:58:00 Equipment Type: Track Action Taken: Termination shunt-repaired/replaced  
Suspected Reason: Equipment failure  
Mntr replaced every trk conn on starts. Replaced NB start. Performed op checks, turned crossing backover to disp.  
Operational Checks Performed Asset: RODENBERG AVE Status Changed To: In Service PCC Notification Sent 12/05/2012 17:02:29

**Updated** 12/05/2012 17:12:01 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** 12-05-2012 17:11:00 **Agency** BILOXI PD **Contact Name** Sara **Phone** 228-392-0641

---

**Log#** [5847029](#) **Status** Closed **Entered** 11-01-2012 13:07:46 **by** Miller, Vern **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 729.8 **Block** 2763

**Section** 3090-Ocean Springs **Asset** RODENBERG AVE **AssetNum** 340205F **Maintainer** Stanfill, M O - ETA: 13:19

**Description** 11/01/2012 13:09:27 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
crossing activated, no train around. dispatcher notified to protect with false/partial activation protection. vern Asset: RODENBERG AVE Status Changed To: Out Of Service PCC Notification Sent 11/01/2012 13:09:27

**Updated** 11/01/2012 13:09:38 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported



. Notification Sent to -Signal Control Center - Atlanta at 11/01/2012 13:09:38

**Updated** 11/01/2012 13:12:14      **by** Myrtie Hackney      **Dept** PSCC      **IT+**  
**Contacted On**      **Agency** p.d.      **Contact Name** opr.#366 **Phone** 228 392 0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 11/01/2012 13:16:22      **by** Jason Gothard      **Dept** Signals      **IT+** .False or partial activation reported  
mntr reports watching a NB train and took no exception. will make further op checks.

**Closed** 11/01/2012 13:35:00      **by** Jason Gothard      **Dept** Signals      **IT+** .False or partial activation reported  
Incident Resolved: 11/01/2012 13:34:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended  
Suspected Reason: Outside party or vandalism mntr reports xing working as intended. ret to disp. Operational Checks  
Performed Asset: RODENBERG AVE Status Changed To: In Service PCC Notification Sent 11/01/2012 13:35:00

**Updated** 11/01/2012 13:36:50      **by** Deborah Anderson      **Dept** PSCC      **IT+**  
**Contacted On** 11-01-2012 13:36:00 **Agency** p.d.      **Contact Name** 317      **Phone** 228 392 0641

---

**Log#** [5682455](#)      **Status** Closed      **Entered** 07-07-2012 06:50:52      **by** Rockhill, Jerry      **Type** Vehicle on Track  
**Supv** Merritt, D      **Reg** SO      **Div** AT      **Sub** NM      **IRI**      **Milepost** 000 729.8      **Block** 2763  
**Section** 3090-Ocean Springs      **Asset** RODENBERG AVE      **AssetNum** 340205F      **Maintainer** Broadway, J L - ETA: 08:43  
**Description** 07/07/2012 06:55:23      **by** Jerry Rockhill      **Dept** Signals      **IT+** Vehicle on Track  
0654 ATL ACD, AA Disp, NM Sub, Loc 2763; PSCC reports vehicle stuck on tracks at mp 000729.78,  
Rodenburg Avenue. Need track and crossings inspected. disp protecting crossing with activation failure msg  
46679 Asset: RODENBERG AVE Status Changed To: Out Of Service PCC Notification Sent 07/07/2012  
06:55:23

**Updated** 07/07/2012 07:06:09      **by** Virgil Adkins      **Dept** PSCC      **IT+**  
**Contacted On** 07-07-2012 07:05:00      **Agency** na      **Contact Name** na      **Phone** na  
PSCC incident # 5682440.

**Closed** 07/07/2012 09:48:58      **by** Bruce McVey      **Dept** Signals      **IT+** Vehicle on Track  
Incident Resolved: 07/07/2012 09:47:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as  
intended Suspected Reason: Outside party or vandalism

**Employee:** J. Broadway

- Vehicle removed, No signal damage.

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: RODENBERG AVE Status Changed To: In Service PCC Notification Sent  
07/07/2012 09:48:58

**Updated** 07/07/2012 09:49:58      **by** Virgil Adkins      **Dept** PSCC      **IT+**  
**Contacted On** 07-07-2012 09:49:00      **Agency** na      **Contact Name** na      **Phone** na

---

**Log#** [5575323](#)      **Status** Closed      **Entered** 04-25-2012 01:52:52      **by** Williams, Joseph      **Type** .False or partial activation reported  
**Supv** Merritt, D      **Reg** SO      **Div** AT      **Sub** NM      **IRI**      **Milepost** 000 729.8      **Block** 2763  
**Section** 3090-Ocean Springs      **Asset** RODENBERG AVE      **AssetNum** 340205F      **Maintainer** Wilson, C E - ETA: 04:22  
**Description** 04/25/2012 01:55:27      **by** Joseph Williams      **Dept** Signals      **IT+** .False or partial activation reported  
0153:Hr Biloxi Police reported that the lights are intermittently activation with no train in sight. 0154:Hr dispatcher notified.  
Notification Sent to -Signal Control Center - Atlanta at 04/25/2012 01:55:27 Asset: RODENBERG AVE Status Changed To: Out  
Of Service PCC Notification Sent 04/25/2012 01:55:27

**Updated** 04/25/2012 01:58:27      **by** Christopher Horman      **Dept** PSCC      **IT+**  
**Contacted On**      **Agency** Biloxi Police      **Contact Name** Freida      **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.



**Closed** 04/25/2012 04:22:04      **by** Matthew Kite      **Dept** Signals      **IT+** .False or partial activation reported  
Incident Resolved: 04/25/2012 04:18:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended Suspected Reason: N/A  
Mntr reports COA. Performed ops check, watched train through. No exceptions noted. Mntr waited at crossing for nearly an hr and never saw intermittent failure of any kind.  
Operational Checks Performed Asset: RODENBERG AVE Status Changed To: In Service PCC Notification Sent 04/25/2012 04:22:04

**Updated** 04/25/2012 04:34:13      **by** Christopher Horman **Dept** PSCC      **IT+**  
**Contacted On** 04-25-2012 04:34:00 **Agency** Biloxi Police      **Contact Name** Disp. Moffit **Phone** 228-392-0641

Page Execution Time: 001.97 seconds

**McDonnell Avenue**

**DOT Crossing #: 340206M**

**RR Milepost #: 730.19**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 14

Status All AssetType All RootAssetType All Department Signals AssetNum 340206M

---

**Log#** [7953108](#) **Status** Closed **Entered** 01-07-2017 22:57:41 **by** Todd, Lee **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.5 **Milepost** 000 730.2 **Block** 2763  
**Section** 3090-7M16 **Asset** MCDONNEL AVE **AssetNum** 340206M **Maintainer** Mannion, R - ETA: 07:04 & James Jr, G H - ETA: 00:18  
**Description** 01/07/2017 22:57:41 **by** Lee Todd **Dept** Signals **IT+** Unknown  
**Updated** 01/07/2017 23:01:17 **by** Lee Todd **Dept** Signals **IT+** .False or partial activation reported  
Local PD reports crossing activated with no train in sight. DOT provided. Dispatcher protecting with false partial #38340 Asset: MCDONNEL AVE Status Changed To: Out Of Service PCC Notification Sent 01/07/2017 23:01:17  
**Updated** 01/07/2017 23:01:19 **by** Lee Todd **Dept** Signals **IT+** .False or partial activation reported  
An email notification for (IRI) asset MCDONNEL AVE (3) has been sent to the following:  
George James Jr  
Danny McKenzie  
**Updated** 01/07/2017 23:10:06 **by** Emily Morton **Dept** PSCC **IT+**  
**Contacted On** **Agency** Local PD **Contact Name** April **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.  
**Updated** 01/08/2017 00:17:23 **by** Terry Johnstone **Dept** Signals **IT+** .False or partial activation reported  
call list exhausted...  
**Updated** 01/08/2017 00:18:49 **by** Terry Johnstone **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Escalated, George James Jr ETA of: N/A  
**Updated** 01/08/2017 04:23:55 **by** Charles Sydney **Dept** Signals **IT+** .False or partial activation reported  
MNTR reports: Found bad 114 hertz shunt. MNTR looking for a replacement shunt  
**Updated** 01/08/2017 04:25:26 **by** Charles Sydney **Dept** Signals **IT+** .False or partial activation reported  
\*\*Correction - Signal Supervisor called in and reported: Found bad 114 hertz shunt. Looking for a replacement shunt  
**Updated** 01/08/2017 06:19:53 **by** Terry Johnstone **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Roger Mannion ETA of: 07:04  
**Updated** 01/08/2017 06:20:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active  
**Closed** 01/08/2017 08:31:57 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 01/08/2017 08:29:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced Termination Shunt

**Employee:** Sig Mgr James

- South bound termination shunt bad, replaced with new ( HZ) shunt.

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: MCDONNEL AVE Status Changed To: In Service PCC Notification Sent 01/08/2017 08:31:57

**Updated** 01/08/2017 08:32:55 **by** Avie Saunders **Dept** PSCC **IT+**  
**Contacted On** 01-08-2017 08:32:00 **Agency** Biloxi Police Department **Contact Name** Rich **Phone** 228-392-0641

---

**Log#** [7952545](#) **Status** Closed **Entered** 01-07-2017 09:53:30 **by** Mcewen, Yolanda **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.25 **Milepost** 000 730.2 **Block** 2763  
**Section** 3090-7M16 **Asset** MCDONNEL AVE **AssetNum** 340206M **Maintainer** Stanfill, M O - ETA: 11:00  
**Description** 01/07/2017 09:53:30 **by** Yolanda Mcewen **Dept** Signals **IT+** Unknown

**Updated** 01/07/2017 09:57:14 **by** Yolanda Mcewen **Dept** Signals **IT+** .False or partial activation reported  
BILOXI PD RPTS GATES DOWN BO TRAIN AA DISP PROTECTING WITH F/P MESG Asset: MCDONNEL AVE Status Changed  
To: Out Of Service PCC Notification Sent 01/07/2017 09:57:14

**Updated** 01/07/2017 09:57:15 **by** Yolanda Mcewen **Dept** Signals **IT+** .False or partial activation reported  
An email notification for (IRI) asset MCDONNEL AVE (2) has been sent to the following:  
George James Jr

**Updated** 01/07/2017 10:00:05 **by** Yolanda Mcewen **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 11:00

**Updated** 01/07/2017 10:28:43 **by** Thera Moore **Dept** PSCC **IT+**  
**Contacted On** 01-07-2017 10:28:00 **Agency** Biloxi Police Department **Contact Name** ANGIE **Phone** 228-392-0641

**Updated** 01/07/2017 11:05:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 01/07/2017 12:39:04 **by** Michael Stanfill **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 01/07/2017 12:38:00 Equipment Type: N/A Action Taken: NTF - UTD Clear on arrival. No problem found.  
Operational Checks Performed Asset: MCDONNEL AVE Status Changed To: In Service PCC Notification Sent 01/07/2017 12:39:04

**Closed** 01/07/2017 12:40:13 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 01/07/2017 12:38:00 Equipment Type: N/A Action Taken: NTF - UTD  
**Incident Resolved. Operational Checks Performed**

**Updated** 01/07/2017 12:46:18 **by** Thera Moore **Dept** PSCC **IT+**  
**Contacted On** 01-07-2017 12:46:00 **Agency** BILOXI PD **Contact Name** brenda **Phone** [REDACTED]

---

**Log#** [7929834](#) **Status** Closed **Entered** 12-19-2016 10:59:51 **by** Williams, Joseph **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 730.2 **Block** 2763

**Section** 3090-7M16 **Asset** MCDONNEL AVE **AssetNum** 340206M **Maintainer** Stanfill, M O - ETA: 17:30

**Description** 12/19/2016 10:59:51 **by** Joseph Williams **Dept** Signals **IT+** Unknown

**Updated** 12/19/2016 11:02:39 **by** Joseph Williams **Dept** Signals **IT+** .False or partial activation reported  
1100:Hr outside party reported that the crossing is activated with no trains in sight. There was no DOT number given. 1101:Hr  
dispatcher DC notified. Asset: MCDONNEL AVE Status Changed To: Out Of Service PCC Notification Sent 12/19/2016 11:02:39

**Updated** 12/19/2016 11:02:40 **by** Joseph Williams **Dept** Signals **IT+** .False or partial activation reported  
An email notification for (IRI) asset MCDONNEL AVE (1) has been sent to the following:  
George James Jr

**Updated** 12/19/2016 11:08:12 **by** Avie Saunders **Dept** PSCC **IT+**  
**Contacted On** 12-19-2016 11:07:00 **Agency** Biloxi Police Department **Contact Name** 1501 **Phone** 228-392-0641  
Railroad St

**Updated** 12/19/2016 11:11:44 **by** Joseph Williams **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Kyle Smith ETA of: 15:11

**Updated** 12/19/2016 15:15:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 12/19/2016 17:18:36 **by** John Williams **Dept** Signals **IT+** .False or partial activation reported  
Maintainer still investigating

**Closed** 12/19/2016 17:31:01 **by** Brad Oglesby **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 12/19/2016 17:30:00 Equipment Type: N/A Action Taken: NTF - UTD THE MAINTAINER DIDN'T FIND ANY  
TROUBLE WITH THE CROSSING, PERFORMED OPERATIONAL CHECKS, AND REMOVED PROTECTION FROM THE  
CROSSING WITH THE DISPATCHER. THE MAINTAINER SUSPECTS THIS INCIDENT WAS CAUSED BY A TAMPER  
WORKING IN THE AREA AT THE TIME OF THIS REPORT. Operational Checks Performed Asset: MCDONNEL AVE Status  
Changed To: In Service PCC Notification Sent 12/19/2016 17:31:01

---

**Log#** [7918478](#) **Status** Closed **Entered** 12-11-2016 07:36:55 **by** Foster, George **Type** .False or partial activation reported

Supv Merritt, D Reg SO Div AT Sub NM IRI 0 Milepost 000 730.2 Block 2763

Section 3090-7M16 Asset MCDONNEL AVE AssetNum 340206M Maintainer Stanfill, M O - ETA: 09:51

Description 12/11/2016 07:36:55 by George Foster Dept Signals IT+ Unknown

Updated 12/11/2016 07:47:40 by George Foster Dept Signals IT+ .False or partial activation reported  
Crossing activated with no trains. Asset: MCDONNEL AVE Status Changed To: Out Of Service PCC Notification Sent 12/11/2016 07:47:40

Updated 12/11/2016 07:55:28 by Terry Lloyd Dept PSCC IT+  
Contacted On Agency 911 Contact Name Brenda Phone 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

Updated 12/11/2016 08:12:46 by Bruce McVey Dept Signals IT+ .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 09:51

Updated 12/11/2016 09:55:00 by TCIS AUTOMATION Dept Signals IT+ .False or partial activation reported  
ETA time reached Status changed to Active

Updated 12/11/2016 11:23:40 by Bruce McVey Dept Signals IT+ .False or partial activation reported  
north bound signal line thru block

Updated 12/11/2016 11:49:42 by Bruce McVey Dept Signals IT+ .False or partial activation reported

Mtr/employee is on-site w/EC-1.

Updated 12/11/2016 12:19:20 by Michael Stanfill Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 12/11/2016 12:18:00 Equipment Type: N/A Action Taken: NTF - UTD Clear on arrival. Found multiple c600 error codes. Hirail circuit looking at all track connections and for broken bonds. None found. Clear error codes and return to dispatcher. Operational Checks Performed Asset: MCDONNEL AVE Status Changed To: In Service PCC Notification Sent 12/11/2016 12:19:20

Closed 12/11/2016 12:20:36 by Bruce McVey Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 12/11/2016 12:18:00 Equipment Type: N/A Action Taken: NTF - UTD  
Incident Resolved. Operational Checks Performed

Updated 12/11/2016 12:31:30 by Avie Saunders Dept PSCC IT+  
Contacted On 12-11-2016 12:31:00 Agency Biloxi Police Department Contact Name Rich Phone 228-392-0641

---

Log# [7703940](#) Status Closed Entered 07-04-2016 17:58:59 by Kondy, Rick Type .False or partial activation reported

Supv Merritt, D Reg SO Div AT Sub NM IRI 0.125 Milepost 000 730.2 Block 2763

Section 3090-7M16 Asset MCDONNEL AVE AssetNum 340206M Maintainer Stanfill, M O - ETA: 21:32

Description 07/04/2016 17:58:59 by Richard Kondy Dept Signals IT+ Unknown

Updated 07/04/2016 18:01:30 by Richard Kondy Dept Signals IT+ .False or partial activation reported  
gates up and down , no trains . disp protecting crossing with false activation # 10213 . Notification Sent to -Signal Control Center - Atlanta at 07/04/2016 18:01:30 Asset: MCDONNEL AVE Status Changed To: Out Of Service PCC Notification Sent 07/04/2016 18:01:30

Updated 07/04/2016 18:01:32 by Richard Kondy Dept Signals IT+ .False or partial activation reported  
An email notification for (IRI) asset MCDONNEL AVE (1) has been sent to the following:  
George James Jr

Updated 07/04/2016 18:19:21 by Alexis Romine Dept PSCC IT+  
Contacted On 07-04-2016 18:19:00 Agency Biloxi Police Department Contact Name 366 Phone 228-392-0641  
Irish Hill Drive

Updated 07/04/2016 19:32:13 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 21:32

Updated 07/04/2016 21:35:00 by TCIS AUTOMATION Dept Signals IT+ .False or partial activation reported  
ETA time reached Status changed to Active

Closed 07/04/2016 23:09:11 by Matthew Kite Dept Signals IT+ .False or partial activation reported

Incident Resolved: 07/04/2016 23:08:00 Equipment Type: N/A Action Taken: NTF - UTD  
Mntr reports crossing COA. Performed op checks, unable to duplicate, no exceptions noted to equip. Turned crossing back over to disp.  
Operational Checks Performed Asset: MCDONNEL AVE Status Changed To: In Service PCC Notification Sent 07/04/2016 23:09:11

**Updated** 07/04/2016 23:11:06 **by** Jolene Woods **Dept** PSCC **IT+**  
**Contacted On** 07-04-2016 23:10:00 **Agency** Biloxi Police Department **Contact Name** Brenda **Phone** 228-392-0641

---

**Log#** [7699990](#) **Status** Closed **Entered** 06-30-2016 20:32:06 **by** Gaspar, Sean **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.2 **Block** 2763

**Section** 3090-7M16 **Asset** MCDONNEL AVE **AssetNum** 340206M **Maintainer** Mannion, R - *ETA*: 22:35

**Description** 06/30/2016 20:32:06 **by** Sean Gaspar **Dept** Signals **IT+** Unknown

**Updated** 06/30/2016 20:34:34 **by** Sean Gaspar **Dept** Signals **IT+** .False or partial activation reported  
xing is intermittently activating w/ no train. dot provided. disp protecting w/ f/p. Notification Sent to -Signal Control Center -  
Atlanta at 06/30/2016 20:34:34 Asset: MCDONNEL AVE Status Changed To: Out Of Service PCC Notification Sent  
06/30/2016 20:34:34

**Updated** 06/30/2016 20:37:49 **by** Jackie McGuirt **Dept** PSCC **IT+**  
**Contacted On** **Agency** local police **Contact Name** newsome **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 06/30/2016 21:05:43 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Roger Mannion ETA of: 22:35

**Updated** 06/30/2016 22:40:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 07/01/2016 00:22:50 **by** Roger Mannion **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 07/01/2016 00:22:00 Equipment Type: N/A Action Taken: NTF - UTD Monitored crossing for over an hour  
in which time it never activated. Performed numerous checks and found no exceptions. No lightening protection burnt up, no  
errors in unit (PMD3), and no other problems noted. Watched two SB trains through crossing with no exceptions. Power  
AC/DC good. Back to dispatcher at 46864 0020 wj. Operational Checks Performed Asset: MCDONNEL AVE Status Changed  
To: In Service PCC Notification Sent 07/01/2016 00:22:50

**Closed** 07/01/2016 00:25:24 **by** David Mates **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 07/01/2016 00:22:00 Equipment Type: N/A Action Taken: NTF - UTD Monitored crossing for over an hour  
in which time it never activated. Performed numerous checks and found no exceptions. No lightening protection burnt up, no  
errors in unit (PMD3), and no other problems noted. Watched two SB trains through crossing with no exceptions. Power  
AC/DC good. Back to dispatcher at 46864 0020 wj. Operational Checks Performed

**Updated** 07/01/2016 00:29:57 **by** Myrtie Hackney **Dept** PSCC **IT+**  
**Contacted On** 07-01-2016 00:29:00 **Agency** local police **Contact Name** April **Phone** 228-392-0641

---

**Log#** [7414158](#) **Status** Closed **Entered** 11-23-2015 07:58:13 **by** Jackson Jr, Marv **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.2 **Block** 2763

**Section** 3090-7M16 **Asset** MCDONNEL AVE **AssetNum** 340206M **Maintainer** Stanfill, M O - *ETA*: 10:23

**Description** 11/23/2015 07:58:13 **by** Marv Jackson Jr **Dept** Signals **IT+** Unknown

**Updated** 11/23/2015 07:59:29 **by** Marv Jackson Jr **Dept** Signals **IT+** .False or partial activation reported  
OSP REPORTED FALSE ACTIVATION AT MCDONNEL AVE. Notification Sent to -Signal Control Center - Atlanta at 11/23/2015  
07:59:29 Asset: MCDONNEL AVE Status Changed To: Out Of Service PCC Notification Sent 11/23/2015 07:59:29

**Updated** 11/23/2015 08:07:40 **by** Avie Saunders **Dept** PSCC **IT+**  
**Contacted On** 11-23-2015 08:05:00 **Agency** Biloxi Police Department **Contact Name** Sara **Phone** 228-392-0641  
Irish Hill Dr

**Updated** 11/23/2015 08:23:03 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 10:23

**Updated** 11/23/2015 10:25:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported

ETA time reached Status changed to Active

**Closed** 11/23/2015 14:43:12 by Bruce McVey Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 11/23/2015 14:42:00 Equipment Type: N/A Action Taken: NTF - UTD

**Employee:** Sig Mgr James

- Crossing was clear when arrived, could not duplicate the trouble. Crossing is working as intended.

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: MCDONNEL AVE Status Changed To: In Service PCC Notification Sent 11/23/2015 14:43:12

**Updated** 11/23/2015 14:51:30 by Waltina Edwards Dept PSCC IT+  
**Contacted On** 11-23-2015 14:51:00 Agency Police Department Contact Name 3947 Phone Phone# 228-392-0641

---

**Log#** [7237301](#) Status **Closed** Entered 07-17-2015 14:32:19 by Jackson Jr, Marv Type .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.2 **Block** 2763

**Section** 3090-7M16 **Asset** MCDONNEL AVE **AssetNum** 340206M **Maintainer** Stanfill, M O - ETA: 16:08

**Description** 07/17/2015 14:32:19 by Marv Jackson Jr Dept Signals IT+ Unknown

**Updated** 07/17/2015 14:34:08 by Marv Jackson Jr Dept Signals IT+ .False or partial activation reported  
OSP REPORTED FALSE ACTIVATION AT MCDONNELL AVE.... Notification Sent to -Signal Control Center - Atlanta at 07/17/2015 14:34:08 Asset: MCDONNEL AVE Status Changed To: Out Of Service PCC Notification Sent 07/17/2015 14:34:08

**Updated** 07/17/2015 14:38:32 by Matthew Kite Dept Signals IT+ .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 16:08

**Updated** 07/17/2015 14:49:23 by Jodi Snyder Dept PSCC IT+  
**Contacted On** 07-17-2015 14:47:00 Agency Biloxi Police Department Contact Name Brenda Phone 228-392-0641  
Irish Hill Dr

**Updated** 07/17/2015 16:10:00 by TCIS AUTOMATION Dept Signals IT+ .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 07/17/2015 19:27:23 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported

**Update** - The ESS left a message requesting an update on the Signal Maintainer's cell phone. LVR

**Closed** 07/17/2015 19:31:07 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 07/17/2015 19:29:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced Termination Shunt

**The Signal Maintainer repaired a bad connection on the Southbound Termination Shunt. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: MCDONNEL AVE Status Changed To: In Service PCC Notification Sent 07/17/2015 19:31:07

**Updated** 07/17/2015 19:44:02 by Kiwana Tompkins Dept PSCC IT+  
**Contacted On** 07-17-2015 19:43:00 Agency Biloxi Police Department Contact Name Jamie Phone 228-392-0641

---

**Log#** [6209916](#) Status **Closed** Entered 07-14-2013 20:09:26 by Belkot, Paul Type .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 730.2 **Block** 2763

**Section** 3090-Ocean Springs **Asset** MCDONNEL AVE **AssetNum** 340206M **Maintainer** Patterson Jr, L D - ETA: 22:58

**Description** 07/14/2013 20:09:26 by Paul Belkot Dept Signals IT+ Unknown

**Updated** 07/14/2013 20:14:58 by Paul Belkot Dept Signals IT+ .False or partial activation reported  
gates down flashers cont no train in area per local pd. AA disp advised to protect crossing as a false partial activation, disp initials WJS. Sent notification to ESS Atlanta div., please call mtr. Notification Sent to -Signal Control Center - Atlanta at 07/14/2013 20:14:58 Asset: MCDONNEL AVE Status Changed To: Out Of Service PCC Notification Sent 07/14/2013 20:14:58

**Updated** 07/14/2013 21:31:09 by Emily Morton Dept PSCC IT+



**Contacted On** Agency Biloxi, ms pd **Contact Name** operator 366 **Phone** 228-392-0641

Reporting party has been verified as the responsible law enforcement agency.

**Updated** 07/14/2013 21:43:50 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Leonard Patterson Jr ETA of: 22:58

**Updated** 07/14/2013 23:00:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 07/15/2013 01:05:51 **by** Leonard Patterson Jr **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 07/15/2013 01:05:00 Equipment Type: Other - explain Action Taken: Other - explain Bungalow extremely hot inside, exhaust fan thermostat adjusted to operate, opened back door too. Corrected several HXP-3 Options in programming. Observed a north & south bound train through – no exceptions. Operational Checks Performed Asset: MCDONNEL AVE Status Changed To: In Service PCC Notification Sent 07/15/2013 01:05:51

**Updated** 07/15/2013 01:11:37 **by** Christopher Horman **Dept** PSCC **IT+**  
**Contacted On** 07-15-2013 01:11:00 **Agency** Biloxi, ms pd **Contact Name** Disp. Ramona **Phone** 228-392-0641

---

**Log#** [6209135](#) **Status** Closed **Entered** 07-13-2013 20:02:48 **by** Buehler, Larry **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.2 **Block** 2763

**Section** 3090-Ocean Springs **Asset** MCDONNEL AVE **AssetNum** 340206M **Maintainer** Stanfill, M O - ETA: 20:16

**Description** 07/13/2013 20:02:48 **by** Larry Buehler **Dept** Signals **IT+** Unknown

**Updated** 07/13/2013 20:06:27 **by** Larry Buehler **Dept** Signals **IT+** .False or partial activation reported  
CITIZEN REPORTS GATES DOWN. Notification Sent to -Signal Control Center - Atlanta at 07/13/2013 20:06:27 Asset: MCDONNEL AVE  
Status Changed To: Out Of Service PCC Notification Sent 07/13/2013 20:06:27

**Updated** 07/13/2013 20:06:43 **by** Larry Buehler **Dept** Signals **IT+** .False or partial activation reported

**Updated** 07/13/2013 20:16:05 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: N/A

**Updated** 07/13/2013 20:17:13 **by** Jesse Gansen **Dept** PSCC **IT+**  
**Contacted On** 07-13-2013 20:16:00 **Agency** Agency Biloxi Police Department **Contact Name** 2317 **Phone** 228-392-0641

**Updated** 07/13/2013 20:20:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 07/13/2013 20:40:47 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 07/13/2013 20:36:00 Equipment Type: Power/batteries Action Taken: Lightning protectors/arrestors replaced  
Mntr found shorted lightning arrestor on MDSA bd, replaced. Performed op checks, turned crossing backover to disp. Bad storms in area at time of incidnet.  
Operational Checks Performed Asset: MCDONNEL AVE Status Changed To: In Service PCC Notification Sent 07/13/2013 20:40:47

**Updated** 07/13/2013 20:45:10 **by** Jesse Gansen **Dept** PSCC **IT+**  
**Contacted On** 07-13-2013 20:44:00 **Agency** Biloxi Police Department **Contact Name** 366 **Phone** 228-392-0641

---

**Log#** [5778134](#) **Status** Closed **Entered** 09-11-2012 14:09:54 **by** Gothard, Jason **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.2 **Block** 2763

**Section** 3090-Ocean Springs **Asset** MCDONNEL AVE **AssetNum** 340206M **Maintainer** Patterson Jr, L D - ETA: 19:06

**Description** 09/11/2012 14:17:30 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
asst R?M reports xing activated with no train. MOW is working in area Asset: MCDONNEL AVE Status Changed To: Out Of Service PCC  
Notification Sent 09/11/2012 14:17:30

**Updated** 09/11/2012 14:17:32 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
A email notification for Multi Failure Count (MFC) asset MCDONNEL AVE (3) has been sent to the following:  
Terrence Smale II  
Vacant Vacant

**Updated** 09/11/2012 14:49:46 **by** Kihron Bristol **Dept** PSCC **IT+**

**Contacted On** 09-11-2012 14:49:00 **Agency** Biloxi Police Department **Contact Name** Desiray **Phone** 228-392-0641  
Irish Hill DR

**Updated** 09/11/2012 17:06:56 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported

The AA Dispatcher is protecting the crossing with a **Type 1 Activation Failure Message# 17183**. LVR

**Closed** 09/11/2012 20:28:46 **by** Leonard Patterson Jr **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 09/11/2012 20:00:00 Equipment Type: Line Wire - aerial/UG Action Taken: Repaired/replaced open wire Suspected Reason: Other department Repaired broken track connections at Veterans Ave (McDonnald DAX's from)- Roadway has Veterans Ave road removed tamping & regulating earlier today. Operational Checks Performed Asset: MCDONNEL AVE Status Changed To: In Service PCC Notification Sent 09/11/2012 20:28:46

**Updated** 09/11/2012 20:49:49 **by** Tanya Josen **Dept** PSCC **IT+**  
**Contacted On** 09-11-2012 20:49:00 **Agency** Biloxi Police Department **Contact Name** Operator Miller **Phone** 228-392-0641

---

**Log#** [5768372](#) **Status** Closed **Entered** 09-04-2012 22:19:37 **by** Carter, Jake **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 730.2 **Block** 2763

**Section** 3090-Ocean Springs **Asset** MCDONNEL AVE **AssetNum** 340206M **Maintainer** Stanfill, M O - ETA: 02:54 & Wilson, C E - ETA: 01:26

**Description** 09/04/2012 22:23:49 **by** Jake Carter **Dept** Signals **IT+** .False or partial activation reported  
Local Pd reports gates are down, lights are flashing, w/no train present;disp is protecting as f/p Notification Sent to - Signal Control Center - Atlanta at 09/04/2012 22:23:49 Asset: MCDONNEL AVE Status Changed To: Out Of Service PCC Notification Sent 09/04/2012 22:23:49

**Updated** 09/04/2012 22:24:21 **by** Jake Carter **Dept** Signals **IT+** .False or partial activation reported  
New Asset Added: 340207U - VETERANS AVE - BILOXI MS

**Updated** 09/04/2012 22:24:30 **by** Jake Carter **Dept** Signals **IT+** .False or partial activation reported  
PCC Notification Sent 09/04/2012 22:24:30 Asset: 340207U - VETERANS AVE - BILOXI MS Status Changed To: Out of Service

**Updated** 09/04/2012 22:24:51 **by** Alison Obrien **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi Pd **Contact Name** David **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 09/04/2012 22:25:12 **by** Alison Obrien **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi Pd **Contact Name** David **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 09/04/2012 22:25:21 **by** Jake Carter **Dept** Signals **IT+** .False or partial activation reported  
Veterans Ave protected w' f/p mess 44231 wcj

**Updated** 09/04/2012 23:43:15 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Mntr Stanfill still finishing work at Chapman Rd. crossing and may not have the required amount of time to troubleshoot incident before going HSL. Mntr requests call list be run.

**Updated** 09/05/2012 00:54:06 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Mntr Stanfill has completed work at Chapman Rd. and is now en-route to assist Mntr Wilson with crossings.

**Closed** 09/05/2012 03:32:47 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 09/05/2012 03:27:00 Equipment Type: Crossing case equipment Action Taken: Replaced card(s) Suspected Reason: Other weather  
Mntr found bad trk module on #2 trk. Replaced, cleared both crossings as they are Daxed together. Performed op checks on both crossings and turned them backover to disp. Crossing equipment had been exposed to Hurricane Isaac.  
Operational Checks Performed Asset: MCDONNEL AVE Status Changed To: In Service PCC Notification Sent 09/05/2012 03:32:47 Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC Notification Sent 09/05/2012 03:32:47

**Updated** 09/05/2012 03:35:56 **by** Alison Obrien **Dept** PSCC **IT+**  
**Contacted On** 09-05-2012 03:35:00 **Agency** Biloxi Pd **Contact Name** Ronda **Phone** 228-392-0641

---

**Log#** [5745245](#) **Status** Closed **Entered** 08-18-2012 02:13:45 **by** Jahay, Brian **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 730.2 **Block** 2763

**Section** 3090-Ocean Springs **Asset** MCDONNEL AVE **AssetNum** 340206M **Maintainer** Stanfill, M O - *ETA*: 06:21

**Description** 08/18/2012 02:18:24 **by** Brian Jahay **Dept** Signals **IT+** .False or partial activation reported  
Officer rpt that the crossing is activated with no train in sight. Protecting w/false partial message. Notification Sent to -  
Signal Control Center - Atlanta at 08/18/2012 02:18:24 **Asset**: MCDONNEL AVE **Status Changed To**: Out Of Service  
**PCC Notification Sent** 08/18/2012 02:18:24

**Updated** 08/18/2012 02:20:59 **by** Alison Obrien **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi PD **Contact Name** Ramona **Phone** 1-228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Closed** 08/18/2012 09:15:20 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 08/18/2012 09:14:00 **Equipment Type**: N/A **Action Taken**: Issue cleared before cause identified  
**Suspected Reason**: Equipment failure

**Employee**: M. Stanfill

- Crossing was clear when MTR arrived, could not duplicate the trouble. Crossing is working as intended.

Did OP Checks, Back/released to AA disp. Watched 2 train NB thru crossing, no exceptions.

Operational Checks Performed **Asset**: MCDONNEL AVE **Status Changed To**: In Service **PCC Notification Sent**  
08/18/2012 09:15:20

**Updated** 08/18/2012 09:17:19 **by** Brooks Clayton **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi PD **Contact Name** Ramona **Phone** 1-228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 08/18/2012 09:18:41 **by** Brooks Clayton **Dept** PSCC **IT+**  
**Contacted On** 08-18-2012 09:18:00 **Agency** Biloxi PD **Contact Name** Eric **Phone** 228-392-0641

---

**Log#** [5576546](#) **Status** Closed **Entered** 04-25-2012 16:46:24 **by** Rosenblatt, Louis **Type** Vehicle on Track

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 730.2 **Block** 2763

**Section** 3090-Ocean Springs **Asset** MCDONNEL AVE **AssetNum** 340206M **Maintainer** Houck, B - *ETA*: 18:10

**Description** 04/25/2012 16:54:45 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track

The AA Dispatcher received a report from the PSCC that McDonnel Avenue, MP 000 730.19, DOT# 340206M, has a vehicle stuck on the track.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 24814**. LVR  
**Asset**: MCDONNEL AVE **Status Changed To**: Out Of Service **PCC Notification Sent** 04/25/2012 16:54:45

**Updated** 04/25/2012 17:34:58 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** 04-25-2012 17:33:00 **Agency** Biloxi Police Department **Contact Name** Opr Sara **Phone** 228-392-0641  
Irish Hill Dr

**Closed** 04/25/2012 18:12:16 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 04/25/2012 18:10:00 **Equipment Type**: N/A **Action Taken**: Eqpt tested & fnd working as intended  
**Suspected Reason**: Outside party or vandalism

**The Signal Maintainer reported that the crossing is newly paved and there is brand new asphalt on the roadway with no marks on it. The rocks have not been disturbed. There is no idication that there was a vehicle stuck on the track. Operational Checks were performed. The Crossing is Back In Service with the Dispatcher. LVR**

Operational Checks Performed **Asset**: MCDONNEL AVE **Status Changed To**: In Service **PCC Notification Sent**  
04/25/2012 18:12:16

**Veterans Avenue**

**DOT Crossing #: 340207U**

**RR Milepost #: 730.29**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 33

Status All AssetType All RootAssetType All Department Signals AssetNum 340207U

---

**Log#** [7761456](#) **Status** Closed **Entered** 08-16-2016 08:08:24 **by** Belkot, Paul **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.3 **Block** 2763

**Section** 3090-7M16 **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Stanfill, M O - ETA: 09:15

**Description** 08/16/2016 08:08:24 **by** Paul Belkot **Dept** Signals **IT+** Unknown

**Updated** 08/16/2016 08:12:03 **by** Paul Belkot **Dept** Signals **IT+** .False or partial activation reported gates down flashers activated no train in area per local pd. AA disp advised to protect crossing as a false partial activation. Sent notification to ESS Atlanta div., please call mtr. Notification Sent to -Signal Control Center - Atlanta at 08/16/2016 08:12:03 Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification Sent 08/16/2016 08:12:03

**Updated** 08/16/2016 08:15:23 **by** Mike Eckstein **Dept** Signals **IT+** .False or partial activation reported Status changed to Dispatched for Michael Stanfill ETA of: 09:15

**Updated** 08/16/2016 08:31:15 **by** Robert Clendening **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi mspd **Contact Name** operator 366 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 08/16/2016 09:20:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported ETA time reached Status changed to Active

**Updated** 08/16/2016 10:34:32 **by** Mark Tyo **Dept** Signals **IT+** .False or partial activation reported Smarts alert notification for njax-asever-04.dmz.csxr(340207U). Fault detected - sigOSStCsAlarm\_000-730.29-340207U-199 ESCALATED:FALSE ACT - \*\*GCP4K TRANSFERRING - TCIS:1 at Veterans Ave - Biloxi MS 08/16/2016 10:02:29 (MP:000-730.29, DOT:340207U)

**Updated** 08/16/2016 10:39:36 **by** Mark Tyo **Dept** Signals **IT+** .False or partial activation reported Smarts alert notification for njax-asever-04.dmz.csxr(340207U). Fault detected - sigOSStCsAlarm\_000-730.29-340207U-199 ESCALATED:FALSE ACT - \*\*GCP4K TRANSFERRING - TCIS:1 at Veterans Ave - Biloxi MS 08/16/2016 10:02:29 (MP:000-730.29, DOT:340207U)

**Updated** 08/16/2016 12:12:28 **by** Gregory Torrence **Dept** Signals **IT+** .False or partial activation reported Placed on standby and op checked due to bad track module on normal side GCP4K unit. Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC Notification Sent 08/16/2016 12:12:28

**Updated** 08/16/2016 12:22:22 **by** Terry Lloyd **Dept** PSCC **IT+**  
**Contacted On** 08-16-2016 12:22:00 **Agency** Biloxi mspd **Contact Name** Sarah **Phone** 228-392-0641

**Closed** 08/19/2016 09:47:34 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported Incident Resolved: 08/19/2016 09:47:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced Track Card

**Employee:** M. Stanfill

- replaced bad track mod #5...

Did OP Checks

Operational Checks Performed

---

**Log#** [7553980](#) **Status** Closed **Entered** 03-10-2016 17:30:48 **by** Gaspar, Sean **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 4 **Milepost** 000 730.3 **Block** 2763

**Section** 3090-7M16 **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer**

**Description** 03/10/2016 17:30:49 **by** Sean Gaspar **Dept** Signals **IT+** Unknown

Smarts alert notification for njax-aserver-04.dmz.csxr(340207U). Fault detected - sigOSStCsAlarm\_000-730.29-340207U-034 LIGHTING BATTERY (XB) GFT ALARM - TCIS:3 at Veterans Ave - Biloxi MS 03/10/2016 17:31:40 (MP:000-730.29, DOT:340207U) [ Count: 13 on Thu Mar 10 22:30:28 2016 ]

**Updated** 03/10/2016 17:31:11 **by** Sean Gaspar **Dept** Signals **IT+** .Other Failure  
Orange 3 Dispatch during business day (Monday - Friday 0700 -1500), but handle to resolution during same business day (even if overtime is required). Use deferment procedure after business hours. Maintainer must obtain protection if the crossing is not working as designed upon arrival.

**Updated** 03/10/2016 17:31:12 **by** Sean Gaspar **Dept** Signals **IT+** .Other Failure  
An email notification for (IRI) asset VETERANS AVE - BILOXI MS (6) has been sent to the following:  
George James Jr  
Danny McKenzie  
John Parr  
Jody Cox

**Closed** 03/15/2016 09:03:40 **by** Bruce McVey **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 03/15/2016 09:03:00 Equipment Type: N/A Action Taken: NTF - UTD

**Employee:** Sig Mgr James

- NEW POWER OFF RELAY ON ORDER

Did OP Checks

Operational Checks Performed

---

**Log#** [7539628](#) **Status** Closed **Entered** 02-29-2016 11:58:30 **by** Jackson Jr, Marv **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 2 **Milepost** 000 730.3 **Block** 2763

**Section** 3090-7M16 **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Mannion, R - ETA: 19:15

**Description** 02/29/2016 11:58:31 **by** Marv Jackson Jr **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340207U). Fault detected - sigOSStCsAlarm\_000-730.29-340207U-005 \*\*AC POWER OFF FOR 20 MINUTES - TCIS:4 at Veterans Ave - Biloxi MS 02/29/2016 11:15:21 (MP:000-730.29, DOT:340207U) [ Count: 2 on Mon Feb 29 16:14:15 2016 ]

**Updated** 02/29/2016 11:59:08 **by** Marv Jackson Jr **Dept** Signals **IT+** .Other Failure  
SMART Notification Sent to -Signal Control Center - Atlanta at 02/29/2016 11:59:08

**Updated** 02/29/2016 11:59:10 **by** Marv Jackson Jr **Dept** Signals **IT+** .Other Failure  
An email notification for (IRI) asset VETERANS AVE - BILOXI MS (5) has been sent to the following:  
George James Jr  
Danny McKenzie  
John Parr  
Jody Cox

**Updated** 02/29/2016 16:27:28 **by** Brad Oglesby **Dept** Signals **IT+** .Other Failure  
Smarts alert notification for njax-aserver-04.dmz.csxr(340207U). Fault detected - sigOSStCsAlarm\_000-730.29-340207U-062 \*\*93% LOW OB: 10.0 V - 93% LOW OB BATT ALARM - TCIS:3 at Veterans Ave - Biloxi MS 02/29/2016 16:05:50 (MP:000-730.29, DOT:340207U)

**Updated** 02/29/2016 16:43:05 **by** Brad Oglesby **Dept** Signals **IT+** .Other Failure  
Smarts alert notification for njax-aserver-04.dmz.csxr(340207U). Fault detected - sigOSStCsAlarm\_000-730.29-340207U-063 \*\*93% LOW X-B: 11.7 V - 93% LOW XB BATT ALARM - TCIS:3 at Veterans Ave - Biloxi MS 02/29/2016 16:41:28 (MP:000-730.29, DOT:340207U)

**Updated** 02/29/2016 16:43:18 **by** Brad Oglesby **Dept** Signals **IT+** .Other Failure  
Smarts alert notification for njax-aserver-04.dmz.csxr(340207U). Fault detected - sigOSStCsAlarm\_000-730.29-340207U-056 ESCALATED:FALSE ACT - GCP4K Bad Communication on Backplane - TCIS:1 at Veterans Ave - Biloxi MS 02/29/2016 16:43:09 (MP:000-730.29, DOT:340207U)

**Updated** 02/29/2016 16:46:35 **by** Brad Oglesby **Dept** Signals **IT+** .Other Failure



1644 ESS ADVISED THE AA DISPATCHER TO PROVIDE PROTECTION ON THE CROSSING AS PER FALSE ACTIVATION STANDARD. A SIGNAL EMPLOYEE NEEDS DISPATCHED TO INVESTIGATE THIS TCIS SMARTS PRIORITY 1 ALARM. THE UNIT HAS DETECTED A FALSE ACTIVATION OCCURRENCE AT THE CROSSING. Notification Sent to -Signal Control Center - Atlanta at 02/29/2016 16:46:35 Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification Sent 02/29/2016 16:46:35

**Updated** 02/29/2016 16:59:25 **by** Brad Oglesby **Dept** Signals **IT+** .Other Failure  
Smarts alert notification for njax-asever-04.dmz.csxr(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-056 CLEARED:\*\*GCP4K COMM GOOD - TCIS:5 at Veterans Ave - Biloxi MS 02/29/2016 16:47:00 (MP:000-730.29, DOT:340207U)

**Updated** 02/29/2016 17:01:23 **by** Roland Knagge **Dept** PSCC **IT+**  
**Contacted On** 02-29-2016 16:59:00 **Agency** Biloxi Police Department **Contact Name** Megan **Phone** 228-392-0641

**Updated** 02/29/2016 17:01:23 **by** Mark Tyo **Dept** Signals **IT+** .Other Failure  
Crossing activated no trains. Disp is protecting

**Updated** 02/29/2016 19:41:05 **by** Brad Oglesby **Dept** Signals **IT+** .Other Failure  
Smarts alert notification for njax-asever-04.dmz.csxr(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-062 CLEARED:OB BATT NORMAL - TCIS:5 at Veterans Ave - Biloxi MS 02/29/2016 19:28:50 (MP:000-730.29, DOT:340207U)

**Updated** 02/29/2016 20:18:06 **by** Roger Mannion **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 02/29/2016 20:18:00 Equipment Type: Power/Batteries Action Taken: Repaired/Replaced  
COAM Power Source Pancake arrestor was shorted out, by-passed until can get a replacement, maintainer planes to get with COAM in morning. Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC Notification Sent 02/29/2016 20:18:06

**Closed** 02/29/2016 20:19:34 **by** Louis Rosenblatt **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 02/29/2016 20:18:00 Equipment Type: Power/Batteries Action Taken: Repaired/Replaced  
COAM Power Source Operational Checks Performed

**Updated** 02/29/2016 20:43:23 **by** Shari Baron **Dept** PSCC **IT+**  
**Contacted On** 02-29-2016 20:42:00 **Agency** Biloxi Police Department **Contact Name** Kayla **Phone** 228-392-0641

---

**Log#** [7535636](#) **Status** Closed **Entered** 02-25-2016 18:13:18 **by** Oglesby, Brad **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 1 **Milepost** 000 730.3 **Block** 2763

**Section** 3090-7M16 **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer**

**Description** 02/25/2016 18:13:18 **by** Brad Oglesby **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-asever-04.dmz.csxr(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-005 \*\*AC POWER OFF FOR 20 MINUTES - TCIS:4 at Veterans Ave - Biloxi MS 02/25/2016 18:08:34 (MP:000-730.29, DOT:340207U) [ Count: 2 on Thu Feb 25 23:07:29 2016 ]

**Updated** 02/25/2016 18:13:50 **by** Brad Oglesby **Dept** Signals **IT+** .Other Failure  
THERE ISN'T A POWER-OFF INDICATION SHOWING AT THE CONTROL POINT OR IN THE BLOCK.

**Updated** 02/25/2016 18:13:53 **by** Brad Oglesby **Dept** Signals **IT+** .Other Failure  
An email notification for (IRI) asset VETERANS AVE - BILOXI MS (4) has been sent to the following:  
George James Jr  
Danny McKenzie  
John Parr

**Updated** 02/25/2016 21:10:09 **by** Brad Oglesby **Dept** Signals **IT+** .Other Failure  
Smarts alert notification for njax-asever-04.dmz.csxr(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-062 \*\*93% LOW OB: 10.0 V - 93% LOW OB BATT ALARM - TCIS:3 at Veterans Ave - Biloxi MS 02/25/2016 21:09:44 (MP:000-730.29, DOT:340207U)

**Updated** 02/26/2016 01:25:58 **by** Jacob Buksar **Dept** Signals **IT+** .Other Failure  
Smarts alert notification for njax-asever-04.dmz.csxr(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-063 \*\*93% LOW X-B: 11.8 V - 93% LOW XB BATT ALARM - TCIS:3 at Veterans Ave - Biloxi MS



02/26/2016 00:18:42 (MP:000-730.29, DOT:340207U)

**Updated** 02/26/2016 01:26:30 **by** Jacob Buksar **Dept** Signals **IT+** .Other Failure  
Orange 3 Dispatch during business day (Monday-Friday 0700-1500), but handle to resolution during same business day (even if overtime is required). Use deferment procedure after business hours. Maintainer must obtain protection if the crossing is not working as designed upon arrival.

**Closed** 02/26/2016 09:42:40 **by** Matthew Kite **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 02/26/2016 09:42:00 Equipment Type: Wiring/Protection Action Taken: Repaired/Replaced Protection

Mntr replaced Tranquell pancake arrestor at crossing. All pwr restored to equip. 2016/02/26 09:37:05 AC POWER BACK ON - TCIS:5# 2016/02/26 09:36:16 OB BATT NORMAL - TCIS:5# 2016/02/26 09:36:07 XB BATT NORMAL - TCIS:5# 2016/02/26 05:09:28 #1 BG BATT NORMAL - TCIS:5# Equip operational, closing incident.

Operational Checks Performed

---

**Log#** [7512427](#) **Status** Closed **Entered** 02-09-2016 15:13:25 **by** Gaspar, Sean **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.5 **Milepost** 000 730.3 **Block** 2763

**Section** 3090-7M16 **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Mannion, R - ETA: 15:52

**Description** 02/09/2016 15:13:25 **by** Sean Gaspar **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-asever-04.dmz.csxr(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-063 \*\*93% LOW X-B: 12.4 V - 93% LOW XB BATT ALARM - TCIS:3 at Veterans Ave - Biloxi MS 02/09/2016 15:12:52 (MP:000-730.29, DOT:340207U) [ Count: 1 on Tue Feb 9 20:11:58 2016 ]

**Updated** 02/09/2016 15:15:25 **by** Sean Gaspar **Dept** Signals **IT+** .Other Failure  
Orange 3 Dispatch during business day (Monday - Friday 0700 -1500), but handle to resolution during same business day (even if overtime is required). Use deferment procedure after business hours. Maintainer must obtain protection if the crossing is not working as designed upon arrival.

**Updated** 02/09/2016 15:15:27 **by** Sean Gaspar **Dept** Signals **IT+** .Other Failure  
An email notification for (IRI) asset VETERANS AVE - BILOXI MS (.5) has been sent to the following:  
George James Jr  
Danny McKenzie

**Updated** 02/09/2016 15:22:40 **by** Louis Rosenblatt **Dept** Signals **IT+** .Other Failure  
Status changed to Dispatched for Roger Mannion ETA of: 15:52

**Updated** 02/09/2016 15:55:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .Other Failure  
ETA time reached Status changed to Active

**Updated** 02/09/2016 18:03:41 **by** Sean Gaspar **Dept** Signals **IT+** .Other Failure  
Smarts alert notification for njax-asever-04.dmz.csxr(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-063 CLEARED:XB BATT NORMAL - TCIS:5 at Veterans Ave - Biloxi MS 02/09/2016 16:06:51 (MP:000-730.29, DOT:340207U)

**Updated** 02/09/2016 18:08:56 **by** Roger Mannion **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 02/09/2016 18:08:00 Equipment Type: Power/Batteries Action Taken: Reset/Replaced Breaker/Fuse bad 240pancake, bypassed until replacement parts are located. All circuits charged properly. Operational Checks Performed

**Closed** 02/09/2016 18:09:53 **by** Louis Rosenblatt **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 02/09/2016 18:08:00 Equipment Type: Power/Batteries Action Taken: Reset/Replaced Breaker/Fuse Operational Checks Performed

---

**Log#** [7504825](#) **Status** Closed **Entered** 02-03-2016 18:15:57 **by** Gaspar, Sean **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.25 **Milepost** 000 730.3 **Block** 2763

**Section** 3090-7M16 **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer**

**Description** 02/03/2016 18:15:58 **by** Sean Gaspar **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-005 \*\*AC POWER OFF FOR 20 MINUTES - TCIS:4 at Veterans Ave - Biloxi MS 02/03/2016 17:54:05 (MP:000-730.29, DOT:340207U) [ Count: 2 on Wed Feb 3 22:53:16 2016 ]

**Updated** 02/03/2016 18:16:19 **by** Sean Gaspar **Dept** Signals **IT+** .Other Failure  
Yellow 4 Dispatch during business day (Monday - Friday 0700 -1500). Resolve by the end of next business day. Should not involve overtime. Use deferment procedure after business hours. Maintainer must obtain protection if the crossing is not working as designed upon arrival.

**Updated** 02/03/2016 18:16:20 **by** Sean Gaspar **Dept** Signals **IT+** .Other Failure  
An email notification for (IRI) asset VETERANS AVE - BILOXI MS (.25) has been sent to the following:  
George James Jr

**Updated** 02/03/2016 21:10:10 **by** Brad Oglesby **Dept** Signals **IT+** .Other Failure  
Smarts alert notification for njax-aserver-04.dmz.csxr(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-005 CLEARED:AC POWER BACK ON - TCIS:5 at Veterans Ave - Biloxi MS 02/03/2016 18:34:34 (MP:000-730.29, DOT:340207U)

**Closed** 02/03/2016 21:10:27 **by** Brad Oglesby **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 02/03/2016 21:10:00 Equipment Type: N/A Action Taken: NTF - UTD . Operational Checks Performed

---

**Log#** [7487451](#) **Status** Closed **Entered** 01-21-2016 17:14:30 **by** Gaspar, Sean **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 730.3 **Block** 2763

**Section** 3090-7M16 **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer**

**Description** 01/21/2016 17:14:30 **by** Sean Gaspar **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-063 \*\*93% LOW X-B: 12.0 V - 93% LOW XB BATT ALARM - TCIS:3 at Veterans Ave - Biloxi MS 01/21/2016 17:12:24 (MP:000-730.29, DOT:340207U) [ Count: 4 on Thu Jan 21 22:11:41 2016 ]

**Updated** 01/21/2016 17:15:04 **by** Sean Gaspar **Dept** Signals **IT+** .Other Failure  
Orange 3 Dispatch during business day (Monday - Friday 0700 -1500), but handle to resolution during same business day (even if overtime is required). Use deferment procedure after business hours. Maintainer must obtain protection if the crossing is not working as designed upon arrival.

**Updated** 01/21/2016 17:15:06 **by** Sean Gaspar **Dept** Signals **IT+** .Other Failure  
An email notification for (IRI) asset VETERANS AVE - BILOXI MS (.125) has been sent to the following:  
George James Jr

**Closed** 01/22/2016 11:00:45 **by** Matthew Kite **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 01/22/2016 11:00:00 Equipment Type: Power/Batteries Action Taken: Commercial Power Restored  
2016/01/21 17:15:33 XB BATT NORMAL - TCIS:5# Mntr reports comm pwr on at crossing, XB bank showing normal. Closing incident.  
Operational Checks Performed

---

**Log#** [7480860](#) **Status** Closed **Entered** 01-17-2016 17:10:48 **by** Lewis, Wendell **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.3 **Block** 2763

**Section** 3090-7M16 **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer**

**Description** 01/17/2016 17:10:48 **by** Wendell Lewis **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-005 \*\*AC POWER OFF FOR 20 MINUTES - TCIS:4 at Veterans Ave - Biloxi MS 01/17/2016 17:09:55 (MP:000-730.29, DOT:340207U) [ Count: 1 on Sun Jan 17 22:09:15 2016 ]

**Updated** 01/17/2016 17:12:34 **by** Wendell Lewis **Dept** Signals **IT+** .Other Failure  
PLEASE HAVE MNTR. CHECK PRIORITY 4 ALARM WHEN BACK ON DUTY.

**Updated** 01/19/2016 16:20:11 **by** Sean Gaspar **Dept** Signals **IT+** .Other Failure  
Smarts alert notification for njax-aserver-04.dmz.csxr(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-005 CLEARED:AC POWER BACK ON - TCIS:5 at Veterans Ave - Biloxi MS 01/19/2016 16:19:59 (MP:000-730.29, DOT:340207U)

**Closed** 01/19/2016 16:20:42 **by** Sean Gaspar **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 01/19/2016 16:20:00 Equipment Type: N/A Action Taken: NTF - UTD Alarm Cleared If the alarm was a priority 3 or 4 the incident should be closed with an Action Taken of "NTF-UTD". If a maintainer was dispatched he should be notified of the clear and is no longer required to visit the site. Operational Checks Performed

---

**Log#** [7449774](#) **Status** Closed **Entered** 12-22-2015 12:21:04 **by** Wilburn, Marion **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.3 **Block** 2763

**Section** 3090-7M16 **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Mannion, R - ETA: 13:53

**Description** 12/22/2015 12:21:04 **by** Marion Wilburn **Dept** Signals **IT+** Unknown

**Updated** 12/22/2015 12:26:53 **by** Marion Wilburn **Dept** Signals **IT+** .False or partial activation reported  
1223 Hrs. Outside party reports crossing is activated with no train present, AA-dispatcher has been notified to protect crossing as false activation. Also no dot number provided. Notification Sent to -Signal Control Center - Atlanta at 12/22/2015 12:26:53 Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification Sent 12/22/2015 12:26:53

**Updated** 12/22/2015 12:40:33 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** 12-22-2015 12:39:00 **Agency** Biloxi Police Department **Contact Name** 352 **Phone** 228-392-0641  
@ Irish Hill Dr.

**Updated** 12/22/2015 12:54:00 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Roger Mannion ETA of: 13:53

**Updated** 12/22/2015 13:55:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 12/22/2015 14:08:34 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 12/22/2015 14:08:00 Equipment Type: N/A Action Taken: NTF - UTD  
Mntr reports MOW doing trk work in app of crossing. Performed op checks, turned crossing back over to disp. All equip functioning as intended.  
Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC Notification Sent 12/22/2015 14:08:34

**Updated** 12/22/2015 18:43:15 **by** Misty Hunter **Dept** PSCC **IT+**  
**Contacted On** 12-22-2015 18:42:00 **Agency** Biloxi Police Department **Contact Name** 3501 **Phone** 228-392-0641

---

**Log#** [7336792](#) **Status** Closed **Entered** 09-27-2015 10:52:26 **by** Lewis, Wendell **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 730.3 **Block** 2763

**Section** 3090-7M16 **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Stanfill, M O - ETA: 11:21

**Description** 09/27/2015 10:52:26 **by** Wendell Lewis **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-020 ESCALATED:FALSE ACT - GATES NOT STARTING TCIS:0 at Veterans Ave - Biloxi MS 09/27/2015 09:16:12 (MP:000-730.29, DOT:340207U) [ Count: 2 on Sun Sep 27 13:16:10 2015 ]

**Updated** 09/27/2015 10:53:05 **by** Wendell Lewis **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-056 ESCALATED:FALSE ACT - GCP4K Bad Communication on Backplane - TCIS:1 at Veterans Ave - Biloxi MS 09/27/2015 09:29:23 (MP:000-730.29, DOT:340207U)

**Updated** 09/27/2015 10:56:27 **by** Wendell Lewis **Dept** Signals **IT+** .Other Failure  
NOTIFIED AA-DISP. TO PROTECT WITH F/P MSG. Notification Sent to -Signal Control Center - Atlanta at

09/27/2015 10:56:27 Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification  
Sent 09/27/2015 10:56:27

**Updated** 09/27/2015 11:02:54 **by** Jolene Woods **Dept** PSCC **IT+**  
**Contacted On** 09-27-2015 11:02:00 **Agency** Biloxi Police Department **Contact Name** Christy **Phone** 228-392-0641  
Irish Hill Dr

**Updated** 09/27/2015 11:07:09 **by** Michael Stanfill **Dept** Signals **IT+** .Other Failure  
maintainer on scene. cutting in signals n beauvoir to kcs.

**Closed** 09/27/2015 11:22:22 **by** Bruce McVey **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 09/27/2015 11:22:00 Equipment Type: N/A Action Taken: NTF - UTD

**Employee:** M. Stanfill

- mtr onsite for cutin working on crossing and testing

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC  
Notification Sent 09/27/2015 11:22:22

**Updated** 09/27/2015 11:30:00 **by** Avie Saunders **Dept** PSCC **IT+**  
**Contacted On** 09-27-2015 11:29:00 **Agency** Biloxi Police Department **Contact Name** Sarah **Phone** 228-392-0641

---

**Log#** [7335345](#) **Status** Closed **Entered** 09-25-2015 22:22:03 **by** Gaspar, Sean **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.3 **Block** 2763

**Section** 3090-7M16 **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Stanfill, M O - ETA: 00:39

**Description** 09/25/2015 22:22:03 **by** Sean Gaspar **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340207U). Fault detected - sigOSTCsAlarm\_000-730.29-  
340207U-199 ESCALATED:FALSE ACT - \*\*GCP4K TRANSFERRING - TCIS:1 at Veterans Ave - Biloxi MS  
09/25/2015 22:20:36 (MP:000-730.29, DOT:340207U) [ Count: 6 on Sat Sep 26 02:20:36 2015 ]

**Updated** 09/25/2015 22:26:46 **by** Sean Gaspar **Dept** Signals **IT+** .Other Failure  
Red 1 Notify dispatcher to protect the crossing with an Activation Failure or False Activation. Notify maintainer. Type of  
dispatcher protection must be communicated to the maintainer. Must be investigated immediately. disp protecting w/  
f/p as per smarts. Notification Sent to -Signal Control Center - Atlanta at 09/25/2015 22:26:46 Asset: VETERANS AVE  
- BILOXI MS Status Changed To: Out Of Service PCC Notification Sent 09/25/2015 22:26:46

**Updated** 09/25/2015 22:39:04 **by** Michele Schwartz **Dept** PSCC **IT+**  
**Contacted On** 09-25-2015 22:37:00 **Agency** Biloxi Police Department **Contact Name** Jackie **Phone** 228-392-0641  
Irish Hill Dr

**Updated** 09/25/2015 22:39:34 **by** Louis Rosenblatt **Dept** Signals **IT+** .Other Failure  
Status changed to Dispatched for Michael Stanfill ETA of: 00:39

**Updated** 09/26/2015 00:40:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .Other Failure  
ETA time reached Status changed to Active

**Closed** 09/26/2015 00:58:29 **by** Jerry Rockhill **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 09/26/2015 00:58:00 Equipment Type: N/A Action Taken: NTF - UTD 0056 mtr reports unable to  
duplicate problem.... verified that the unit was transferring but has stopped. no bad weather in area... mtr cleared error  
codes and will check on unit Sat. during cut in.... op cks ok and crossing back in service with disp... Operational  
Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC Notification Sent  
09/26/2015 00:58:29

**Updated** 09/26/2015 01:31:17 **by** Jerome Shepard **Dept** PSCC **IT+**  
**Contacted On** 09-26-2015 01:31:00 **Agency** Biloxi Police Department **Contact Name** Operator **Phone** 228-392-0641

**Log#** [7157862](#) **Status** Closed **Entered** 05-26-2015 07:29:44 **by** Williams, Joseph **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.3 **Block** 2763

**Section** 3090-7M16 **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Stanfill, M O - ETA: 09:14

**Description** 05/26/2015 07:29:44 **by** Joseph Williams **Dept** Signals **IT+** Unknown

**Updated** 05/26/2015 07:33:31 **by** Joseph Williams **Dept** Signals **IT+** .False or partial activation reported  
0730:Hr Biloxi police reported that the crossings are activated with no trains in sight. 0732:Hr dispatcher BMH notified. Asset:  
VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification Sent 05/26/2015 07:33:31

**Updated** 05/26/2015 07:33:43 **by** Joseph Williams **Dept** Signals **IT+** .False or partial activation reported  
New Asset Added: 340206M - MCDONNEL AVE

**Updated** 05/26/2015 07:33:57 **by** Joseph Williams **Dept** Signals **IT+** .False or partial activation reported  
. Notification Sent to -Signal Control Center - Atlanta at 05/26/2015 07:33:57 Asset: MCDONNEL AVE Status Changed To: Out Of  
Service PCC Notification Sent 05/26/2015 07:33:57

**Updated** 05/26/2015 07:34:36 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported

Storms in area at time of incident.

**Updated** 05/26/2015 07:35:50 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 09:14

**Updated** 05/26/2015 07:37:06 **by** Jackie McGuirt **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi **Contact Name** Deserea **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 05/26/2015 09:15:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 05/26/2015 11:18:41 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 05/26/2015 11:18:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced Track Card

**Employee:** M. Stanfill

- replaced track mod on #2 track @ Veterans ave.... replaced TRM at Mcdonnel ave... due to storms in area at time of incident.

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC Notification Sent 05/26/2015  
11:18:41 Asset: MCDONNEL AVE Status Changed To: In Service PCC Notification Sent 05/26/2015 11:18:41

**Updated** 05/26/2015 11:27:51 **by** Waltina Edwards **Dept** PSCC **IT+**  
**Contacted On** 05-26-2015 11:25:00 **Agency** Biloxi Police Department **Contact Name** 347 **Phone** Phone# 228-392-0641

---

**Log#** [7115898](#) **Status** Closed **Entered** 04-27-2015 01:19:31 **by** Gothard, Jason **Type** Vehicle on Track

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.3 **Block** 2763

**Section** 3090-7M16 **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Broadway, J L - ETA: 03:39

**Description** 04/27/2015 01:19:31 **by** Jason Gothard **Dept** Signals **IT+** Unknown

**Updated** 04/27/2015 01:20:09 **by** Jason Gothard **Dept** Signals **IT+** Vehicle on Track  
atl chief, aa disp, nm sub, vehicle on the tracks at mp 000730.3 at Veterans Ave Asset: VETERANS AVE - BILOXI  
MS Status Changed To: Out Of Service PCC Notification Sent 04/27/2015 01:20:09

**Updated** 04/27/2015 01:35:34 **by** Jodi Snyder **Dept** PSCC **IT+**  
**Contacted On** 04-27-2015 01:35:00 **Agency** Biloxi Police Department **Contact Name** 1955 **Phone** 228-392-0641

**Updated** 04/27/2015 01:39:06 **by** Jason Gothard **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Joshua Broadway ETA of: 03:39



**Updated** 04/27/2015 03:40:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Closed** 04/27/2015 05:04:52 **by** Jason Gothard **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 04/27/2015 05:04:00 Equipment Type: N/A Action Taken: Track Occupied car removed, no signal damage. made op checks and ret to disp. 12 sec gate down time. Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC Notification Sent 04/27/2015 05:04:52

**Updated** 04/27/2015 05:24:19 **by** Jodi Snyder **Dept** PSCC **IT+**  
**Contacted On** 04-27-2015 05:23:00 **Agency** Biloxi Police Department **Contact Name** April **Phone** 228-392-0641

---

**Log#** [7005193](#) **Status** Closed **Entered** 02-13-2015 08:29:23 **by** Lewis, Wendell **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.3 **Block** 2763

**Section** 3090-7M16 **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Stanfill, M O - ETA: 09:20

**Description** 02/13/2015 08:29:23 **by** Wendell Lewis **Dept** Signals **IT+** Unknown

**Updated** 02/13/2015 08:32:59 **by** Wendell Lewis **Dept** Signals **IT+** .False or partial activation reported  
08:25 FLASHERS AND GATES ACTIVATED WITH NO TRAIN....NOTIFIED AA-DISP. TO PROTECT F/P ACTIVATION. Notification Sent to -Signal Control Center - Atlanta at 02/13/2015 08:32:59 Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification Sent 02/13/2015 08:32:59

**Updated** 02/13/2015 08:40:49 **by** Michele Schwartz **Dept** PSCC **IT+**  
**Contacted On** **Agency** BILOXI PD **Contact Name** DESIREE **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 02/13/2015 08:50:30 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 09:20

**Updated** 02/13/2015 09:25:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 02/13/2015 13:04:31 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 02/13/2015 13:02:00 Equipment Type: Track Circuit Action Taken: Track Wire/Connection  
Mntr found bad high resistance trk conn in siding near NE Beauvoir, repaired. Performed op checks, turned crossing backover to disp. Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC Notification Sent 02/13/2015 13:04:31 Root Cause Asset 2764 009 SE BEAUVOIR TO NE BEAUVIOR SIDING Added

**Updated** 02/13/2015 13:10:48 **by** Waltina Edwards **Dept** PSCC **IT+**  
**Contacted On** 02-13-2015 13:10:00 **Agency** Biloxi Police Department **Contact Name** 2922 **Phone** Phone# 228-392-0641

---

**Log#** [6954941](#) **Status** Closed **Entered** 01-09-2015 14:43:58 **by** Gaspar, Sean **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.3 **Block** 2763

**Section** 3090-7M16 **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Stanfill, M O - ETA: 15:50

**Description** 01/09/2015 14:43:58 **by** Sean Gaspar **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-asever-04.dmz.csxr(340207U). Fault detected - sigOSTCsAlarm\_000-730.29-340207U-099 ESCALATED:FALSE ACT - \*\*GCP4K TRANSFERRING - TCIS:1 at Veterans Ave - Biloxi MS  
01/08/2015 09:38:13 (MP:000-730.29, DOT:340207U) [ Count: 12 on Fri Jan 9 19:36:30 2015 ]

**Updated** 01/09/2015 14:45:52 **by** Sean Gaspar **Dept** Signals **IT+** .Other Failure  
Red 1 Notify dispatcher to protect the crossing with an Activation Failure or False Activation. Notify maintainer. Type of dispatcher protection must be communicated to the maintainer. Must be investigated immediately. disp protecting w/ f/p as per smarts. Notification Sent to -Signal Control Center - Atlanta at 01/09/2015 14:45:52 Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification Sent 01/09/2015 14:45:52

**Updated** 01/09/2015 14:48:52 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** 01-09-2015 14:47:00 **Agency** Biloxi Police Department **Contact Name** Angie **Phone** 228-392-0641

@ RR St.

**Updated** 01/09/2015 14:50:02 **by** Louis Rosenblatt **Dept** Signals **IT+** .Other Failure  
Status changed to Dispatched for Michael Stanfill ETA of: 15:50

**Updated** 01/09/2015 15:37:54 **by** Sean Gaspar **Dept** Signals **IT+** .Other Failure  
Smarts alert notification for njax-asever-04.dmz.csxr(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-006 GATES STAYED DOWN BEHIND TRAIN - TCIS:3 at Veterans Ave - Biloxi MS 01/09/2015 15:29:25 (MP:000-730.29, DOT:340207U)

**Closed** 01/09/2015 15:44:53 **by** Louis Rosenblatt **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 01/09/2015 15:40:00 Equipment Type: N/A Action Taken: NTF - UTD

**The Signal Maintainer reported that the Crossing was working when he got there. He was unable to duplicate the problem. A Communications Maintainer was working on the modem at the time of the report. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC  
Notification Sent 01/09/2015 15:44:53

**Updated** 01/09/2015 16:12:32 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** 01-09-2015 16:09:00 **Agency** Biloxi Police Department **Contact Name** 366 **Phone** 228-392-0641  
@ RR St.

---

**Log#** [6952507](#) **Status** Closed **Entered** 01-08-2015 09:56:06 **by** Jackson Jr, Marv **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.3 **Block** 2763  
**Section** 3090-7M16 **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Smith, K E - ETA: 14:13  
**Description** 01/08/2015 09:56:06 **by** Marv Jackson Jr **Dept** Signals **IT+** Unknown

**Updated** 01/08/2015 09:57:28 **by** Marv Jackson Jr **Dept** Signals **IT+** .False or partial activation reported  
OSP REPORTS FALSE ACTIVATION AT VETERANS AVE.... Notification Sent to -Signal Control Center - Atlanta at 01/08/2015 09:57:28 Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification Sent 01/08/2015 09:57:28

**Updated** 01/08/2015 10:01:29 **by** Christina Martorano **Dept** PSCC **IT+**  
**Contacted On** 01-08-2015 10:00:00 **Agency** Biloxi Police **Contact Name** 347 **Phone** 228-392-0641  
Pass Rd

**Updated** 01/08/2015 10:34:01 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Kyle Smith ETA of: 14:13

**Updated** 01/08/2015 12:32:43 **by** Kyle Smith **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 01/08/2015 12:32:00 Equipment Type: N/A Action Taken: NTF - UTD COA Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC Notification Sent 01/08/2015 12:32:43

**Closed** 01/08/2015 12:33:56 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 01/08/2015 12:33:00 Equipment Type: N/A Action Taken: NTF - UTD **Operational Checks Performed**

**Updated** 01/08/2015 12:36:00 **by** Christina Martorano **Dept** PSCC **IT+**  
**Contacted On** 01-08-2015 12:35:00 **Agency** Biloxi Police **Contact Name** Dillon **Phone** 228-392-0641  
Pass Rd

---

**Log#** [6701962](#) **Status** Closed **Entered** 07-11-2014 06:58:14 **by** McClure, Dale **Type** .Other Failure  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.3 **Block** 2763  
**Section** 3090-Ocean Springs **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Broadway, J L - ETA: 08:22



**Description** 07/11/2014 06:58:14 **by** Dale McClure **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-asever-04.dmz.csxr(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-002 ESCALATED:ACT FAIL - \*\*WARNING TIME TK1: 18 - SHORT WARNING - TCIS:1 at Veterans Ave - Biloxi MS 07/11/2014 06:56:31 (MP:000-730.29, DOT:340207U) [ 1 at ]

**Updated** 07/11/2014 07:02:22 **by** Dale McClure **Dept** Signals **IT+** .Other Failure  
AA DISP. NOTIFIED AND INSTRUCTED TO PROTECT AS A/F STOP AND FLAG, AS PER SMARTS PRIORITY ALARM, UNTIL CHECKED. Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification Sent 07/11/2014 07:02:22

**Updated** 07/11/2014 07:07:40 **by** Matthew Kite **Dept** Signals **IT+** .Other Failure  
Status changed to Dispatched for Joshua Broadway ETA of: 08:22

**Updated** 07/11/2014 07:13:53 **by** Michele Schwartz **Dept** PSCC **IT+**  
**Contacted On** 07-11-2014 07:13:00 **Agency** Biloxi Police Department **Contact Name** 315 **Phone** 228-392-0641  
@ Irish Hill Dr

**Updated** 07/11/2014 08:25:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .Other Failure  
ETA time reached Status changed to Active

**Closed** 07/11/2014 09:30:10 **by** Joshua Broadway **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 07/11/2014 09:29:00 Equipment Type: N/A Action Taken: Track Occupied train meet at north Beauvoir os is island circuit, north bound was in siding and this is on going issue due to crossing design. Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC Notification Sent 07/11/2014 09:30:10

**Updated** 07/11/2014 09:34:00 **by** Jodi Snyder **Dept** PSCC **IT+**  
**Contacted On** 07-11-2014 09:32:00 **Agency** Biloxi Police Department **Contact Name** 315 **Phone** 228-392-0641  
@ Irish Hill Dr

---

**Log#** [6564584](#) **Status** Closed **Entered** 04-05-2014 07:54:19 **by** McClure, Dale **Type** .Other Failure  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 730.3 **Block** 2763  
**Section** 3090-Ocean Springs **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Houck, B - ETA: 09:16

**Description** 04/05/2014 07:54:19 **by** Dale McClure **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-asever-04.dmz.csxr(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-002 ESCALATED:ACT FAIL - \*\*WARNING TIME TK1: 19 - SHORT WARNING - TCIS:1 at Veterans Ave - Biloxi MS 04/05/2014 07:51:29 (MP:000-730.29, DOT:340207U) [ 1 at ]

**Updated** 04/05/2014 07:57:35 **by** Dale McClure **Dept** Signals **IT+** .Other Failure  
AA DISP. NOTIFIED AND INSTRUCTED TO PRTOECT AS A/F STOP AND FLAG, AS PER SMARTS PRIORITY ALARM, UNTIL CHECKED. Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification Sent 04/05/2014 07:57:35

**Updated** 04/05/2014 07:59:50 **by** Alexis Romine **Dept** PSCC **IT+**  
**Contacted On** 04-05-2014 07:59:00 **Agency** Biloxi Police Department **Contact Name** Dispatcher Brenda **Phone** 228-392-0641  
@ Irish Hill Drive

**Updated** 04/05/2014 08:02:08 **by** Bruce McVey **Dept** Signals **IT+** .Other Failure  
Meet at time of incident Q605-03 SB in the siding Q602-05 NB on the main also 707 in block (16836 A Summers)

**Updated** 04/05/2014 08:16:48 **by** Bruce McVey **Dept** Signals **IT+** .Other Failure  
Status changed to Dispatched for Bradley Houck ETA of: 09:16

**Updated** 04/05/2014 09:20:10 **by** TCIS AUTOMATION **Dept** Signals **IT+** .Other Failure  
ETA time reached Status changed to Active

**Closed** 04/05/2014 10:02:42 **by** Bruce McVey **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 04/05/2014 10:02:00 Equipment Type: N/A Action Taken: Track Occupied

**Employee:** B. Houck

- train meet at time of incident.. train started from stop... sped up thru xing, (was stopped on the DAX,timed out)

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC Notification Sent 04/05/2014 10:02:42

**Updated** 04/05/2014 10:04:12 **by** Alexis Romine **Dept** PSCC **IT+**  
**Contacted On** 04-05-2014 10:03:00 **Agency** Biloxi Police Department **Contact Name** Dispatcher Sarah **Phone** 228-392-0641  
@ Irish Hill Drive

---

**Log#** [6523590](#) **Status** Closed **Entered** 03-07-2014 15:02:04 **by** Gaspar, Sean **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.3 **Block** 2763

**Section** 3090-Ocean Springs **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Stanfill, M O - *ETA: 15:13*

**Description** 03/07/2014 15:02:04 **by** Sean Gaspar **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-034 LIGHTING BATTERY (XB) GFT ALARM - TCIS:3 at Veterans Ave - Biloxi MS 03/07/2014 15:02:02 (MP:000-730.29, DOT:340207U) [ 1 at ]

**Updated** 03/07/2014 15:02:24 **by** Sean Gaspar **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-017 "Operating Batt" OB GFT ALARM - TCIS:3 at Veterans Ave - Biloxi MS 03/07/2014 15:02:24 (MP:000-730.29, DOT:340207U)

**Updated** 03/07/2014 15:02:46 **by** Sean Gaspar **Dept** Signals **IT+** .Other Failure  
Orange 3 Dispatch during business day (Monday - Friday 0700 -1500), but handle to resolution during same business day (even if overtime is required). Use deferment procedure after business hours. Maintainer must obtain protection if the crossing is not working as designed upon arrival.

**Updated** 03/10/2014 15:13:42 **by** Louis Rosenblatt **Dept** Signals **IT+** .Other Failure  
Status changed to Dispatched for Michael Stanfill ETA of: N/A

**Updated** 03/10/2014 15:15:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .Other Failure  
ETA time reached Status changed to Active

**Closed** 03/10/2014 15:16:08 **by** Louis Rosenblatt **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 03/10/2014 15:15:00 Equipment Type: N/A Action Taken: NTF - UTD

**The Signal Maintainer reported that there are no ground faults at the location. Everything is working properly. LVR**

Operational Checks Performed

---

**Log#** [6470546](#) **Status** Closed **Entered** 01-31-2014 14:41:09 **by** Jackson Jr, Marv **Type** .Other Failure

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 730.3 **Block** 2763

**Section** 3090-Ocean Springs **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Stanfill, M O - *ETA: 15:45*

**Description** 01/31/2014 14:41:09 **by** Marv Jackson Jr **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-aserver-04.dmz.csxr(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-002 ESCALATED:ACT FAIL - \*\*WARNING TIME TK1: 7 - SHORT WARNING - TCIS:1 at Veterans Ave - Biloxi MS 01/31/2014 14:38:01 (MP:000-730.29, DOT:340207U) [ 1 at ]

**Updated** 01/31/2014 14:43:29 **by** Marv Jackson Jr **Dept** Signals **IT+** .Other Failure  
SMART ALARM ESCALATED:ACT FAIL - \*\*WARNING TIME TK1: 7 - SHORT WARNING - TCIS:1 at Veterans Ave - Biloxi MS 01/31/2014 14:38:01 (MP:000-730.29, DOT:340207U) [ 1 at ] Notification Sent to -Signal Control Center - Atlanta at 01/31/2014 14:43:29 Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification Sent 01/31/2014 14:43:29

**Updated** 01/31/2014 14:45:44 **by** Matthew Kite **Dept** Signals **IT+** .Other Failure  
Status changed to Dispatched for Michael Stanfill ETA of: 15:45

**Updated** 01/31/2014 14:46:25 **by** Max Todd **Dept** PSCC **IT+**  
**Contacted On** 01-31-2014 14:45:00 **Agency** Biloxi Police Department **Contact Name** 347 **Phone** 228-392-0641  
at Irish Hill Dr.

**Updated** 01/31/2014 15:50:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .Other Failure  
ETA time reached Status changed to Active

**Closed** 01/31/2014 16:14:21 **by** Louis Rosenblatt **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 01/31/2014 16:14:00 Equipment Type: N/A Action Taken: Track Occupied

**The Signal Maintainer reported that Maintenance of Way was working on the approach circuit at the time of the report. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC  
Notification Sent 01/31/2014 16:14:21

**Updated** 01/31/2014 16:23:03 **by** Max Todd **Dept** PSCC **IT+**  
**Contacted On** 01-31-2014 16:22:00 **Agency** Biloxi Police Department **Contact Name** dispatch **Phone** 228-392-0641  
at Irish Hill Dr.

---

**Log#** [6455702](#) **Status** Closed **Entered** 01-22-2014 15:21:24 **by** Gaspar, Sean **Type** .Other Failure  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.3 **Block** 2763  
**Section** 3090-Ocean Springs **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Houck, B - *ETA: 16:39*  
**Description** 01/22/2014 15:21:24 **by** Sean Gaspar **Dept** Signals **IT+** Unknown  
Smarts alert notification for njax-asever-04.dmz.csxr(340207U). Fault detected - sigOSStCsAlarm\_000-730.29-340207U-002 ESCALATED:ACT FAIL - \*\*WARNING TIME TK1: 11 - SHORT WARNING - TCIS:1 at Veterans Ave - Biloxi MS 01/22/2014 15:16:33 (MP:000-730.29, DOT:340207U) [ 1 at ]

**Updated** 01/22/2014 15:24:32 **by** Sean Gaspar **Dept** Signals **IT+** .Other Failure  
Red 1 Notify dispatcher to protect the crossing with an Activation Failure or False Activation. Notify maintainer. Type of dispatcher protection must be communicated to the maintainer. Must be investigated immediately. disp protecting w/ act/fail as per smarts. multiple mow crews working there at this time. Notification Sent to -Signal Control Center - Atlanta at 01/22/2014 15:24:32 Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification Sent 01/22/2014 15:24:32

**Updated** 01/22/2014 15:27:37 **by** Max Todd **Dept** PSCC **IT+**  
**Contacted On** 01-22-2014 15:26:00 **Agency** Biloxi Police Department **Contact Name** 2901 **Phone** 228-392-0641  
at Irish Hill Dr.

**Updated** 01/22/2014 15:39:17 **by** Louis Rosenblatt **Dept** Signals **IT+** .Other Failure  
Status changed to Dispatched for Bradley Houck ETA of: 16:39

**Closed** 01/22/2014 16:27:00 **by** Louis Rosenblatt **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 01/22/2014 16:25:00 Equipment Type: N/A Action Taken: NTF - UTD

**The Signal Supervisor reported that Maintenance of Way was working on the approach circuit at the time of the report. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC  
Notification Sent 01/22/2014 16:27:00

**Updated** 01/22/2014 16:29:32 **by** Max Todd **Dept** PSCC **IT+**  
**Contacted On** 01-22-2014 16:28:00 **Agency** Biloxi Police Department **Contact Name** 2317 **Phone** 228-392-0641  
at Irish Hill Dr.

---

**Log#** [6379661](#)    **Status** Closed    **Entered** 11-25-2013 10:38:10    **by** Wilburn, Marion    **Type** .Other Failure  
**Supv** Merritt, D    **Reg SO**    **Div** AT    **Sub** NM    **IRI** 0    **Milepost** 000 730.3    **Block** 2763  
**Section** 3090-Ocean Springs    **Asset** VETERANS AVE - BILOXI MS    **AssetNum** 340207U    **Maintainer** Stanfill, M O - *ETA: 11:10*

**Description** 11/25/2013 10:38:11    **by** Marion Wilburn    **Dept** Signals    **IT+** Unknown  
Smarts alert notification for njax-asever-04.dmz.csxr(340207U). Fault detected - sigOSStCsAlarm\_000-730.29-340207U-002 ESCALATED:ACT FAIL - \*\*WARNING TIME TK1: 17 - SHORT WARNING - TCIS:1 at Veterans Ave - Biloxi MS 11/25/2013 09:48:15 (MP:000-730.29, DOT:340207U) [ 1 at ]

**Updated** 11/25/2013 10:46:26    **by** Marion Wilburn    **Dept** Signals    **IT+** .Other Failure  
1038 HRS PLEASE INFORM MAINTAINER CROSSING IS BEING PROTECTED AS ACTIVATION FAILURE.  
Notification Sent to -Signal Control Center - Atlanta at 11/25/2013 10:46:26 Asset: VETERANS AVE - BILOXI MS  
Status Changed To: Out Of Service PCC Notification Sent 11/25/2013 10:46:26

**Updated** 11/25/2013 10:49:03    **by** Max Todd    **Dept** PSCC    **IT+**  
**Contacted On** 11-25-2013 10:48:00 **Agency** Biloxi Police Department **Contact Name** 3293 **Phone** 228-392-0641  
at Irish Hill Dr.

**Updated** 11/25/2013 11:00:34    **by** Bruce McVey    **Dept** Signals    **IT+** .Other Failure  
Status changed to Dispatched for Michael Stanfill ETA of: 11:10

**Closed** 11/25/2013 11:21:39    **by** Bruce McVey    **Dept** Signals    **IT+** .Other Failure  
Incident Resolved: 11/25/2013 11:21:00 Equipment Type: Other - explain Action Taken: Other - explain

**Employee:** M. Stanfill

- train stilling still on the approach, then started, speedingg up over the xing , det at 10, at xing at 12 MPH....

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC  
Notification Sent 11/25/2013 11:21:39

**Updated** 11/25/2013 11:27:46    **by** Max Todd    **Dept** PSCC    **IT+**  
**Contacted On** 11-25-2013 11:27:00 **Agency** Biloxi Police Department **Contact Name** 308 **Phone** 228-392-0641  
at Irish Hill Dr.

**Updated** 11/25/2013 12:06:21    **by** Joseph Williams    **Dept** Signals    **IT+** .Other Failure  
Smarts alert notification for njax-asever-04.dmz.csxr(340207U). Fault detected - sigOSStCsAlarm\_000-730.29-340207U-002 CLEARED:WARNING TIME NORMAL TK1 - TCIS:5 at Veterans Ave - Biloxi MS 11/25/2013 11:37:49 (MP:000-730.29, DOT:340207U)

**Closed** 11/25/2013 12:42:59    **by** Bruce McVey    **Dept** Signals    **IT+** .Other Failure  
Incident Resolved: 11/25/2013 12:42:00 Equipment Type: Other - explain Action Taken: Other - explain CLOSED  
Operational Checks Performed

---

**Log#** [6316257](#)    **Status** Closed    **Entered** 10-07-2013 04:48:48    **by** Belkot, Paul    **Type** .Other Failure  
**Supv** Merritt, D    **Reg SO**    **Div** AT    **Sub** NM    **IRI** 0    **Milepost** 000 730.3    **Block** 2763  
**Section** 3090-Ocean Springs    **Asset** VETERANS AVE - BILOXI MS    **AssetNum** 340207U    **Maintainer** Stanfill, M O - *ETA: 06:30*

**Description** 10/07/2013 04:48:48    **by** Paul Belkot    **Dept** Signals    **IT+** Unknown  
Smarts alert notification for njax-asever-04.dmz.csxr(340207U). Fault detected - sigOSStCsAlarm\_000-730.29-340207U-002 ESCALATED:ACT FAIL - \*\*WARNING TIME TK1: 16 - SHORT WARNING - TCIS:1 at Veterans Ave - Biloxi MS 10/07/2013 04:31:51 (MP:000-730.29, DOT:340207U) [ 1 at ]

**Updated** 10/07/2013 04:55:35    **by** Paul Belkot    **Dept** Signals    **IT+** .Other Failure  
Smarts alert notification for njax-asever-04.dmz.csxr(340207U). Fault detected - sigOSStCsAlarm\_000-730.29-340207U-002 ESCALATED:ACT FAIL - \*\*WARNING TIME TK1: 16 - SHORT WARNING - TCIS:1 at Veterans Ave - Biloxi MS 10/07/2013 04:31:51 (MP:000-730.29, DOT:340207U) [ 1 at ]. AA disp advised to protect crossing

as a activation failure, disp initials MSC. LAST TRAIN IN AREA WAS X60905 REPORTED NO EXCEPTIONS, PER DISP....X60905 WAS MEETING LOCAL IN AREA. SENT NOTIFICATION TO ESS ATLANTA DIV., PLEASE CALL MTR. Notification Sent to -Signal Control Center - Atlanta at 10/07/2013 04:55:35 Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification Sent 10/07/2013 04:55:35

**Updated** 10/07/2013 05:00:21 **by** Jerry Rockhill **Dept** Signals **IT+** .Other Failure  
Status changed to Dispatched for Michael Stanfill ETA of: 06:30

**Updated** 10/07/2013 05:10:14 **by** Jerry Rockhill **Dept** Signals **IT+** .Other Failure  
event log shows train meet at beauvoir....sb train x60905 was down mainline and m72606 was nb out of siding at time of smarts alarm....

**Updated** 10/07/2013 05:25:29 **by** Alison Obrien **Dept** PSCC **IT+**  
**Contacted On** 10-07-2013 05:24:00 **Agency** Biloxi Police Department **Contact Name** Jerry **Phone** 228-392-0641  
@ Railroad Street

**Updated** 10/07/2013 06:12:05 **by** Sean Gaspar **Dept** Signals **IT+** .Other Failure  
Smarts alert notification for njax-aserver-04.dmz.csxr(340207U). Fault detected - sigOSTCsAlarm\_000-730.29-340207U-002 CLEARED:WARNING TIME NORMAL TK1 - TCIS:5 at Veterans Ave - Biloxi MS 10/07/2013 06:08:09 (MP:000-730.29, DOT:340207U)

**Updated** 10/07/2013 06:35:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .Other Failure  
ETA time reached Status changed to Active

**Updated** 10/07/2013 07:44:18 **by** Bruce McVey **Dept** Signals **IT+** .Other Failure  
onsite

**Updated** 10/07/2013 09:14:24 **by** Bruce McVey **Dept** Signals **IT+** .Other Failure  
Mtr onsite-to see train thru xing.

**Updated** 10/07/2013 11:17:11 **by** Bruce McVey **Dept** Signals **IT+** .Other Failure  
Mtr onsite-to see train thru xing

**Closed** 10/07/2013 11:24:29 **by** Bruce McVey **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 10/07/2013 11:24:00 Equipment Type: N/A Action Taken: Train/Cars cleared circuit

**Employee:** M. Stanfill

- train meet (local was the nb comming out of siding).... hit 22mph comming out ....

Did OP Checks, Back/released to AA disp. Watched SB train thru crossing, no exceptions. down the main

Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC  
Notification Sent 10/07/2013 11:24:29

**Updated** 10/07/2013 11:27:08 **by** Max Todd **Dept** PSCC **IT+**  
**Contacted On** 10-07-2013 11:26:00 **Agency** Biloxi Police Department **Contact Name** 2922 **Phone** 228-392-0641  
at Irish Hill Dr.

---

**Log#** [6209128](#) **Status** Closed **Entered** 07-13-2013 19:46:02 **by** Gaspar, Sean **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.3 **Block** 2763  
**Section** 3090-Ocean Springs **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Stanfill, M O - ETA: 20:34

**Description** 07/13/2013 19:46:02 **by** Sean Gaspar **Dept** Signals **IT+** Unknown

**Updated** 07/13/2013 19:52:06 **by** Sean Gaspar **Dept** Signals **IT+** .False or partial activation reported  
xing is activated w/ no train. dot provided. disp protecting w/ f/p. Notification Sent to -Signal Control Center - Atlanta at 07/13/2013 19:52:06 Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification Sent 07/13/2013 19:52:06

**Updated** 07/13/2013 19:54:18 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported



Status changed to Dispatched for Michael Stanfill ETA of: 20:34

**Updated** 07/13/2013 19:54:53 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** **Agency** local police **Contact Name** jackie **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 07/13/2013 20:35:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 07/13/2013 20:39:02 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 07/13/2013 20:35:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended  
Mntr reports COA. Performed op checks, no exceptions noted. Turned crossing backover to disp. Believe crossing was mistaken for McDonnell Ave(had an issue), which is next to Veterans.  
Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC Notification  
Sent 07/13/2013 20:39:02

**Updated** 07/13/2013 20:44:38 **by** Jesse Gansen **Dept** PSCC **IT+**  
**Contacted On** 07-13-2013 20:43:00 **Agency** Biloxi Police **Contact Name** 366 **Phone** 228-392-0641

---

**Log#** [6137154](#) **Status** Closed **Entered** 05-23-2013 16:30:44 **by** Mercado, Wito **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.3 **Block** 2763

**Section** 3090-Ocean Springs **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Houck, B - ETA: 18:56

**Description** 05/23/2013 16:30:44 **by** Jesuito Mercado **Dept** Signals **IT+** Unknown

**Updated** 05/23/2013 16:33:45 **by** Jesuito Mercado **Dept** Signals **IT+** .False or partial activation reported  
1630hr Outside party reports crossing is activating intermittently with no trains present... Notification Sent to -Signal Control Center -  
Atlanta at 05/23/2013 16:33:45 Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification Sent  
05/23/2013 16:33:45

**Updated** 05/23/2013 16:39:18 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported

The AA Dispatcher is protecting the crossing with a **Type 2 False / Partial Activation Message# 23209**. LVR

**Updated** 05/23/2013 16:45:39 **by** Sean Reid **Dept** PSCC **IT+**  
**Contacted On** 05-23-2013 16:44:00 **Agency** Biloxi Police Department **Contact Name** Disp # 2901 **Phone** 228-392-0641  
@ Irish Hill Dr.

**Updated** 05/23/2013 17:26:59 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Bradley Houck ETA of: 18:56

**Updated** 05/23/2013 19:00:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 05/23/2013 19:48:50 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 05/23/2013 19:48:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended

**The Signal Maintainer reported that the crossing was working when he got there. He reviewed the status log and determined that there was a normal train move from 15:49 to 15:53 through the crossing. There were no errors on the unit. All voltages and grounds are good. All track readings are good. He cleared the status log. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC Notification Sent 05/23/2013 19:48:50

**Updated** 05/23/2013 19:56:08 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** 05-23-2013 19:56:00 **Agency** Biloxi Police Department **Contact Name** 2901 **Phone** 228-392-0641

---

**Log#** [6093841](#) **Status** Closed **Entered** 04-24-2013 20:13:09 **by** Oglesby, Brad **Type** .Other Failure

Supv Merritt, D Reg SO Div AT Sub NM IRI 0 Milepost 000 730.3 Block 2763

Section 3090-Ocean Springs Asset VETERANS AVE - BILOXI MS AssetNum 340207U Maintainer Patterson Jr, L D - ETA: 23:03

**Description** 04/24/2013 20:13:09 by Brad Oglesby Dept Signals IT+ Unknown  
Smarts alert notification for nind2008app.dmz(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-002 ESCALATED:ACT FAIL - \*\*WARNING TIME TK1: 16 - SHORT WARNING - TCIS:1 at Veterans Ave - Biloxi MS 04/24/2013 20:11:32 (MP:000-730.29, DOT:340207U) [ 1 at ]

**Updated** 04/24/2013 20:19:13 by Brad Oglesby Dept Signals IT+ .Other Failure  
2015 ADVISED THE AA DISPATCHER(INITIALS-WJS) TO PROVIDE PROTECTION ON THE CROSSING AS PER ACTIVATION FAILURE STANDARD. A SIGNAL MAINTAINER NEEDS DISPATCHED TO INVESTIGATE THIS TCIS SMARTS PRIORITY 1 ALARM. THE GCP4K UNIT HAS DETECTED AN ACTIVATION FAILURE OCCURRENCE(SHORT WARNING TIME) AT THE CROSSING. NORTHBOUND TRAIN# S61424 WAS WORKING IN THE AREA ON THE MAIN TRACK AT SAME TIME THIS ALARM WAS RECEIVED. Notification Sent to -Signal Control Center - Atlanta at 04/24/2013 20:19:13 Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification Sent 04/24/2013 20:19:13

**Updated** 04/24/2013 20:36:57 by Brad Oglesby Dept Signals IT+ .Other Failure  
Smarts alert notification for nind2008app.dmz(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-002 CLEARED:WARNING TIME NORMAL TK1 - TCIS:5 at Veterans Ave - Biloxi MS 04/24/2013 20:32:39 (MP:000-730.29, DOT:340207U)

**Updated** 04/24/2013 20:46:05 by Kihron Bristol Dept PSCC IT+  
**Contacted On** 04-24-2013 20:45:00 Agency Biloxi Police Department Contact Name 366 Phone 228-392-0641 Irish Hill Dr

**Updated** 04/24/2013 21:19:35 by Louis Rosenblatt Dept Signals IT+ .Other Failure

A message was left on the Signal Supervisor's mobile phone.

**Updated** 04/24/2013 21:33:04 by Louis Rosenblatt Dept Signals IT+ .Other Failure  
Status changed to Dispatched for Leonard Patterson Jr ETA of: 23:03

**Updated** 04/24/2013 23:05:00 by TCIS AUTOMATION Dept Signals IT+ .Other Failure  
ETA time reached Status changed to Active

**Closed** 04/24/2013 23:28:50 by Leonard Patterson Jr Dept Signals IT+ .Other Failure  
Incident Resolved: 04/24/2013 23:28:00 Equipment Type: Other - explain Action Taken: Other - explain Diagnostic Log & Train Log matches information of train switching. GCWD design in O.S. can generate logic of "Short Warning Time" with switching movements. Crossing found to be working as designed. Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC Notification Sent 04/24/2013 23:28:50

**Updated** 04/24/2013 23:34:06 by Gloria Andino Dept PSCC IT+  
**Contacted On** 04-24-2013 23:34:00 Agency Biloxi Police Department Contact Name 392 Phone 228-392-0641

---

**Log#** [6028374](#) **Status** Closed **Entered** 03-12-2013 20:37:34 by Oglesby, Brad **Type** .Other Failure

Supv Merritt, D Reg SO Div AT Sub NM IRI 0 Milepost 000 730.3 Block 2763

Section 3090-Ocean Springs Asset VETERANS AVE - BILOXI MS AssetNum 340207U Maintainer Houck, B - ETA: 22:22

**Description** 03/12/2013 20:37:34 by Brad Oglesby Dept Signals IT+ Unknown  
Smarts alert notification for nind2008app.dmz(340207U). Fault detected - sigOStCsAlarm\_000-730.29-340207U-002 ESCALATED:ACT FAIL - \*\*WARNING TIME TK1: 18 - SHORT WARNING - TCIS:1 at Veterans Ave - Biloxi MS 03/12/2013 20:33:36 (MP:000-730.29, DOT:340207U) [ 1 at ]

**Updated** 03/12/2013 20:47:04 by Brad Oglesby Dept Signals IT+ .Other Failure  
2044 ADVISED THE ATLANTA CHIEF(INITIALS-SAF) TO PROVIDE PROTECTION ON THE CROSSING AS PER ACTIVATION FAILURE STANDARD. A SIGNAL MAINTAINER NEEDS DISPATCHED TO INVESTIGATE THIS TCIS SMARTS PRIORITY 1 ALARM. THE GCP4K UNIT HAS DETECTED AN ACTIVATION FAILURE OCCURRENCE(SHORT WARNING TIME ON #1 TRACK) AT THE CROSSING. TRAIN#S Q60911(SITTING IN THE SIDING) AND S61212(WORKING ON THE MAIN TRACK) WERE MEETING IN THE AREA AT THE SAME



TIME THIS ALARM WAS RECEIVED. Notification Sent to -Signal Control Center - Atlanta at 03/12/2013 20:47:04  
Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification Sent 03/12/2013  
20:47:04

**Updated** 03/12/2013 21:19:10 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** 03-12-2013 20:48:00 **Agency** Biloxi Police Department **Contact Name** 3248 **Phone** 228-392-0641  
@ Irish Hill Dr.

**Updated** 03/12/2013 21:22:27 **by** TCIS AUTOMATION **Dept** Signals **IT+** .Other Failure  
Status changed to Dispatched for ETA of: 22:22

**Updated** 03/12/2013 22:25:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .Other Failure  
ETA time reached Status changed to Active

**Closed** 03/12/2013 23:22:34 **by** Louis Rosenblatt **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 03/12/2013 22:46:00 Equipment Type: N/A Action Taken: Train/Cars cleared circuit

**The Signal Maintainer reported that the crossing is working as intended. There was a meet going on at the time of the alarm. S61212 Northbound was on the Main just South of NE Beauvoir waiting on Q60911 Southbound to clear the OS. The island circuit for Veterans Avenue is inside the OS at NE Beauvoir. S61212 did not have a detection speed because the train occupied the island after being stopped on the approach of Veterans Avenue. S61212's movement caused the short warning time.**

**The Signal Maintainer made Operational Checks and watched Q61212 Northbound through the crossing with exceptions taken. The Crossing is Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC  
Notification Sent 03/12/2013 23:22:34

**Updated** 03/12/2013 23:33:50 **by** Robert Clendening **Dept** PSCC **IT+**  
**Contacted On** 03-12-2013 23:33:00 **Agency** Biloxi Police Department **Contact Name** Zorich **Phone** 228-392-0641

---

**Log#** [5890280](#) **Status** Closed **Entered** 12-05-2012 15:39:38 **by** Mercado, Wito **Type** .False or partial activation reported

**Supv** Merritt, D **Reg SO** **Div** AT **Sub** NM **IRI** **Milepost** 000 730.3 **Block** 2763

**Section** 3090-Ocean Springs **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Houck, B - ETA: 17:03

**Description** 12/05/2012 15:42:21 **by** Jesuito Mercado **Dept** Signals **IT+** .False or partial activation reported  
1540hr Local pd reports crossing is activated with no trains present... Notification Sent to -Signal Control Center - Atlanta at  
12/05/2012 15:42:21 Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification Sent  
12/05/2012 15:42:21

**Updated** 12/05/2012 16:03:54 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** **Agency** BILOXI PD **Contact Name** Oper 2901 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 12/05/2012 17:06:02 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Mntr doing work on Rodenberg Crossing, next to Veterans. Had to replace start at Rodenberg. Would have caused crossing to activate while working. Mntr en-route to test and clear crossing.

**Closed** 12/05/2012 17:52:30 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 12/05/2012 17:47:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended  
Suspected Reason: Other electrical  
Mntr troubleshooting Rodenberg crossing at time of incident causing crossing to activate. Mntr performed op checks,  
Veterans crossing working as intended, turned crossing backover to disp.  
Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC Notification Sent  
12/05/2012 17:52:30

**Updated** 12/05/2012 17:53:54 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** 12-05-2012 17:53:00 **Agency** BILOXI PD **Contact Name** Angela **Phone** 228-392-0641

---

**Log#** [5868816](#) **Status** Closed **Entered** 11-18-2012 08:13:21 **by** Gaspar, Sean **Type** .Other Failure  
**Supv** Merritt, D **Reg SO** **Div** AT **Sub** NM **IRI** **Milepost** 000 730.3 **Block** 2763  
**Section** 3090-Ocean Springs **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Broadway, J L - ETA: 11:05  
**Description** 11/18/2012 08:13:21 **by** Sean Gaspar **Dept** Signals **IT+** Unknown  
Smarts alert notification for nind2008app.dmz(340207U). Fault detected - sigOSStCsAlarm\_000-730.29-340207U-002  
ESCALATED:ACT FAIL - \*\*WARNING TIME TK1: 19 - SHORT WARNING - TCIS:1 at Veterans Ave - Biloxi MS  
11/18/2012 08:03:43 (MP:000-730.29, DOT:340207U) [ 1 at ]

**Updated** 11/18/2012 08:16:29 **by** Sean Gaspar **Dept** Signals **IT+** .Other Failure  
Red 1 Notify dispatcher to protect the crossing with an Activation Failure or False Activation. Notify maintainer. Type  
of dispatcher protection must be communicated to the maintainer. Must be investigated immediately. disp protecting  
w/ act/failure as per smarts. disp reports train meet at approx time of alarm. Notification Sent to -Signal Control  
Center - Atlanta at 11/18/2012 08:16:29 Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service  
PCC Notification Sent 11/18/2012 08:16:29

**Updated** 11/18/2012 08:48:48 **by** Bruce McVey **Dept** Signals **IT+** .Other Failure  
Meet happened at time of incident, Q601-16 SB out of the siding at SE Beauvoir and Q602-18 NB on the main.

**Updated** 11/18/2012 08:49:10 **by** Myrtie Hackney **Dept** PSCC **IT+**  
**Contacted On** 11-18-2012 08:48:00 **Agency** Biloxi Police Department **Contact Name** Ramona **Phone** 228-392-0641  
@ Irish Hill Dr

**Updated** 11/18/2012 11:57:47 **by** Sean Gaspar **Dept** Signals **IT+** .Other Failure  
Smarts alert notification for nind2008app.dmz(340207U). Fault detected - sigOSStCsAlarm\_000-730.29-340207U-002  
CLEARED:WARNING TIME NORMAL TK1 - TCIS:5 at Veterans Ave - Biloxi MS 11/18/2012 11:57:05 (MP:000-  
730.29, DOT:340207U)

**Closed** 11/18/2012 12:44:25 **by** Joshua Broadway **Dept** Signals **IT+** .Other Failure  
Incident Resolved: 11/18/2012 12:37:00 Equipment Type: Crossing case equipment Action Taken: Clear on Arrival -  
Proper Operation Verified Suspected Reason: Other department Crossing is located in OS at N. Beauvoir, this is a  
recurring event when N-bound train is waiting on S-bound and then accelerates through the crossing. Verified  
operation with a similar train move, cause is trains accelerating in approach of road crossing. Operational Checks  
Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC Notification Sent 11/18/2012  
12:44:25

**Updated** 11/18/2012 12:46:36 **by** Virgil Adkins **Dept** PSCC **IT+**  
**Contacted On** 11-18-2012 12:45:00 **Agency** Biloxi Police Department **Contact Name** 317 **Phone** 228-392-0641  
@ Irish Hill Dr

---

**Log#** [5842248](#) **Status** Closed **Entered** 10-29-2012 20:30:44 **by** Tyo, Mark **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg SO** **Div** AT **Sub** NM **IRI** **Milepost** 000 730.3 **Block** 2763  
**Section** 3090-Ocean Springs **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Stanfill, M O - ETA: 23:25  
**Description** 10/29/2012 20:36:39 **by** Mark Tyo **Dept** Signals **IT+** .False or partial activation reported  
Police report crossing activated no trains. DOT # was given. Disp is protecting. Notification Sent to -Signal Control Center -  
Atlanta at 10/29/2012 20:36:39 Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification  
Sent 10/29/2012 20:36:39

**Updated** 10/29/2012 20:38:48 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi PD **Contact Name** 3236 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 10/29/2012 20:43:38 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported

The AA Dispatcher is protecting the crossing with a **Type 2 False / Partial Activation Message# 28964**. LVR

**Updated** 10/29/2012 22:56:22 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported

**Update** - The Signal Maintainer is still working on [Incident 5842194](#). LVR

**Closed** 10/30/2012 02:46:00 by Matthew Kite Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 10/30/2012 02:43:00 Equipment Type: Crossing case equipment Action Taken: Replaced card(s)  
Suspected Reason: Equipment failure  
Mntr replace trk #2 trk module, calibrated, timed a NB and SB train through crossing. Performed op checks, turned crossing backover to disp.  
Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC Notification Sent 10/30/2012 02:46:00

**Updated** 10/30/2012 02:58:05 by Christopher Horman Dept PSCC IT+  
**Contacted On** 10-30-2012 02:54:00 Agency Biloxi PD Contact Name Disp. 352 Phone 228-392-0641

---

**Log#** [5707547](#) **Status** Closed **Entered** 07-24-2012 06:13:43 by Belkot, Paul **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 730.3 **Block** 2763  
**Section** 3090-Ocean Springs **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Stanfill, M O - ETA: 07:39  
**Description** 07/24/2012 06:17:53 by Paul Belkot Dept Signals IT+ .False or partial activation reported  
GATES DOWN NO TRAIN IN AREA PER BILOXI MS PD. AA DISP ADVISED TO PROTECT CROSSING AS A FALSE PARTIAL ACTIVATION, DISP INITIALS SJR. SENT NOTIFICATION TO ESS ATLANTA DIV., PLEASE CALL MTR. Notification Sent to -Signal Control Center - Atlanta at 07/24/2012 06:17:53 Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification Sent 07/24/2012 06:17:53

**Updated** 07/24/2012 06:17:54 by Paul Belkot Dept Signals IT+ .False or partial activation reported  
A email notification for Multi Failure Count (MFC) asset VETERANS AVE - BILOXI MS (3) has been sent to the following:  
Terrence Smale II  
John Parr

**Updated** 07/24/2012 06:27:12 by Jesse Gansen Dept PSCC IT+  
**Contacted On** 07-24-2012 06:27:00 Agency BILOXI MS PD Contact Name OPERATOR 352 Phone 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Closed** 07/24/2012 15:05:56 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 07/24/2012 14:30:00 Equipment Type: Crossing case equipment Action Taken: Replaced card(s) Suspected Reason: Equipment failure  
**The Signal Maintainer replaced the #2 Track Module and calibrated the GCP 4000 unit. He watched two Northbound trains and one Southbound train through the crossing. Warning times were good. The Crossing was placed Back In Service with the Dispatcher. LVR**  
Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC Notification Sent 07/24/2012 15:05:56

**Updated** 07/24/2012 15:13:18 by Jerome Shepard Dept PSCC IT+  
**Contacted On** 07-24-2012 15:13:00 Agency BILOXI MS PD Contact Name Operator Miller Phone 228-392-0641

---

**Log#** [5694174](#) **Status** Closed **Entered** 07-15-2012 05:50:04 by Tyo, Mark **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 730.3 **Block** 2763  
**Section** 3090-Ocean Springs **Asset** VETERANS AVE - BILOXI MS **AssetNum** 340207U **Maintainer** Houck, B - ETA: 07:08  
**Description** 07/15/2012 05:54:05 by Mark Tyo Dept Signals IT+ .False or partial activation reported  
Police report both crossings activated. DOT #'s were given. Disp is protecting. Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification Sent 07/15/2012 05:54:05

**Updated** 07/15/2012 05:54:19 by Mark Tyo Dept Signals IT+ .False or partial activation reported  
New Asset Added: 340206M - MCDONNEL AVE

**Updated** 07/15/2012 05:54:24 by Mark Tyo Dept Signals IT+ .False or partial activation reported  
PCC Notification Sent 07/15/2012 05:54:24 Asset: 340206M - MCDONNEL AVE Status Changed To: Out of Service

**Updated** 07/15/2012 05:54:34 by Mark Tyo Dept Signals IT+ .False or partial activation reported

. Notification Sent to -Signal Control Center - Atlanta at 07/15/2012 05:54:34

**Updated** 07/15/2012 05:57:21      **by** Daniel Johnson      **Dept** PSCC      **IT+**  
**Contacted On**                      **Agency** Biloxi PD      **Contact Name** 1955      **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 07/15/2012 06:08:15      **by** Jerry Rockhill      **Dept** Signals      **IT+** .False or partial activation reported  
0607 mtr reports heavy rain with lightning in area at time of call...mtr accepted in field on another call nearby...mtr waiting for storm to pass...

**Closed** 07/15/2012 08:34:44      **by** William OConnell      **Dept** Signals      **IT+** .False or partial activation reported  
Incident Resolved: 07/15/2012 08:34:00 Equipment Type: Other - explain Action Taken: Other - explain Suspected Reason: Lightning Lightning strike blew out arrestors and equipment at both crossings... Arrestors and equipment replaced, both crossings tested and working as intended.... Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC Notification Sent 07/15/2012 08:34:44 Asset: MCDONNEL AVE Status Changed To: In Service PCC Notification Sent 07/15/2012 08:34:44

**Updated** 07/15/2012 08:40:45      **by** Daniel Johnson      **Dept** PSCC      **IT+**  
**Contacted On** 07-15-2012 08:40:00 **Agency** Biloxi PD      **Contact Name** brenda      **Phone** 228-392-0641

---

**Log#** [5686250](#)      **Status** Closed      **Entered** 07-10-2012 07:49:00      **by** Wilburn, Marion      **Type** .False or partial activation reported

**Supv** Merritt, D      **Reg** SO      **Div** AT      **Sub** NM      **IRI**      **Milepost** 000 730.3      **Block** 2763

**Section** 3090-Ocean Springs      **Asset** VETERANS AVE - BILOXI MS      **AssetNum** 340207U      **Maintainer** Stanfill, M O - ETA: 08:59

**Description** 07/10/2012 07:53:27      **by** Marion Wilburn      **Dept** Signals      **IT+** .False or partial activation reported  
0749 Hrs police dept reported gates down with no train present. AA-dispatcher has been informed to protect crossing as false activation. Asset: VETERANS AVE - BILOXI MS Status Changed To: Out Of Service PCC Notification Sent 07/10/2012 07:53:27

**Updated** 07/10/2012 07:54:38      **by** Clifford Keen      **Dept** PSCC      **IT+**  
**Contacted On**                      **Agency** Police dept      **Contact Name** Ms. Lola      **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Closed** 07/10/2012 11:25:35      **by** Bruce McVey      **Dept** Signals      **IT+** .False or partial activation reported  
Incident Resolved: 07/10/2012 11:24:00 Equipment Type: Other - explain Action Taken: Other - explain Suspected Reason: Lightning

**Employee:** M. Stanfill

- main side track converter hit by lighting,locked in standby, ordered part to replace.

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: VETERANS AVE - BILOXI MS Status Changed To: In Service PCC Notification Sent 07/10/2012 11:25:35

**Updated** 07/10/2012 11:31:11      **by** Alison Obrien      **Dept** PSCC      **IT+**  
**Contacted On** 07-10-2012 11:30:00 **Agency** Police dept      **Contact Name** Alexas      **Phone** 228-392-0641

Page Execution Time: 002.95 seconds

**Iris Street**

**DOT Crossing #: 340208B**

**RR Milepost #: 730.83**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 8

Status All AssetType All RootAssetType All Department Signals AssetNum 340208B

---

|   |                      |  |   |   |                           |                   |
|---|----------------------|--|---|---|---------------------------|-------------------|
| <b>Log#</b> <a href="#">7239707</a>   | <b>Status</b> Closed | <b>Entered</b> 07-19-2015 20:12:46     | <b>by</b> Hillard, James                  | <b>Type</b> .False or partial activation reported |                           |                   |
| <b>Supv</b> Merritt, D  | <b>Reg</b> SO        | <b>Div</b> AT                          | <b>Sub</b> NM                             | <b>IRI</b> 0                                      | <b>Milepost</b> 000 730.8 | <b>Block</b> 2763 |
| <b>Section</b> 3089-7M17  | <b>Asset</b> IRIS ST | <b>AssetNum</b> 340208B                | <b>Maintainer</b> Mannion, R - ETA: 22:00 |   |                           |                   |
| <b>Description</b> 07/19/2015 20:12:46  |                      | <b>by</b> James Hillard                | <b>Dept</b> Signals                       | <b>IT+</b> Unknown                                |                           |                   |
| <b>Updated</b> 07/19/2015 20:16:17  |                      | <b>by</b> James Hillard                | <b>Dept</b> Signals                       | <b>IT+</b> .False or partial activation reported  |                           |                   |
| OSP reports that the crossing is activated with no trains. DOT# provided. Dispatcher protecting with false/partial message# 47605 Notification Sent to -Signal Control Center - Atlanta at 07/19/2015 20:16:17 Asset: IRIS ST Status Changed To: Out Of Service PCC Notification Sent 07/19/2015 20:16:17   |                      |  |   |   |                           |                   |
| <b>Updated</b> 07/19/2015 20:20:11  |                      | <b>by</b> Kiwana Tompkins              | <b>Dept</b> PSCC                          | <b>IT+</b>  |                           |                   |
| <b>Contacted On</b> 07-19-2015 20:18:00   |                      | <b>Agency</b> Biloxi Police Department | <b>Contact Name</b> Dispatcher Chris      | <b>Phone</b> 228-392-0641                         |                           |                   |
| Greater Ave   |                      |  |   |   |                           |                   |
| <b>Updated</b> 07/19/2015 20:30:23  |                      | <b>by</b> Matthew Kite                 | <b>Dept</b> Signals                       | <b>IT+</b> .False or partial activation reported  |                           |                   |
| Status changed to Dispatched for Roger Mannion ETA of: 22:00  |                      |  |   |   |                           |                   |
| <b>Updated</b> 07/19/2015 22:05:00  |                      | <b>by</b> TCIS AUTOMATION              | <b>Dept</b> Signals                       | <b>IT+</b> .False or partial activation reported  |                           |                   |
| ETA time reached Status changed to Active   |                      |  |   |   |                           |                   |
| <b>Updated</b> 07/19/2015 23:55:20  |                      | <b>by</b> Roger Mannion                | <b>Dept</b> Signals                       | <b>IT+</b> .False or partial activation reported  |                           |                   |
| Incident Resolved: 07/19/2015 23:55:00 Equipment Type: Power/Batteries Action Taken: Charger Repaired/Replaced B-14 Charger was fried. also AC tranquell was hit, which is probably what caused charger to bake. Other chargers were working as intended. Checked crossing gave back to dispatcher at 2355 with message number 47772. Operational Checks Performed Asset: IRIS ST Status Changed To: In Service PCC Notification Sent 07/19/2015 23:55:20 |                      |  |   |   |                           |                   |
| <b>Closed</b> 07/19/2015 23:59:50   |                      | <b>by</b> Jerry Rockhill               | <b>Dept</b> Signals                       | <b>IT+</b> .False or partial activation reported  |                           |                   |
| Incident Resolved: 07/19/2015 23:55:00 Equipment Type: Power/Batteries Action Taken: Charger Repaired/Replaced . Operational Checks Performed   |                      |  |   |   |                           |                   |
| <b>Updated</b> 07/20/2015 00:02:12  |                      | <b>by</b> Michele Schwartz             | <b>Dept</b> PSCC                          | <b>IT+</b>  |                           |                   |
| <b>Contacted On</b> 07-20-2015 00:01:00   |                      | <b>Agency</b> Biloxi Police Department | <b>Contact Name</b> Brandy                | <b>Phone</b> 228-392-0641                         |                           |                   |
| Greater Ave   |                      |  |   |   |                           |                   |

---

|  |                      |  |   |   |                           |                   |
|--|----------------------|--|---|---|---------------------------|-------------------|
| <b>Log#</b> <a href="#">6696701</a>  | <b>Status</b> Closed | <b>Entered</b> 07-07-2014 20:23:14     | <b>by</b> Carter, Jake                    | <b>Type</b> .False or partial activation reported |                           |                   |
| <b>Supv</b> Merritt, D   | <b>Reg</b> SO        | <b>Div</b> AT                          | <b>Sub</b> NM                             | <b>IRI</b> 0                                      | <b>Milepost</b> 000 730.8 | <b>Block</b> 2763 |
| <b>Section</b> 3089-Gulfport   | <b>Asset</b> IRIS ST | <b>AssetNum</b> 340208B                | <b>Maintainer</b> Mannion, R - ETA: 22:59 |   |                           |                   |
| <b>Description</b> 07/07/2014 20:23:14   |                      | <b>by</b> Jake Carter                  | <b>Dept</b> Signals                       | <b>IT+</b> Unknown                                |                           |                   |
| <b>Updated</b> 07/07/2014 20:27:23   |                      | <b>by</b> Jake Carter                  | <b>Dept</b> Signals                       | <b>IT+</b> .False or partial activation reported  |                           |                   |
| Local Pd reports xng is activated, w/no trains present;disp is protecting as f/p Notification Sent to -Signal Control Center - Atlanta at 07/07/2014 20:27:23 Asset: IRIS ST Status Changed To: Out Of Service PCC Notification Sent 07/07/2014 20:27:23 |                      |  |   |   |                           |                   |
| <b>Updated</b> 07/07/2014 20:30:38   |                      | <b>by</b> Jackie McGuirt               | <b>Dept</b> PSCC                          | <b>IT+</b>  |                           |                   |
| <b>Contacted On</b> 07-07-2014 20:30:00  |                      | <b>Agency</b> Biloxi Police Department | <b>Contact Name</b> Oper: Tiffany         | <b>Phone</b> 228-392-0641                         |                           |                   |
| <b>Updated</b> 07/07/2014 20:59:52   |                      | <b>by</b> Louis Rosenblatt             | <b>Dept</b> Signals                       | <b>IT+</b> .False or partial activation reported  |                           |                   |
| Status changed to Dispatched for Roger Mannion ETA of: 22:59   |                      |  |   |   |                           |                   |
| <b>Updated</b> 07/07/2014 23:00:00   |                      | <b>by</b> TCIS AUTOMATION              | <b>Dept</b> Signals                       | <b>IT+</b> .False or partial activation reported  |                           |                   |
| ETA time reached Status changed to Active  |                      |  |   |   |                           |                   |



**Closed** 07/07/2014 23:39:16 **by** Roger Mannion **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 07/07/2014 23:39:00 Equipment Type: N/A Action Taken: Track Occupied Train crew (572) stated they had to pick up a car in the siding and caused the crossing to activate without going through the crossing. Checked crossing and found no exceptions. Returned to dispatcher at 2338 jmr. Operational Checks Performed Asset: IRIS ST Status Changed To: In Service PCC Notification Sent 07/07/2014 23:39:16

**Updated** 07/07/2014 23:48:15 **by** Kiwana Tompkins **Dept** PSCC **IT+**  
**Contacted On** 07-07-2014 23:47:00 **Agency** Biloxi Police Department **Contact Name** Dispatcher 3297 **Phone** 228-392-0641

---

**Log#** [6368480](#) **Status** Closed **Entered** 11-16-2013 13:48:36 **by** McClure, Dale **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.8 **Block** 2763  
**Section** 3089-Gulfport **Asset** IRIS ST **AssetNum** 340208B **Maintainer** Broadway, J L - ETA: 17:44 & James Jr, G H - ETA: 16:51  
**Description** 11/16/2013 13:48:36 **by** Dale McClure **Dept** Signals **IT+** Unknown

**Updated** 11/16/2013 13:53:45 **by** Dale McClure **Dept** Signals **IT+** .False or partial activation reported  
TRUCK DRIVER REPORTED GATES PUMPING/ NO TRAINS AT THIS CROSSING. AA DISP. NOTIFIED AND INSTRUCTED TO PRTOECT AS FALSE/ PARTIAL ACTIVATION UNTIL CHECKED. NOTE: AA DISP. MAKING A TRAIN MEET AT LOCATION AND HOLDING ONE TRAIN JUST OFF THE CROSSING UNTIL COMPLETED. Asset: IRIS ST Status Changed To: Out Of Service PCC Notification Sent 11/16/2013 13:53:45

**Updated** 11/16/2013 13:58:51 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** 11-16-2013 13:58:00 **Agency** Biloxi Police Department **Contact Name** Operator 3246 **Phone** 228-392-0641  
Greater Ave

**Updated** 11/16/2013 14:30:06 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported

X179-13 was in the siding at tiem of incident.

**Updated** 11/16/2013 15:23:51 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Escalated, George James Jr ETA of: N/A

**Updated** 11/16/2013 15:24:34 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Call list exhausted. Notified Sig Sup James and NOC C&S Manager.

**Updated** 11/16/2013 16:44:43 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Joshua Broadway ETA of: 17:44

**Updated** 11/16/2013 16:45:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 11/16/2013 16:51:34 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Escalated, George James Jr ETA of: N/A

**Closed** 11/16/2013 19:23:17 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 11/16/2013 17:23:00 Equipment Type: Gate Action Taken: Damaged gate or sections-replaced/repared  
Mntr reports gate was cracked on underbelly running length of gate. Due to getting hung-up on equipment on-site, replaced. Performed op checks, turned crossing backover to disp.  
Operational Checks Performed Asset: IRIS ST Status Changed To: In Service PCC Notification Sent 11/16/2013 19:23:17

**Updated** 11/16/2013 19:38:28 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** 11-16-2013 19:38:00 **Agency** Biloxi Police Department **Contact Name** Hailey **Phone** 228-392-0641

---

**Log#** [6182071](#) **Status** Closed **Entered** 06-24-2013 03:13:29 **by** Carter, Jake **Type** -Informational  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.8 **Block** 2763  
**Section** 3089-Gulfport **Asset** IRIS ST **AssetNum** 340208B **Maintainer** Houck, B - ETA: 04:38



**Description** 06/24/2013 03:13:29 **by** Jake Carter **Dept** Signals **IT+** Unknown

**Updated** 06/24/2013 03:17:26 **by** Jake Carter **Dept** Signals **IT+** -Informational  
 Local Pd reports 1 gate is staying up at all times;disp is protecting as f/p Notification Sent to -Signal Control Center - Atlanta at 06/24/2013 03:17:26 Asset: IRIS ST Status Changed To: Out Of Service PCC Notification Sent 06/24/2013 03:17:26

**Updated** 06/24/2013 03:23:36 **by** Christopher Horman **Dept** PSCC **IT+**  
**Contacted On** 06-24-2013 03:22:00**Agency** Biloxi Police Department **Contact Name** Disp. Snider **Phone** 228-392-0641 @ Greater Street

**Updated** 06/24/2013 03:38:20 **by** Jerry Rockhill **Dept** Signals **IT+** -Informational  
 Status changed to Dispatched for Bradley Houck ETA of: 04:38

**Updated** 06/24/2013 04:40:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** -Informational  
 ETA time reached Status changed to Active

**Closed** 06/24/2013 05:33:51 **by** Jerry Rockhill **Dept** Signals **IT+** -Informational  
 Incident Resolved: 06/24/2013 05:33:00 Equipment Type: Gate mechanism Action Taken: Cleaned 0530 mtr reports cleaning power up contact in mech....op cks ok and crossing back in service with disp... Operational Checks Performed Asset: IRIS ST Status Changed To: In Service PCC Notification Sent 06/24/2013 05:33:51

**Updated** 06/24/2013 05:37:19 **by** Gloria Andino **Dept** PSCC **IT+**  
**Contacted On** 06-24-2013 05:37:00**Agency** Biloxi Police Department **Contact Name** Disp. Snider **Phone** 228-392-0641

**Log#** [5949719](#) **Status** Closed **Entered** 01-20-2013 06:23:42 **by** Rockhill, Jerry **Type** Train-vehicle collision  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 730.8 **Block** 2763  
**Section** 3089-Gulfport **Asset** IRIS ST **AssetNum** 340208B **Maintainer** Mannion, R - ETA: 09:09

**Description** 01/20/2013 06:26:10 **by** Jerry Rockhill **Dept** Signals **IT+** Train-vehicle collision  
 0625 Atl chief, aa disp, nm sub, train struck unoccupied vehicle at Iris Street mp 000 730.8.....disp protecting crossing with activation failure msg 28715.... Asset: IRIS ST Status Changed To: Out Of Service PCC Notification Sent 01/20/2013 06:26:10

**Updated** 01/20/2013 06:26:12 **by** Jerry Rockhill **Dept** Signals **IT+** Train-vehicle collision  
 Notification has been sent to the following: Vacant Vacant Danny McKenzie Jody Cox C Manager

**Updated** 01/20/2013 06:28:43 **by** Christina Martorano **Dept** PSCC **IT+**  
**Contacted On** 01-20-2013 06:28:00 **Agency** n/a **Contact Name** n/a **Phone** n/a

**Updated** 01/20/2013 07:09:02 **by** TCIS AUTOMATION **Dept** Signals **IT+** Train-vehicle collision  
 Status changed to Dispatched for ETA of: 09:09

**Updated** 01/20/2013 09:10:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Train-vehicle collision  
 ETA time reached Status changed to Active

**Closed** 01/20/2013 09:44:38 **by** Roger Mannion **Dept** Signals **IT+** Train-vehicle collision  
 Incident Resolved: 01/20/2013 09:44:00 Equipment Type: Other - explain Action Taken: Other - explain Checked crossing for damages and found none. Tested crossing for operation with no exceptions. Gave back to dispatcher at 0930. Operational Checks Performed Asset: IRIS ST Status Changed To: In Service PCC Notification Sent 01/20/2013 09:44:38

**Updated** 01/20/2013 09:47:11 **by** Christina Martorano **Dept** PSCC **IT+**  
**Contacted On** 01-20-2013 09:47:00 **Agency** n/a **Contact Name** n/a **Phone** n/a

**Log#** [5883463](#) **Status** Closed **Entered** 11-30-2012 17:12:32 **by** Gaspar, Sean **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 730.8 **Block** 2763  
**Section** 3089-Gulfport **Asset** IRIS ST **AssetNum** 340208B **Maintainer** Patterson Jr, L D - ETA: 19:55

**Description** 11/30/2012 17:16:56 **by** Sean Gaspar **Dept** Signals **IT+** .False or partial activation reported  
xing is activated w/ no train. dot provided. disp protecting w/ f/p. Notification Sent to -Signal Control Center - Atlanta at 11/30/2012  
17:16:56 Asset: IRIS ST Status Changed To: Out Of Service PCC Notification Sent 11/30/2012 17:16:56

**Updated** 11/30/2012 17:28:08 **by** Sean Reid **Dept** PSCC **IT+**  
**Contacted On** 11-30-2012 17:27:00 **Agency** local police **Contact Name** kirk **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 11/30/2012 17:30:23 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported

The AA Dispatcher received a report that Iris Street, MP 000 730.83, DOT# 340208B, is activated with no trains present.

The AA Dispatcher is protecting the Crossing with a **Type 2 False / Partial Activation Message# 39680**. LVR

**Closed** 11/30/2012 20:23:15 **by** Leonard Patterson Jr **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 11/30/2012 20:23:00 Equipment Type: Crossing case equipment Action Taken: Repaired/adjusted island  
circuit Suspected Reason: Equipment failure Siding PMD-2 Standby Island Transmitter Module bad. Placed unit to Normal Side,  
unit functioning properly on Normal Side. Operational Checks Performed Asset: IRIS ST Status Changed To: In Service PCC  
Notification Sent 11/30/2012 20:23:15

**Updated** 11/30/2012 20:27:02 **by** Tanya Joson **Dept** PSCC **IT+**  
**Contacted On** 11-30-2012 20:26:00 **Agency** local police **Contact Name** Operator Eric **Phone** 228-392-0641

---

**Log#** [5822804](#) **Status** Closed **Entered** 10-15-2012 08:43:57 **by** Jackson Jr, Marvin **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 730.8 **Block** 2763

**Section** 3089-Gulfport **Asset** IRIS ST **AssetNum** 340208B **Maintainer** Houck, B - ETA: 09:58

**Description** 10/15/2012 08:45:29 **by** Marv Jackson Jr **Dept** Signals **IT+** .False or partial activation reported  
LOCAL PD REPORTED FALSE ACTIVATION AT IRIS STREET....BILOXI MS. Notification Sent to -Signal Control Center - Atlanta at  
10/15/2012 08:45:29 Asset: IRIS ST Status Changed To: Out Of Service PCC Notification Sent 10/15/2012 08:45:29

**Updated** 10/15/2012 08:54:38 **by** Jesse Gansen **Dept** PSCC **IT+**  
**Contacted On** **Agency** LOCAL PD **Contact Name** LOCAL PD **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Closed** 10/15/2012 12:38:52 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 10/15/2012 12:38:00 Equipment Type: Track Action Taken: Termination shunt-repaired/replaced Suspected Reason:  
Outside party or vandalism

**Employee:** B. Houck

- Vandels beat and broke NB start for xing, replaced with new start

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: IRIS ST Status Changed To: In Service PCC Notification Sent 10/15/2012 12:38:52

**Updated** 10/15/2012 12:45:59 **by** Clifford Keen **Dept** PSCC **IT+**  
**Contacted On** 10-15-2012 12:45:00 **Agency** Biloxi Police Department **Contact Name** DISP DESIREE **Phone** 228-392-0641

**Updated** 10/15/2012 12:47:18 **by** Clifford Keen **Dept** PSCC **IT+**  
**Contacted On** 10-15-2012 12:46:00 **Agency** BILOXI PD **Contact Name** DISP DESIREE **Phone** 228-392-0641

---

**Log#** [5786611](#) **Status** Closed **Entered** 09-18-2012 09:02:31 **by** Jackson Jr, Marvin **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 730.8 **Block** 2763

**Section** 3089-Gulfport **Asset** IRIS ST **AssetNum** 340208B **Maintainer** Houck, B - ETA: 10:01

**Description** 09/18/2012 09:04:10 **by** Marv Jackson Jr **Dept** Signals **IT+** .False or partial activation reported  
LOCAL OFFICER REPORTED IRIS STREET XING ACTIVATED W/O TRAIN. Notification Sent to -Signal Control Center - Atlanta at  
09/18/2012 09:04:10 Asset: IRIS ST Status Changed To: Out Of Service PCC Notification Sent 09/18/2012 09:04:10

**Updated** 09/18/2012 09:08:35 **by** Clifford Keen  
**Contacted On** 09-18-2012 09:07:00 **Agency** BILOXI PD  
EMSR DATA BASE USED.

**Dept** PSCC **IT+**  
**Contact Name** DISP 347 **Phone** 228-392-0641

**Closed** 09/18/2012 11:16:07 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 09/18/2012 11:15:00 Equipment Type: Crossing case equipment Action Taken: Replaced card(s) Suspected  
Reason: Equipment failure

**Employee:** B. Houck

- Found bad IST card in unit, locked in main, looking for parts

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: IRIS ST Status Changed To: In Service PCC Notification Sent 09/18/2012 11:16:07

**Updated** 09/18/2012 11:24:07 **by** Raheem Roberts **Dept** PSCC **IT+**  
**Contacted On** 09-18-2012 11:24:00 **Agency** Biloxi Police Department **Contact Name** Disp 315 **Phone** 228-392-0641  
North of Greater Ave

Page Execution Time: 002.24 seconds

**Beauvoir Road**

**DOT Crossing #: 340209H**

**RR Milepost #: 731.85**

## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 29

Status All AssetType All RootAssetType All Department Signals AssetNum 340209H

---

**Log#** [7960319](#) **Status** Closed **Entered** 01-12-2017 15:22:54 **by** Kondy, Rick **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 731.8 **Block** 2763

**Section** 3089-7M17 **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Mannion, R - ETA: 15:58

**Description** 01/12/2017 15:22:54 **by** Richard Kondy **Dept** Signals **IT+** Unknown

**Updated** 01/12/2017 15:25:12 **by** Richard Kondy **Dept** Signals **IT+** .False or partial activation reported  
gates down , no trains . disp protecting crossing with false activation # 46341 . Asset: BEAUVOIR RD Status Changed To: Out  
Of Service PCC Notification Sent 01/12/2017 15:25:12

**Updated** 01/12/2017 15:28:24 **by** Richard Kondy **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Roger Mannion ETA of: 15:58

**Updated** 01/12/2017 16:00:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 01/12/2017 16:36:24 **by** Roger Mannion **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 01/12/2017 16:36:00 Equipment Type: N/A Action Taken: Track Occupied MoW working in OS, no other  
issues, once work was complete verified crossing to be working as intended. Operational Checks Performed Asset: BEAUVOIR  
RD Status Changed To: In Service PCC Notification Sent 01/12/2017 16:36:24

**Closed** 01/12/2017 16:36:47 **by** Willie Alford **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 01/12/2017 16:36:00 Equipment Type: N/A Action Taken: Track Occupied . Operational Checks Performed

**Updated** 01/12/2017 20:42:57 **by** Alexis Romine **Dept** PSCC **IT+**  
**Contacted On** **Agency** // **Contact Name** biloxi police **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 01/12/2017 20:43:12 **by** Alexis Romine **Dept** PSCC **IT+**  
**Contacted On** **Agency** // **Contact Name** biloxi police **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

---

**Log#** [7871416](#) **Status** Closed **Entered** 11-04-2016 05:18:55 **by** Clairmont, Paul **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 731.8 **Block** 2763

**Section** 3089-7M17 **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Stanfill, M O - ETA: 06:55

**Description** 11/04/2016 05:18:55 **by** Paul Clairmont **Dept** Signals **IT+** Unknown

**Updated** 11/04/2016 05:25:10 **by** Paul Clairmont **Dept** Signals **IT+** .False or partial activation reported  
Crossing activated, no trains. Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 11/04/2016  
05:25:10

**Updated** 11/04/2016 05:26:31 **by** Paul Clairmont **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 06:55

**Updated** 11/04/2016 06:12:19 **by** Brooks Clayton **Dept** PSCC **IT+**  
**Contacted On** 11-04-2016 06:10:00 **Agency** Biloxi PD **Contact Name** Krysten **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 11/04/2016 07:00:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 11/04/2016 07:45:49 **by** Michael Stanfill **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 11/04/2016 07:45:00 Equipment Type: N/A Action Taken: NTF - UTD Crossing was clear on arrival.  
Unable to duplicate. Clear error codes on both units. Gate decent time is 14 seconds. Operational Checks Performed Asset:  
BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 11/04/2016 07:45:49

**Closed** 11/04/2016 07:47:57 by Paul Belkot Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 11/04/2016 07:45:00 Equipment Type: N/A Action Taken: NTF - UTD .... Operational Checks Performed

**Updated** 11/04/2016 08:00:59 by Terry Lloyd Dept PSCC IT+  
**Contacted On** 11-04-2016 08:00:00 Agency Biloxi PD Contact Name Brenda Phone 228-392-0641

---

**Log#** [7682276](#) **Status** Closed **Entered** 06-17-2016 13:18:12 **by** Wilburn, Marion **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 731.9 **Block** 2763

**Section** 3089-7M17 **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Mannion, R - ETA: 15:01

**Description** 06/17/2016 13:18:12 **by** Marion Wilburn **Dept** Signals **IT+** Unknown

**Updated** 06/17/2016 13:22:54 by Marion Wilburn Dept Signals IT+ .False or partial activation reported  
1320 Hrs. Police dispatch reports gates going up and down with no train present, gate also came down on top of Garbage Truck and one gate is bent. AA-dispatcher has been notified to protect crossing as false activation. Notification Sent to -Signal Control Center - Atlanta at 06/17/2016 13:22:54 Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 06/17/2016 13:22:54

**Updated** 06/17/2016 13:31:04 by Matthew Kite Dept Signals IT+ .False or partial activation reported  
Status changed to Dispatched for Roger Mannion ETA of: 15:01

**Updated** 06/17/2016 13:34:34 by Robert Clendening Dept PSCC IT+  
**Contacted On** Agency Police dept. Contact Name Operator 2292 Phone 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Closed** 06/17/2016 14:22:24 by Matthew Kite Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 06/17/2016 14:22:00 Equipment Type: Gate Action Taken: Damaged gate or sections-replaced/repaired  
Mntr replaced bent gate at crossing, gates pumping due to M723 working in area moving onto crossing ckt. Performed op checks, 14 sec gate des time. Turned crossing back over to disp.  
Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 06/17/2016 14:22:24

**Updated** 06/17/2016 14:49:19 by Waltina Edwards Dept PSCC IT+  
**Contacted On** 06-17-2016 14:46:00 Agency Police Department Contact Name 2922 Phone 228-392-0641

---

**Log#** [7525638](#) **Status** Closed **Entered** 02-19-2016 00:07:49 **by** Buksar, Jake **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 731.9 **Block** 2763

**Section** 3089-7M17 **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Stanfill, M O - ETA: 01:54

**Description** 02/19/2016 00:07:49 **by** Jacob Buksar **Dept** Signals **IT+** Unknown

**Updated** 02/19/2016 00:15:27 by Jacob Buksar Dept Signals IT+ .False or partial activation reported  
Local PD reports the crossing is intermittently activating. They also said there is a train parked on the approach circuit away from the crossing. L60917 was parked in the siding. DOT# provided. Dispatcher protecting with a false partial. Notification Sent to -Signal Control Center - Atlanta at 02/19/2016 00:15:27 Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 02/19/2016 00:15:27

**Updated** 02/19/2016 00:24:30 by Thera Moore Dept PSCC IT+  
**Contacted On** Agency Biloxi PD Contact Name OPR 3497 Phone 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 02/19/2016 00:24:38 by Jerry Rockhill Dept Signals IT+ .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 01:54

**Updated** 02/19/2016 00:51:58 by Jerry Rockhill Dept Signals IT+ .False or partial activation reported  
0048 aa disp reports a train meet at Beauvoir and trains were slowing down as they approached the crossing area....mtr enroute to ck crossing...

**Updated** 02/19/2016 01:55:00 by TCIS AUTOMATION Dept Signals IT+ .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 02/19/2016 03:20:08 by Jerry Rockhill Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 02/19/2016 03:20:00 Equipment Type: N/A Action Taken: NTF - UTD 0318 MTR REPORTS COA AND

UNABLE TO DUPLICATE PROBLEM.... MTR WATCHED MEET AT BEAUVOIR WITH NO ISSUES....MTR DID REPLACE 2 LIGHTNING ARRESTORS...OP CKS OK AND UNDER DISP CONTROL... Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 02/19/2016 03:20:08

**Updated** 02/19/2016 04:20:00 **by** Sabrina Smith **Dept** PSCC **IT+**  
**Contacted On** 02-19-2016 04:19:00**Agency** Biloxi PD **Contact Name** 1955 **Phone** 228-392-0641

---

**Log#** [7413013](#) **Status** Closed **Entered** 11-22-2015 02:08:32 **by** Rockhill, Jerry **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 731.9 **Block** 2763

**Section** 3089-7M17 **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Stanfill, M O - *ETA*: 03:42

**Description** 11/22/2015 02:08:32 **by** Jerry Rockhill **Dept** Signals **IT+** Unknown

**Updated** 11/22/2015 02:09:44 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
0209cident Type: TRK Dispatch incident Number: 50019 Incident Date: 22-NOV-15 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000, 0730.4000 Right Mile Post: 000, 0731.9000 Asset: 2763 007, Asset Name: MAIN PTC Flag: N Incident Description: BILOXI BRIDGETENDER SAID BEAUVOIR RD XING AT 731.85 LIGHTS BLINKING AND GATES UP. .... af 23553 Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 11/22/2015 02:09:44

**Updated** 11/22/2015 02:12:24 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 03:42

**Updated** 11/22/2015 02:23:59 **by** Thera Moore **Dept** PSCC **IT+**  
**Contacted On** 11-22-2015 02:23:00**Agency** Biloxi Police Department **Contact Name** ramona **Phone** 228-392-0641

**Updated** 11/22/2015 03:45:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 11/22/2015 03:54:39 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 11/22/2015 03:53:00 Equipment Type: N/A Action Taken: NTF - UTD 0351 Mtr reports coa and unable to duplicate problem....very windy at this time and gate may have gotten stuck in windguard... train went thru prior to mtrs arrival....op cks ok and crossing back in service with disp.. Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 11/22/2015 03:54:39

**Updated** 11/22/2015 04:09:42 **by** Kiwana Tompkins **Dept** PSCC **IT+**  
**Contacted On** 11-22-2015 04:07:00**Agency** Biloxi Police Department **Contact Name** Dispatcher Ramona **Phone** 228-392-0641

---

**Log#** [7338681](#) **Status** Closed **Entered** 09-28-2015 17:02:59 **by** Carter, Jake **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 731.9 **Block** 2763

**Section** 3089-7M17 **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Mannion, R - *ETA*: 19:09

**Description** 09/28/2015 17:02:59 **by** Jake Carter **Dept** Signals **IT+** Unknown

**Updated** 09/28/2015 17:06:48 **by** Jake Carter **Dept** Signals **IT+** .False or partial activation reported  
Local Pd reports gates are staying down, after last train;disp is protecting as f/p Notification Sent to -Signal Control Center - Atlanta at 09/28/2015 17:06:48 Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 09/28/2015 17:06:48

**Updated** 09/28/2015 17:09:38 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Roger Mannion ETA of: 19:09

**Updated** 09/28/2015 17:34:19 **by** Jackie McGuirt **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi Pd **Contact Name** Brandi **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 09/28/2015 19:10:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 09/28/2015 19:58:08 **by** Roger Mannion **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 09/28/2015 19:58:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced Track Card upon arrival 80012 card in 1CWU unit for #2 track was flashing rapidly, replaced card, calibrated, tested, watched SB train over crossing with no further exceptions. Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In



**Closed** 09/28/2015 20:00:59 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported  
 Incident Resolved: 09/28/2015 19:58:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced Track  
 Card Resolved to close. Operational Checks Performed

**Updated** 09/28/2015 20:51:47 by Terry Lloyd Dept PSCC IT+  
**Contacted On** 09-28-2015 20:51:00 Agency Biloxi Pd Contact Name Brandi Phone 228-392-0641

**Log#** [7215550](#) **Status** Closed **Entered** 07-02-2015 20:27:25 by Foster, George **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 731.9 **Block** 2763

**Section** 3089-7M17 **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Mannion, R - ETA: 21:36

**Description** 07/02/2015 20:27:25 by George Foster Dept Signals IT+ Unknown

**Updated** 07/02/2015 20:31:39 by George Foster Dept Signals IT+ .False or partial activation reported  
 Caller reported that the last train was going through the crossing and the gates started pumping up and down as the train was on the crossing. The caller said the lights remained flashing the entire time. The last train was a north bound K84601 and had not reported any exceptions. Dispatcher is protecting crossing with activation failure message 18894. Notification Sent to -Signal Control Center - Atlanta at 07/02/2015 20:31:39 Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 07/02/2015 20:31:39

**Updated** 07/02/2015 20:36:57 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported  
 Status changed to Dispatched for Roger Mannion ETA of: 21:36

**Updated** 07/02/2015 21:02:19 by Myrtie Hackney Dept PSCC IT+  
**Contacted On** 07-02-2015 21:01:00 Agency Biloxi Police Department Contact Name Jamie Phone 228-392-0641  
 @ Oakwood Dr

**Updated** 07/02/2015 21:40:00 by TCIS AUTOMATION Dept Signals IT+ .False or partial activation reported  
 ETA time reached Status changed to Active

**Updated** 07/02/2015 23:37:36 by Reed Dawley Dept Signals IT+ .False or partial activation reported  
 Train traffic in area.

**Updated** 07/03/2015 00:23:08 by Roger Mannion Dept Signals IT+ .False or partial activation reported  
 Incident Resolved: 07/03/2015 00:23:00 Equipment Type: N/A Action Taken: NTF - UTD Made checks for crossing, watched two NB and one SB train go through crossing with no exceptions. Made all operational checks and found no exceptions. There are however high winds in the area, but the gates are not going up and down. Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 07/03/2015 00:23:08

**Closed** 07/03/2015 00:23:43 by Casimir Noga Dept Signals IT+ .False or partial activation reported  
 Incident Resolved: 07/03/2015 00:23:00 Equipment Type: N/A Action Taken: NTF - UTD Made checks for crossing, watched two NB and one SB train go through crossing with no exceptions. Made all operational checks and found no exceptions. There are however high winds in the area, but the gates are not going up and down. Operational Checks Performed

**Updated** 07/03/2015 01:21:10 by Kiwana Tompkins Dept PSCC IT+  
**Contacted On** 07-03-2015 01:21:00 Agency Biloxi Police Department Contact Name 1955 Phone 228-392-0641

**Log#** [7208221](#) **Status** Closed **Entered** 06-28-2015 07:53:26 by Miller, Vern **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 731.9 **Block** 2763

**Section** 3089-7M17 **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer**

**Description** 06/28/2015 07:53:26 by Verlon Miller Dept Signals IT+ Unknown

**Updated** 06/28/2015 07:54:41 by Verlon Miller Dept Signals IT+ .False or partial activation reported  
 crossing activated, no train around. dispatcher notified to protect with false/partial activation protection. vern Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 06/28/2015 07:54:41

**Updated** 06/28/2015 07:54:53 by Verlon Miller Dept Signals IT+ .False or partial activation reported  
 . Notification Sent to -Signal Control Center - Atlanta at 06/28/2015 07:54:53

**Updated** 06/28/2015 08:20:41 **by** Deborah Anderson **Dept** PSCC **IT+**  
**Contacted On** **Agency** p.d. **Contact Name** angie **Phone** 228 392 0641  
Reporting party has been verified as the responsible law enforcement agency.

**Closed** 06/28/2015 10:56:03 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 06/28/2015 10:55:00 Equipment Type: Power/Batteries Action Taken: Commercial Power Restored

**Employee:** J. Broadway

- Commercial power restored after power company did repairs to their equipment.

Did OP Checks

Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 06/28/2015 10:56:03

**Updated** 06/28/2015 11:03:14 **by** Robert Clendening **Dept** PSCC **IT+**  
**Contacted On** 06-28-2015 11:01:00 **Agency** p.d. **Contact Name** Angie **Phone** 228 392 0641

---

**Log#** [7123954](#) **Status** Closed **Entered** 05-02-2015 01:19:49 **by** Rockhill, Jerry **Type** Vehicle on Track

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 731.9 **Block** 2763

**Section** 3089-7M17 **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Broadway, J L - *ETA*: 03:01

**Description** 05/02/2015 01:19:49 **by** Jerry Rockhill **Dept** Signals **IT+** Unknown

**Updated** 05/02/2015 01:21:59 **by** Jerry Rockhill **Dept** Signals **IT+** Vehicle on Track  
0121 ATLANTA CHIEF, AA DISPATCHER, NM SUB, LOCATION 2763-007, PSCC REPORTS CAR ON TRACKS AT BEAUVOIR RD MP 000731.85. ....af 25710... Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 05/02/2015 01:21:59

**Updated** 05/02/2015 01:31:59 **by** Jerry Rockhill **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Joshua Broadway ETA of: 03:01

**Updated** 05/02/2015 01:45:06 **by** Jesse Gansen **Dept** PSCC **IT+**  
**Contacted On** 05-02-2015 01:43:00 **Agency** Biloxi Police Department **Contact Name** 2292 **Phone** 228 392-0641  
PSCC Incident Report - #7123950

**Closed** 05/02/2015 03:57:01 **by** Jerry Rockhill **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 05/02/2015 03:56:00 Equipment Type: N/A Action Taken: NTF - UTD 0354 mtr reports vehicle removed and no damage found.... op cks ok and crossing back in service with disp Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 05/02/2015 03:57:01

**Updated** 05/02/2015 04:09:49 **by** Robert Clendening **Dept** PSCC **IT+**  
**Contacted On** 05-02-2015 04:09:00 **Agency** Biloxi Police Department **Contact Name** April **Phone** 228 392-0641

---

**Log#** [7082988](#) **Status** Closed **Entered** 04-03-2015 16:05:56 **by** Tyo, Mark **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 731.9 **Block** 2763

**Section** 3089-7M17 **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Richardson, G L - *ETA*: 18:56

**Description** 04/03/2015 16:05:56 **by** Mark Tyo **Dept** Signals **IT+** Unknown

**Updated** 04/03/2015 16:11:20 **by** Mark Tyo **Dept** Signals **IT+** .False or partial activation reported  
Reported crossing activated no trains. Disp is protecting. Notification Sent to -Signal Control Center - Atlanta at 04/03/2015 16:11:20 Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 04/03/2015 16:11:20

**Updated** 04/03/2015 16:22:56 **by** Jesse Gansen **Dept** PSCC **IT+**  
**Contacted On** 04-03-2015 16:22:00 **Agency** Biloxi PD **Contact Name** Jennifer **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 04/03/2015 16:56:55 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Gregory Richardson ETA of: 18:56

**Updated** 04/03/2015 19:00:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported

ETA time reached Status changed to Active

**Closed** 04/03/2015 19:02:46 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 04/03/2015 19:01:00 Equipment Type: N/A Action Taken: NTF - UTD

**The Signal Maintainer reported that the Crossing was working when he got there. He shunted the Main and the Siding North and South Approaches with no issues. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 04/03/2015 19:02:46

**Updated** 04/03/2015 19:06:23 by Jolene Woods Dept PSCC IT+  
**Contacted On** 04-03-2015 19:06:00 Agency Biloxi PD Contact Name eric Phone 228-392-0641

---

**Log#** [7039674](#) **Status** Closed **Entered** 03-05-2015 14:58:11 by Gaspar, Sean **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 731.9 **Block** 2763

**Section** 3089-7M17 **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Stanfill, M O - ETA: 17:04

**Description** 03/05/2015 14:58:11 by Sean Gaspar Dept Signals IT+ Unknown

**Updated** 03/05/2015 15:02:05 by Sean Gaspar Dept Signals IT+ .False or partial activation reported  
xing is activated w/ no train. dot provided. disp protecting w/ f/p. Notification Sent to -Signal Control Center - Atlanta at 03/05/2015 15:02:05 Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 03/05/2015 15:02:05

**Updated** 03/05/2015 15:04:45 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 17:04

**Updated** 03/05/2015 15:21:40 by Myrtie Hackney Dept PSCC IT+  
**Contacted On** Agency local police Contact Name dillon Phone 228-392-0641

Reporting party has been verified as the responsible law enforcement agency.

**Closed** 03/05/2015 16:16:22 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 03/05/2015 16:15:00 Equipment Type: N/A Action Taken: Track Occupied

**The Signal Maintainer reported that the Crossing was working when he got there. There was a train pulling in the siding at the time of the report. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 03/05/2015 16:16:22

**Updated** 03/05/2015 16:43:48 by Roland Knagge Dept PSCC IT+  
**Contacted On** 03-05-2015 16:42:00 Agency local police Contact Name Jackie Phone 228-392-0641

---

**Log#** [6760778](#) **Status** Closed **Entered** 08-21-2014 08:45:15 by Jackson Jr, Marv **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 731.9 **Block** 2763

**Section** 3089-7M17 **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Mannion, R - ETA: 09:53 & Patterson Jr, L D - ETA: 14:36

**Description** 08/21/2014 08:45:15 by Marv Jackson Jr Dept Signals IT+ Unknown

**Updated** 08/21/2014 08:47:11 by Marv Jackson Jr Dept Signals IT+ .False or partial activation reported  
LOCAL PD REPORTED FALSE ACTIVATION AT BEAUVOIR RD...XING ACTIVATED W/O TRAIN. Notification Sent to -Signal Control Center - Atlanta at 08/21/2014 08:47:11 Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 08/21/2014 08:47:11

**Updated** 08/21/2014 08:53:34 by Jason Gothard Dept Signals IT+ .False or partial activation reported  
Status changed to Dispatched for Roger Mannion ETA of: N/A

**Updated** 08/21/2014 08:55:08 by Marvin Smoot Dept PSCC IT+  
**Contacted On** 08-21-2014 08:55:00 Agency Biloxi Police Department Contact Name Tiffany Phone 228-392-0641  
@ Oakwood Dr

**Updated** 08/21/2014 09:55:14 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 08/21/2014 12:08:13 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
mntr onsite, troubleshooting

**Updated** 08/21/2014 13:56:54 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
mntr reports suspected bad TJC, having trouble finding a replacement

**Closed** 08/21/2014 17:26:19 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 08/21/2014 17:22:00 Equipment Type: Crossing Controller Action Taken: Repaired/replaced tunable joint coupler

**The Signal Technician reported that the East rail TJC was replaced and adjusted at the NAS SE Beauvoir. Q60221 was watched by with a 33 second Activation Time. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 08/21/2014 17:26:19

**Updated** 08/21/2014 17:36:27 **by** Sean Reid **Dept** PSCC **IT+**  
**Contacted On** 08-21-2014 17:35:00 **Agency** Biloxi Police Department **Contact Name** Disp # Moffett **Phone** 228-392-0641  
@ Oakwood Dr

---

**Log#** [6727554](#) **Status** Closed **Entered** 07-29-2014 09:01:53 **by** Wilburn, Marion **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 731.9 **Block** 2763

**Section** 3089-Gulfport **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Patterson Jr, L D - ETA: 11:37 & James Jr, G H - ETA: 12:46

**Description** 07/29/2014 09:01:53 **by** Marion Wilburn **Dept** Signals **IT+** Unknown

**Updated** 07/29/2014 09:05:48 **by** Marion Wilburn **Dept** Signals **IT+** .False or partial activation reported  
0902 Hrs. 911-center reports gates down with lights flashing and no train in sight, AA-dispatcher has been informed to protect crossing as false activation. Notification Sent to -Signal Control Center - Atlanta at 07/29/2014 09:05:48 Asset: BEAUVOIR RD  
Status Changed To: Out Of Service PCC Notification Sent 07/29/2014 09:05:48

**Updated** 07/29/2014 09:22:49 **by** Alexis Romine **Dept** PSCC **IT+**  
**Contacted On** **Agency** 911-center **Contact Name** Operator 3359 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 07/29/2014 09:46:48 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Escalated, George James Jr ETA of: 12:46

**Updated** 07/29/2014 10:37:47 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Leonard Patterson Jr ETA of: 11:37

**Updated** 07/29/2014 11:40:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 07/29/2014 13:36:58 **by** Leonard Patterson Jr **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 07/29/2014 13:36:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced/Reset CPU Found mainline unit EZ 3, shut off cabinet & reseated modules, turned unit on & EZ 100 EX 80. Checked approach, bonds ok. Watched Q579 by no exceptions, waiting for Q572. No faults activations. Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 07/29/2014 13:36:58

**Closed** 07/29/2014 13:38:25 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 07/29/2014 13:38:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced/Reset CPU  
Incident Resolved: 07/29/2014 13:36:00 Operational Checks Performed

**Updated** 07/29/2014 13:51:19 **by** Jackie McGuirt **Dept** PSCC **IT+**  
**Contacted On** 07-29-2014 13:51:00 **Agency** 911-center **Contact Name** Oper: Sarah **Phone** 228-392-0641

**Closed** 07/29/2014 15:02:00 **by** Leonard Patterson Jr **Dept** Signals **IT+** .False or partial activation reported  
Q572 by, ne exceptions

**Log#** [6683536](#) **Status** Closed **Entered** 06-27-2014 19:13:52 **by** Gaspar, Sean **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.25 **Milepost** 000 731.9 **Block** 2763  
**Section** 3089-Gulfport **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Brown, K L - *ETA*: 21:31  
**Description** 06/27/2014 19:13:52 **by** Sean Gaspar **Dept** Signals **IT+** Unknown  
**Updated** 06/27/2014 19:17:19 **by** Sean Gaspar **Dept** Signals **IT+** .False or partial activation reported  
 xing is activated w/ no train. dot provided. disp protecting w/ f/p. Notification Sent to -Signal Control Center - Atlanta at 06/27/2014 19:17:19 Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 06/27/2014 19:17:19  
**Updated** 06/27/2014 19:17:22 **by** Sean Gaspar **Dept** Signals **IT+** .False or partial activation reported  
 An email notification for Multi Failure Count (MFC) asset BEAUVOIR RD (3) has been sent to the following:  
 George James Jr  
 Danny McKenzie  
**Updated** 06/27/2014 19:22:44 **by** Avie Saunders **Dept** PSCC **IT+**  
**Contacted On** 06-27-2014 19:21:00 **Agency** Biloxi Police Department **Contact Name** 315 **Phone** 228-392-0641  
 Oakwood Dr  
**Updated** 06/27/2014 20:01:58 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
 Status changed to Dispatched for Kenneth Brown ETA of: 21:31  
**Updated** 06/27/2014 21:35:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
 ETA time reached Status changed to Active  
**Closed** 06/27/2014 22:22:03 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
 Incident Resolved: 06/27/2014 22:19:00 Equipment Type: N/A Action Taken: NTF - UTD

**The Signal Maintainer reported that the Crossing was working when he got there. He said that there was a strong storm passing through the area at the time of the report. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 06/27/2014 22:22:03

**Log#** [6682099](#) **Status** Closed **Entered** 06-26-2014 21:17:04 **by** Tyo, Mark **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 731.9 **Block** 2763  
**Section** 3089-Gulfport **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Houck, B - *ETA*: 21:54  
**Description** 06/26/2014 21:17:04 **by** Mark Tyo **Dept** Signals **IT+** Unknown  
**Updated** 06/26/2014 21:20:50 **by** Mark Tyo **Dept** Signals **IT+** .False or partial activation reported  
 Reported crossing activated no trains. DOT # was given. Disp is protecting. Notification Sent to -Signal Control Center - Atlanta at 06/26/2014 21:20:50 Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 06/26/2014 21:20:50  
**Updated** 06/26/2014 21:24:59 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
 Status changed to Dispatched for Bradley Houck ETA of: 21:54  
**Updated** 06/26/2014 21:28:05 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi PD **Contact Name** Jackie **Phone** 228-392-0641  
 Reporting party has been verified as the responsible law enforcement agency.  
**Updated** 06/26/2014 21:55:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
 ETA time reached Status changed to Active  
**Closed** 06/26/2014 22:53:49 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
 Incident Resolved: 06/26/2014 22:53:00 Equipment Type: N/A Action Taken: NTF - UTD 2251 mtr reports coa and unable to duplicate problem....sb train stopped prior to crossing to request permission to cross the red signal at se Beauvoir...causing crossing to activate ...op cks ok and crossing back in service with disp... Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 06/26/2014 22:53:49  
**Updated** 06/26/2014 22:56:38 **by** Kiwana Tompkins **Dept** PSCC **IT+**  
**Contacted On** 06-26-2014 22:55:00 **Agency** Biloxi PD **Contact Name** Dispatcher 2292 **Phone** 228-392-0641



**Log#** [6673773](#) **Status** Closed **Entered** 06-21-2014 12:30:11 **by** Jackson Jr, Marv **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 731.9 **Block** 2763

**Section** 3089-Gulfport **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Houck, B - ETA: 14:10

**Description** 06/21/2014 12:30:11 **by** Marv Jackson Jr **Dept** Signals **IT+** Unknown

**Updated** 06/21/2014 12:32:01 **by** Marv Jackson Jr **Dept** Signals **IT+** .False or partial activation reported  
LOCAL PD REPORTED FALSE ACTIVATION AT BEAUVOIR RD...XING ACTIVATED W/O TRAIN. Notification Sent to  
-Signal Control Center - Atlanta at 06/21/2014 12:32:01 Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC  
Notification Sent 06/21/2014 12:32:01

**Updated** 06/21/2014 12:34:56 **by** Robert Clendening **Dept** PSCC **IT+**  
**Contacted On** **Agency** LOCAL PD **Contact Name** SARA **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 06/21/2014 12:40:35 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Bradley Houck ETA of: 14:10

**Closed** 06/21/2014 13:51:39 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 06/21/2014 13:51:00 Equipment Type: Crossing Controller Action Taken: Repaired/Replaced Track  
Card

**Employee:** undefined

- Relay drive card replaced...

Did OP Checks, Back/released to AA disp. Watched tamper thru xing, no exception)

Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 06/21/2014  
13:51:39

**Updated** 06/21/2014 13:53:13 **by** Avie Saunders **Dept** PSCC **IT+**  
**Contacted On** 06-21-2014 13:52:00 **Agency** Local PD **Contact Name** 376 **Phone** 228-392-0641

---

**Log#** [6593326](#) **Status** Closed **Entered** 04-25-2014 23:44:43 **by** Rowe, Christopher **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 731.9 **Block** 2763

**Section** 3089-Gulfport **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Patterson Jr, L D - ETA: 03:33

**Description** 04/25/2014 23:44:43 **by** Christopher Rowe **Dept** Signals **IT+** Unknown

**Updated** 04/25/2014 23:48:03 **by** Christopher Rowe **Dept** Signals **IT+** .False or partial activation reported  
CROSSING ACTIVATED NO TRAINS IN THE VICINITY Notification Sent to -Signal Control Center - Atlanta at 04/25/2014  
23:48:03 Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 04/25/2014 23:48:03

**Updated** 04/25/2014 23:50:26 **by** Alison Obrien **Dept** PSCC **IT+**  
**Contacted On** **Agency** BILOXI PD **Contact Name** DISPATCHER **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 04/26/2014 01:33:53 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Leonard Patterson Jr ETA of: 03:33

**Updated** 04/26/2014 03:35:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 04/26/2014 03:55:57 **by** Jerry Rockhill **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 04/26/2014 03:55:00 Equipment Type: N/A Action Taken: NTF - UTD 0358 mtr reports coa and unable to  
duplicate problem....mtr watched train thru ok...op cks ok and crossing back in service with disp... Operational Checks Performed  
Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 04/26/2014 03:55:57

**Updated** 04/26/2014 04:41:08 **by** Alison Obrien **Dept** PSCC **IT+**  
**Contacted On** 04-26-2014 04:40:00 **Agency** BILOXI PD **Contact Name** Ramona **Phone** 228-392-0641

---

**Log#** [6592993](#) **Status** Closed **Entered** 04-25-2014 17:02:15 **by** Tyo, Mark **Type** .False or partial activation reported

Supv Merritt, D Reg SO Div AT Sub NM IRI 0 Milepost 000 731.9 Block 2763

Section 3089-Gulfport Asset BEAUVOIR RD AssetNum 340209H Maintainer Houck, B - ETA: 18:31

Description 04/25/2014 17:02:15 by Mark Tyo Dept Signals IT+ Unknown

Updated 04/25/2014 17:05:45 by Mark Tyo Dept Signals IT+ .False or partial activation reported  
Reported crossing activated no trains. DOT # was given. Disp is protecting. Notification Sent to -Signal Control Center - Atlanta at 04/25/2014 17:05:45 Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 04/25/2014 17:05:45

Updated 04/25/2014 17:11:41 by Sean Reid Dept PSCC IT+  
Contacted On Agency Biloxi PD Contact Name 3359 Phone 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

Updated 04/25/2014 17:51:48 by Michael Foster Dept Signals IT+ .False or partial activation reported  
Status changed to Dispatched for Bradley Houck ETA of: 18:31

Updated 04/25/2014 18:35:00 by TCIS AUTOMATION Dept Signals IT+ .False or partial activation reported  
ETA time reached Status changed to Active

Closed 04/25/2014 19:18:13 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 04/25/2014 19:14:00 Equipment Type: N/A Action Taken: NTF - UTD

**The Signal Maintainer reported that the Crossing was working when he got there. He found an alarm for high EZ on Track 2, the Siding. He walked the entire track and pounded in all the track connections. He cleared the alarms and watched the crossing. The Crossing never went back into trouble. He resealed the cards. Everything looked good. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 04/25/2014 19:18:13

Updated 04/25/2014 19:21:55 by Avie Saunders Dept PSCC IT+  
Contacted On 04-25-2014 19:21:00 Agency Biloxi PD Contact Name Theta Phone 228-392-0641

---

Log# [6498282](#) Status Closed Entered 02-18-2014 19:59:00 by Tyo, Mark Type .False or partial activation reported

Supv Merritt, D Reg SO Div AT Sub NM IRI 0 Milepost 000 731.9 Block 2763

Section 3089-Gulfport Asset BEAUVOIR RD AssetNum 340209H Maintainer Houck, B - ETA: 21:08 & James Jr, G H - ETA: 20:29

Description 02/18/2014 19:59:00 by Mark Tyo Dept Signals IT+ Unknown

Updated 02/18/2014 20:09:59 by Mark Tyo Dept Signals IT+ Unknown  
Status changed to Escalated, George James Jr ETA of: 20:29

Updated 02/18/2014 20:10:09 by Mark Tyo Dept Signals IT+ Unknown  
Status changed to Dispatched for Bradley Houck ETA of: 20:30

Updated 02/18/2014 20:11:21 by Mark Tyo Dept Signals IT+ .False or partial activation reported  
OSP reported train was approaching crossing and they did not see gates or lights activate for movement. They did say that train was moving slow, Q57218 was going into siding and had no exception with crossing. NOC Manager Batchelor, Signal Supervisor James and DTO all notified. Notification Sent to -Signal Control Center - Atlanta at 02/18/2014 20:11:21 Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 02/18/2014 20:11:21

Updated 02/18/2014 20:25:36 by Jerome Shepard Dept PSCC IT+  
Contacted On Agency Biloxi PD Contact Name Jennifer Phone 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

Updated 02/18/2014 20:49:35 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported  
Status changed to Dispatched for Bradley Houck ETA of: 21:08

Updated 02/18/2014 20:50:00 by TCIS AUTOMATION Dept Signals IT+ .False or partial activation reported  
ETA time reached Status changed to Active

Closed 02/18/2014 20:57:13 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 02/18/2014 20:54:00 Equipment Type: N/A Action Taken: NTF - UTD



The Signal Supervisor reported that the crossing was working as intended. The Train Crews took no exception to the crossing. The Crossing was shunt-tested. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR

Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 02/18/2014 20:57:13

Updated 02/18/2014 21:27:42 by Jesse Gansen Dept PSCC IT+  
Contacted On 02-18-2014 21:27:00 Agency Biloxi PD Contact Name Jennifer Phone 228-392-0641

---

Log# [6107327](#) Status Closed Entered 05-03-2013 18:06:37 by Gaspar, Sean Type -Activation failure reported  
Supv Merritt, D Reg SO Div AT Sub NM IRI 0 Milepost 000 731.9 Block 2763  
Section 3089-Gulfport Asset BEAUVOIR RD AssetNum 340209H Maintainer Houck, B - ETA: 19:29  
Description 05/03/2013 18:06:37 by Sean Gaspar Dept Signals IT+ Unknown

Updated 05/03/2013 18:16:05 by Sean Gaspar Dept Signals IT+ -Activation failure reported  
local police report that the fire chief recieved a report that a train was at the roadway when the xing activated and there was not enough warning time and the lights and gates were not working properly. no further info available. number to fire chief was given as [REDACTED] attempted to get more info and no one is available after working hours for attempted follow up call for more info. disp reports no issues w/ xing by train crews. disp protecting w/ act/failure. Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 05/03/2013 18:16:05

Updated 05/03/2013 18:16:07 by Sean Gaspar Dept Signals IT+ -Activation failure reported  
Notification has been sent to the following: George James Jr Danny McKenzie Jody Cox C Manager

Updated 05/03/2013 18:22:27 by Sean Gaspar Dept Signals IT+ -Activation failure reported  
c&s manager, ctd and local supvr notified and briefed.

Updated 05/03/2013 18:26:28 by Sean Reid Dept PSCC IT+  
Contacted On Agency local police Contact Name freada Phone 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

Updated 05/03/2013 18:59:23 by Louis Rosenblatt Dept Signals IT+ -Activation failure reported  
Status changed to Dispatched for Bradley Houck ETA of: 19:29

Updated 05/03/2013 19:30:00 by TCIS AUTOMATION Dept Signals IT+ -Activation failure reported  
ETA time reached Status changed to Active

Closed 05/03/2013 21:10:39 by Louis Rosenblatt Dept Signals IT+ -Activation failure reported  
Incident Resolved: 05/03/2013 21:02:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended

The Signal Maintainer reported performing all Operational Checks with no issues. The GCP-3000 unit did show a short warning time of 13 seconds for a Northbound train. The Detection Speed for the train was 9 MPH and the Island speed was 6 MPH indicating that the train accelerated on the approach.

The Signal Maintainer knocked the starts out on both ends and all the couplers. He checked for high signal at each point. He shunted both approaches on both tracks. He briefed his Supervisor with the findings. The Crossing was placed Back In Service with Dispatcher. LVR

Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 05/03/2013 21:10:39

Updated 05/03/2013 21:12:07 by Sean Reid Dept PSCC IT+  
Contacted On 05-03-2013 21:11:00 Agency Biloxi Police Department Contact Name sarah Phone 228-392-0641

---

Log# [6064920](#) Status Closed Entered 04-06-2013 18:19:50 by Miller, Vern Type .False or partial activation reported  
Supv Merritt, D Reg SO Div AT Sub NM IRI 0 Milepost 000 731.9 Block 2763  
Section 3089-Gulfport Asset BEAUVOIR RD AssetNum 340209H Maintainer Houck, B - ETA: 19:38  
Description 04/06/2013 18:19:50 by Verlon Miller Dept Signals IT+ Unknown

**Updated** 04/06/2013 18:26:45 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
crossing activated with no train around. dispatcher notified to protect with false/partial activation protection. vern Asset: BEAUVOIR RD Status  
Changed To: Out Of Service PCC Notification Sent 04/06/2013 18:26:45

**Updated** 04/06/2013 18:27:04 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
. Notification Sent to -Signal Control Center - Atlanta at 04/06/2013 18:27:04

**Updated** 04/06/2013 18:28:09 **by** Tanya Joson **Dept** PSCC **IT+**  
**Contacted On** **Agency** p.d. **Contact Name** oper.#3235 **Phone** 228 392 0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 04/06/2013 19:03:08 **by** Neal Osborne **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Bradley Houck ETA of: 19:38

**Updated** 04/06/2013 19:40:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 04/06/2013 20:16:41 **by** Tony Harris **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 04/06/2013 20:16:00 Equipment Type: Gate Action Taken: Freed gate - no gate mech realignment Mtr reports gate was  
hitting wind gaurd,shifted due to high winds, he adjusted wind gaurd and set timing on gate. made op checks, returned to disp. Operational  
Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 04/06/2013 20:16:41

**Updated** 04/06/2013 20:23:51 **by** Sean Reid **Dept** PSCC **IT+**  
**Contacted On** 04-06-2013 20:22:00**Agency** Biloxi Police Department **Contact Name** Disp # Stephanie **Phone** 228-392-0641

---

**Log#** [5897168](#) **Status** Closed **Entered** 12-11-2012 02:17:46 **by** Rowe, Christopher **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 731.9 **Block** 2763/2764

**Section** 3089-Gulfport **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Patterson Jr, L D - ETA: 04:45

**Description** 12/11/2012 02:21:13 **by** Christopher Rowe **Dept** Signals **IT+** .False or partial activation reported  
CROSSING ACTIVATED NO TRAINS IN THE VICINITY Notification Sent to -Signal Control Center - Atlanta at 12/11/2012 02:21:13  
Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 12/11/2012 02:21:13

**Updated** 12/11/2012 02:22:52 **by** Alison Obrien **Dept** PSCC **IT+**  
**Contacted On** **Agency** BILOXI PD **Contact Name** DISPATCH CENTER **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Closed** 12/11/2012 06:49:06 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 12/11/2012 06:45:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended Suspected  
Reason: Outside party or vandalism  
Tech reports COA. Walked trk, watched a couple SB trains on main, took no exceptions to equipment. Turned crossing backover to  
disp. While in field, disp reported to tech issue with drk bulb at NAS NE Beauvoir for trains moving into siding. Tech reported bad red  
lamp on top head of sig. Replaced bulb, gave back to disp.  
Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 12/11/2012 06:49:06

**Updated** 12/11/2012 06:53:15 **by** Brooks Clayton **Dept** PSCC **IT+**  
**Contacted On** **Agency** BILOXI PD **Contact Name** DISPATCH CENTER **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Closed** 12/11/2012 23:07:36 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 12/11/2012 06:45:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended Suspected  
Reason: Outside party or vandalism  
CORRECTION - SAS into siding not NAS as written earlier in ticket.  
Operational Checks Performed

---

**Log#** [5836552](#) **Status** Closed **Entered** 10-25-2012 06:52:30 **by** Wilburn, Marion **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 731.9 **Block** 2763

**Section** 3089-Gulfport **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Houck, B - ETA: 08:14

**Description** 10/25/2012 06:56:21 **by** Marion Wilburn **Dept** Signals **IT+** .False or partial activation reported  
0653 Hrs 911-center reported crossing is activated.AA-dispatcher informed to protect crossing as f/a. Notification Sent to  
-Signal Control Center - Atlanta at 10/25/2012 06:56:21 Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC  
Notification Sent 10/25/2012 06:56:21

**Updated** 10/25/2012 06:56:22 **by** Marion Wilburn **Dept** Signals **IT+** .False or partial activation reported  
A email notification for Multi Failure Count (MFC) asset BEAUVOIR RD (3) has been sent to the following:  
Terrence Smale II  
Danny McKenzie

**Updated** 10/25/2012 07:07:46 **by** Myrtie Hackney **Dept** PSCC **IT+**  
**Contacted On** **Agency** 911-center **Contact Name** Oper-364 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 10/25/2012 07:45:05 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
• Last move/train over xing: NB Q602-25 30 min before the xing was reported.

**Closed** 10/25/2012 08:51:24 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 10/25/2012 08:46:00 Equipment Type: Other - explain Action Taken: Other - explain Suspected  
Reason:

**Employee:** B. Houck

- Cleaned contacts on island 2 card and reseated card,

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 10/25/2012  
08:51:24

**Updated** 10/25/2012 09:00:55 **by** Brooks Clayton **Dept** PSCC **IT+**  
**Contacted On** **Agency** 911-center **Contact Name** Oper-364 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 10/25/2012 09:02:56 **by** Brooks Clayton **Dept** PSCC **IT+**  
**Contacted On** 10-25-2012 09:02:00 **Agency** Biloxi PD **Contact Name** 308 **Phone** 228-392-0641

---

**Log#** [5834382](#) **Status** Closed **Entered** 10-23-2012 14:48:27 **by** Carter, Jake **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 731.9 **Block** 2763

**Section** 3089-Gulfport **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Houck, B - ETA: 15:39

**Description** 10/23/2012 14:52:43 **by** Jake Carter **Dept** Signals **IT+** .False or partial activation reported  
Local Pd reports gates are going up/down, lights are flashing, w/no train present;unable to contact AA Disp, AtICh is  
to protect as f/p Notification Sent to -Signal Control Center - Atlanta at 10/23/2012 14:52:43 Asset: BEAUVOIR RD  
Status Changed To: Out Of Service PCC Notification Sent 10/23/2012 14:52:43

**Updated** 10/23/2012 14:57:18 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi Pd **Contact Name** Ola **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 10/23/2012 14:58:31 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported

The AA Dispatcher is protecting the crossing with a **Type 2 False / Partial Activation Message# 18263**. LVR

**Updated** 10/23/2012 14:58:46 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported

**Closed** 10/23/2012 17:12:29 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 10/23/2012 16:06:00 Equipment Type: N/A Action Taken: Issue cleared before cause identified  
Suspected Reason: Equipment failure

**The Signal Maintainer reported that the crossing was working when he got there. There were no error codes  
in either GCP 3000 unit. A Northbound train was coming out at Beauvoir at the time of the report. The  
Crossing is Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent  
10/23/2012 17:12:29

**Updated** 10/23/2012 17:55:25 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** 10-23-2012 17:55:00 **Agency** Biloxi Pd **Contact Name** Sara **Phone** 228-392-0641

---

**Log#** [5833388](#) **Status** Closed **Entered** 10-23-2012 02:38:22 **by** Williams, Joseph **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 731.9 **Block** 2763

**Section** 3089-Gulfport **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Houck, B - ETA: 03:46

**Description** 10/23/2012 02:41:08 **by** Joseph Williams **Dept** Signals **IT+** .False or partial activation reported  
0238:Hr Biloxi Police reported that the gates are down with lights flashing and no trains in sight. 0240:Hr dispatcher notified. Notification Sent to -Signal Control Center - Atlanta at 10/23/2012 02:41:08 Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 10/23/2012 02:41:08

**Updated** 10/23/2012 02:46:36 **by** Gloria Andino **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi Police **Contact Name** Eric **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 10/23/2012 04:52:59 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Mntr Houck is on-site. Reports crossing COA, mntr still troubleshooting.

**Closed** 10/23/2012 05:09:04 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 10/23/2012 05:00:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended  
Suspected Reason: Outside party or vandalism Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 10/23/2012 05:09:04

**Updated** 10/23/2012 05:14:36 **by** Alison Obrien **Dept** PSCC **IT+**  
**Contacted On** 10-23-2012 05:14:00 **Agency** Biloxi Police **Contact Name** Eric **Phone** 228-392-0641

---

**Log#** [5778161](#) **Status** Closed **Entered** 09-11-2012 14:24:56 **by** Hofer, Dave **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 731.9 **Block** 2763

**Section** 3089-Gulfport **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Houck, B - ETA: 15:37

**Description** 09/11/2012 14:33:04 **by** David Hofer **Dept** Signals **IT+** .False or partial activation reported  
14:24 Local pd reported an outside party called them to report. On 09/10/12 around 07:30 that a train was parked near the crossing. As she was going across the road the gates and lights activated for a train on the other track. She felt the crossing was slow to activate along with the issue she could not see it approaching due to the parked train. Notified the AA dispatcher to protect the crossing as an activation failure. Notification Sent to -Signal Control Center - Atlanta at 09/11/2012 14:33:04 Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 09/11/2012 14:33:04

**Updated** 09/11/2012 14:37:26 **by** Kihron Bristol **Dept** PSCC **IT+**  
**Contacted On** 09-11-2012 14:37:00 **Agency** Dispatcher **Contact Name** Local pd **Phone** 228.392.0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 09/11/2012 22:24:26 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported

**Update** - The Signal Maintainer reported finding a burnt Light Control Module. He has not been able to locate a replacement. The crossing protection has been changed to a **Type 2 False / Partial Activation Message# 18563** per Supervisor Smale due to half the lights are working. A replacement Light Control Module will be located during Regular Working Hours. LVR

**Updated** 09/12/2012 01:40:14 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Awaiting replacement part. F/P Prot provided. Setting status to informational.

**Updated** 09/21/2012 13:05:12 **by** Terrence Smale II **Dept** Signals **IT+** .False or partial activation reported  
assigned XoRail project MS2012012 Beauvoir Rd to design relays in place of the SSCCU. They understand the time constraints we are under.

**Closed** 09/28/2012 21:23:17 **by** Terry Thrasher **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 09/28/2012 21:23:00 Equipment Type: Crossing case equipment Action Taken:  
Repaired/adjusted/replaced other Suspected Reason: Equipment failure Mtr reports relays have been installed at location, crossing has been tested and returned to service with train Disp. Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 09/28/2012 21:23:17

**Updated** 09/28/2012 21:37:58 **by** Alison Obrien **Dept** PSCC **IT+**

**Contacted On** 09-28-2012 21:37:00 **Agency** Local pd **Contact Name** David **Phone** 228.392.0641

---

**Log#** [5604559](#) **Status** Closed **Entered** 05-15-2012 00:40:57 **by** Belkot, Paul **Type** -Activation failure reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 731.9 **Block** 2763

**Section** 3089-Gulfport **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Stanfill, M O - ETA: 02:02

**Description** 05/15/2012 00:53:51 **by** Paul Belkot **Dept** Signals **IT+** -Activation failure reported  
Biloxi Miss. pd reports gate and lights did not activate(gates did not come down and lights did ot come on)for approaching train...reported by outside caller to police. AA disp advised to protect crossing as a activation failure, q60913 sb on siding and q60214 nb on main had a meet...no exceptions reported by either train crew per AA disp. NOC manager updated and advised. Atlanta ctd advised initials TSM. Sent notification to ess Atlanta div. please call mtr. Notification Sent to -Signal Control Center - Atlanta at 05/15/2012 00:53:51 Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 05/15/2012 00:53:51

**Updated** 05/15/2012 00:53:53 **by** Paul Belkot **Dept** Signals **IT+** -Activation failure reported  
Notification has been sent to the following: Terrence Smale II John Parr Vacant Vacant C Manager

**Updated** 05/15/2012 00:58:17 **by** Gloria Andino **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi Ms. pd **Contact Name** operator 366 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Closed** 05/15/2012 04:59:55 **by** Matthew Kite **Dept** Signals **IT+** -Activation failure reported  
Incident Resolved: 05/15/2012 04:53:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended  
Suspected Reason: N/A  
Mntr reports crossing COA. Performed yearly test, no exceptions noted, 14 sec gate descent time. Turned crossing backover to disp.  
Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 05/15/2012 04:59:55

**Updated** 05/15/2012 05:01:35 **by** Christopher Horman **Dept** PSCC **IT+**  
**Contacted On** 05-15-2012 05:01:00 **Agency** Biloxi Ms. pd **Contact Name** Disp. Julie **Phone** 228-392-0641

---

**Log#** [5596610](#) **Status** Closed **Entered** 05-09-2012 08:11:25 **by** Wilburn, Marion **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 731.9 **Block** 2763

**Section** 3089-Gulfport **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Houck, B - ETA: 09:56

**Description** 05/09/2012 08:17:08 **by** Marion Wilburn **Dept** Signals **IT+** .False or partial activation reported  
0814 Hrs 911-center reported none of the gates lights on northside of crossing are working and half the lights on mast are flashing, AA-dispatcher has been notified to protect crossing as activation failure. Notification Sent to -Signal Control Center - Atlanta at 05/09/2012 08:17:08 Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent 05/09/2012 08:17:08

**Updated** 05/09/2012 08:21:50 **by** Virgil Adkins **Dept** PSCC **IT+**  
**Contacted On** 05-09-2012 08:21:00 **Agency** 911-center **Contact Name** Operator 308 **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Closed** 05/09/2012 10:30:04 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 05/09/2012 10:29:00 Equipment Type: Crossing case equipment Action Taken: Replaced card(s) Suspected Reason: Other electrical gate wire shorted and burned up light module card on west gate. replaced card and made op checks, repaired wires and ret to disp. Operational Checks Performed Asset: BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 05/09/2012 10:30:04

**Updated** 05/09/2012 10:42:34 **by** Virgil Adkins **Dept** PSCC **IT+**  
**Contacted On** 05-09-2012 10:39:00 **Agency** Biloxi Police Department **Contact Name** 308 **Phone** 228-392-0641

---

**Log#** [5503923](#) **Status** Closed **Entered** 03-05-2012 11:26:50 **by** McClure, Dale **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 731.9 **Block** 2763

**Section** 3089-Gulfport **Asset** BEAUVOIR RD **AssetNum** 340209H **Maintainer** Houck, B - ETA: 12:58

**Description** 03/05/2012 11:35:31 **by** Dale McClure **Dept** Signals **IT+** .False or partial activation reported  
A email notification for Multi Failure Count (MFC) asset BEAUVOIR RD (3) has been sent to the following:  
Terrence Smale II  
John Parr



**Updated** 03/05/2012 11:35:31 **by** Dale McClure **Dept** Signals **IT+** .False or partial activation reported  
POLICE REPORTED CROSSING ACTIVATED/ NO TRAINS PRESENT. AA DISP. NOTIFIED AND INSTRUCTED TO PROTECT AS  
FALSE/ PARTIAL ACTIVATION UNTIL CHECKED. Asset: BEAUVOIR RD Status Changed To: Out Of Service PCC Notification Sent  
03/05/2012 11:35:31

**Updated** 03/05/2012 11:40:38 **by** Virgil Adkins **Dept** PSCC **IT+**  
**Contacted On** 03-05-2012 11:39:00 **Agency** BILOXI, MS **Contact Name** JACKIE (POLICE) **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Closed** 03/05/2012 15:00:11 **by** Leonard Patterson Jr **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 03/05/2012 15:00:00 Equipment Type: Other - explain Action Taken: Other - explain Suspected Reason: N/A  
Dispatcher making a meet at Beauvoir 3 north & 1 south in siding, when reported. Issue clear upon arrival, EZ & EX on all 3 units  
looked good. Discussed with Brad Houck to possibly watch for tail rings when possible. Operational Checks Performed Asset:  
BEAUVOIR RD Status Changed To: In Service PCC Notification Sent 03/05/2012 15:00:11

**Updated** 03/05/2012 15:10:44 **by** Tanya Joson **Dept** PSCC **IT+**  
**Contacted On** 03-05-2012 15:10:00 **Agency** POLICE **Contact Name** Operator 386 **Phone** 228-392-0641

Page Execution Time: 003.07 seconds

**Eisenhower Drive**

**DOT Crossing #: 340210C**

**RR Milepost #: 733.02**



## Incident Detail



From 03/01/2012 To 03/07/2017

Total Incidents 12

Status All AssetType All RootAssetType All Department Signals AssetNum 340210C

---

**Log#** [7554940](#) **Status** Closed **Entered** 03-11-2016 11:45:07 **by** Kite, Matt **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0.125 **Milepost** 000 733.0 **Block** 2764  
**Section** 3089-7M17 **Asset** EISENHOWER DR **AssetNum** 340210C **Maintainer** Mannion, R - ETA: 13:23  
**Description** 03/11/2016 11:45:07 **by** Matthew Kite **Dept** Signals **IT+** Unknown  
**Updated** 03/11/2016 11:46:15 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Incident Type: TRK Dispatch incident Number: 06187 Incident Date: 11-MAR-16 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000, 0732.0000 Right Mile Post: 000, 0739.3000 Asset: 2764 001, Asset Name: MAIN PTC Flag: N Incident Description: WEST SIDE GATE NOT ACTIVATING AT EISENHOWER DRIVE 000733.02...REPORTED BY Q61411 Copied frm DIRT. Disp prot with A/F #14564. Asset: EISENHOWER DR Status Changed To: Out Of Service PCC Notification Sent 03/11/2016 11:46:15

**Updated** 03/11/2016 11:46:17 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
An email notification for (IRI) asset EISENHOWER DR (1) has been sent to the following:  
George James Jr

**Updated** 03/11/2016 11:49:50 **by** Jodi Snyder **Dept** PSCC **IT+**  
**Contacted On** 03-11-2016 11:48:00 **Agency** Biloxi Police Department **Contact Name** Megan **Phone** 228-392-0641  
Edgewater Dr

**Updated** 03/11/2016 11:53:12 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Roger Mannion ETA of: 13:23

**Updated** 03/11/2016 13:25:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 03/11/2016 14:36:28 **by** Roger Mannion **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 03/11/2016 14:36:00 Equipment Type: Gate Action Taken: Freed gate - no gate mech realignment Gate hung up behind wind guard due to high winds and storms in area. Move gate from behind guard and moved wind guard. Operational Checks Performed Asset: EISENHOWER DR Status Changed To: In Service PCC Notification Sent 03/11/2016 14:36:28

**Closed** 03/11/2016 14:38:29 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 03/11/2016 14:36:00 Equipment Type: Gate Action Taken: Freed gate - no gate mech realignment Crossing BIS with disp. Operational Checks Performed

**Updated** 03/11/2016 14:56:44 **by** Jackie McGuirt **Dept** PSCC **IT+**  
**Contacted On** 03-11-2016 14:56:00 **Agency** Biloxi Police Department **Contact Name** Oper: Angie **Phone** 228-392-0641

---

**Log#** [7532125](#) **Status** Closed **Entered** 02-23-2016 22:21:01 **by** Carter, Jake **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 733.0 **Block** 2764  
**Section** 3089-7M17 **Asset** EISENHOWER DR **AssetNum** 340210C **Maintainer** Stanfill, M O - ETA: 01:46  
**Description** 02/23/2016 22:21:01 **by** Jake Carter **Dept** Signals **IT+** Unknown  
**Updated** 02/23/2016 22:24:09 **by** Jake Carter **Dept** Signals **IT+** .False or partial activation reported  
Local Pd reports xng is activated, w/no trains present;disp is protecting as f/p Notification Sent to -Signal Control Center - Atlanta at 02/23/2016 22:24:09 Asset: EISENHOWER DR Status Changed To: Out Of Service PCC Notification Sent 02/23/2016 22:24:09  
**Updated** 02/23/2016 22:28:53 **by** Jake Carter **Dept** Signals **IT+** .False or partial activation reported

..1 gate has been reported to be broken at this loc Notification Sent to -Signal Control Center - Atlanta at 02/23/2016 22:28:53

**Updated** 02/23/2016 22:30:35 **by** Alyson Trouba **Dept** PSCC **IT+**  
**Contacted On** 02-23-2016 22:30:00 **Agency** Biloxi Pd **Contact Name** May **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 02/23/2016 23:16:51 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 01:46

**Updated** 02/24/2016 01:10:45 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Severe storm passed through area. Mntr is working 3-4 separate crossing issues. Will move to crossings as quickly and safely as time and weather permit.

**Updated** 02/24/2016 01:50:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 02/24/2016 06:03:32 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 02/24/2016 06:03:00 Equipment Type: Gate Action Taken: Damaged gate or sections-replaced/repared  
Mntr replaced west gate at crossing due to damage frm storm. Performed op checks, turned crossing back over to disp.  
Operational Checks Performed Asset: EISENHOWER DR Status Changed To: In Service PCC Notification Sent 02/24/2016 06:03:32

**Updated** 02/24/2016 06:06:52 **by** Christina Martorano **Dept** PSCC **IT+**  
**Contacted On** 02-24-2016 06:06:00 **Agency** Biloxi Pd **Contact Name** Courtney **Phone** 228-392-0641

---

**Log#** [7376279](#) **Status** Closed **Entered** 10-26-2015 08:53:48 **by** Williams, Joseph **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 733.0 **Block** 2764

**Section** 3089-7M17 **Asset** EISENHOWER DR **AssetNum** 340210C **Maintainer** Mannion, R - ETA: 09:37

**Description** 10/26/2015 08:53:48 **by** Joseph Williams **Dept** Signals **IT+** Unknown

**Updated** 10/26/2015 08:56:08 **by** Joseph Williams **Dept** Signals **IT+** .False or partial activation reported  
0854:Hr Biloxi Police reported that there is one gate down with lights flashing. 0855:Hr dispatcher notified Notification Sent to -Signal Control Center - Atlanta at 10/26/2015 08:56:08 Asset: EISENHOWER DR Status Changed To: Out Of Service  
PCC Notification Sent 10/26/2015 08:56:08

**Updated** 10/26/2015 08:58:48 **by** Jolene Woods **Dept** PSCC **IT+**  
**Contacted On** **Agency** Biloxi Police **Contact Name** Sara **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 10/26/2015 09:07:39 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Roger Mannion ETA of: 09:37

**Updated** 10/26/2015 09:40:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 10/26/2015 10:00:18 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 10/26/2015 09:58:00 Equipment Type: Gate Action Taken: Freed gate - no gate mech realignment

**Employee:** R. Mannion

- WING GOT GATGE CAUGHT ON CANILEVER.....FREED GATE...

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: EISENHOWER DR Status Changed To: In Service PCC Notification Sent 10/26/2015 10:00:18

**Updated** 10/26/2015 10:01:51 **by** Jolene Woods **Dept** PSCC **IT+**  
**Contacted On** 10-26-2015 10:01:00 **Agency** Biloxi Police **Contact Name** Brenda **Phone** 228-392-0641

---

**Log#** [7321144](#) **Status** Closed **Entered** 09-15-2015 12:00:10 **by** Tucker, Kelly **Type** Vehicle on Track  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 733.0 **Block** 2764  
**Section** 3089-7M17 **Asset** EISENHOWER DR **AssetNum** 340210C **Maintainer** Mannion, R - ETA: 12:24  
**Description** 09/15/2015 12:00:10 **by** Kelly Tucker **Dept** Signals **IT+** Unknown  
**Updated** 09/15/2015 12:00:46 **by** Kelly Tucker **Dept** Signals **IT+** Vehicle on Track  
TRUCK STUCK ON TRACK Asset: EISENHOWER DR Status Changed To: Out Of Service PCC Notification Sent  
09/15/2015 12:00:46  
**Updated** 09/15/2015 12:04:16 **by** Kelly Tucker **Dept** Signals **IT+** Vehicle on Track  
Status changed to Dispatched for Roger Mannion ETA of: 12:24  
**Updated** 09/15/2015 12:21:36 **by** Nikole Ross **Dept** PSCC **IT+**  
**Contacted On** 09-15-2015 12:21:00 **Agency** Biloxi Police Department **Contact Name** Jackie **Phone** 228-392-0641  
Edgewater Dr

**Updated** 09/15/2015 12:25:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track  
ETA time reached Status changed to Active  
**Updated** 09/15/2015 12:57:14 **by** Jack Nickless **Dept** Signals **IT+** Vehicle on Track  
PCC Notification Sent 09/15/2015 12:57:14 Asset: 340210C - EISENHOWER DR Status Changed To: In Service

**Closed** 09/15/2015 12:59:22 **by** Jack Nickless **Dept** Signals **IT+** Vehicle on Track  
Incident Resolved: 09/15/2015 12:58:00 Equipment Type: N/A Action Taken: Track Occupied MTR REPORTS  
VEHICLE WAS REMOVED AND MTR FOUND NO DAMAGE TO XING .XING IS WORKING AS INTENDED.  
Operational Checks Performed

**Updated** 09/15/2015 13:01:45 **by** Byron Tinsley **Dept** PSCC **IT+**  
**Contacted On** 09-15-2015 13:01:00 **Agency** Biloxi Police Department **Contact Name** 2922 **Phone** 228-392-0641  
Edgewater Dr

---

**Log#** [7128800](#) **Status** Closed **Entered** 05-05-2015 20:16:32 **by** Gaspar, Sean **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 733.0 **Block** 2764  
**Section** 3089-7M17 **Asset** EISENHOWER DR **AssetNum** 340210C **Maintainer** Mannion, R - ETA: 22:32  
**Description** 05/05/2015 20:16:32 **by** Sean Gaspar **Dept** Signals **IT+** Unknown  
**Updated** 05/05/2015 20:20:04 **by** Sean Gaspar **Dept** Signals **IT+** .False or partial activation reported  
xing is activated w/ no train. dot provided. disp protecting w/ f/p. Notification Sent to -Signal Control Center - Atlanta at  
05/05/2015 20:20:04 Asset: EISENHOWER DR Status Changed To: Out Of Service PCC Notification Sent 05/05/2015  
20:20:04  
**Updated** 05/05/2015 20:32:16 **by** Louis Rosenblatt **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Roger Mannion ETA of: 22:32  
**Updated** 05/05/2015 20:55:17 **by** Roland Knagge **Dept** PSCC **IT+**  
**Contacted On** **Agency** local police **Contact Name** jackie **Phone** 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 05/05/2015 22:35:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 05/05/2015 23:32:18 **by** Roger Mannion **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 05/05/2015 23:32:00 Equipment Type: Power/Batteries Action Taken: Repaired/Replaced COAM  
Power Source Power issue, Breaker tripped at pole due to AC Lightening Protection shorted in house, Rewired AC Power  
and monitored proper charging of battery banks. Gave back to dispatcher with message number 31551 2318 ads

Operational Checks Performed Asset: EISENHOWER DR Status Changed To: In Service PCC Notification Sent  
05/05/2015 23:32:18

**Closed** 05/05/2015 23:34:07 by Matthew Kite Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 05/05/2015 23:32:00 Equipment Type: Power/Batteries Action Taken: Repaired/Replaced COAM  
Power Source  
Operational Checks Performed

**Updated** 05/05/2015 23:49:13 by Kihron Bristol Dept PSCC IT+  
**Contacted On** 05-05-2015 23:48:00 Agency local police Contact Name Dillon Phone 228-392-0641

---

**Log#** [7081686](#) **Status** Closed **Entered** 04-02-2015 17:22:11 by Tyo, Mark **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 733.0 **Block** 2764  
**Section** 3089-7M17 **Asset** EISENHOWER DR **AssetNum** 340210C **Maintainer** Mannion, R - ETA: 20:01  
**Description** 04/02/2015 17:22:11 by Mark Tyo Dept Signals IT+ Unknown

**Updated** 04/02/2015 17:27:58 by Mark Tyo Dept Signals IT+ .False or partial activation reported  
Reported gates slow in activating. Disp is protecting. Notification Sent to -Signal Control Center - Atlanta at 04/02/2015  
17:27:58 Asset: EISENHOWER DR Status Changed To: Out Of Service PCC Notification Sent 04/02/2015 17:27:58

**Updated** 04/02/2015 17:35:42 by Myrtie Hackney Dept PSCC IT+  
**Contacted On** Agency Biloxi PD Contact Name Jennifer Phone 228-392-0641  
Reporting party has been verified as the responsible law enforcement agency.

**Updated** 04/02/2015 18:01:48 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported  
Status changed to Dispatched for Roger Mannion ETA of: 20:01

**Updated** 04/02/2015 18:44:33 by Roger Mannion Dept Signals IT+ .False or partial activation reported  
Activated crossing with shunt and by dropping XR relay, gate decent time with both methods was 13 seconds from start to  
completion of movement. Do not see slow activation. Currently waiting on North Bound train to go through crossing so  
crossing can be observed with train movement.

**Updated** 04/02/2015 19:49:47 by Roger Mannion Dept Signals IT+ .False or partial activation reported  
watched northbound train, all warning times in accordance with standards, 34 second warning time. No exceptions. Waiting  
on South Bound train.

**Updated** 04/02/2015 20:05:00 by TCIS AUTOMATION Dept Signals IT+ .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 04/02/2015 20:18:44 by Roger Mannion Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 04/02/2015 20:18:00 Equipment Type: N/A Action Taken: NTF - UTD Watched Southbound train, all  
warning times in accordance with standards, 41 second warning time. No exceptions. Did not see any reason with four  
different methods someone would assume a slow activation. Returned to dispatcher. Operational Checks Performed Asset:  
EISENHOWER DR Status Changed To: In Service PCC Notification Sent 04/02/2015 20:18:44

**Updated** 04/02/2015 20:24:03 by Jolene Woods Dept PSCC IT+  
**Contacted On** 04-02-2015 20:23:00 Agency Biloxi PD Contact Name Jackie Phone 228-392-0641

**Closed** 04/02/2015 20:24:53 by Louis Rosenblatt Dept Signals IT+ .False or partial activation reported  
Incident Resolved: 04/02/2015 20:24:00 Equipment Type: N/A Action Taken: NTF - UTD Resolved to close. Operational  
Checks Performed

---

**Log#** [7033061](#) **Status** Closed **Entered** 03-02-2015 11:10:50 by Miller, Vern **Type** .False or partial activation reported  
**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 733.0 **Block** 2764  
**Section** 3089-7M17 **Asset** EISENHOWER DR **AssetNum** 340210C **Maintainer** Stanfill, M O - ETA: 12:57  
**Description** 03/02/2015 11:10:50 by Verlon Miller Dept Signals IT+ Unknown

**Updated** 03/02/2015 11:12:12 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
crossing activated, no train around. dispatcher notified to protect with false/partial activation protection. vern Asset: EISENHOWER  
DR Status Changed To: Out Of Service PCC Notification Sent 03/02/2015 11:12:12

**Updated** 03/02/2015 11:12:24 **by** Verlon Miller **Dept** Signals **IT+** .False or partial activation reported  
. Notification Sent to -Signal Control Center - Atlanta at 03/02/2015 11:12:24

**Updated** 03/02/2015 11:18:33 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: 12:57

**Updated** 03/02/2015 11:39:55 **by** Waltina Edwards **Dept** PSCC **IT+**  
**Contacted On** 03-02-2015 11:39:00 **Agency** Biloxi Police Department **Contact Name** 347 **Phone** 228-392-0641

**Closed** 03/02/2015 12:58:31 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 03/02/2015 12:58:00 Equipment Type: N/A Action Taken: Track Occupied COA, NB train was in the block at time  
of report. made op checks and ret to disp. Operational Checks Performed Asset: EISENHOWER DR Status Changed To: In Service  
PCC Notification Sent 03/02/2015 12:58:31

**Updated** 03/02/2015 13:05:38 **by** Michele Schwartz **Dept** PSCC **IT+**  
**Contacted On** 03-02-2015 13:04:00 **Agency** Biloxi Police Department **Contact Name** Brenda **Phone** 228-392-0641

---

**Log#** [6728951](#) **Status** Closed **Entered** 07-30-2014 04:44:32 **by** Kite, Matt **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 733.0 **Block** 2764

**Section** 3089-Gulfport **Asset** EISENHOWER DR **AssetNum** 340210C **Maintainer** Stanfill, M O - ETA: 04:50

**Description** 07/30/2014 04:44:32 **by** Matthew Kite **Dept** Signals **IT+** Unknown

**Updated** 07/30/2014 04:46:17 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

While on-site at nearby crossing making repairs mntr observed outside party struck and knocked gate off at crossing.

**Updated** 07/30/2014 04:50:53 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for Michael Stanfill ETA of: N/A

**Updated** 07/30/2014 04:55:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Updated** 07/30/2014 05:03:32 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported

Disp prot crossing with F/P prot #38388.

Asset: EISENHOWER DR Status Changed To: Out Of Service PCC Notification Sent 07/30/2014 05:03:32

**Updated** 07/30/2014 05:23:15 **by** Thera Moore **Dept** PSCC **IT+**  
**Contacted On** 07-30-2014 05:21:00 **Agency** Biloxi Police Department **Contact Name** john **Phone** 228-392-0641  
Edgewater Dr

**Closed** 07/30/2014 06:13:46 **by** Matthew Kite **Dept** Signals **IT+** .False or partial activation reported  
Incident Resolved: 07/30/2014 06:12:00 Equipment Type: Gate Action Taken: Replaced shear pin/rehung original gate  
Mntr rehung east gate. Performed op checks, turned crossing backover to disp.  
Operational Checks Performed Asset: EISENHOWER DR Status Changed To: In Service PCC Notification Sent 07/30/2014  
06:13:46

**Updated** 07/30/2014 06:18:12 **by** Jodi Snyder **Dept** PSCC **IT+**  
**Contacted On** 07-30-2014 06:17:00 **Agency** Biloxi Police Department **Contact Name** John **Phone** 228-392-0641  
Edgewater Dr

---

**Log#** [6496341](#) **Status** Closed **Entered** 02-17-2014 20:05:48 **by** Rosenblatt, Louis **Type** Vehicle on Track



**Supv** Merritt, D   **Reg** SO   **Div** AT   **Sub** NM   **IRI** 0   **Milepost** 000 733.0   **Block** 2764  
**Section** 3089-Gulfport   **Asset** EISENHOWER DR   **AssetNum** 340210C   **Maintainer** Houck, B - *ETA: 21:07*  
**Description** 02/17/2014 20:05:48   **by** Louis Rosenblatt   **Dept** Signals   **IT+** Unknown  
**Updated** 02/17/2014 20:06:17   **by** Louis Rosenblatt   **Dept** Signals   **IT+** Vehicle on Track

The AA Dispatcher received a report that Eisenhower Drive, MP 000 733.02, DOT# 340210C, NM Sub, has a vehicle on the track.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 10381**. LVR  
Asset: EISENHOWER DR Status Changed To: Out Of Service PCC Notification Sent 02/17/2014 20:06:17

**Updated** 02/17/2014 20:07:18   **by** Louis Rosenblatt   **Dept** Signals   **IT+** Vehicle on Track  
Status changed to Dispatched for Bradley Houck ETA of: 21:07

**Updated** 02/17/2014 21:10:00   **by** TCIS AUTOMATION   **Dept** Signals   **IT+** Vehicle on Track  
ETA time reached Status changed to Active

**Closed** 02/17/2014 21:17:40   **by** Louis Rosenblatt   **Dept** Signals   **IT+** Vehicle on Track  
Incident Resolved: 02/17/2014 21:17:00 Equipment Type: N/A Action Taken: NTF - UTD

**The Signal Maintainer reported that there was no signal damage. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR**

Operational Checks Performed Asset: EISENHOWER DR Status Changed To: In Service PCC Notification Sent 02/17/2014 21:17:40

---

**Log#** [6061196](#)   **Status** Closed   **Entered** 04-04-2013 07:07:13   **by** McVey, Bruce   **Type** .False or partial activation reported

**Supv** Merritt, D   **Reg** SO   **Div** AT   **Sub** NM   **IRI** 0   **Milepost** 000 733.0   **Block** 2764  
**Section** 3089-Gulfport   **Asset** EISENHOWER DR   **AssetNum** 340210C   **Maintainer** Houck, B - *ETA: 08:10*  
**Description** 04/04/2013 07:07:13   **by** Bruce McVey   **Dept** Signals   **IT+** Unknown  
**Updated** 04/04/2013 07:07:44   **by** Bruce McVey   **Dept** Signals   **IT+** .False or partial activation reported

- Notification:

atl chief, aa disp, nm sub, nb train reports west gate at eisenhower drive at mp 000733.0 :COPIED

Asset: EISENHOWER DR Status Changed To: Out Of Service PCC Notification Sent 04/04/2013 07:07:44

**Updated** 04/04/2013 07:08:34   **by** Bruce McVey   **Dept** Signals   **IT+** .False or partial activation reported  
• Disp is protecting with A/F mess. # 44961

**Updated** 04/04/2013 07:10:26   **by** Bruce McVey   **Dept** Signals   **IT+** .False or partial activation reported  
Status changed to Dispatched for Bradley Houck ETA of: 08:10

**Updated** 04/04/2013 07:25:12   **by** Myrtie Hackney   **Dept** PSCC   **IT+**  
**Contacted On** 04-04-2013 07:24:00 **Agency** Biloxi Police Department **Contact Name** 347 **Phone** 228-392-0641

**Updated** 04/04/2013 08:15:00   **by** TCIS AUTOMATION   **Dept** Signals   **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 04/04/2013 09:51:05   **by** Bruce McVey   **Dept** Signals   **IT+** .False or partial activation reported  
Incident Resolved: 04/04/2013 09:50:00 Equipment Type: Gate mechanism Action Taken: Other - explain

**Employee:** B. Houck

- east gate was hung up in wind guard, mtr repaired also bad pogo on gate .... replaced that also

Did OP Checks, Back/released to AA disp. 44961 Annulled w/ 45272

Operational Checks Performed Asset: EISENHOWER DR Status Changed To: In Service PCC Notification Sent 04/04/2013 09:51:05

**Updated** 04/04/2013 09:52:48 **by** Misty Hunter **Dept** PSCC **IT+**  
**Contacted On** 04-04-2013 09:52:00 **Agency** Biloxi Police Department **Contact Name** 347 **Phone** 228-392-0641

---

**Log#** [5915578](#) **Status** Closed **Entered** 12-26-2012 06:24:18 **by** Foster, George **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 733.0 **Block** 2764

**Section** 3089-Gulfport **Asset** EISENHOWER DR **AssetNum** 340210C **Maintainer** Broadway, J L - ETA: 08:07

**Description** 12/26/2012 06:35:19 **by** George Foster **Dept** Signals **IT+** .False or partial activation reported

Crossing activated with no trains in sight. Dispatcher protecting with false partial activation MSG# 39195. Notification Sent to -Signal Control Center - Atlanta at 12/26/2012 06:35:19 Asset: EISENHOWER DR Status Changed To: Out Of Service PCC Notification Sent 12/26/2012 06:35:19

**Updated** 12/26/2012 06:37:42 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for ETA of: 08:07

**Updated** 12/26/2012 06:48:38 **by** Virgil Adkins **Dept** PSCC **IT+**  
**Contacted On** 12-26-2012 06:47:00 **Agency** Biloxi Police Department **Contact Name** 3248 **Phone** 228-392-0641

**Updated** 12/26/2012 08:10:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
ETA time reached Status changed to Active

**Closed** 12/26/2012 08:44:01 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported

Incident Resolved: 12/26/2012 08:43:00 Equipment Type: Power/batteries Action Taken: Breaker reset reset ac power feed breaker at the pole. made op checks and ret to disp. Operational Checks Performed Asset: EISENHOWER DR Status Changed To: In Service PCC Notification Sent 12/26/2012 08:44:01

**Updated** 12/26/2012 08:47:49 **by** Brooks Clayton **Dept** PSCC **IT+**  
**Contacted On** 12-26-2012 08:47:00 **Agency** Biloxi Police Department **Contact Name** Stephnie **Phone** 228-392-0641

---

**Log#** [5910936](#) **Status** Closed **Entered** 12-20-2012 16:46:59 **by** Oglesby, Brad **Type** .False or partial activation reported

**Supv** Merritt, D **Reg** SO **Div** AT **Sub** NM **IRI** **Milepost** 000 733.0 **Block** 2764

**Section** 3089-Gulfport **Asset** EISENHOWER DR **AssetNum** 340210C **Maintainer** Houck, B - ETA: 17:57

**Description** 12/20/2012 16:50:03 **by** Brad Oglesby **Dept** Signals **IT+** .False or partial activation reported

1646 THE LOCAL PD REPORTED THE CROSSING IS ACTIVATED WITHOUT ANY TRAINS PRESENT(DOT NUMBER PROVIDED). 1648 ADVISED THE AA DISPATCHER(INITIALS-WJS) TO PROVIDE PROTECTION ON THE CROSSING AS PER FALSE ACTIVATION STANDARD. Notification Sent to -Signal Control Center - Atlanta at 12/20/2012 16:50:03 Asset: EISENHOWER DR Status Changed To: Out Of Service PCC Notification Sent 12/20/2012 16:50:03

**Updated** 12/20/2012 16:57:11 **by** TCIS AUTOMATION **Dept** Signals **IT+** .False or partial activation reported  
Status changed to Dispatched for ETA of: 17:57

**Updated** 12/20/2012 16:57:16 **by** Jerome Shepard **Dept** PSCC **IT+**  
**Contacted On** **Agency** BILOXI PD **Contact Name** DISPATCHER **Phone** 228 392-0641

Reporting party has been verified as the responsible law enforcement agency.

**Closed** 12/20/2012 17:42:13 **by** Jason Gothard **Dept** Signals **IT+** .False or partial activation reported

Incident Resolved: 12/20/2012 17:41:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as intended mntr reports COA. made op checks and ret to dsip. Operational Checks Performed Asset: EISENHOWER DR Status Changed To: In Service PCC Notification Sent 12/20/2012 17:42:13

**Updated** 12/20/2012 17:53:49 **by** Sean Reid **Dept** PSCC **IT+**  
**Contacted On** 12-20-2012 17:52:00 **Agency** Biloxi Police Department **Contact Name** 1955 **Phone** 228-392-0641



@ Edgewater Dr.

Page Execution Time: 002.95 seconds