Attachment 10. TOPS Inspection

DCA12MA020 Maintenance Factual Report

TOPS Men	aber:			Date:	
1 1					
		OUT-BR	HEFING	DATE:	
	Name			Title	
Kyn	Register S-		Stood	of MANIONAVEC	
LAWR	NCE Pir	trapaulo	CEO		
Louic	HALC		Train	or Opus	
KurT	BARTON		Direc	or Opius	
Burl	BOYD	Print list of all Opera	Chief	PiloT	
			tor personnet present		
		TOPS AUDI	T RESULTS		
	Recomm	ended for TOPS m	nembership		
AUDIT RESULTS		ended for TOPS m to TOPS standard		items listed above have bee	n
	1 1 1 1		• 1	perator does not meet TOP ached list of discrepancies	S
OPERATOR REPRESENTA	TIVE:	SIGNATURE:			
		NAME:	Luc	e film	
				Please Print	
		TITLE:	AudiTi		
				Please Print	
				2 1	
TOPS AUDITO	R:	SIGNATURE:			
		NAME:	Lawrence	I. Fietiopeu	6
				Please Print	
		FOR INTERNA	L USE ONLY		
Approved by t	he Membership Revi	iew Committee			
			Signa	ure I	Date
Approved by the	TOPS Board of Dir	ectors			
			Signat	ure I	Date

Findings, comments and narrative to be provided in Audit Report to be submitted with this audit form.

JEN- Please ATTACK TO SUNDANCE AUDIT

Revision: 2/24/2011 - Final

TOPS Member: Sundance Helicopters

Date:_7/11-12/2011___

Date:	July 11-12, 2011	State in a distantial teacher described followers on the control of the control of the section o
Company:	Sundance Helicopters	man of the second of the secon
Address:	5596 Haven Street	
City, State, Zip	Las Vegas, NV. 89119	
Telephone:	702-736-0606	
FAX:	702-736-1183	
		and it is the property of the contract of the

IN-BRIEFING:	Name/Title:	Kurt Barton, Director of Operations		
AREAS OF INT	EREST:	All		
		Key Personnel		<u>-</u>
	Title	Name	How long in position (yrs)?	How long with company (yrs)?
C	EO/President:	Lawrence Pietropaule	3	3
Director	of Operations:	Kurt Barton	8	8
Director of	Maintenance:	Kyle Reynolds	1	11
Sa	fety Manager:	Michael Flaherty	4	6

GENERAL OPERATIONS

1. Regional areas of operation:

Contiguous United States and District of Columbia

2. Who has operational control?

Operational management team

3. List air tour bases include name of Base Manager and Field Elevation

J. 1318t a		e name of Base manager t		
Base	Elevation	Manager	Aircraft Make/Model Assigned	Number
KLAS	2100 Ft.	Kurt Barton	AS-350	18
			As-130	4
1G4	4825	Ray Medina	Aircraft based in KLAS	
		-		
•				

TOPS Member: Sundance Helicopters

Date:_7/11-12/2011____

Audit Areas

Bullet points under the audit categories summarize TOPS Program requirements and indicate areas required to be reviewed during the audit. Refer to the TOPS Program of Safety for specific requirements.

For each section, use the 1-4 scale. 1 Non-compliance with TOPS Standards, 2 Meets TOPS Standards with areas for improvement, 3 Meets TOPS standards, 4 Meets TOPS standards with areas that exceed. Comments are required for each audit category.

_	1				
A.		MAN	AGEMENT		
	Non-compliance with TOPS Standards	2. Areas for improvement	3. Meets TOPS standards	4. Exceeds TOPS stan	dards
			X		
1.	Key Personnel Qua	lification		Area audited?	X
2.	Establishment of Cl procedures	ear Operating Standards b	ased on safe and professiona	Area audited?	x
3.	other operators and	appropriate agencies	other safety procedures with	Area auaitea?	X
	dance but with oth		nembers of managemen	it bring a broad le	vel

Date: 7/11-12/2011

TOPS Member: Sundance Helicopters

В.		S	SAFETY			•	
	Non-compliance with TOPS Standards	2. Areas for improvement	3. Meets TOPS standards	4. E	xceeds TOPS stand	lards	
			X		X		
1.	, ,	lemonstrates a clear and codard by which operations a	onsistent commitment to Safe are conducted	ety	Area audited?	x	
2.	Safety Manager as	part of top management			Area audited?	x	
3.		anagement Program included before an incident or accident and accident or accident and accident accident and accident ac	ding a safety reporting progradent happens	m	Area audited?	х	
4.	Emergency Respon	se Plan			Area audited?	х	
5.	Safety Training inc	luding Human Factors Tra	nining		Area audited?	х	

Comments: The SMS program is new as of Jan 11, 2011.

Human factors is taught through the company training captain on a regular basis.

All top managers are taught the SMS program and buy into it.

Spider tracks are incorporated on the flight following process and are overlaid over Google Earth.

The company has secret shoppers that are experienced in aviation ride along and report their findings on a quarterly basis. The passengers are unknown to the employees they come in contact with.

NOTE: It was suggested that TOPS adopt a standard TOPS SMS program dealing with all tour subjects. TOPS is a safety orientated group and I feel this suggestion warrants discussion.

_						
<i>C</i> .		FLIGHT	<i>OPERATIONS</i>			
	Non-compliance with TOPS Standards	2. Areas for improvement	3. Meets TOPS standards	4. E	xceeds TOPS stand	ards
			X			
1.	Operational Contro	l			Area audited?	X
2.		cedures standardized to inc IMC recovery procedures,	•	ites,	Area audited?	X
3.	Passenger briefings	and escorting during ramp	operations		Area audited?	X
4.	Aircraft properly ed	uipped for the mission and	the area being flown		Area audited?	х
5.	Emergencies Proces	dures unique to the mission	profile flown		Area audited?	х
6.	Operator plan for or	ngoing oversight of tour rou	ites and flight operations		Area audited?	х
		control is obviously in ontrol over the fleet.	the hands of the peop	le wh	o are required	l to
of fili follo Pass Only The dis the	ght tracks and air wing is two way vengers are escort one aircraft is all company uses seey exist. These sl	cking is done by Spide craft location at any timoice. ted to and from aircraft owed to hover on the racret shoppers at a minimoppers are aviation santeresting items to be i	ne. Back up and supple on every flight. amp at any given time. mum of once a quarter vvy and are reliable. A	emen	ital flight entify problem	

ľ	PILOTS	•	
2. Areas for improvement	3. Meets TOPS standards	4. Exceeds TOPS stand	ards
	X		
ffing and crew rest		Area audited?	X
mentation		Area audited?	X
_	-	Area audited?	X
average age of the p	oilots and total flight tim		
		ouse with outside	
9 p			
•			
	improvement ffing and crew rest mentation ons meet TOPS stateway age of the plot staff is very	ffing and crew rest mentation ions meet TOPS standards. At this time the average age of the pilots and total flight time the pilot staff is very high.	improvement X Iffing and crew rest Area audited? Area audited? Area audited? Area audited? Area audited? Innertation Area audited? Area audited? Innertation Area audited?

1 57		ET LCTT	COODDINATION		
<i>E</i> .	Non-compliance with	2. Areas for	3. Meets TOPS standards	4. Exceeds TOPS stand	orde
	TOPS Standards	improvement	5. Meets 1013 standards	4. Exteeus 1013 stand	aius
			X	X	1
1.	Manifesting proced	ures		Area audited?	X
2.	Flight Following			Area audited?	X
3.	Emergency Respons	se Plan		Area audited?	Х
4.	Flight following per	sonnel training and docu	mentation	Area audited?	X
Ther and	re is a trained pers over sees all ramp	activities, clears air	ircraft on the heliport. The craft and supervises rames SMS program and is effectively	p activities.	dio

TOPS Member: Sundance Helicopters

Date:_7/11-12/2011____

F.			CLIPORT		
1. N	4. Exceeds TOPS standard	ls			
			X		
1.	Meets FAA standard	ds		Area audited? X	-
2.	Properly equipped a	nd maintained		Area audited? X	
3.	Provides a safe and operations	functional area for passeng	ger movement and flight	Area auditeď? X	
The 3. S	if the aircraft is sl aircraft are all pro ee previous pages	nut down. perly equipped for the	with assistance of grou		

G.		MAI	NTENANCE		
1.	Non-compliance with TOPS Standards	2. Areas for improvement	3. Meets TOPS standards	4. Exceeds TOPS stand	lards
			X		
1.	Maintenance areas a	nd shops		Area audited?	X
2.	Technical publicatio	ns and manuals		Area audited?	x
3.	Parts and supplies			Area audited?	X
4.	Maintenance quality	assurance (company size	e appropriate)	Area audited?	X
A quand	uality assurance pe records.	erson has been place Paper and electronic	function on a non-interf	stem to oversee wo	

Н.		MAINTENAI	NCE PERSONNEL		
	Non-compliance with TOPS Standards	2. Areas for improvement	3. Meets TOPS standards	4. Exceeds TOPS stand	ards
			X	Х	
1.	Mechanic qualificat	ions, staffing and crew res	t	Area audited?	X
2.	Mechanic training and documentation Area audited? X				
Com	ments: Maintenanc umented and is ge	e personnel have Euro	Copter training each year. This training is do	ear. Training is	

I.		GROUND SUP	PORT PERSONNEL				
	ion-compliance with TOPS Standards	2. Areas for improvement	3. Meets TOPS standards	4. Exceeds TOPS standards			
	X		X				
1.	Training and docum	entation		Area audited?			
2.	Passenger briefing	Area audited? X					
3.	3. Loading and unloading helicopters Area audited?						
The One the o	observation during the	g the audit was that th briefing and one pilot ected on the spot and	the briefing is thorough the passengers were call called out his passeng changes in the procedu	ed out to register at er during the briefing.			

TOPS Member: Sundance Helicopters Date:_7/11-12/2011____

J.	AREAS OF SPECIAL INTEREST					
Instructions: Comments are required for each area of special interest.						
1.	Flight Coordination – flight following systems/methods	Area audited?	X			
2.	Emergency Response Plan – plan suitability and training	Area audited?	X			
3.	Ground Support Personnel – Passenger briefing system (live, PP, video, visual aids)	Area audited?	x			
4.	Maintenance - Quality Assurance methods scaled for the operator size	Area audited?	x			
5.	Management – Process for passenger complaints about safety or safety of flight issues, including follow up procedure.	Area audited?	x			

Comments: Items 1 thru 4 previously covered in this report.

There is a system in place where passengers and employees can bring problems, complaints or situations to the attention of Safety and Management. Negative items are acted upon and brought to a successful conclusion.

11

TOPS Member: Sundance Helicopters

Date:_7/11-12/2011_

		E D			
I	Location	Manager	Date		
1. K	(LAS	Kurt, Barton	7-11-11		
2.	Grand Canyon West	Ray Medina	7-12-11		
3.					
4.			ompany procedures and policies		

12

TOPS Member: Sundance Helicopters

Date: 7/11-12/2011____

FLIGHT OBSERVATIONS						
Location	Tour	Date				
KLAS	Twi-Light	7-11-11				
Grand Canyon Wes	t	7-12-11				
ghts.						
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,						

TOPS INFLIGHT OBSERVATION GUIDELINES

The following are areas for review and evaluation during In-flight Observations:

- 1. Manifesting, Briefing and Aircraft Loading
- 2. Ramp/Airport Operations
- 3. Takeoff and Landing
- 4. Cruise Flight
 - Routes
 - Terrain
 - Altitudes
 - Traffic
- 5. Offsite Landing Areas

TOPS	AUDIT RECOMMENDATIONS, BEST PRACTICES AND DISCREPANCIES
Instructions: Id	entify each item as a discrepancy, recommendation or best practice
ITEM	RECOMMENDATIONS, BEST PRACTICES AND DISCREPANCIES
General Comments	There are no outstanding negative items
Safety	The company has secret shoppers that are experienced in aviation ride along and report their findings on a quarterly basis. The passengers are unknown to the employees they come in contact with.
Safety	NOTE: It was suggested that TOPS adopt a standard TOPS SMS program dealing with all tour subjects. TOPS is a safety orientated group and I feel this suggestion warrants discussion
Flight Opns	The company uses secret shoppers at a minimum of once a quarter to identify problems is they exist. These shoppers are aviation savvy and are reliable. Also searches of U-Tube bring out some interesting items to be investigated
Flight Opns	The company uses secret shoppers at a minimum of once a quarter to identify problems is they exist. These shoppers are aviation savvy and are reliable. Also searches of U-Tube bring out some interesting items to be investigated
Maintenanc e	Maintenance personnel have EuroCopter training each year. Training is documented and is generally 40 hours per year. This training is done on site.
Ground Support Personnel	One observation during the audit was that the passengers were called out to register at the counter during the briefing and one pilot called out his passenger during the briefing. These items were corrected on the spot and changes in the procedures have been made, there is no outstanding finding.

TOPS Member: Sundance Helicopters Date:_7/11-12/2011____

OUT-BR				RIJ		DATE:		
Name				_	Title			
Kyle Reynolds					Director of Maintenance			
Louis Hall					Training Captain			
Kurt Barton				Director of Operations				
Burl Boyd					Chief Pilot			
Print list of all Operator personnel present								
TOPS AUDIT RESULTS								
	X Recommended for TOPS membership							
AUDIT RESULTS		Recommended for TOPS membership (After items listed above have been corrected to TOPS standards).					ave been	
	Not Recommended for TOPS membership (Operator does not meet TOPS Standards. Re-audit recommended.) See attached list of discrepancies							
OPERATOR REPRESENTA	TIVE:		SIGNATURE):				
			NAME):				
					Pl	lease Print		
			TITLE	::				
					Pl	lease Print		
TOPS AUDITOR:			SIGNATURE	<i>:</i> :	Variate	· · · · · ·	4	
			NAME	:	Vernon Albert			
			Please Print					
	-							
			FOR INTER	NAL_	USE ONLY			
Approved by the Membership Review Committee					Cionatura		Dota	
Approved by the TOPS Board of Directors					Signature Signature		Date	

Findings, comments and narrative to be provided in Audit Report to be submitted with this audit form.