

Attachment 13. Report Showing Last Bolt Change N351WM

DCA12MA020 Maintenance Factual Report

MAKE	rocopter	DISCREPANCY LIST SUNDANCE HELICOPTERS 5596 Haven Street, Las Vegas, Nevada, 89119 Phone: (702) 736-0606, Fax: (702) 736-1415	DATE	20-08
MODEL	AS350B2		AFT TT	12210.9
S/N	2167		ENG TT	6778.2
REG.	N351WM		PAGE	8 of 8

DESCRIPTION	CORRECTIVE ACTION
-------------	-------------------

#29 <div style="border: 1px solid black; padding: 5px; margin: 10px 0;"> C/W 30 day portable fire extinguisher inspection. </div>	Performed inspection of portable fire extinguisher. No defects noted at this time. Next inspection to be c/w on or before <u>12/22/08</u>
--	---

NAME	DATE	NAME	DATE
[Redacted]	11/22/08	[Redacted]	12/22/08

#30 <i>4w SB# 29.00.10 REPLACEMENT OF HYDRAULIC HOSES FOR HELICOPTERS WITH MORE THAN 5000 FH OR MORE THAN 12 YEARS OLD.</i>	Removed outdated Hydraulic Hoses and Replaced with Following New Hoses 3ea Servo Hyd Hoses P/N 704A34-412-033, PO#4780, 3ea P/N 704A34-412-035, PO#4780 Hyd Valve/Filter Assy Hose P/N 704A34-412-015, PO#4086, Hose P/N 704A34-412-038, PO#4780 TR Servo Hose P/N 704A34-412-020, PO#3969, Hose P/N 704A34-412-021, PO#3969 Hose P/N 704A34-412-046, PO#3969, Hose P/N 704A34-412-042, PO#4780. Performed GRN Run Leak Ck No Defects Noted. REF AS350 SB 29.00.10.
---	---

NAME	DATE	NAME	DATE
[Redacted]	11/22/08	[Redacted]	22 Nov 08.

#31 <i>F/A Servo Input Rod Lower Bearing is worn And Binding.</i>	Removed worn + Binding Rod End Bearing and Installed New Bearing P/N A0212CG20E2AR, PO#1082, Also Removed worn Hardware on upper bearings of Input Rod, Installed New Bolt P/N 22731BC060020M, PO#12279, New washer P/N 23111AG0606E, PO#2949 New Nut P/N A5NA0045-060BCL, PO#1663, No Defects Noted. OPEC Good. Ref ECMM Ch 67
--	---

NAME	DATE	NAME	DATE
[Redacted]	22 Nov 08.	[Redacted]	22 Nov 08.

#32 <i>Rotor Brake Requires Shimming</i>	Reshimmed Rotor Brake with Shim's that were on Hand. Operational CK was good No Defects Noted.
---	--

NAME	DATE	NAME	DATE
[Redacted]	22 Nov 08.	[Redacted]	22 Nov 08.

Ref ECMM Ch 63.