

## **MEMORANDUM OF RECORD**

Eric Alleyne
Air Safety Investigator
National Transportation Safety Board
Office of Aviation Safety - Eastern
Region

NTSB Case Number: ERA20LA171

**Telephone correspondence: Steven** 

Davidson (FAA inspector)

Email date: 5/8/2020

**Subject: Accident examination** 

findings

In a telephone interview with inspector Davidson, we went over the accident findings. He said that the left wingtip spar was buckled. He found scrapping on the belly skin, left wing tip and gear doors. The main landing gear assembly tubes were all broken and he was going to release the airplane to the owner. He review the maintenace logbooks and did not see any discrepancies in the logbooks. He gave me (NTSB IIC) the contact information to the mechanic that would be further inspecting the damaged airplane and said he would not be returning for follow up on this event.