

**NTSB Docket Item
DCA-05-MR-009
Metrolink collision and derailment
Glendale, California
January 26, 2005**

Metrolink Train Dispatcher Efficiency Test Information

A-1) Employee Data

From: 7/1/04
To: 1/26/05

EmployeeName	TestDate	Desk	Supervisor	Time	RR	Bk	Test	P/F	Comments
Lawson, MD	7/6/2004	T-VL1	Monarch, KR	8:32	GC	O	1.5	P	
				8:32	GC	O	1.6	P	
				8:32	GC	M	1.3.1	P	DISCUSSED RULE OF THE WEEK AND GCOR
				8:32	GC	M	1.44	P	SIGNED HOURS OF SERVICE FORM
				8:32	SC	M	2.14.1	P	RULE OF THE WEEK
				8:32	GC	O	1.12	P	
				5:50	GC	O	1.3.2	P	
				5:50	EP	S	Q	P	RULE 8.15 - REPORTING RUN THROUGH SWITCH - SCRRR RULE VIOLATION FORM
				5:50	EP	S	Q	P	RULE 8.15 - REPORTING RUN THROUGH SWITCH - SDNR RULE VIOLATION FORM
				5:50	SC	M	6.42	P	BRIEFING - MOVEMENT WITHIN CONTROL POINT OR M
5:50	GC	O	1.5	P					
5:50	GC	O	1.1.2	P					
5:50	GC	O	1.1	P					
5:50	GC	O	1.6	P					
7:28	TD	M	10.3.2	P					
7:28	GC	O	2.4	P					
7:28	SC	M	6.1	P	GOOD READBACK				

11/11/2004 VL1 TRAI Eliker

EmployeeName	TestDate	Desk	Supervisor	Time	RR	Bk	Test	P/F	Comments
				7:28	SC	M	9.13	P	PERMISSION TO HAND OPERATE DUAL CONTROL SWITCH AT CP COLONIA
				7:28	GC	O	2.8	P	
				7:28	GC	O	2.2	P	
				7:28	SC	M	10.3.2	P	TRACK AND TIME E/L CP POSAS AND MADERA
	11/12/2004	VL1 TRAI	Elliker						
				7:20	SC	M	2.14	P	OBSERVE RULE 6.32.2 TO ML 204
				7:20	TD	M	6.32.2	P	XING AT BLEDSOE ST MP 23.18
	11/14/2004	VLRV1	Monarch, KR						
				7:18	GC	O	2.4	P	
				7:18	GC	O	1.5	P	
				7:18	GC	M	10.0	P	FAMILIAR WITH CTC TERRITORY
				7:18	SC	M	9.12.1	P	AT CP WOODMAN
				7:18	SC	M	9.12	P	
				7:18	GC	O	8.3	P	
				7:18	SC	M	6.1	P	GOOD READBACK
				7:18	GC	O	5.11	P	
				7:18	GC	O	2.14.1	P	
				7:18	GC	O	2.1	P	
				7:18	GC	M	1.44	P	COMPLETED REQUIRED FLAGGING FORM
				7:18	GC	O	1.6	P	
				7:18	GC	O	1.1.2	P	
				7:18	GC	O	1.1.1	P	
				7:18	GC	O	1.1	P	
				7:18	GC	M	2.2	P	

EmployeeName	TestDate	Desk	Supervisor	Time	RR	Bk	Test	P/F	Comments
				7:18	GC	M	1.13	P	
				8:16	EP	S	A	P	NOTIFICATION OF ML SHERIFFS DISPATCH CENTER
	11/22/2004	VL1	Bailey	7:50	SC	M	6.1	P	
				7:50	GC	O	1.5	P	
				7:50	GC	O	1.44	P	
				7:50	GC	O	2.5	P	
				7:50	GC	O	2.4	P	
				7:50	GC	O	2.3	P	
				7:50	GC	O	2.2	P	
				7:50	SC	M	2.14	P	
				7:50	SC	M	9.12.1	P	FLAG ML101 AT CP SANTA SUSANA
				7:50	SC	M	6.32.2	P	SHELDON
	12/2/2004	VL1	Eliker	5:50	TD	M	6.32.6	P	BRIEFING - RULE OF THE WEEK BLOCKING PUBLIC CROSSING
				5:50	GC	O	1.1	P	
				5:50	GC	O	1.1.2	P	
				5:50	GC	O	1.3.2	P	
				5:50	GC	O	1.5	P	
				5:50	EP	S	Q	P	BRIEFING - SCRRRA GRADE AND NON-GRADE CROSSING ACCIDENT NOTIFICATION
				5:50	EP	S	Q	P	BRIEFING - SDNR GRADE AND NON-GRADE CROSSING ACCIDENT NOTIFICATION
				5:50	GC	O	1.6	P	
				10:30	GC	O	2.2	P	

EmployeeName	TestDate	Desk	Supervisor	Time	RR	Bk	Test	P/F	Comments
				10:30	GC	O	2.4	F	USE OVER BETWEEN TRANSMISSIONS
				10:30	GC	O	2.8	P	
				10:30	SC	M	6.4.1	P	REVERSE MOVE TO ML 1071112 BETWEEN TOPANGA AND DESOTO
				10:30	SC	M	6.1	P	GOOD READBACK
				10:38	SC	M	2.19	P	OBSERVE RULE 6.32.2
				10:38	TD	M	6.32.2	P	ERRINGER RD MP 434..
				10:40	SC	M	10.1	P	AUTHORITY TO ENTER SIDING TO SP7135 BETWEEN SAUGUS AND CANYON
	12/4/2004	VL/RS1	Elliker						
				11:10	EP	S	A	P	NOTIFIED METROLINK SHERIFF ABOUT TRESPASSERS AT EAST END OF TUNNEL 26
				12:03	GC	O	2.4	P	
				12:03	GC	O	2.8	P	
				12:03	GC	O	2.2	P	
				12:03	SC	M	9.12.1	P	FLAG UP 4928 FROM NOI TRACK TO NOI TRACK AT WOODMAN
	12/10/2004	VL1	Bailey						
				9:20	GC	O	2.3	P	
				9:20	GC	O	2.4	P	
				9:20	GC	O	2.2	P	
				9:20	SC	M	6.1	P	
				9:20	SC	M	10.3.2	P	
				9:20	SC	M	10.3.1	P	
				9:20	SC	M	10.3	P	TRACK AND TIME BETWEEN CP HUMPHREYS AND EAST LIMITS OF CP HOOD
				9:20	GC	O	2.5	P	
				12:32	SC	M	15.1	P	ISSUED T.B.

EmployeeName	TestDate	Desk	Supervisor	Time	RR	Bk	Test	P/F	Comments
	12/22/2004	VLY2	Blackford	15:10	EP	S	Q	P	Q AND A ABOUT RULE 6.32.2
				15:10	GC	O	1.1.2	P	
	1/18/2005	VL1	Elliker	5:50	GC	O	1.6	P	BRIEFING - SDNR VANDALISM AND SUSPICIOUS ACTIVITY NOTIFICATION
				5:50	EP	S	Q	P	BRIEFING - SCRRRA VANDALISM AND SUSPICIOUS ACTIVITY NOTIFICATION
				5:50	EP	S	Q	P	BRIEFING - SCRRRA VANDALISM AND SUSPICIOUS ACTIVITY NOTIFICATION
				5:50	GC	O	1.3.2	P	
				5:50	GC	O	1.1	P	
				5:50	GC	O	1.1.2	P	
				5:50	GC	O	1.5	P	
				8:20	TD	M	1.29	F	DELAYED ML2087 WITH SAUGUS LCL
				9:02	GC	O	2.2	P	
				9:02	GC	O	2.4	P	
				9:02	GC	O	2.5	P	
				9:02	SC	M	10.3.2	P	TRACK AND TIME IN SIDING BETWEEN HOOD AND PORTAL
				9:02	TD	M	10.3.4	P	
				9:02	SC	M	6.1	P	GOOD READBACK
				10:30	SC	M	6.4.1	P	REVERSE MOVE ML 107/112 BETWEEN TOPANGA AND DESOTO
	1/19/2005	VL1	Elliker	10:10	SC	M	2.14	P	RULE 6.32.2
				10:10	TD	M	6.32.2	P	XING OSBOURNE ST, MP 18.41
				10:50	SC	M	2.14	P	20 MPH SPEED RESTRICTION BETWEEN MP 69.30 AND MP 69.33

EmployeeName	TestDate	Desk	Supervisor	Time	RR	Bk	Test	P/F	Comments
	1/24/2005	VNT1	Graham	8:42	SC	O	10.3.2	P	TRACK AND TIME ON MAIN TRACK BETWEEN CP STRATHEARN CP SANTA SUSANA
				8:42	EP	S	Q	P	PROCEDURE WHEN TRAIN IS IN EMERGENCY ON MULTIPLE MAIN TRACK
				8:42	GC	O	1.1	P	
				8:42	GC	O	1.5	P	
				8:42	GC	O	1.6	P	
				8:42	GC	O	1.8	P	
				8:42	GC	O	2.1	P	
				8:42	GC	O	2.2	P	
				8:42	GC	O	2.4	P	
				8:42	SC	O	6.1	P	CORRECT REPEAT