

INCIDENT / ACCIDENT REPORT

MIAMI-DADE COUNTY

MIAMI-DADE AVIATION DEPARTMENT - GENERAL AVIATION AIRPORTS

EVENT DATA	TIME / OFF / MD / YR	DATE	NOTIFIED BY	TIME DISPATCHED (MIL)	TIME ARRIVED (MIL)	TIME COMPLETED (MIL)
	OPF	7/12/2011	OPF-ATCT	1320	1325	1400
INCIDENT OR ACCIDENT		NATURE OF INCIDENT / ACCIDENT		DAMAGE RECOVERY CONTROL NUMBER		OFFICER / CASE NUMBER (ACCIDENT ONLY)
Incident		aircraft wing struck rwy		n/a		
FIRE UNIT / ALOAM NUMBER			LOCATION			
FOAM 25/139045			rwy 12/30			

SECTION 1	INDIVIDUAL INVOLVED		COMPANY		MDAD I.D. NUMBER	DRIVERS TRAINING EXP.	
	Luis Adan Hernandez						
	CURRENT ADDRESS (CITY / STATE / ZIP CODE)				DRIVER LICENSE NUMBER	STATE	TYPE
					Pilot Lic#		
VEHICLE / AIRCRAFT / EQUIPMENT TYPE		MAKE	MODEL	YEAR	VEHICLE OWNER		
Lear Jet		Gates Lear Jet	35	1975	Robinson Air Crane Co		
TAG / REGISTRATION NUMBER		STATE	VEHICLE IDENTIFICATION NUMBER		COMPANY VEHICLE NUMBER	MDAD VEHICLE DECAL (LAST 6)	
N-110UN							

SECTION 2	INDIVIDUAL INVOLVED		COMPANY		MDAD I.D. NUMBER	DRIVERS TRAINING EXP.	
	Leo Cordero		co-pilot				
	CURRENT ADDRESS (CITY / STATE / ZIP CODE)				DRIVER LICENSE NUMBER	STATE	TYPE
VEHICLE / AIRCRAFT / EQUIPMENT TYPE		MAKE	MODEL	YEAR	VEHICLE OWNER		
TAG / REGISTRATION NUMBER		STATE	VEHICLE IDENTIFICATION NUMBER		COMPANY VEHICLE NUMBER	MDAD VEHICLE DECAL (LAST 6)	

SECTION 3	INDIVIDUAL INVOLVED		COMPANY		MDAD I.D. NUMBER	DRIVERS TRAINING EXP.	
	CURRENT ADDRESS (CITY / STATE / ZIP CODE)				DRIVER LICENSE NUMBER	STATE	TYPE
VEHICLE / AIRCRAFT / EQUIPMENT TYPE		MAKE	MODEL	YEAR	VEHICLE OWNER		
TAG / REGISTRATION NUMBER		STATE	VEHICLE IDENTIFICATION NUMBER		COMPANY VEHICLE NUMBER	MDAD VEHICLE DECAL (LAST 6)	

At 1320 hrs. OPF-ATCT notified R-50 to assist an aircraft that on landing the wing struck the runway. The a/c was able to taxi on it's own power to his FBO base J & P Aviation. The airplane sustained severe damage to the right win tip area .close to the external fuel tank but a minimum amount of fuel was leaked during the incident, according with the MDRF unit on the scene. Notified by this unit were: OCR and PIO on duty(1336-1350 hrs)Miami FSDO, John Woods, and Edward De Silva(1430-1500 hrs).OPF Airport Mnger Chris McArthur also responded to the incident.Runway 12/30 was inspected and returned to service withIn 20 minutes of occurrence.No further details at this moment.

ADMIN	REPORT WRITTEN BY	SIGNATURE	POSITION	MDAD I.D. NUMBER
	Carlos B Beltran		A.Attendant	
SUPERVISOR (PRINT NAME AND SIGN)				
CHRIS McARTHUR				