

## **MEMORANDUM for RECORD**

Ralph E. Hicks Senior Air Safety Investigator Eastern Region Aviation

## Date: September 20, 2017 Person Contacted: Mr. Kevin Ensminger – Manager, Bombardier Business Aircraft NTSB Accident Number: ERA16LA323 – San Juan, PR

This investigator inquired to Bombardier (Kevin Ensminger) regarding the Goodyear part # 178K23-5 tires that were installed on YV1738. He responded by email that the 178K23-5 tires were approved by Bombardier and included in the Lear 25D Illustrated Parts Catalog (IPC).