
Date of Service: 8/26/2011 ETA Given: NA AR#: Flight #: 11 - 84352 Patient Name: TACORONTE, KARI Vehicle: N352LN Unit: LN 2-2 Taken By: Cox, Korey **RUN TIMES** Call Started: 17:18:16 08/26/11 Dispatched By: Cox, Korey Call Taken: 17:19:55 08/26/11 Call Source/Phone #: Pilot Notified/Dispatch: 17:20:00 Caller Name: Kristv Weather Check: 17:21:09 Responded From: Initial Lift Off: 17:30:21 Call Type: Revenue Arrive Pt Location: 17:58:37 **Primary Complaint:** <None> Depart Pt on board: 18:13:11 Complaint #2: <None> Arrive Receiving: 00:00:00 **Dispatch Complaint:** In Service: 00:00:00 Loaded Statute Miles: 72 **CREW INFORMATION** Pilot: Freudenberg James Med 1: Bever, Randy (Hrt-SD) Med 2: Frakes Chris (Hrt-SD) **Dispatch Comments:** PATIENT INFORMATION Patient Name: TACORONTE, KARI Patient DOB: Patient SSN: Age/Sex/Wt: Female Address 1: Address 2: City, State Zip: PICK-UP AND DESTINATION INFORMATION Pick Up Information Initial Priority: Revenue - Interhospital Harrison County Hospital - ER Referring MD: Madsen BETHANY, MO 64424 Phone: 40° 15.923' N x 94° 1.592' W **Drop Off Information** Liberty Memorial Hospital - ER Transport Priority: Revenue - Interhospital LIBERTY, MO 64068 Recieving MD: ROBB 39° 16.440' N x 94° 25.470' W Phone: FLIGHT PLAN Calculated Calculated Flight Status Arrived/Departed Waypoint Name Heading Distance <u>Souls</u> Fuel ETE LifeNet 2-2 Base (Rosecrans Memorial A/P) On Ground 08/26/2011 17:30:21 LifeNet 2-2 Base (Rosecrans Memorial A/P) to Harrison 50.0nm 02:00 In Flight 00:27:25 County Hospital 08/26/2011 17:58:37 Harrison County Hospital On Ground Harrison County Hospital to Midwest National Air Center 08/26/2011 18:13:10 188 57.5nm 00:16 00:31:30 In Flight Airport Midwest National Air Center Airport On Ground Midwest National Air Center Airport to Liberty Memorial 6.3nm 233 00:00 00:03:27 In Flight Hospital Liberty Memorial Hospital On Ground Liberty Memorial Hospital to LifeNet 2-2 Base (Rosecrans 318 In Flight 00:20:18 Memorial A/P) LifeNet 2-2 Base (Rosecrans Memorial A/P) On Ground TRIP NOTES

		A STATE OF THE PROPERTY OF THE	TRIP HISTORY
<u>Date</u>	<u>Time</u>	Ву	Description
8/26/2011	17:20:55	KLCOX	Call Taken
8/26/2011	17:21:00	KŁCOX	Snapshot of dispatch modules was captured
8/26/2011	17:21:00	KLCOX	Assigned to Unit ID LN 2-2 on Vehicle N352LN
8/26/2011	17:21:00	CUSTINCD	Incident Number 603233 applied.
8/26/2011	17:21:00	KLCOX	Auto page was queued.
8/26/2011	17:21:09	KLCOX	Weather Check
8/26/2011	17:24:19	KLCOX	Changed Name from <unknown> to TACORONTE, KARI</unknown>
8/26/2011	17:25:11	KLCOX	Added Note: ** Dispatch - NA in map page per program specifics
8/26/2011	17:26:36	KLCOX	Added Note: ** Dispatch - Requestor asked to secure helipad and provide cot for
	.,		the crew upon arrival. Also requested a call back confirming acceptance
8/26/2011	17:26:39	KLCOX	
8/26/2011	17:26:39	KLCOX	Added Pick-Up Apt/Ste/Rm: ER
8/26/2011	17:26:39	KLCOX	Deleted Pick-Up Zone (was ø⊡Ö)
8/26/2011	17:26:39	KLCOX	Added Pick-Up Map Page: NA
8/26/2011	17:26:39	KLCOX	Added Drop-Off Facility: Liberty Memorial Hospital
8/26/2011	17:26:39	KLCOX	Added Drop-Off Address: 2525 GLENN HENDREN
8/26/2011	17:26:39	KLCOX	Added Drop-Off Apt/Ste/Rm: ER
8/26/2011	17:26:39	KLCOX	Added Drop-Off City: LIBERTY
8/26/2011	17:26:39	KLCOX	Added Drop-Off State: MO
8/26/2011	17:26:39	KLCOX	Added Drop-Off ZIP Code: 64068
8/26/2011	17:26:39	KLCOX	Added Drop-Off Phone:
8/26/2011	17:26:39	KLCOX	Added Source Name: Kristy
8/26/2011	17:26:39	KLCOX	Added Treating Doctor: NA
8/26/2011	17:26:39	KLCOX	Added Personal Doctor: Madsen
8/26/2011	17:26:39	KLCOX	Changed Estimated Distance from 0.0 to 71.7
8/26/2011	17:26:39	KLCOX _	Added Dispatch Comments: IN 2.2 Elight # 04252
8/26/2011	17:26:39	KLCOX	Added Alert: Special Instructions
8/26/2011	17:27:12	KLCOX	Changed Taken Time from 17:20:55 to 17:19:55
8/26/2011	17:27:12	KLCOX	Changed Assigned Time from 17:21:00 to 17:20:00
8/26/2011	17:30:21	KLCOX	En Route
8/26/2011	17:30:21	KLCOX	Specified Fuel: 02:00 (hh:mm)
8/26/2011	17:30:21	KLCOX	Specified number of Souls: 3
8/26/2011	17:31:01	KLCOX	Added Note: ** Dispatch - 1729CDT Lori Bethany ER called back and stated Dr
0/00/00/4	4		Robb accepted pt at Liberty ER.
8/26/2011	17:31:53	KLCOX	Changed Treating Doctor from NA to ROBB
8/26/2011	17:34:05	KLCOX	Added Note: ** Dispatch - 1732CDT Miles Liberty ER verified pt acceptance for
0/00/0044	47.50.07	W OOV	ER
8/26/2011	17:59:37	KLCOX	At Scene
8/26/2011	17:59:45	KLCOX	Changed At Scene Time from 17:59:37 to 17:58:37
8/26/2011	18:12:27	KLCOX	Added Note: ** Dispatch - 1759CDT Pilot callled andd verified safe landing and
8/26/2011	18:13:10	KLCOX	time Specified Evel: 00:45 (khyram)
8/26/2011	18:13:10	KLCOX	Specified Fuel: 00:45 (hh:mm)
8/26/2011	18:13:11	KLCOX	Specified number of Souls: 4
8/26/2011	18:14:44	KLCOX	Transporting
	19:17:01		Added Note: ** Dispatch - Risk Assessment Matrix Code - B
8/26/2011	19.17.01	KBARGSTAL	Added Note: ** Dispatch - 1913 called Clay county back to confirm report of downed aircrafttail # and colors confirmed
8/26/2011	19:20:03	OBURR	
GIZGIZUTI	10.20.00	ODUNK	Added Note: ** Dispatch - @1856 called John at Midwest A/P, he advised he
			was expecting a/c 10 minutes ago, advised their was a training pilot in the air who would head toward last known coords to search area
8/26/2011	19:21:32	KBARGSTAF	Added Note: ** Dispatch - 1920 calLED ER charge RN to advise that pt was
			involved in an accident and would not be being transported
			The state of the s

(1 constitution of the second	estapos printeses estamos estamos establecidos los los establecidos por la como establecido de la como establecido	<u>ſŖŲŢŗĸĬŖĸĬŖĸĬŖĸĬŖŖĬŖĸĬŖŖŶĸŶŖŶŖŶĸŶŊŶĨ</u> ŶŶŦŦŶ	
8/26/2011	19:21:34	OBURR	Added Note: ** Dispatch - @1910 Stacy with Clay County called and advised there was reports of a/c down near hwy 69 and Cameron Rd, advised Fire and
8/26/2011	40.00.50	Online	EMS were enroute
0/20/2011	19:22:50	OBURR	Added Note: ** Dispatch - @1918 notified Christina at LifeFlight Eagle to stand
			down 2nd a/c, she advised 14 min ETE for second a/c, I advised her that I did not have GC, she said she would call Clay County Direct
8/26/2011	19:31:11	OBURR	Added Note: ** Dispatch - @1930 notified Nikki in Harrison ER of a/c involved in
		0201111	incident
8/26/2011	19:31:41	JSKYLER	Added Note: ** Dispatch - 1822 Arranged fuel with Midwest Fuel - John, gave 19 min ETE
8/26/2011	19:32:35	JSKYLER	Added Note: ** Dispatch - 1845 Contacted Midwest Fuel - John to find out if A/C
8/26/2011	19:38:04	JSKYLER	nad landed, he advised they had not would have crew call upon land Added Note: ** Dispatch - 1849 Contacted Midwest Fuel - John he advised he had contact with A/C approx 5-7 mins previous and they were about 5mi north of
0/06/0044	40,00,04	1010// 50	A/P
8/26/2011	19:38:34	JSKYLER	Added Note: ** Dispatch - 1851 Attempted contact with pilot via work cell and personal cell
8/26/2011	19:41:03	JSKYLER	Added Note: ** Dispatch - 1853 - 1855 Attempted to contact Clay Cnty Dispatch, number would not ring through
8/26/2011	19:41:41	JSKYLER	Added Note: ** Dispatch - 1857 Contacted Liberty Police - McGregor was given
			dispatch number for Clay Cnty
8/26/2011	19:42:12	JSKYLER	Added Note: ** Dispatch - 1858 Contacted Clay Cnty - Heather she advised they
8/26/2011	19:43:42	OPLIBB	had not received any reports but would call back if they heard anything
0/20/2011	19.43.42	OBURR	Added Note: ** Dispatch - Tried multiple times to reach Clay County Regional A/P to check on status of a/c, no number listed under AirNav and numbers found
			using Google were incorrect
8/26/2011	19:43:47	JSKYLER	Added Note: ** Dispatch - 1900 Contacted Clay cnty - Heather requesting they
0/00/0044	40.440-		send a unit to last known coordinates
8/26/2011	19:44:07	JSKYLER	Added Note: ** Dispatch - 1901 Attempted to contact pilot personal cell again, no
8/26/2011	19:46:26	JSKYLER	Added Note: ** Dispatch 1903 Contacted Life Flight Fords Lavings at 1903
J. M. G. M. G. T. T.	, o. , o	OOKILLIK	Added Note: ** Dispatch - 1903 Contacted LifeFlight Eagle - Lori requesting A/C in area try air to air, she advised the A/C was unable to make contact
8/26/2011	19:47:07	JSKYLER	Added Note: ** Dispatch - 1906 Contacted Clay cnty - Tim he advised they had
0/00/0044	40 47 00	10100000	received reports of smoke coming from a field and were sending units
8/26/2011	19:47:30	JSKYLER	Added Note: ** Dispatch - Add to previous note - Smoke in field at Cameron Rd x Hwy 69
8/26/2011	19:49:07	JSKYLER	Added Note: ** Dispatch - 1909 Contacted LifeFlight Eagle - Lori requested they
			dispatch A/C to last known coordinates
8/26/2011	19:49:41	JSKYLER	Added Note: ** Dispatch - 1910 Contacted Clay Cnty - Tim confirmed fire &
8/26/2011	19:49:59	IOMALED	ambulance were en route to scene, should be arriving in a few minutes
8/26/2011	19:49:59	JSKYLER JSKYLER	Added Note: ** Dispatch - 1911 Clay Cnty called confirmed 2 fatalities
0,20,2011	10.00.22	JORTELIX	Added Note: ** Dispatch - 1912 Contacted LF Eagle - Lori for ETE, she advised 18 mins
8/26/2011	19:51:56	JSKYLER	Added Note: ** Dispatch - 1913 Contacted Clay Cnty - Stacy advising 16 min
0.10.0.10.0.4.4	40.50.00		ETE for LF Eagle, she confirmed crash and multiple fatalities
8/26/2011	19:52:23	JSKYLER	Added Note: ** Dispatch - 1915 Contacted LF Eagle - Lori requesting 2nd A/C
8/26/2011	19:52:49	JSKYLER	Added Note: ** Dispatch - 1916 Contacted Clay Cnty - Stacy for GC for LF Eagle
8/26/2011	19:53:01	JSKYLER	Added Note: ** Dispatch - 1916 Passed GC to LF Eagle - Lori
8/26/2011	19:53:13	JSKYLER	Added Note: ** Dispatch - 1917 Clay Cnty - Stacy confirmed 4 fatalities
8/26/2011	19:53:29	JSKYLER	Added Note: ** Dispatch - 1923 LF Eagle - Lori advised 7 min ETE
8/26/2011	19:55:51	JSKYLER	Added Note: ** Dispatch - 1924 LF Eagle - Kristina called wanting to confirm
0/00/0044	40-50-40	10104 ==	having A/C continue to scene
8/26/2011	19:56:12	JSKYLER	Added Note: ** Dispatch - 1927 Was given 4 min ETE by LF Eagle - Lori
8/26/2011	19:56:42	JSKYLER	Added Note: ** Dispatch - 1934 LF Eagle - Lori called advising landed on scene
8/26/2011	19:57:04	JSKYLER	Added Note: ** Dispatch - 1944 Contacted LF Eagle - Lori she advised she had no news, hadn't heard from crew
8/26/2011	19:59:12	JSKYLER	Added Note: ** Dispatch - 1957 Contacted LF Eagle - Dick, he confirmed all 4
			fatalities



Unit Name	Date / Time	Lattitude	Longitude	Altitude	Heading	Speed
MO LifeNet 2-2 N352L	N 26-Aug-11 5:28:02 P	M No GPS	No GPS	00000	Market and the interest and the feet of the feet	000
MO LifeNet 2-2 N352L	N 26-Aug-11 5:28:31 P	M 39:46.216 N	094:54.187 W	01128		000
MO LifeNet 2-2 N352L	N 26-Aug-11 5:29:01 P	M 39:46.216 N	094:54.187 W	00968	etattetterin a value est romas e	000
MO LifeNet 2-2 N352L	N 26-Aug-11 5:29:45 Pl	M 39:46.516 N	094:54.201 W	01096		041
MO LifeNet 2-2 N352L	N 26-Aug-11 5:30:14 PI	M 39:46.841 N	094:53.574 W	01176		093
MO LifeNet 2-2 N352L	N 26-Aug-11 5:30:44 PI	M 39:47.421 N	094:52.784W	01480		104
MO LifeNet 2-2 N352L	N 26-Aug-11 5:31:13 Pl	M 39:47.900 N	094:51.863 W	01640		109
MO LifeNet 2-2 N352L	N 26-Aug-11 5:31:42 Pl	M 39:48.438 N	094:50.890 W	01664		116
MO LifeNet 2-2 N352L	N 26-Aug-11 5:32:11 PI	M 39:49.017 N	094:49.948 W	01688		111
MO LifeNet 2-2 N352L	N 26-Aug-11 5:32:40 PI	M 39:49.602 N	094:49.097 W	01880		111
MO LifeNet 2-2 N352L	N 26-Aug-11 5:34:08 Pt	M 39:51.273 N	094:46.068 W	01728		121
MO LifeNet 2-2 N352L	N 26-Aug-11 5:34:38 PI	M 39:51.816 N	094:44.992 W	01736		117
MO LiteNet 2-2 N352L	N 26-Aug-11 5:35:07 PI	M 39:52.310 N	094:43.955 W	01744		115
MO LifeNet 2-2 N352L	N 26-Aug-11 5:35:36 Pt	VI 39:52.853 N	094:42.961 W	01744		118
MO LifeMet 2-2 N352L	N 26-Aug-11 5:36:04 Pt	M 39:53.386 N	094:41.986 W	01744		116
MO LifeNet 2-2 N352L	N 26-Aug-11 5:36:34 Pt	M 39:53.906 N	094:40.947 W	01832		114
MO LifeNet 2-2 N352L	N 26-Aug-11 5:37:03 Pt	V 39:54.395 N	094:39.945 W	01904		112
MO LifeNet 2-2 N352L	N 26-Aug-11 5:37:32 Pt	M 39:54.895 N	094:38.947 W	01936		114
MO LifeNet 2-2 N352L	N 26-Aug-11 5:38:02 Pt	M 39:55.424 N	094:37.903 W	01976	· · · · · · · · · · · · · · · · · · ·	114
MO LifeNet 2-2 N352L	N 26-Aug-11 5:38:31 PI	M 39:55.907 N	094:36.889 W	02064		114
MO LifeNet 2-2 N352L	N 26-Aug-11 5:39:00 Pt	M 39:56,413 N	094:35.872 W	02104		116
MO LifeNet 2-2 N352L	N 26-Aug-11 5:39:29 Pt	√ 39:56.996 N	094:34.877 W	02072		120
MO LifeNet 2-2 N352L	N 26-Aug-11 5:39:58 Pt	M 39:57.606 N	094:33.897 W	02064		120
MO LifeNet 2-2 N352L	V 26-Aug-11 5:40:28 Pt	M 39:58.205 N	094:32.839 W	01984		122
MO LifeNet 2-2 N352L	V 26-Aug-11 5:40:57 Ph	M 39:58.734 N	094:31.783 W	01984		116
Service Commission of the Comm	V 26-Aug-11 5:41:26 Ph	and the second second second	094:30.783 W	01960	· · · · · · · · · · · · · · · · · · ·	120
MO LifeNet 2-2 N352L	V 26-Aug-11 5:41:55 Ph	vi 39:59.817 N	094:29.730 W	01936	**************************************	119
MOTHUMAN 2-2 MAEST	1 26-Ann-11 5-42-25 Dk	√ 40·00 317 N	በባፈ-28 ቤ1ፊ ላል/	กาจจะ		118

Unit Name	Date / Time	Lattitude	Longitude	Altitude Heading	Speed
VO LifeNet 2-2 N35	2LN 26-Aug-11 5:41:26	PM 39:59.284 N	094:30.783 W	01960	120
VIO LifeNet 2-2 N35	2LN 26-Aug-11 5:41:55	PM 39:59.817 N	094:29,730 W	01936	119
VO LifeNet 2-2 N35	2LN 26-Aug-11 5:42:25	PM 40:00.317 N	094:28.614W	01936	118
WO LiteNet 2-2 N35	2LN 26-Aug-11 5:42:54	PM 40:00.855 N	094:27.547 W	01864	128
MO LifeNet 2-2 N35	2 LN 26-Aug-11 5:43:23	PM 40:01.431 N	094:26.527 W	01856	121
VIO LifeNet 2-2 N35	2LN 26-Aug-11 5:43:52	PM 40:01.985 N	094:25.478 W	01880	118
MO LiteNet 2-2 N35	2LN 26-Aug-11 5:44:22	PM 40:02.531 N	094:24.385 W	01848	121
vi0 LiteNet 2-2 N35	<mark>2LN 26-Aug-11 5:44:51</mark>	PM 40:03.077 N	094:23.322W	01800	121
MO LifeNet 2-2 N35	2LN 26-Aug-11 5:45:21 I	PM 40:03.649 N	094:22.232 W	01768	123
VIO LifeNet 2-2 N35	2LN 26-Aug-11 5:45:49 I	PM 40:04.176 N	094:21.200 W	01744	122
VO LifeNet 2-2 N35)	2LN 26-Aug-11 5:46:18 I	PM 40:04.700 N	094:20.107 W	01680	122
40 LifeNet 2-2 N35	2LN 26-Aug-11 5:46:47 I	PM 40:05.281 N	094:19.054W	01648	123
/IO LifeNet 2-2 N35;	2LN 26-Aug-11 5:47:16 (PM 40:05.831 N	094:18.009 W	01656	119
40 LifeNet 2-2 N35)	2LN 26-Aug-11 5:47:45 (PM 40:06.356 N	094:16.952W	01632	119
40 LiteNet 2-2 N35(2LN 26-Aug-11 5:48:43 (PM 40:07.469 N	094:14.996 W	01768	113
/IO LifeNet 2-2 N35	2LN 26-Aug-11 5:49:12 I	PM 40:07.989 N	094:14.012 W	01856	112
40 LifeNet 2-2 N352	2LN 26-Aug-11 5:49:42 F	PM 40:08.513 N	094:13.022W	01976	116
/10 LifeNet 2-2 N35/	LN 26-Aug-11 5:50:11 F	PM 40:09.055 N	094:11.968 W	01840	121
40 LifeNet 2-2 N352	2LN 26-Aug-11 5:50:40 F	PM 40:09.564 N	094:10.892 W	01800	119
40 LifeNet 2-2 N352	2LN 26-Aug-11 5:51:09 F	PM 40:10.071 N	094:09.848 W	01856	116
40 LifeNet 2-2 N352	LN 26-Aug-11 5:51:38 F	PM 40:10,627 N	094:08.872 W	01936	116
40 LifeNet 2-2 N352	LN 26-Aug-11 5:52:07 F	PM 40:11.121 N	094:07,832 W	01968	117
10 LifeNet 2-2 N352	<mark>LN</mark> 26-Aug-11 5:52:36 F	PM 40:11.588 N	094:06.748 W	01952	122
10 LifeNet 2-2 N352	LN 26-Aug-11 5:53:05 F	PM 40:12.230 N	094:05.777 W	01944	121
10 LifeNet 2-2 N352	2N 26-Aug-11 5:53:34 F	PM 40:12.945 N	094:04.845 W	01832	127
10 LifeNet 2-2 N352	LN 26-Aug-11 5:54:03 F	PM 40:13.683 N	094:03.959 W	01776	119
10 LifeNet 2-2 N352	LN 26-Aug-11 5:54:32 F	M 40:14.311 N	094:03.120 W	01544	106
AO LifaNat 9-9 NRES	и м 96-дин-11 Б.ББ.Л2 Г	N ROR LI-NL MC	.09.4∙02.415.VV	N1 44N	naa

Unit Name	Date / Time	Lattitude	Longitude	Altitude	Heading	Snead
MO LifeNet 2-2 N352LN	26-Aug-11 5:54:32 PM	40:14.311 N	094:03.120 W	01544	And the state of t	ореси 10
MO LifeNet 2-2 N352LN	26-Aug-11 5:55:02 PM	40:14.898 N	094:02.415 W	01440		08
MO LifeNet 2-2 N352LN	26-Aug-11 5:55:34 PM	40:15.545 N	094:01.914W	01424	designed areas some constructions	07
MO LiteNet 2-2 N352LN	26-Aug-11 5:56:33 PM	40:15.882 N	094:01.472 W	01112		00
VIO LifeNet 2-2 N352LN	26-Aug-11 5:57:02 PM	40:15.857 N	094:01.502 W	00968		00
dO LifeNet 2-2 N352LN	26-Aug-11 5:57:31 PM	40:15.856 N	094:01.506 W	00944	······································	000
VO LiteNet 2-2 N352LN	26-Aug-11 5:58:00 PM	40:15.856 N	094:01.506 W	00944		001
dO LiteNet 2-2 N352LN			094:01.506 W	00960		000
10 LifeNet 2-2 N352LN			094:01.506 W	00928		000
10 LifeNet 2-2 N352LN	26-Aug-11 6:10:33 PM	40:15.858 N	094:01.509 W	00960		000
10 LifeNet 2-2 N352LN			094:01.509 W	00920		000
IO LifeNet 2-2 N352LN			094:01:509 W	00928	Service Control	000
IO LifeNet 2-2 N352LN			094:01.534W	01176	. ۋەسىي يەسەد سىدىسەد ئ	061
IO LifeNet 2-2 N352LN			094:01.744W	01344	······································	094
O LiteNet 2-2 N352LN	26-Aug-11 6:13:02 PM	40:14.232 N	094:01.912 W	01384		100
O LifeNet 2-2 N352LN	26-Aug-11 6:13:31 PM	40:13.371 N	094:02.169 W	01384		109
O LifeNet 2-2 N352LN			094:02.408 W	01336		114
O LifeNet 2-2 N352LN	26-Aug-11 6:14:29 PM	40:11.590 N	094:02.664W	01328		112
O LifeNet 2-2 N352LN (094:02.854W	01272	······································	116
O LiteNet 2-2 N352LN (094:03.000 W	01256		115
O LiteNet 2-2 N352LN 2	26-Aug-11 6:15:57 PM	40:08.808 N	094:03.144W	01264		112
O LifeNet 2-2 N352LN 2	26-Aug-11 6:16:27 PM	40:07.885 N	094:03.286 W	01336		111
O LifeNet 2-2 N352LN 2	26-Aug-11 6:16:56 PM	40:06.998 N	094:03.484W	01 408	2	110
D LifeNet 2-2 N352LN 2	26-Aug-11 6:17:25 PM	40:06.122 N	094:03,800 W	01384		116
D LifeNet 2-2 N352LN 2	26-Aug-11 6:17:54 PM	40:05.240 N	094:04.207 W	01352		115
DiLifeNet 2-2 N352LN 2	26-Aug-11 6:18:24 PM	40:04.322 N	094:04.604W	01312		116
O LifeNet 2-2 N352LN 2	6-Aug-11 6:18:53 PM	40:03.408 N	094:04.860 W	01312		114
() i ifaNat 2-2 N9521 N 2	'G-Δun=11 G·19·23 PM .	40:02 464 N	094:05 108 W	N1 288		116

Unit Name	Date / Time	Lattitude	Longitude	Altitude Headin	Speed
VIO LifeNet 2-2 N352	LN 26-Aug-11 6:18:53 PM	40:03.408 N	094:04.860 W	01312	114
MO LifeNet 2-2 N352	LN 26-Aug-11 6:19:23 PM	40:02.464 N	094:05.108 W	01288	116
MO LifeNet 2-2 N352	LN 26-Aug-11 6:19:51 PM	40:01.594 N	094:05.361 W	01320	113
MO LifeNet 2-2 N352	LN 26-Aug-11 6:20:21 PM	40:00.670 N	094:05.634W	01360	112
MO LifeNet 2-2 N352	LN 26-Aug-11 6:20:50 PM	39:59.800 N	094:05.921 W	01440	110
MO LifeNet 2-2 N352	LN 26-Aug-11 6:21:20 PM	39:58.896 N	094:06.222 W	01480	113
MO LiteNet 2-2 N352	LN 26-Aug-11 6:21:49 PM	39:58.007 N	094:06.479 W	01520	112
MO LiteNet 2-2 N352	LIN 26-Aug-11 6:22:18 PM	39:57.108 N	094:06.730 W	01512	114
MONTH IN THE PROPERTY OF THE P	LN 26-Aug-11 6:22:47 PM		094:06.983 W	01544	112
WO LifeNet 2-2 N352	LN 26-Aug-11 6:23:16 PM	39:55.317 N	094:07.211 W	01584	113
MO LiteNet 2-2 N352	LN 26-Aug-11 6:23:45 PM	39:54.424 N	094:07.460 W	01608	114
MO LifeNet 2-2 N352	LN 26-Aug-11 6:24:15 PM	39:53.480 N	094:07.728 W	01576	115
vIO LifeNet 2-2 N352	N 26-Aug-11 6:24:44 PM	39:52.572 N	094:08.001 W	01592	115
VO LifeNet 2-2 N352	N 26-Aug-11 6:25:13 PM	39:51.670 N	094:08.277 W	01616	114
VIO LifeNet 2-2 N352	N 26-Aug-11 6:25:42 PM	39:50.768 N	094:08.539 W	01616	115
MO LifeNet 2-2 N352	N 26-Aug-11 6:26:11 PM	39:49.841 N	094:08.782 W	01560	117
MO LifeNet 2-2 N352	N 26-Aug-11 6:26:39 PM	39:48.949 N	094:09.024W	01544	116
MO LiteNet 2-2 N352	_N 26-Aug-11 6:27:08 PM	39:48.038 N	094:09.275 W	01560	115
rin erination mendalah arang dari ada baran keringan bahan bahan bahan bahan bahan bahan bahan bahan bahan bah	.N 26-Aug-11 6:27:37 PM	And the enterty of the	094:09.577 W	01584	117
иO LifeNet 2-2 N352	.N 26-Aug-11 6:28:07 PM	39:46.193 N	094:09.934W	01584	116
//O LifeNet 2-2 N352	N 26-Aug-11 6:28:36 PM	39:45.286 N	094:10.268 W	01584	118
40 LifeNet 2-2 N352	N 26-Aug-11 6:29:05 PM	39:44.378 N	094:10.606 W	01616	117
40 LifeNet 2-2 N352I	N 26-Aug-11 6:29:33 PM	39:43.503 N	094:10.930 W	01616	116
/IO LifeNet 2-2 N352	N 26-Aug-11 6:30:02 PM	39:42.598 N	094:11.245 W	01600	115
/O LifeNet 2-2 N352	.N 26-Aug-11 6:30:32 PM	39:41.666 N	094:11.486W	01624	113
40 LifeNet 2-2 N352	N 26-Aug-11 6:31:01 PM	39:40.776 N	094:11.714W	01640	111
40 LifeNet 2-2 N3521	JN 26-Aug-11 6:31:30 PM	39:39.902 N	094:11.990 W	01648	: 111
JO I ifoNot 9-9 NRE?	N 26-Aug-11 6:31:59 PM	39-39 N17 N	N9∆12 223 W	การาธ	119

MO LifeNet 2-2 N352LN	26-Aug-11 6:31:30 PM 39:39.902 N	094:11.990 W	01648	111
MO LifeNet 2-2 N352LN	26-Aug-11 6:31:59 PM 39:39.017 N	094:12.223 W	01616	112
MO LiteNet 2-2 N352LN	26-Aug-11 6:32:28 PM 39:38.135 N	094:12.472 W	01592	111
MO LifeNet 2-2 N352LN	26-Aug-11 6:32:56 PM 39:37.285 N	094:12.694W	01600	111
MO LifeNet 2-2 N352LN	26-Aug-11 6:33:25 PM 39:36.406 N	094:12.966 W	01576	112
MO LifeNet 2-2 N352LN	26-Aug-11 6:33:55 PM 39:35.515 N	094:13.242 W	01648	108
MO LifeNet 2-2 N352LN	26-Aug-11 6:34:24 PM 39:34.638 N	094:13.485 W	01616	111
MO LifeNet 2-2 N352LN	26-Aug-11 6:34:53 PM 39:33.740 N	094:13.658 W	01600	112
MO LifeNet 2-2 N352LN	26-Aug-11 6:35:22 PM 39:32.860 N	094:13.914W	01608	112
MO LifeNet 2-2 N352LN	26-Aug-11 6:35:50 PM 39:32.002 N	094:14.142 W	01600	113
MO LifeNet 2-2 N352LN	26-Aug-11 6:36:19 PM 39:31.110 N	094:14.381 W	01600	112
MO LifeNet 2-2 N352LN	26-Aug-11 6:36:49 PM 39:30.194 N	094:14.620 W	01600	110
MO LifeNet 2-2 N352LN	26-Aug-11 6:37:18 PM 39:29.324 N	094:14.884 W	01616	111
MO LifeNet 2-2 N352LN	26-Aug-11 6:37:47 PM: 39:28.448 N	094:15.141 W	01616	111
MO LifeNet 2-2 N352LN	26-Aug-11 6:38:17 PM 39:27.538 N	094:15.410 W	01600	112
MO LifeNet 2-2 N352LN	26-Aug-11 6:38:46 PM 39:26.662 N	094:15.738 W	01568	113
MO LiteNet 2-2 N352LN	26-Aug-11 6:39:14 PM 39:25.800 N	094:16.017 W	01504	113
MO LifeNet 2-2 N352LN	26-Aug-11 6:39:43 PM 39:24.911 N	094:16.280 W	01448	113
MO LifeNet 2-2 N352LN	26-Aug-11 6:40:12 PM 39:24.017 N	094:16.600 W	01336	118
viO LifeNet 2-2 N352LN	26-Aug-11 6:40:41 PM 39:23.118 N	094:16.998 W	01256	116
VIO LifeNet 2-2 N352LN	26-Aug-11 6:41:10 PM : 39:22.228 N	094:17.377 W	01200	116