

Aircraft Accident Package
OUN-FCT-0001
N4252G, SR20
June 9, 2016, 1810 UTC
Destroy: December 9, 2018 UTC

Section 1.

Table of Contents


Table of Contents

SECTION NO.	TITLE
SECTION 1.	Table of Contents
SECTION 2.	FAA Form 8020-6, Report of Aircraft Accident, and FAA Form 8020-6-1, Report of Aircraft Accident (Continuation Sheet)
SECTION 3.	Review of Services Memo
SECTION 4.	FAA Form 7230-4, Daily Record of Facility Operation
SECTION 5.	Personnel Log
SECTION 6.	FAA Form 7230-10, Position Logs
SECTION 7.	Facility Layout Chart
SECTION 8.	Airport Diagram
SECTION 9.	Weather Products

Section 2.

FAA Form 8020-6, Report of Aircraft Accident,
and FAA Form 8020-6-1, Report of Aircraft Accident (Continuation Sheet)

FAA Form 8020-6, Report of Aircraft Accident

DEPARTMENT OF TRANSPORTATION FEDERAL AVIATION ADMINISTRATION		REPORT DATE June 21, 2016	REPORT NO. OUN-FCT-0001				
REPORT OF AIRCRAFT ACCIDENT		NAME OF REPORTING FACILITY Westheimer FCT (OUN)					
1. AIRCRAFT IDENTIFICATION AND TYPE N4252G, SR20	2. DATE/TIME OF ACCIDENT (UTC) June 9, 2016; 1810 UTC	3. LOCATION OF ACCIDENT (MAND) Houston, TX, 1/2 mi. northwest of Hobby Airport					
		LATITUDE/LONGITUDE (OPTL)					
4. NATURE OF ACCIDENT Aircraft crashed on departure		5. TYPE OF FLIGHT VFR					
6. FLIGHT CREW	NAME	POSITION	ADDRESS (CITY AND STATE)	UNINJURED	INJURED	FATALITY	UNKN
	Dana Gray	Pilot	Moore, OK			X	
7. PASSENGER DATA	NUMBER ABOARD AIRCRAFT 2	NUMBER UNINJURED 0	NUMBER INJURED 0	NUMBER FATALITIES 2			
8. AIRCRAFT DAMAGE Destroyed		9. PROPERTY DAMAGE Unknown					
10. OPERATING STATUS OF NAVIGATIONAL AIDS/LIGHTS/COMMUNICATIONS Normal							
11. WEATHER DATA (USE UTC DATE/TIME)	REPORT JUST PRIOR TO ACCIDENT Houston Hobby METAR-1810 UTC: wind zero eight zero at one one knots, visibility one zero statute miles, few clouds four thousand five hundred, temperature three two, dew point two two, altimeter two nine nine four						
	FIRST REPORT SUBSEQUENT TO ACCIDENT Houston Hobby METAR-1815: wind zero eight zero at one one gusts one nine, visibility one zero statute miles, few clouds four thousand five hundred, temperature three two, dew point two two, altimeter two nine nine three						
12. ATO PERSONNEL INVOLVED	NAME	FACILITY	OPERATING POSITION	CHECK IF EYEWITNESS			
* OPERATING INITIALS							
13. SIGNATURE OF FACILITY MANAGER Phillip A. Miner 							



DEPARTMENT OF TRANSPORTATION
FEDERAL AVIATION ADMINISTRATION

REPORT DATE
June 16, 2016

REPORT NO.
OUN-FCT-0001

REPORT OF AIRCRAFT ACCIDENT

(Continuation Sheet)

NAME OF REPORTING FACILITY
Westheimer FCT (OUN)

14. CHRONOLOGICAL SUMMARY OF FLIGHT

June 9, 2016

ALL TIMES BELOW ARE COORDINATED UNIVERSAL TIME
UNLESS OTHERWISE SPECIFIED

1501 N4252G called Ground Control (GC) for taxi and a southbound departure. GC instructed N4252G to taxi to Runway 21. N4252G acknowledged.

1508 N4252G called Local Control (LC) and advised ready for takeoff southbound and requested a frequency for traffic advisories. LC advised N4252G to contact Oklahoma City departure on 124.2 for flight following and cleared N4252G for takeoff on Runway 21. N4252G acknowledged.

1510 LC advised N4252G a frequency change was approved.

No More Follows

Section 3.

Review of Services Memo



Robinson Aviation (RVA), Inc.

Our Quality Goal: "Do each job right the first time, every time."

Memorandum

Date: June 15, 2016

To: Accident File OUN-FCT-0001

From: Phillip A. Miner, Manager, Westheimer FCT, OUN FCT

Subject: **INFORMATION**: Review of Services Memo
Aircraft Accident N4252G
Houston, TX, June 9, 2016

OUN FCT conducted a review of services concerning N4252G and was determined to have routine services. As the holding facility with routine services I certify the following data has been retained in accordance with FAA Order 8020.16. Additionally, I certify that the following originals/digital copies are on file in this office.

FAA Form 8020-6
FAA Form 8020-6-1
FAA Form 7230-4
FAA Form 7230-10
Personnel Log
Certified Original Copies of Voice Recordings
Certified Working Copies of Voice Recordings
Facility Layout Chart
Airport Diagram
Weather Products

Section 4.

FAA Form 7230-4, Daily Record of Facility Operation

DAILY RECORD OF FACILITY OPERATION				PAGE NO
				Page 1 of 1
LOCATION Norman, OK				DATE
				Jun 9, 2016
IDENTIFICATION OUN		TYPE FACILITY ATCT		OPERATING POSITION
				OS/CIC
UTC TIME				CHECKED BY
				<i>[Signature]</i>
REMARKS				AIR TRAFFIC MANAGER
				Phillip Miner
1300	H.HERLONG ON, WCLC. -- HG			
2045	J. TRICE ON, WCLC. -- JT			
0259	COB. -- JT			
I CERTIFY that entries above are correct, that all scheduled operations have been accomplished except as noted, and that all abnormal occurrences and conditions have been recorded.				SIGNATURE(S) OF WATCH SUPERVISOR(S) 

FAA Form 7230-4

OUN-FCT-0001
N4252G

Section 5.
Personnel Log

Max Westheimer, OK, Area IV

Sign In/Sign Out

Week Of 6/5 - 6/11

DATE 5 Sun

SIGNATURE	INT	IN	OUT	HOURS	REMARKS
[Redacted]	PM				
[Redacted]	BD	1915	2215		
[Redacted]	HG				
[Redacted]	SR	1030	1830	8	
[Redacted]	JT	0745	1545	8	

DATE 9 Thur

SIGNATURE	INT	IN	OUT	HOURS	REMARKS
[Redacted]	PM	1030	1830	8	
[Redacted]	BD				RDO
[Redacted]	HG	0745	1545	8	
[Redacted]	SR				RDO
[Redacted]	JT	1315	2215	9	

DATE 6 Mon

SIGNATURE	INT	IN	OUT	HOURS	REMARKS
[Redacted]	PM	08	16	8	
[Redacted]	BD	1030	1630	8	
[Redacted]	HG	1915	2215	8	
[Redacted]	SR	0745	1545	8	
[Redacted]	JT				

DATE 10 Fri

SIGNATURE	INT	IN	OUT	HOURS	REMARKS
[Redacted]	PM	08	16	8	
[Redacted]	BD				
[Redacted]	HG	0745	1545	8	
[Redacted]	SR	1415	2215	8	
[Redacted]	JT	1030	1830	8	

DATE 7 Tues

SIGNATURE	INT	IN	OUT	HOURS	REMARKS
[Redacted]	PM	08	16	8	
[Redacted]	BD	0745	1545	8	
[Redacted]	HG	1415	2215	8	
[Redacted]	SR	1030	1830	8	
[Redacted]	JT				

DATE 11 Sat

SIGNATURE	INT	IN	OUT	HOURS	REMARKS
[Redacted]	PM				
[Redacted]	BD	1415	2215		
[Redacted]	HG				
[Redacted]	SR	1030	1830	8	
[Redacted]	JT	0745	1545	8	

DATE 8 Wed

SIGNATURE	INT	IN	OUT	HOURS	REMARKS
[Redacted]	PM				SVAC
[Redacted]	BD	0745	1545		
[Redacted]	HG	1030	1830	8	
[Redacted]	SR				
[Redacted]	JT	1415	2215	8	

DATE _____

SIGNATURE	INT	IN	OUT	HOURS	REMARKS

OUN Form 1320.1-1 Rev. 6-1-13

OUN-FCT-0001
N4252G

Section 6.

FAA Form 7230-10, Position Logs

Position Log

(1) FACILITY ID	(2) POSITION IDENTIFIER	(3) Pos Type	(4) DATE		
O, U, N	G, C		0, 6, 10, 9, 1, 6		
(5) TIME ON	(6) INITIALS	(7) TIME OFF	(8) Code	Where Combined	
				(9) POSITION IDENTIFIER	(10) Position Type
13,0,0		15,29		LC	LC
15,30	P, M	17,04	S		
17,05	H, G	19,52	C		
19,53	J, T	21,44	C		
21,45		0,25,9		LC	LC

CODE:
 C = ATCS/ATA M = Trainee/Developmental Monitoring
 S = Supervisor/Staff Spec. R = Trainee/Developmental Certification/
 T = Trainee/Developmental Evaluation

Position Log


(1) FACILITY ID	(2) POSITION IDENTIFIER	(3) Pos Type	(4) DATE		
O, U, N	LC		0, 6, 10, 9, 1, 6		
(5) TIME ON	(6) INITIALS	(7) TIME OFF	(8) Code	Where Combined	
				(9) POSITION IDENTIFIER	(10) Position Type
13,00	H, G	17,04	C		
17,05	P, M	17,59	S		
18,00	J, T	19,52	C		
19,53	P, M	21,44	S		
21,45	J, T	0,25,9	C		

CODE:
 C = ATCS/ATA M = Trainee/Developmental Monitoring
 S = Supervisor/Staff Spec. R = Trainee/Developmental Certification/
 T = Trainee/Developmental Evaluation

Section 7.

Facility Layout Chart

WESTHEIMER FCT LAYOUT



Section 8.


Airport Diagram

16091

AIRPORT DIAGRAM

AL-198 (FAA)

WILLIAM P HOBBY (HOU)
HOUSTON, TEXAS



Section 9.

Weather Products

Westheimer FCT

Weather Products 06/09/16

METAR KHOU 091810Z 08011KT 10SM FEW045 32/22 2994

METAR KHOU 091815Z 08011G19KT 10SM FEW045 32/22 2993

I certify the attached copy of the METAR originated from the KHOU APG-link to archived weather is an accurate copy of the original.

Phillip A. Miner

Phillip A. Miner
Air Traffic Manager
Westheimer FCT

OUN-FCT-0001
N4252G