



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Washington, D.C. 20594

January 3, 2018

Attachment 8 – Air Canada’s Ramp Reconciliation Report

OPERATIONAL FACTORS/HUMAN PERFORMANCE

DCA17IA148

Ramp_Reconciliation_Report_AC0759_08_YYZ-SFO_-_RLST(1)

RLST AC0759 07(1)
FLIGHT: AC0759
ROUTING: *YYZ*SFO
STD: 07/08/17 0055z
RLST SUBMIT DATE: 7/8 0126z
AGENT: [REDACTED]

CME(2) OK
BAG(2) OK
ZFW(4) OK
OFP(2) OK
Cgo(1) WARN
LP(2) WARN
LI(1) OK
Fuel Slip(1) OK
FOB(3) OK
Rmp-F(1) OK
Pax(1) OK
L/S(0) ERROR
ACK(0) ERROR
OUT(0) ERROR
OFF(0) ERROR

All weights in [KG]

Bags Count: 104
Cargo: 241
FP Underload: 1369
Underload TOW: 1334
DOW: 44360
ZFW: 57605
LOAD: 13245
TOW: 74995
LAW: 61184
ZFW CG: 37.74
TOW CG: 31.86

ITEMS LEFT ON THE GROUND

.....
: BLK 0AC BT YYZ SFO SFO 30 2 DOM :
: 30 BT 2 :
: BLK 0AC BT YYZ SFO SFO 15 1 INT :
: 15 BT 1 :
:.....

ITEMS POSITIONED

LOWER DECK

PART 2 TO FOLLOW

=

Ramp_Reconciliation_Report_AC0759_08_YYZ-SFO_-_RLST(1)

RLST AC0759 07(1)
FLIGHT: AC0759
ROUTING: *YYZ*SFO
STD: 07/08/17 0055z
RLST SUBMIT DATE: 7/8 0126z
AGENT: ██████████

```
.....  
:11  NIL :  
:12  AKH59157AC B YYZ SFO SFO 697 32 41 :  
:    615 B 32 41 :  
:13  AKH59604R7 M YYZ SFO 241 0 35 :  
:31  AKH54393AC B YYZ SFO SFO 547 32 31 :  
:    465 B 32 31 :  
:32  AKH55468AC B YYZ SFO SFO 277 32 13 :  
:    195 B 32 13 :  
:41  AKH59554AC BF YYZ SFO SFO 217 6 9 :  
:    135 BF 6 9 :  
:42  AKH57673AC B YYZ SFO SFO 112 13 2 :  
:    30 B 13 2 :  
:51  BLK 0AC BF,GB YYZ SFO 84 0 8 :  
:    30 BF 0 2 :  
:    54 GB 0 6 :  
.....
```

CABIN LOAD

```
.....  
:0A  NIL :  
:0B  NIL :  
:0C  NIL :  
.....
```

NESTED EQUIPMENT
NONE