

**Docket No. SA-532**

**Exhibit No. 2-I**

**NATIONAL TRANSPORTATION SAFETY BOARD**

**Washington, D.C.**

Operations/Human Performance Group Chairmen  
US Airways - ECAM Exceptions

(1 Page)

## **Attachment 8**

**to Operations / Human Performance Group Factual Report**

**DCA09MA026**

**ECAM EXCEPTIONS**

**— Immediate Actions Index —**

Capt PFD, ND and the Upper ECAM Display Blank.....	iv
ENG (1 or 2) FIRE (On Ground) .....	ii
Engine-Out Unable to Maintain Altitude .....	iii
Engine Tailpipe Fire .....	ii
Evacuation .....	i
SMOKE/AVIONICS SMOKE/FUMES .....	iv
Unreliable Speed Indication/ADR Check Procedure .....	iv

**— ECAM Exceptions Index —**

<u>AVIONICS SMOKE</u> .....	iv
<u>BRAKES HOT</u> (On Ground Only) .....	60
<u>ENG DUAL FAILURE</u> .....	27
<u>FUEL</u> (L or R) WING TANK LO LVL.....	54
<u>NAV ADR</u> (1+2 or 2+3 or 1+3) FAULT .....	41
<u>SMOKE</u> (FWD or AFT) CARGO SMOKE (With Cargo Door Open) .....	11