

## **Minimum Altitude for VFR**

**Number:** 08-2015

**Issue Date:** 12/18/15

**Issuer:** Raj Helweg, Chief Pilot

**Issued To:** Regional Management  
(And posted to 411 for pilots)

**Response Type:**  Critical – requires an immediate response or action  
 Non-critical – does not require an immediate response

**Archive Note:** The content of this bulletin will be rolled into the appropriate manual at the next revision and this bulletin will be archived.

**Location:** Air Methods Bulletins are posted on FlightDeck > Resources > Corp Pubs > Air Methods Bulletins.

### **General Information:**

Estimated 800,000 + Drones/UAS sold this holiday season, we have determined the best way to mitigate encounters is to follow section 3.9-Minimum Altitude for VFR of the [General Operations Manual \(GOM\)](#). Effective immediately we will be implementing a zero tolerance policy for deviation.

### **Further Information:**

Any questions regarding this bulletin should be addressed to:

**Raj Helweg**

Chief Pilot

██████████

████████████████████

**Dennis Mc Call**

Director of Operations

██████████

████████████████████