

Attachment 3

to Operations Group Factual Report

DCA11FA084A/B

**ASA JEPPESEN 10.9 PAGE DEPICTING
BOS TAXIWAYS**

B-ATIS Descriptive 127.87	BOSTON Tower 128.0	ACARS D-ATIS PDC	BOSTON Clearance (GN) 121.65	Ground 121.9
VOT 111.0	Helicopter 124.72		BOSTON Departure (R) 133.0	
Rwy 4-27R, 150R, 30R, 14-32	Rwys 4-27L, 5, 27			
	132.22			

CAUTION: Be alert to runway crossing clearances. Readback of all runway holding instructions is required.

Flight crew must complete weight and balance paper work prior to taxi.

INTL Terminal, and north and south cargo arrivals contact Airport Gate Control on 131.1 before entering departing ramp areas.

RUNWAY INCURSION HOTSPOTS [FIS] (For information only, not to be construed as ATIS instructions)

CAUTION FOR THE FOLLOWING CONDITIONS:

- [F57] Rwy "4L APCH" when taxiing on TWY B to Rwy 4R and Rwy 9.
- [F58] Rwy 9-27 active when taxiing outbound on TWY C to Rwy 33L.
- [F59] Rwy 4L/22R active when taxiing on TWYs E and K at Rwy 9.
- [F60] Rwy 22L active when taxiing inbound on TWY E from Rwy 27.
- [F61] Rwy 33L active when taxiing outbound on TWYs C and D to Rwy 27.

