

Attachment 9

to Operations Group Factual Report

DCA08MA098


**GLOBAL EXEC AVIATION
ABORTED TAKEOFF PROFILES**

GLOBAL EXEC AVIATION

PART 135 TRAINING PROGRAM

LEAR 60 (LR-60)

FLIGHT MANEUVERS



Engine Failure—Below V₁ Speed

D-64


REVISION 12—JUNE 12, 2008

GLOBAL EXEC AVIATION

PART 135 TRAINING PROGRAM

LEAR 60 (LR-60)

FLIGHT MANEUVERS



Engine Failure—At or Above V₁ Speed

REVISION 12—JUNE 12, 2008

D-65