

DOCKET NO. **SA- 516**

EXHIBIT NO. **2C**

**NATIONAL TRANSPORTATION SAFETY BOARD
WASHINGTON, D.C**

DISPATCH RELEASE

OU JFKKATH
.MKCVDTW 172117

-----DISPATCH RELEASE-----

RF 00900/17JUL A P17119 TO LFPG
KJFK 185000 LFPG 711900
DUE CDL 27-51-2 FLIGHT PLAN FUEL BURN INCREASED BY 2 PER CENT
STRAIGHT RLSE DUE TO EINN/EIDW BELOW MINS
MEL 27-51-2 2L CANOE FLAPTRACK FAIRING
MEL 79-1 3 THRUST REVERSER
MEL 34-23 WEATHER RADAR
ANDRE BAUMGARDT DEPARTING DISP SCTR 79 718-244-2935
RLS TM 172115 RECEIVING DISP SCTR 32

FUEL SUMMARY:
ORIG/DEST KJFK/LFPG
RLSE FUEL 185000
TAXI FUEL 4500
TOTAL 189500

CAPT ADD -----
TOTAL FUEL -----

CAPTAIN -----

FUEL BURN COST FIGURE REFLECTS CURRENT PRICE AT DEPARTURE STATION
RELEASE 00900/17JUL/KJFK-LFPG PAGE 01 OF 01

NI: 00044 07/172117

OU JFKKATH
.MKCVDTW 172158

-----DISPATCH RELEASE-----

RF 00900/17JUL A P17119 TO LFPG
KJFK 176600 LFPG 709200
DUE CDL 27-51-2 FLIGHT PLAN FUEL BURN INCREASED BY 2 PER CENT
NEW RELEASE DUE TO PAYLOAD CHANGE.
MEL 27-51-2 2L CANOE FLAPTRACK FAIRING
MEL 79-1 3 THRUST REVERSER
MEL 34-23 WEATHER RADAR
STRAIGHT RELEASE DUE TO SNN DUB WX BELOW MIN.
* BUST PREVIOUS RELEASE *
ANDRE BAUMGARDT DEPARTING DISP SCTR 79 718-244-2935
RLS TM 172149 RECEIVING DISP SCTR 32

FUEL SUMMARY:
ORIG/DEST KJFK/LFPG
RLSE FUEL 176600
TAXI FUEL 4500
TOTAL 181100

CAPT ADD -----
TOTAL FUEL -----

CAPTAIN -----

FUEL BURN COST FIGURE REFLECTS CURRENT PRICE AT DEPARTURE STATION
RELEASE 00900/17JUL/KJFK-LFPG PAGE 01 OF 01

NI: 00110 07/172159

WSI METAR KISP 14:08(09)GMT 18-JUL-96

WSI METAR KISP 14:08(09)GMT 18-JUL-96

KISP 181050Z 0000KT 8SM FEW200 21/21 A3008 RMK SLP190
 KISP 180950Z 0000KT 8SM SCT250 19/19 A3009 RMK SLP193
 KISP 180850Z 0000KT 8SM SCT250 21/20 A3008 RMK SLP190=
 KISP 180750Z 0000KT 8SM SCT250 21/20 A3008 RMK SLP190
 KISP 180650Z 0000 8SM BKN250 22/20 A3008 RMK SLP190
 KISP 180550Z 0000 8SM BKN250 22/21 A3008 RMK SLP190 10212 20267
 54000=
 KISP 180550Z 0000 8SM BKN250 22/21 A3008 RMK SLP190 10212
 20267 54000
 KISP 180450Z 0000KT 8SM SKC 22/20 A3008 RMK SLP190
 KISP 180350Z 0000KT 8SM SKC 23/20 A3008 RMK SLP190
 KISP 180250 0000KT 8SM SKC 24/21 A3008 RMK SLP190 51010
 KISP 180150Z 0000KT 8SM SKC 25/21 A3008 RMK SLP190
 KISP 180050Z 25003KT 8SM SKC 25/22 A3005 RMK SLP181=
 KISP 172350Z 22004KT 8SM SKC 27/23 A3005 RMK SLP181 10030 20027
 53003=
 KISP 172250Z 24005KT 8SM FEW080 29/22 A3004 RMK SLP176 HAZY
 KISP 172150Z 24008KT 8SM SCT085 29/21 A3004 RMK SLP176
 KISP 172050Z 22013KT 8SM SCT060 30/22 A3004 RMK SLP176 56007
 KISP 171945Z COR 26008KT 8SM SCT040 30/22 A3004 RMK TCU N
 SLP176=
 KISP 171945Z 26008KT 8SM SCT040 30/32 A3004 RMK SLP176 TCU N
 KISP 171845Z 23011KT 8SM SCT040 30/21 A3004 RMK SLP176
 KISP 171750Z 20009KT 8SM FEW080 30/20 A3006 RMK SLP183 10295 20230
 58007=
 KISP 171750Z 20009KT 8SM FEW080 30/20 A3006 RMK SLP183 10295
 20230 58007
 KISP 171650Z 33003KT 8SM FEW080 30/18 A3008 RMK SLP190
 KISP 171551Z 26009KT 8SM FEW030 SCT080 SCT150 30/18 A3008 RMK
 SLP190=
 KISP 171450Z 30004KT 4SM HZ BKN080 29/21 A3008 RMK SLP190
 54000=
 KISP 171450Z 30004KT 4SM HZ BKN080 29/21 A3008 RMK SLP190 54000
 KISP 171350 29003KT 4SM HZ BKN080 27/21 A3008 RMK SLP190
 KISP 171250 25004KT 5SM HZ SCT120 26/21 A3008 RMK SLP190
 KISP 171150Z 26003KT 4SM BR HZ BKN130 23/21 A3008 RMK SLP190
 70014/ 10230 20210 52003=
 KISP 171050Z 27005KT 4SM BR HZ BKN090 OVC200 22/21 A3008 RMK
 SLP190=

WSI METAR KJFK 14:08(41)GMT 18-JUL-96

WSI METAR KJFK 14:08(41)GMT 18-JUL-96

KJFK 181051Z 0000KT 9SM SCT100 24/21 A3010 RMK AO2 SLP192
 T02390206=
 KJFK 180951Z 26004KT 9SM FEW100 22/21 A3010 RMK AO2 SLP191
 T02170206=
 KJFK 180851Z 28004KT 10SM CLR 23/20 A3009 RMK AO2 SLP189
 T02280200 55003
 KJFK 180851Z 28004KT 10SM CLR 23/20 A3009 RMK AO2 SLP189 T02280200
 55003=
 KJFK 180751Z 0000KT 10SM CLR 24/19 A3009 RMK AO2 SLP190
 T02440194=
 KJFK 180651Z 0000KT 10SM CLR 24/20 A3010 RMK AO2 SLP192
 T02390200=
 KJFK 180551Z 31005KT 10SM CLR 26/19 A3010 RMK AO2 SLP193
 T02560189 10278 20250 50003
 KJFK 180551Z 31005KT 10SM CLR 26/19 A3010 RMK AO2 SLP193 T02560189
 10278 20250 50003=
 KJFK 180451Z 29005KT 10SM CLR 26/19 A3011 RMK AO2 SLP194
 T02560189 403060222
 KJFK 180451Z 29005KT 10SM CLR 26/19 A3011 RMK AO2 SLP194 T02560189
 403060222=
 KJFK 180351Z 29007KT 10SM CLR 26/19 A3010 RMK AO2 SLP192
 T02610189=
 KJFK 180251Z 26008KT 10SM CLR 26/20 A3009 RMK AO2 SLP190
 T02610200 51008
 KJFK 180251Z 26008KT 10SM CLR 26/20 A3009 RMK AO2 SLP190 T02610200
 51008=
 KJFK 180151Z 24007KT 10SM CLR 26/21 A3009 RMK AO2 SLP190
 T02610211=
 KJFK 180051Z 24009KT 10SM FEW100 27/21 A3008 RMK AO2 SLP185
 T02670206=
 KJFK 172351Z 22008KT 10SM SCT060 BKN070 BKN090 28/21 A3007
 RMK AO2 WSHT 2306 RAB18E29 SLP183 P0000 60000 T02780211
 10306 20278 53007
 KJFK 172351Z 22008KT 10SM SCT060 BKN070 BKN090 28/21 A3007 RMK AO2
 WSHT 2306 RAB18E29 SLP183 P0000 60000 T02780211 10306 20278
 53007=
 KJFK 172327Z 28008KT 10SM -RA BKN060 BKN095 29/20 A3007 RMK AO2
 WSHT 2306 RAB18 P0000= (SPECI)
 KJFK 172327Z 28008KT 10SM -RA BKN060 BKN095 29/20 A3007 RMK
 AO2 WSHT 2306 RAB18 P0000 (SPECI)
 KJFK 172251Z 23011KT 10SM BKN060 BKN100 28/21 A3006 RMK AO2
 SLP179 VCSH NW T02830211
 KJFK 172251Z 23011KT 10SM BKN060 BKN100 28/21 A3006 RMK AO2 SLP179
 VCSH NW T02830211=
 KJFK 172151Z 24010KT 10SM FEW060 29/21 A3005 RMK AO2 SLP175
 T02940206=
 KJFK 172051Z 23013KT 10SM SCT060 30/21 A3005 RMK AO2 SLP175
 T03000206 56008=
 KJFK 171851Z 22016KT 10SM SCT050 30/21 A3006 RMK AO2 SLP180

WSI SA JFK 14:07(59)GMT 18-JUL-96

WSI SA JFK 14:07(58)GMT 18-JUL-96

JFK SA 1051 AO2A 100 SCT 9 192/75/69/0000/010/-
JFK SA 0951 AO2A 100 SCT 9 191/71/69/2604/010/-
JFK SA 0851 AO2A CLR BLO 120 10+ 189/73/68/2804/009/ 55003=
JFK SA 0751 AO2A CLR BLO 120 10+ 190/76/67/0000/009/-
JFK SA 0651 AO2A CLR BLO 120 10+ 192/75/68/0000/010/-
JFK SA 0551 AO2A CLR BLO 120 10+ 193/78/66/3105/010/ 50003 10082 20077=
JFK SA 0451 AO2A CLR BLO 120 10+ 194/78/66/2905/011/ 400870072=
JFK SA 0351 AO2A CLR BLO 120 10+ 192/79/66/2907/010/-
JFK SA 0251 AO2A CLR BLO 120 10+ 190/79/68/2608/009/ 51008=
JFK SA 0151 AO2A CLR BLO 120 10+ 190/79/70/2407/009/-
JFK SA 0051 AO2A 100 SCT 10+ 185/80/69/2409/008/-
JFK SA 2351 AO2A 60 SCT E70 BKN 90 BKN 10+ 183/82/70/2208/007/ 53007
6000/ 10087 20082 WSHFT 2306 RAB18E29 PCPN 0000=
JFK SA 2327 AO2A E60 BKN 95 BKN 10+R- 84/68/2808/007/ WSHFT 2306 RAB18
PCPN 0000=
JFK SP 2327 AO2A E60 BKN 95 BKN 10+R- 84/68/2808/007/ WSHFT 2306 RAB18
PCPN 0000=
JFK SA 2251 AO2A E60 BKN 100 BKN 10+ 179/83/70/2311/006/ VCSH NW=
JFK SA 2151 AO2A 60 SCT 10+ 176/85/69/2410/005/-
JFK SA 2051 AO2A 60 SCT 10+ 175/86/69/2313/005/ 56008=
JFK SA 1851 AO2A 50 SCT 10+ 180/86/70/2216/006/-
JFK SA 1751 AO2A 45 SCT 10+ 183/85/69/2314/007/ 58010 10086 20075=
JFK SA 1551 AO2A 110 SCT 10+ 192/84/67/2508/010/-
JFK SA 1451 AO2A 110 SCT 10+ 194/84/65/2712/011/ 53003=
JFK SA 1351 AO2A 70 SCT 10+ 192/79/64/2711/010/-
JFK SA 1251 AO2A 80 SCT 8 193/77/67/2608/010/-
JFK SA 1151 AO2A 37 SCT 100 SCT 7 190/76/68/2607/009/ 50003 6000/ 10076
20072 RAB11E27 PCPN 0000=
JFK SA 1051 AO2A 95 SCT 4F 193/73/69/2507/010/-

JFKWXTW

.HDQRMTW 181139/DEA00832

160346 FAP/17110/000803-17JUL/000800-17JUL/JFK-CDG 000000DAP
 160346 DG01 039700001A0008001115411154 000000DAP
 160943 FAP/C/17110/000800-16JUL/JFK-CDG/X/ 4A071FXOP
 160943 DG01 043900002A0008001115411154 000000DAP
 160943 DG01 043900003A0008001115411154 000000DAP
 160953 FAP/17305/000803-17JUL/000800-17JUL/JFK-CDG 000000DAP
 160953 EQUIP SUB FOR 0800/17JUL C029 JFK/CDG 000000DAP
 160953 DG01 039700004A0008001115411154 000000DAP
 160953 DG01 039700005A0008001115411154 000000DAP
 160955 FAP/C/17305/000800-17JUL/JFK-CDG/X/ 4A071EXOP
 160955 DG01 043900006A0008001115411154 000000DAP
 160955 DG01 043900007A0008001115411154 000000DAP
 160956 FAP/17119/000881-17JUL/000800-17JUL/JFK-CDG 000000DAP
 160956 EQUIP SUB FOR 0800/17JUL A029 JFK/CDG 000000DAP
 160956 DG01 039700008A0008001115411154 000000DAP
 160956 DG01 039700009A0008001115411154 000000DAP
 161006 FAP/C/17119/000800-17JUL/JFK-CDG/X/ 4A071EXOP
 161006 DG01 043900010A0008001115411154 000000DAP
 161006 DG01 043900011A0008001115411154 000000DAP
 161006 FAP/17119/000881-17JUL/000800-17JUL/JFK-CDG 000000DAP
 161006 DG01 039700012A0008001115411154 000000DAP
 170523 JA6100 F001 ATWA17052300080000000017JUL1115417119
 JFK / CDG 00 /

000000048200000 > 000000DAP
 170758 FAP/C/17119/000800-17JUL/JFK-CDG/X/ 4A071EXOP
 170758 DG01 043900013A0008001115411154 000000DAP
 170758 DG01 043900014A0008001115411154 000000DAP
 170804 FCA800/17JUL/CDG/FCO/3/18JUL A0091CXOP
 170804 DG01 056500015A0008001115411154 000000DAP
 170805 FTE ETD 800/17JUL/CDG/1715 A00912XOP
 170805 DG01 056500016A0008001115411154 000000DAP
 170806 FTE ETD 800/17JUL/CDG/0715 A00912XOP
 170806 DG01 056500017A0008001115411154 000000DAP
 170816 FCE800/17JUL/CDG/FCO/INMN/0910 A00912XOP
 170816 DG01 056500018A0008001115411154 000000DAP
 170824 FAP/17119/000881-17JUL/000800-17JUL/JFK-FCO 000000DAP
 170824 DG01 056500019A0008001115411154 000000DAP
 171246 FTH800/17JUL FTG/RU CDGWDTW CDGKOTW CDGKLTW CDGYRTW
 PRELIMINARY ESTIMATED PAYLOAD F800/17 TTL PAYLOAD 15000
 LBS CDGKLTW/MT C7061ACB1

171250 JA6100 F001 ATWA17125000080000000017JUL1115417119
 CDG / FCO 00 /
 00000001000000 > 000000DAP
 171401 FYNJFK/800/17JUL//27 E30112JK2
 171401 DG01 056500020A0008001115411154 000000DAP
 171720 JA6100 F001 ATWA17172000080000000017JUL1115417119
 JFK / CDG 00 /
 000000054700000 > 000000DAP

171948 FTH800/17JUL JFK/F/E OLLIE KRICK 59537 4A0B16FPL
 171948 FTH 800/17JUL JFK/CAP KEVORKIAN 47647 4A1023FPL
 172015 FTH 800/17JUL JFK/F/E CAMPBELL 12649 4A0B16FPL
 172027 FTH800/17JUL JFK/CAP SNYDER 82853 4A1016XJF
 172043 FTH 800/17JUL JFK/F/E DOUG ESHLEMAN 13633 4A1021FPL
 172117 F005 ATWA172117000800 17JUL JFK RC/PLAN 9298/0101
 JFKWDTW CDGYSTW *RLS ONLY JFKKATW * -----DISPATCH
 RELEASE----- RF 00800/17JUL A P17119 TO LFPG KJFK
 185000 LFPO 711900 DUE CDL 27-51-2 FLIGHT PLAN FUEL BURN
 INCREASED BY 2 PER CENT STRAIGHT RLSE DUE TO

CONTINUED

JFKWXTW
 .HDQRMTW 181139/DEA00832

CONTINUED
 EINN/EIDW

BELOW MINS MEL 27-51-2 2L CANOE FLAPTRACK FAIRING MEL
 78-1 3 THRUST REVERSER MEL 34-23 WEATHER RADAR ANDRE
 BAUMGARDT DEPARTING DISP SCTR 79 718-244-2935 RLS TM
 172115 RECEIVING DISP SCTR 32 FUEL SUMMARY* ORIG/DEST
 KJFK/LFPG RLSE FUEL 185000 TAXI FUEL 4500 TOTAL
 189500 CAPT ADD ----- TOTAL FUEL -----
 CAPTAIN

 FUEL BURN COST FIGURE REFLECTS CURRENT PRICE AT
 DEPARTURE STATION 010000DAP

172117 F005 ATWA172117000800 17JUL JFK 010000DAP
 172117 F003 ATWA172117000800 17JUL 17119 JFK 0071001850 0004507
 010000DAP
 172117 F003 ATWA172117000800 17JUL 17119 CDG 000000000000RY
 0000000 010000DAP
 172118 FTH 800/17JUL JFK/DH CAP GID MILLER 60321 4A0B16FPL
 172136 FWQ-JFKB7TW *FOR 800/R81R87R55/FI*800-17JUL.JFKCDBFCO
 CD1316JK2
 172158 F005 ATWA172158000800 17JUL JFK RC/PLAN 9378/0101
 JFKWDTW CDGYSTW \$RLS ONLY JFKKATW \$ -----DISPATCH
 RELEASE----- RF 00800/17JUL A P17119 TO LFPG KJFK
 176600 LFPG 708300 DUE CDL 27-51-2 FLIGHT PLAN FUEL BURN
 INCREASED BY 2 PER CENT NEW RELEASE DUE TO PAYLOAD
 CHANGE. MEL 27-51-2 2L CANOE FLAPTRACK FAIRING MEL
 78-1 3 THRUST REVERSER MEL 34-23 WEATHER RADAR
 STRIAIGHT RELEASE DUE TO \$NN DUB WX BELOW MIN. * BUST
 PREVIOUS RELEASE * ANDRE BAUMGARDT DEPARTING DISP SCTR
 79 718-244-2935 RLS TM 172149 RECEIVING DISP SCTR 32
 FUEL SUMMARY* ORIG/DEST KJFK/LFPG RLSE FUEL 176600
 TAXI FUEL 4500 TOTAL 181100 CAPT ADD ----- TOTAL
 FUEL ----- CAPTAIN

 FUEL BURN COST FIGURE REFLECTS CURRENT PRICE AT
 DEPARTURE STATION 010000DAP

172158 F003 ATWA172158000800 17JUL 17119 JFK 0063001766 0004507
 010000DAP
 172158 F005 ATWA172158000800 17JUL JFK 010000DAP
 172158 F003 ATWA172158000800 17JUL 17119 CDG 000000000000RY
 0000000 010000DAP
 172244 FTH800/17JUL FTG/QU JFKKATW JFKWBTW JFKYRTW FINAL FUEL
 TWA(800 P(17119 RLSE FUEL (176600 TAXI FUEL (4500
 CAPT ADD (0000 TOTAL FUEL (181100 JFKWD/(172244Z/K/J
 4A072FXNY
 172253 FTE ETD TWS00/17JUL JFK 2330/11 E50214JK2
 172253 DG01 056500021A0008001115411154 000000DAP
 172332 FTE ETD TWS00/17JUL JFK 0000/71-BAG PULL E50214JK2
 172332 DG01 056500022A0008001115411154 000000DAP
 180001 FTE ONO TWS00/17JUL JFK 0001 E50112JK2
 180001 DG01 056500023A0008001115411154 000000DAP
 180010 DMR/000800/17JUL/JFK FSTA ATH/08/0000/17119/A DSTA
 JFK/12/8000/17119/A/DSI 0000/MLDA 40/MLAA 00/AFN
 000881/AFD 17JUL/SAT 1190/ASAT 1190/AAT 1238/AAAT
 1238/DFN 000800/DFD 17JUL/SDT 1380/ASDT 1380/ADT
 0001/ADT 1111/AFN 0000/ASAT 0000/AAAT 0000/DFN 0000/ADT

0120/IMIN 0115/IMCT 0115/CD90 0000/CD91 0000/DLMN
0061/KEY TUETODT0B747 B747 / ASTA CDG/08/0000/
SDDTE 17JUL/ADTE 18JUL/SADTE 17JUL/AADTE 17JUL/SDDIF
0000/ADDIF 0001/SADIF 0000/AADIF 0000/ CD1

CONTINUED

QL7 00184 07/181140

JFKWXTW
.HDQRMTW 181139/DEA00832

CONTINUED

316JK2

180010 FTE DND TW800 17JUL JFK 0002/0035 CD1316JK2
180010 DMR/000800/17JUL/JFK FSTA ATH/08/0000/17119/A DSTA
JFK/12/8000/17119/A/DSI 0000/MLDA 40/MLAA 00/AFN
000881/AFD 17JUL/SAT 1190/ASAT 1190/AAT 1238/AAAT
1238/DFN 000800/DFD 17JUL/SDT 1380/ASDT 1380/ADT
0002/AADT 1442/EMIN 0000/AAGT 0000/MTFD 0120/MTDC
0120/IMIN 0115/IMCT 0115/CD90 0000/CD91 0000/DLMN
0062/KEY TUETODT0B747 B747 / ASTA CDG/08/0000/
SDDTE 17JUL/ADTE 18JUL/SADTE 17JUL/AADTE 17JUL/SDDIF
0000/ADDIF 0001/SADIF 0000/AADIF 0000/ CD1316JK2

180010 DG01 056500024A0008001115411154 000000DAP
180018 FTE DLY TW800 17 P17119 JFK DA.30 11 DB.32 71 E50214JK2
180018 DG01 056500025A0008001115411154 000000DAP
180019 DEP FI TW800/AN N93119/DA JFK/DT 0002/DF 0019/DS CDG
DT DDL ISP 180019 1951 - /ET 0628 DDLXCXA
180019 DMR/000800/17JUL/JFK FSTA ATH/08/0000/17119/A DSTA
JFK/12/8000/17119/A/DSI 0000/MLDA 40/MLAA 00/AFN
000881/AFD 17JUL/SAT 1190/ASAT 1190/AAT 1238/AAAT
1238/DFN 000800/DFD 17JUL/SDT 1380/ASDT 1380/ADT
0002/AADT 1442/EMIN 0000/AAGT 0000/MTFD 0120/MTDC
0120/IMIN 0115/IMCT 0115/CD90 0000/CD91 0000/DLMN
0062/KEY TUETODT0B747 B747 / ASTA CDG/08/0000/
SDDTE 17JUL/ADTE 18JUL/SADTE 17JUL/AADTE 17JUL/SDDIF
0000/ADDIF 0001/SADIF 0000/AADIF 0000/ 000000 DD

180019 DG01 056500026A0008001115411154 000000DAP
180020 AGM FI TW800/AN N93119 DT DDL HPN 180020 2013 -
FOT/DA JFK/FB 1235 DDLXCXA
180020 DG01 056500027A0008001115411154 000000DAP
180034 FTE DLY TW800 17 P17119 JFK DA.30 14 DB.32 71 E50214JK2
180034 DG01 056500028A0008001115411154 000000DAP
180050 JA6100 F001 ATWA1800500008000000000017JUL1115417119
CDG / FCD 00 /
000000006100000 > 000000DAP

180121 JSXL00081753900080011154JFKCDG0A02918300019171190590771P1
83005473104500033 380513DAP

180155 FWQ-STLDATW /*000800-17JUL.JFKCDG 777777XFT
180205 FWQ-STLDATW /*000800-17JUL.JFKCDG 777777XFT
180219 FCT800/17JUL/JFK/CDG/INNN/PLANE/FFFF/FFFF/OMNN/INNN
A0091CXOP

180219 DG01 056500029A0008001115411154 000000DAP
180220 FAP/C/17119/800-17JUL/JFK-FCD/X/ A0082CXOP
180220 DG01 060400030A0008001115411154 000000DAP
180314 FWQ-JFKDBTW /*000800-17JUL.JFKCDG 777777XFT
180350 FTE DLY TW800 17 P17119 JFK DA.00 00 DB.00 00 A00814XOP
180350 DG01 056500031A0008001115411154 000000DAP
180437 800/17JUL CANCELLATION JFK TO FCD CODE 79 -----
A0091CXOP
180437 DG01 056500032A0008001115411154 000000DAP