DOCKET NO. SA-510

EXHIBIT NO. 2M-1

NATIONAL TRANSPORTATION SAFETY BOARD

ADDENDUM TO EXHIBIT 2M PASSENGER INTERVIEW SUMMARY

NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety Washington, D.C. 20594

January 18, 1995

ADDENDUM TO EXHIBIT NO. 2M PASSENGER INTERVIEW SUMMARY

The following corrections should be made to:

- 1. Page 2, b, #3. Correction should read:
 - * heard no unusual noises
- 2. Page 2, b, #5. Correction should read:
 - * heard no unusual noises
- 3. Page 2, b, #8. Correction should read:
 - * heard no unusual noises

Charles F. Leonard

Operations Group Chairman