

NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety Washington, D.C. 20594

October 27, 2016

Attachment 5 – ACARS Communication

OPERATIONAL FACTORS

DCA16IA200

QU ATLDDDL .DDLXCXA 080242 A83 FI DL2845/AN N333NW DT DDL RAP 080242 M45A - 1202/07 KMSP/KRAP .N333NW /ON 0242/FOB

QU ATLDDDL
.DDLXCXA 080245
A80
FI DL2845/AN N333NW
DT DDL RAP 080245 M46A
- 3401/07 KMSP/KRAP .N333NW
JUST LANDED AT ELLSWORTH

QUATLDDDL.1UPLINK.MSG

** NO ACK REQ **

%ROGER. GIVE ME A CALL WHEN ABLE.

NAME: JOHN C. DENMAN

TITLE: FLT - SUPERINTENDENT

DESK: 5-0088

QU XXXXXDL
.ATLXGDL 080303
KM 23:03:35 00 REC
DL2845 RQ PATCH DD88 R13 60/61 P2
ATL SB
DD GA

DL OVR 30YRS NVR HAD ANYTHING LIKE THIS COORD WITH ELLS RIGHT N OW WHAT HAPPENED INITIAL $32\,$

//UTM WORKING OTHER FLT//

DD2 GIVE DETAILS PARKED BRAKES ON LOCATION START FROM THERE DL ENG OFF APU SEC PPL OUT THERE THATS WHERE AT DP2

HD 2845 08JUL0303 SPL 45f

JOHN HANG UP ALL CALLS CALL YOU BACK CELL JOHN PATCH IN THRU PHONE LINE HANG UP

QU ATLDDDL
.DDLXCXA 080322
A84
FI DL2845/AN N333NW
DT DDL RAP 080322 M49A
- 1304/07 KMSP/KRAP .N333NW

/IN 0244/FOB /BLK

QU XXXXXDL

.ATLXGDL 080347

KM 23:47:48 00 REC

DL2845 RQ PATCH DD88 R14 62/63 P2

ATL SB

DD GA

DL TRIED CALL DP DIRECT CHIEF PILOT SLC BASE COMMAND WING COMMA N ON BOARD PPRWORK INTACT RDY GO GIVE CLEAR GO TO RAP DONT NEED

ANYTHING GOOD ON FR JUST NEED CLEARANCE 13000 RWY FAA NUMS FOR P

E RFORM HE SAID 13000 RUN NUMS FOR RAP

HD 2845 08JUL0347 SPL 45f

GUESS LAST AIRLINER DID

DD DP GOING AROUND ROOM GET AUTH COMPLETE GOOD NEWS COMMAND LET

LAUNCH DONT KNOW CA

N DO AS AIRLINE YET YOU WERE CALLING DP

DL CALLED DIRECT LINE VOICEMAIL

DD SWAMPED SB

DL WILLING GIVE US QQQ TELL ABOUT IT GO THRU BASE COMMAND DONT

K NOW HOW LONG ON AC

DD RGR WILL NEED NEW FLT PLN WDR BEFORE LAUNC

HD 2845 08JUL0347 SPL 45f

H DL SEND ACARS

DD RIGHT IF CAN DO THAT GRT NEWS GIVE YOU CALL BACK HAVE YOUR C

ELL

DL 907-230-3151 DOWN ABOUT 35PERCENT CAN PLUG IN GO FROM THERE

DD STILL GOING AROU

ND INFO CALL BACK

DL THX

QU XXXXXDL

.ATLXGDL 080419

GM 00:19:15 00 ALL

DL2845 RQST PATCH DD88 62/69/P6/R20

ATI DD GA

DL2845 I SENT LEFT CTR RT CTR NO FUEL IN OUTBOARDS

GOT BACK INFO ON ACARS IS THERE ANYTHING ELSE U NEED

ATLDD SDBY WL CHK W/LC THEY ARE TRYING TO CONFIRM THAT

DL2845 CAN U ACARS ME BACK I NEED WDR WL WE BE ABLE

TO DO AN AUT

HD 2845 08JUL0419 SPL 45f

OMATIC OR MANUAL

ATLDD IT WL LIKELY NOT RECOGNIZE

DONT WANT TO DRAIN UR BATTERY WL CALL U BACK

DL2845 TH

EY ARE READY FOR US TO DEPART

ATLDD R CLR

QU XXXXXDL

.ATLXGDL 080438

KM 00:38:47 00 REC

DL2845 RQ PATCH DD88 R13 60/61 P2

ATL SB

DD GA

DL CK

DD FR IMBALANCE RT WING

DL CAN DO

DD STRIP TO MILITARY

DL SENT THAT ALREADY

DD CORRECT VIA EMAIL HAS THAT RAP TWR WILL BE CLOSED

DL AWARE

DD ASKED STAY THEY ARE NOT AWARE RTE HAS OVR EAST TO LOW QQQ D

IR

ECT RAP ONLY THING DO MAKE FLT PLN WORK

NO PROB DOING THAT

DD THINK GOOD DP NOT REQUEST TALK

DL CALL WHEN GET OVR GIVEN CLEARANCE GO OVR EVERYTHING TAKEN CA

RE OF HERE ZERO FR WT SEND VIA WDR

DD FR SLIP APPROVE FLT OPS VERBAL PAPER CANT DO NOT ELECTRONIC

S

TATION YOURE AT DOES NOT DO ELEC VERBAL

DL NOW

DD PATCH IN LC

LC VERIFY FR LT TANK

DL 4020 BURNING OFF APU CTR 140 5320 ENG START BURN OUT RT TANK

BRING BACK BALAN

CE BEFORE TAKE OFF

LC GET DOWN 4020 LT 4900 RT 140 CTR

DL OK

DD FR SLIP

DL AFFIRM CPY DOWN

DD LC GOOD

LC FR BASED ON THOSE NUMS EVERYTHING ELSE NO DIFF WORKING NORM

FLT SEND NUMS FROM HERE

DD ACARS RELEASE

DL WDR ALSO

LC SEND FROM

CSR 2023

HERE

DL DONE GET RDY

ECT TO LOW VOR FLY DIRECT TO RWY RAP

DL CLEARANCE FROM

DD SB ELLSWORTH TWR TRAVIS BECK
DL CAN HANDLE FROM THERE ANYTHING ELSE
DD GOOD TO GO
DL SIGN OFF GET RDY SB WAITING FOR ACARS
DD RIGHT NOW
DL THX

.DDLXCXA 080505 A81 FI DL2845/AN N333NW DT DDL RAP 080505 M59A - 1003/07 KRCA/KRAP .N333NW /OUT 0505/FOB /FBD /CLS 0401 /OPN /LIT /DRK

QU ATLDDDL
.DDLXCXA 080515
A82
FI DL2845/AN N333NW
DT DDL RAP 080515 M60A
- 1102/07 KRCA/KRAP .N333NW
/OFF 0515/FOB
/MOVEMENT